037-124-014 CE13-0012 211 THERESA STREET

CODE ENFORCEMENT OFFICER
CASSIDY ANDERSON
NOVEMBER 8, 2021

211 Theresa St Property frontage





211 Theresa St Window seal is not weather tight Living room window







211 Theresa St Glazing broken








211 Theresa St Living room windows and kitchen windows





211 Theresa St.
Combo Smoke detector and carbon monoxide detector
Keyed locks on both bedrooms







211 Theresa St Mildew on bathroom ceiling and wall







211 Theresa St Inoperable and unregistered vehicle







211 Theresa St Unapproved materials used to cover detached garage walls penetration in fire rating, required 5/8 or ½ inch gypsum board








211 Theresa St

Detached garage door covered without benefit of permit

Extension cords have been removed

water intrusion at skylight







211 Theresa St Foam spray and particle board surrounding wall base in detached garage







211 Theresa St Penetration in fire rating requires 5/8 or ½ inch gypsum board Water intrusion








211 Theresa St glazing broken in window glazing






211 Theresa St Existing accessory structure with unpermitted electrical



211 Theresa St Unpermitted electrical in existing accessory structure







211 Theresa St Unpermitted electrical throughout detached structure





