virtual



BOARD OF COMMUNITY SERVICES REGULAR MEETING AGENDA AND SUMMARY REPORT - CANCELLED SEPTEMBER 28, 2022

This meeting is being CANCELLED due to technological difficulties of the agenda not posting to the City's website. Items that are currently on the agenda will be continued to the next meeting. The next regular meeting will be held on October 26,2022 at 4:

4:00 P.M.

PURSUANT TO GOVERNMENT CODE SECTION 54953(E) AND THE RECOMMENDATION OF THE HEALTH OFFICER OF THE COUNTY OF SONOMA, BOARD OF COMMUNITY SERVICE MEMBERS WILL BE PARTICIPATING IN TODAY'S MEETING VIA ZOOM WEBINAR. BOARD MEMBERS AND STAFF ARE PARTICIPATING FROM REMOTE LOCATIONS AND/OR PRACTICING APPROPRIATE SOCIAL DISTANCING. MEMBERS OF THE PUBLIC MAY VIEW AND LISTEN TO THE MEETING AS NOTED ON THE CITY'S WEBSITE AND ON THE AGENDA.:

> • BY ZOOM BY VISITING HTTPS://SRCITY-ORG.ZOOM.US/J/84092970056, OR

• BY PHONE BY DIALING 877-853-5257 AND ENTERING WEBINAR ID: 840 9297 0056

DEADLINES AND INSTRUCTIONS FOR PUBLIC COMMENT ARE SET FORTH BELOW:

PUBLIC COMMENTS

Live Public Comment: The public accessing the meeting through the Zoom link or dial-in will be able to provide public comment on agenda items at the time the Agenda item is discussed during the Board of Community Services Meeting. Go to https://srcity.org/virtualparticipation for more information.

E-mail Public Comment: To submit an e-mailed public comment to the Board of Community Services, please send to: BOCS-comments@srcity.org by 5:00pm Tuesday, September 27, 2022. Identify in the subject line of your e-mail the Agenda Item Number on which you wish to comment, provide your name in the body of the e-mail and your comment. Please limit your e-mail to approximately 400 words. E-mail public comments will be added to the record prior to the start of the meeting.

E-mail public comments received by the deadline will be distributed to the Board of Community Services members and uploaded to the agenda prior to the start of the Board Meeting for public access. Emails received will not be read into the record.

1. CALL TO ORDER

2. ROLL CALL

3. PUBLIC COMMENTS FOR NON-AGENDA MATTERS

This is the time when any person may address matters not listed on this agenda, but which are within the subject matter of the jurisdiction of the Board of Community Services. Each speaker will be allowed three minutes to share their comments.

4. APPROVAL OF MINUTES

4.1 Regular Meeting Minutes - August 24, 2022 Draft

Attachments: Regular Meeting Minutes - August 24, 2022 - Draft

5. REPORTS ON UPCOMING EVENTS AND ACCOMPLISHED EVENTS

5.1 Upcoming Events and Accomplished Events

Attachments: UPCOMING EVENTS AND ACCOMPLISHED EVENTS

6. DIRECTOR UPDATES

This time is reserved for the Department Director/Deputy Director to provide a briefing on issues of interest. No action will be taken on these matters except to possibly place a particular item on a future agenda for consideration.

7. CHAIR/BOARD MEMBERS' REPORTS

The Chair and Board Members may provide brief updates relevant to their district, Recreation and Parks, or updates relevant to the subject matter within the jurisdiction of the Board of Community Services

8. SCHEDULED ITEMS

8.1 NEIGHBORHOOD SERVICES PROGRAMS

Recreation Coordinator Juan Flores will provide a Neighborhood Services update which will include a recap of the School of Rec program.

Recommended Action: Information

Attachments: Presentation

8.2 PARKS CONDITION ASSESSMENT AND PRIORITIZATION REPORT UPDATE

Assistant Parks Planner, Emily Ander, will present minor updates regarding the Parks Condition Assessment, address comments received from the Board of Community Services meeting on August 24,2022 and discuss next steps.

Recommended Action: Discussion and feedback

<u>Attachments:</u> <u>Presentation</u> <u>Report</u> Appendix

9. COMMITTEE REPORTS

9.1 Mayor's Lunch for Committee/Board Chairs

Recommended Action: Information

9.2 Santa Rosa Waterways Advisory Committee

Recommended Action: Information

10 WRITTEN AND/OR ELECTRONIC COMMUNICATIONS

10.1 ZEST Newsletter

<u>Attachments:</u> <u>ZEST Newsletter</u>

11. FUTURE AGENDA ITEMS

This schedule is tentative and subject to change pending final publication and posting of the Meeting Agenda. This time is reserved for discussion whether to place matters on a future agenda for further discussion.

12. ADJOURNMENT

The next regularly scheduled meeting if the Board of Community Services will be held on Wednesday, October 26th at 4:00 p.m.

The City of Santa Rosa does not discriminate against individuals with disabilities in its employment, services, benefits, facilities, programs, or activities. Requests for accommodations, auxiliary aids, or services necessary to participate in a city program, service, or activity, including printed information in alternate formats, are available by contacting the Parks office at 707-543-3291 or 707-543-3770 (TTY Relay at 711) or smcclure@srcity.org. Requests should be submitted as far in advance as possible, but no later than two business days before the scheduled meeting.

This information can also be accessed via the internet at: http://srcity.org. Any writing or documents provided to a majority of the Board of Community Services regarding any item on this agenda will be made available for public inspection at the Parks Office, 55 Stony Point Road, Santa Rosa, CA during regular business hours by contacting the contacting the Parks office at 707-543-3293 or 707-543-3770 (TTY Relay at 711) or smcclure@srcity.org. Requests should be submitted as far in advance as possible, but no later than two business days before the scheduled meeting.

City of Santa Rosa



Text File

File Number: 22-111BCS

Agenda Date: 9/28/2022

Version: 1

Status: In Committee

In Control: Board of Community Services

Agenda Number: 4.1

File Type: BCS- Minutes



4:00 PM

Board of Community Services Meeting Minutes - Draft

Wednesday, August 24, 2022

1. CALL TO ORDER

The meeting was called to order by Chair Pitts at 4:04 pm

2. ROLL CALL

Present: 6 - Chair Logan Pitts, Vice Chair Steven Spillman, Board Member Guido Boccaleoni, Board Member Madonna Cruz, Board Member Carole Quandt, and Board Member Carolina Spence

Absent: 1 - Board Member Terri Griffin

3. PUBLIC COMMENTS FOR NON-AGENDA ITEMS

Citizen Molly spoke regarding an email she submitted the previous month to the BOCS Comments email address. Email was included in Public Correspondence link. Comments were concern for the condition of Peter Springs Park.

3.1 PUBLIC CORRESPONDENCE

<u>Attachments:</u> <u>Public Correspondence</u> Late Correspondence.pdf

Approved as submitted

4. APPROVAL OF MINUTES

4.1 Regular Meeting Minutes - May 25, 2022 Final

Attachments: Regular Meeting minutes May 25 2022 - Final and approved.pdf

Approved as submitted

5. REPORTS ON UPCOMING EVENTS AND ACCOMPLISHED EVENTS

A list of accomplished and upcoming events was distributed to the Board and made available to the public prior to the meeting. Parks Deputy Director Santos highlighted the following:

Upcoming:

- South Davis Master Planning meeting in the park, in person 9/10/22
- SR History tour on Rosie the Trolley, tickets still available for 9/24 & 26 tours

Accomplishments:

- June 7 Council approved an application to the state and a grant was received for the Kawana Springs Park improvements
- Doyle Park is the home park for the SR Scuba Divers professional PECOS League baseball team
- **5.1** Upcoming Events and Accomplished Events

Attachments: UPCOMING EVENTS AND ACCOMPLISHED EVENTS

Approved as submitted

Meeting Minutes - Draft

6. DIRECTOR UPDATES

Parks Deputy Director Santos provided the following update:

• Finley Aquatic project to replace the wading pool with the Spray ground is on schedule More details to follow

• A scoping meeting for the Roseland Creek Community Park Master Plan Environmental Impact Report was held on8/17. It was a preliminary meeting to get community feedback before the main environmental process begins.

• The BVGC transitioned from the previous operator to operation under Touchstone Golf without any loss of golf tee times to the community. The restaurant will be opening early October. More information is available on their website: bennetvalleygolf.com, and feedback is welcomed.

• The fire damaged roadway along Fountaingrove Pkwy and Coffey Park/Barnes Rd is happening. There will be approx. 20,000 plants replaced. Project is expected to take about 6 months.

• Council approved a grant application for improvements to MLK Park and Newhall Bike Trail. The grant is to update the entire park with enhanced community features, and upgrades to the trail. We should be notified by November if the application will continue to the next round of evaluation.

• We have a new Assistant City Manager Daryel Dunston. Jason Nutt will continue to oversee the Parks as the Assistant City Manager over the Public Works Division.

7. CHAIR/BOARD MEMBERS' REPORTS

Chair Pitts – Went to the Galvin Park clean up with Dianna MacDonald. Went to the Scuba Divers play-off game. Visited, Live Oaks and Peter Springs Parks. Well used parks, by the neighborhoods.

Vice Chair Spillman – Met with the County and the City about the trail that is going to connect Sonoma and Santa Rosa going through the Oakmont/Annadel Park. Looking forward to that. Visits Juilliard Park every week. Currently a Bocce tournament happening.

Member Spence – Visited Howarth Park. Noted that a lot of RVs are street parking but not creating a disruption to the park. She is the Chair on the committee for the Merit Awards. One more reminder Sept 19th and the Finley Auditorium.

Member Boccaleoni – Commented on Southwest Community Park, noting that it is very busy, and the neighborhood would like to see additional playground equipment. Need better parking and sidewalks going to Dutton. Also, the park could use more play areas for little ones.

Member Cruz– Finley Center Senior Expo, two co-workers connected with a lot of Seniors with services. Also, enjoying riding her bike on the trail.

Member Quandt – Attended the Juilliard Park Music in the Park. Wonderful blend of Rec and Parks. Kudos to the Park Maintenance team for removing a Cypress tree at the Rural Cemetery. Lamplight Tours, 9/17 sold out for the Rural Cemetery. Also, County Eucalyptus tree removal program starting back up.

8. SCHEDULED ITEMS

Meeting Minutes - Draft

8.1 MEASURE M - PARKS CONDITION ASSESSMENT AND PRIORITIZATION REPORT

Parks Planner, Emily Ander, will present an update of the Parks Condition Assessment and Prioritization Report funded by Measure M - Parks for All

Recommended Action: Discussion and feedback

<u>Attachments:</u> <u>MEASURE M REPORT</u> <u>MEASURE M APPENDIX</u> <u>MEASURE M PRESENTATION</u>

Parks Planner, Emily Ander with Callander Associates, presented an update of the Parks Condition Assessment and Prioritization Report funded by Measure M – Parks for All

Recommended Action: Discussion and feedback

The report that was prepared in May was reviewed in detail to explain how a park was measured by specific criteria.

Board Questions/Feedback:

- The Board recommended that they have more time to review and before it is presented at Council, that the Council Members be allowed more time to review, as it was a lengthy report.

- The information was quite detailed.
- How will the completion of items be communicated?
- How does the city update the data?
- Perception is the report is higher level and not meant for public
- The ranking numbers were a bit confusing.
- Is there an interactive version of this report?
- Noted that the parks are noted by Quadrant. Would like to see the

Meeting Minutes - Draft

district more highlighted so that it can be reviewed by Council (per district).

- Report is dazzling and compliments to the staff and consultant.

Public Comment:

Steve R – wanted to discuss Prince Memorial Greenway. #46 Priority in report. Would like it ranked higher for priority.

9. COMMITTEE REPORTS

9.1 Mayor's Lunch for Committee/Board Chairs

Recommended Action: Information

Mayor's lunch was cancelled

9.2 Santa Rosa Waterways Advisory Committee

Recommended Action: Information

No meeting last month, not in several months Fencing at the Hyatt hotel is up. Property on Brookwood, no longer for lease.

10. WRITTEN AND/OR ELECTRONIC COMMUNICATIONS

ZEST Newsletter June - August 2022 was included as an attachment to this agenda

10.1 ZEST Newsletter

Attachments: ZEST Newsletter

11. FUTURE AGENDA ITEMS

- Can we add close captioning?
- Interim updates when time between meeting is extended?
- Update on parks that are in current revision

Meeting Minutes - Draft

12. ADJOURNMENT

The next regularly scheduled meeting of the Board of Community Services will be held on Wednesday, September 28th at 4 p.m.

Approved on:

Shelley McClure, Recording Secretary

City of Santa Rosa



Text File

File Number: 22-333BCS

Agenda Date: 9/28/2022

Version: 1

Status: In Committee

In Control: Board of Community Services

Agenda Number: 5.1

File Type: BCS-Agenda Item

SEPTEMBER 28, 2022 UPCOMING AND ACCOMPLISHED EVENTS

UPCOMING EVENTS:

- Sept 23 Oct 2: A Theater for Children Presents: Moana in the Steele Lane Community Center Dohn Theater
- Oct 8: Park-A-Month volunteer workday Finley Community Park <u>srcity.org/1028</u>
- Oct 22: Floating Pumpkin Patch at Ridgway Swim Center. An afternoon filled with games, pumpkin decorating and pumpkin-splashing fun! scitty.org/2913
- Oct 29: Halloween at Howarth. Visit Howarth Park in your favorite costume for trick-or-treating fun! srcity.org/2164
- Oct 29: Neighborhood Services Trunk or Treat and Movie event at Finley Community Park <u>www.srcity.org/2108</u>
- Early Oct: Construction began on a new area for two new picnic tables at DeTurk Roundbarn Park between the dog park and Boyce St. Completion is anticipated in early October. More information is available here: https://www.srcity.org/CivicAlerts.aspx?AID=1913

ACCOMPLISHED EVENTS:

- August 1: Neighborhood Services offered free memberships for program participation to "priority neighborhoods" described in the Community Safety Scorecard as neighborhoods with high risk factors for disadvantaged youth. A tool to look up addresses of interested participants was developed, marketed and has helped increase awareness and involvement in Neighborhood services programs <u>Neighborhood Services: Priority Neighborhoods</u>
- August 13: Over 40 people enjoyed the Stones and Images Rural Cemetery tour.
- August 22: Neighborhood Services after-school programs began at seven Burbank Housing sites. <u>https://www.srcity.org/3048/After-School-Programs</u>
- **August 26:** Reception for The Moonlight Quilt Guild will be held at the Steele Lane Community Center from 5-7pm. They will be displaying their work at the Community Center through the month of September.
- Sept 2: Movies in the Park, Howarth Park showing film "Luca" srcity.org/2170
- September 10: The fourth and final community meeting for the South Davis Neighborhood Park Master Plan update project was conducted in person at the park on Saturday, September 10, from 2 4p.m. The draft Master Plan was shared with the community. The presentation was followed by community input. Spanish interpretation was provided. A survey is available, in English and Spanish, until October 1st. The survey will be available on the project webpage and paper copies will be available upon request. Project information can be found here: https://srcity.org/3714/South-Davis-Park.
- September 10: Park-A-Month event at A Place to Play was cancelled due to excessive heat
- September 12: Adult Fall Softball season begins. Men's and Co-ed teams play at Northwest Softball fields Monday-Friday, 6pm-10pm. <u>srcity.org/1089</u>
- September 12: Neighborhood Services Fall sports began including Cheerleading and Sports Clinics, and Junior Warriors Basketball. <u>https://www.srcity.org/3047/Sports</u>
- Sept 16: Oktoberfest at Finley Community Center srcity.org/905
- Sept 16-17: Rural Cemetery Lamplight Tours srcity.org/1080
- Sept 19: The 40th Annual Merit Awards ceremony at Finley Community Center. 12 extraordinary individuals and organizations received awards for their service to the community. srcity.org/1241
- Sept 24: City Outdoor Booters youth soccer league begins. srcity.org/1126
- Sept 24 &26: Santa Rosa History Tour on Rosie the Trolley Registration Page

City of Santa Rosa



Text File

File Number: 22-327BCS

Agenda Date: 9/28/2022

Version: 1

Status: In Committee

In Control: Board of Community Services

Agenda Number: 8.1

File Type: BCS-Agenda Item



Neighborhood Services board of community services Juan Flores,

SEPTEMBER 28, 2022

JUAN FLORES, RECREATION COORDINATOR

Neighborhood Services

Early Intervention & Prevention programing that promotes positive youth development through recreational, social and athletic activities



Past Seasons Programs & Events

RECREATION CAMPS

- Recreation Sensation Summer Camp
 - 4 Locations
 - 70-120 Participants per location

FAMILY EVENTS

 Splash Bash @ Ridgway Swim Center

TEEN PROGRAMS

- Teen Sports Camp
- Volunteer L.I.T. Program







Current Programs

AFTER SCHOOL PROGRAMS

- 8 Burbank Housing Locations
- Elementary and Middle School Youth
- Serving 10 to 20 youth at each location

SPORTS

- Co-ed Cheer
- Jr. Warriors Basketball
- Sport Clinics







Upcoming Programs & Events

CAMPS

- Fall Break Camp
- Winter Break Camp
- Spring Break Camp

FAMILY EVENTS

- Halloween Bash
 - Trunk or Treat
 - Movie in the Park
- Fairytale Ball

CLASSES & SPORTS

- Futsal
- Intro to Dance
- Jr. Warriors Basketball
- NFL Flag Football








Become a Neighborhood Services Member


Neighborhood Services has a FREE membership program, which is used to qualify families to participate in low-cost sports, recreation, and afterschool programs. To become a member, you must live within Santa Rosa and provide verification of one of the following:

 Social Security Supplemental or Disability Income
 Public assistance through Sonoma County Human Services Department (ie:Temporary Assistance for Needy Families [TANF], food stamps/CalFresh)
 Housing Assistance Program
 MediCal Benefits
 Children in foster care and children and families experiencing homelessness
 Residents of Neighborhood Services' priority areas as identified through the

Violence Prevention Partnership's Community Safety Scorecard.




South Park, Corby/Hearn, and Roseland



West Steele & West 9th

High-Need Areas


Corby/Hearn Roseland South Park W. 9th W. Steele Lane



COMMUNITY SAFETY SCORECARD



Community Safety Scorecard



Domain	Indicator	Measured as
Economic Conditions	Cost of Living	% rent-burdened households
	Employment	% of unemployed
	Home Ownership	% of owner-occupied housing units
	Income	% of families below poverty
Crime and Safety	Arrests	Arrests per 1,000 residents
	Child Abuse & Neglect	Child abuse and neglect incidents per 1,000 children
	Gang Involvement	Gang-related incidents per 1,000 residents
	Narcotics	Narcotics-related incidents per 1,000 residents
	Youth Violent Crime	Youth-involved violent crime incidents per 1,000 youth
Family and Community Connectedness	Access to Health Care	% of insured population
	Civic Engagement	% of active voting age population
	Family Trauma	Domestic violence incidents per 1,000 residents
	Violence Prevention	Violence prevention nonprofits per 10,000 residents
School Conditions	Attendance	Elementary school truancy rate
	Discipline	Suspension rate
	Early Childhood Edu.	Licensed childcare seats per 100 children ages 0-5
	Graduation	High school cohort graduation rate




Over 1,500 Neighborhood Services Members







Questions?



City of Santa Rosa



Text File

File Number: 22-332BCS

Agenda Date: 9/28/2022

Version: 1

Status: In Committee

In Control: Board of Community Services

Agenda Number: 8.2

File Type: BCS-Agenda Item



- CITY OF SANTA ROSA -PARKS CONDITION ASSESSMENT & PRIORITIZATION REPORT

- FUNDED BY MEASURE M - PARKS FOR ALL -



PRIORITY 3. CONSULTANT RECOMMENDATIONS FOR DEFERRED

RFP asked consultant to provide:

- 1. Condition Assessment
- 2. Deferred Maintenance Analysis
- 3. Project Prioritization





- Staff would like to report on feedback received.
- Staff would like to hear comments and questions from the Board in order to finalize the Parks Condition Assessment & Prioritization Report.



QUESTIONS?

- DRAFT FINAL -









32

TABLE OF CONTENTS





TABLE OF CONTENTS

Executive Summary7			
Introduction			
Process			
Park Ranking.26Community Parks.28Neighborhood Parks.54Open Spaces.158Public Gathering Areas & Plazas.184Special Purpose Parks.192Trail Parks.200Roadway Landscapes.212			
Analysis270Citywide Analysis272Cost Analysis276Quadrant Analysis278City Council District Analysis282Park Type Analysis284Playground Analysis286Sports Field Analysis288Sports Court Analysis290			
Acknowledgments292			
Appendices			

LIST OF FIGURES



Figure 1	Citywide Parks Map	
Figure 2	Revision Table	
Figure 3	Example Amenities vs Assets	
Figure 4	Priority Ranking Weighted Values	
Figure 5	Park and Roadway Categories	
Figure 6	Priority Ranking Categories	
Figure 7	Recreation Programming Ranking	
Figure 8	Recreation Programming Scale	
Figure 9	Condition Rating Criteria	
Figure 10	Condition Rating Examples	
Figure 11	Play Value Ranking	
Figure 12	ADA Ranking Scale	
Figure 13	ADA Ranking Examples	
Figure 14	Useful Life Span Remaining	
Figure 15	Life Span Calculation	
Figure 16	Estimated Unit Cost Table	
Figure 17	Asset Areas Extracted from GIS	
Figure 18	Citywide Analysis Table	
Figure 19	Citywide Analysis Map	
Figure 20	Cost Analysis Table	
Figure 21	Cost Analysis Map	
Figure 22	Quadrant Analysis Table - Highest Priority	
Figure 23	Quadrant Analysis Map - Highest Priority	
Figure 24	Quadrant Analysis Table - Lowest Priority	
Figure 25	Quadrant Analysis Map - Highest Priority	
Figure 26	City Council District Analysis Table	
Figure 27	City Council District Analysis Map	
Figure 28	Park Type Analysis Table	
Figure 29	Park Type Analysis Map	
Figure 30	Playground Analysis	
Figure 31	Sports Field Analysis	
Figure 32	32 Sports Court Analysis	

EXECUTIVE SUMMARY

EXECUTIVE SUMMARY

The Parks Prioritization Report is a system-wide park assessment prepared for the City of Santa Rosa. The report evaluates parks and roadway landscapes maintained by the Recreation and Parks Department and provides a tool to help determine the allocation of funding for capital projects. Taking into account factors including condition, level of recreation programming, degree of accessibility, and play value, the report establishes a priority ranking based on each site's need for improvements. The report is intended to be utilized by City Staff, City Council, the Board of Community Services, and the community to provide a transparent look into the City's current park system and allow collective and well-informed decision making to improve park facilities and roadway landscapes over time. The report includes a description of the ranking methodology, a summary of each park and roadway landscape, and an analysis of the ranking results.

2005

7

Executive Summary

INTRODUCTION

Jaab

THE REAL PROPERTY AND AND ADDRESS OF A REAL PROPERTY AND ADDRESS OF A REAL PROPERTY ADDRESS OF ADDRES

YAK BOARD

Mathema

I SIG VAN

8



INTRODUCTION

BACKGROUND

In February 2021, the City of Santa Rosa (City) embarked on developing a comprehensive, system-wide report for parks and roadway landscapes maintained by the Recreation and Parks Department that would be a tool to prioritize the allocation of funding for improvements.

The City's park system is divided by Highways 101 and 12, creating four quadrants, and is made up of over 1,000 acres contained in over 100 park sites and over 70 acres of roadway landscapes. 85 of Santa Rosa's parks and 13 acres of roadway landscapes were assessed as a part of this report. Park sites are categorized into six park types, including neighborhood parks, community parks, special purpose parks, open spaces, public gathering areas and plazas, and trail parks. A number of city parks were not included as part of this report due to being under development. The selection of roadway landscapes that were evaluated represent a sample of the roadway landscape conditions found throughout the City to provide a general understanding of the overall condition of roadway landscapes maintained by the Recreation and Parks department.

Though the City's Recreation and Parks Department maintains all park sites on a scheduled basis, and a maintenance contractor provides mowing and blowing services at all park sites, the condition of park sites continue to be burdened by an insufficient quantity of maintenance staff since the 2008 economic recession. This has resulted in the current state of the City's park system, which has a substantial number of deferred maintenance deficiencies that need to be



Figure 1: Citywide Parks Map

addressed in order to uphold the condition of parks to a standard that provides value to the community.

Measure M – Parks for All, a sales tax that funds park improvements and maintenance, was passed by Sonoma County voters in 2018. Measure M funds, in addition to other funding sources, provides the City with the opportunity to begin addressing deferred maintenance needs across the park system. This report evaluates existing parks and roadway landscapes and determines the prioritization of these facilities to enable the City to make objective decisions on how to best utilize available funds for park improvements.

PURPOSE

The Parks Prioritization Report determines a ranking for each park facility based on the level of need it has for new improvements. The City will utilize the report to develop an effective approach to using the financial resources available to improve park infrastructure. This system-wide ranking provides the City with a decision-making tool to help determine how best to allocate funding for improvements across the entire system. A methodology using both qualitative and quantitative data was created to determine the objective system-wide ranking. Objectivity was an essential factor in determining park and roadway landscape rankings to ensure proper and efficient use of City financial resources.

The report will be primarily viewed and used by Park Planning Staff to make decisions on future capital improvement projects and by Parks Maintenance Staff to identify park amenities that are in critical need of attention. The report is also a resource for City Council and the Board of Community Services to assist in making informed decisions regarding park improvement projects and for the community to gain a holistic understanding of not only the parks in their neighborhood but also the condition of parks throughout the city. Application of this report will help move towards an improved park system that provides enjoyment and added play value to the community.

HOW TO USE THIS REPORT

Introduction: Explains the reasons for the development of the report and who the Report was written for. It also includes a summary of updates to the Report.

Process: Describes the approach to creating the prioritization ranking and the methodologies used for each ranking and supplemental category. Also includes a summary of the financial resources available for park improvements.

Park Ranking: Includes a cut sheet for each park and roadway landscape that contains the data for each ranking and a supplemental category specific to that site. Parks are sorted into the six park types and ordered alphabetically within each park type grouping.

Analysis: Includes an analysis of findings from the ranking results by evaluating the highest rank parks across the City within each quadrant and based on cost.

Acknowledgments: Includes a list of contributors to the Report.

Appendices: Includes references that supplement information described in the Report. A glossary can be found that describes terminology used within the Report.

REVISIONS

The Report is a living document that will periodically receive updates to reflect changes in the condition of existing parks as well as the addition of new parks into the City's park system. This section summarizes updates made to the report.

#	DATE	DESCRIPTION

Figure 2: Revision Table

PROCESS

......

12 Process

6 (Carl 14)



PROCESS CONDITION ASSESSMENT

The team performed a system-wide condition assessment to determine the current state of each park and roadway landscape. This included the evaluation of all the assets and amenities found at each site.

Prior to site investigations, an asset and amenity list was developed as well as an established rating criteria for each type of asset, see Figures 9 and 10. Amenities are defined as attributes of a park that have a designated use, such as sports fields, playgrounds, and dog parks. Assets are defined as specific components that make up a park amenity. For an amenity such as a playground, the assets would be identified as the play equipment, play surfacing, perimeter fencing, and so forth, see Figure 3 for examples.

The asset and amenity list represent all typical conditions across the park system. The rating criteria establishes a common scale in order to maintain objective results. For the site investigations, assets within each category were rated based on the rating criteria. The average rating of all the assets within an amenity was calculated to determine the amenity rating. The same approach was used to assess both park and roadway landscape conditions, though fewer amenities were identified to capture the components of a roadway landscape. In a number of cases, critical assets were established within an amenity. A critical asset is an asset that is essential to the function and usability of an amenity. The rating of an amenity cannot exceed the rating of its critical assets. The rating of an amenity will defer to the rating of its critical assets if the critical asset rating is lower than the average rating of all the assets.

A number of amenities, including irrigation, lighting, drainage, structures, and water features, were initially given a limited assessment due to the limitations posed for testing and verifying the functionality of such amenities. For these limited assessment items, checklists were developed for Park Maintenance Staff, who are more familiar with these items, to provide input. The combination of site investigations and city staff input resulted in a more complete and accurate conditions assessment.

Select structures, which had already been evaluated in the Facilities Condition Assessment (2018), were excluded from the assessment. These structures included



Amenity = Playground Assets = Equipment Curb Surfacing Furnishings Barriers Signs

Figure 3: Example Amenities vs Assets

buildings, such as community centers and restrooms, swimming pool facilities, shade structures, and bridges. Riparian zones and natural landscape areas that do not receive regular maintenance, such as weeding, pruning, and blowing, were also excluded from the assessment since they are not perceived as potential candidates for capital improvements unlike typical park amenities.

The result of the condition assessment provides a rating for each asset and amenity for a given park. The data was used to generate an overall condition ranking for the park to be used as one of the priority ranking categories, which is further explored in the next chapter.



Amenity = Tennis Courts Assets = Lighting Equipment Surfacing Furnishings Barriers Signs

AMENITY & ASSET LIST

Below is the complete list of amenities (indicated in red text) and their associated assets (in black text) used to evaluate the various elements at each park. Critical assets are identified with an asterisk (*).

GENERAL FURNISHINGS

Benches Tables Bike Racks Drinking Fountains Flag Pole Trash/Recycling Receptacle

GENERAL LANDSCAPE

Turf Non-Turf Ornamental Landscape Unplanted Landscape Natural Landscape

GENERAL TREES

Park Trees Trees in Natural Areas

GENERAL HARDSCAPE

Asphalt Concrete Pavers Decomposed Granite Amphitheater

GENERAL IRRIGATION

System Operation System Type Controller

GENERAL LIGHTING System Operation

GENERAL BARRIERS

Fencing / Walls Gates Guardrails Handrails Bollards

GENERAL SIGNAGE

Park ID Wayfinding Park Rules Traffic Signs Interpretive Signage Kiosks

GENERAL DRAINAGE

Culvert Curb and Gutter Drain Inlet Swales

GENERAL STRUCTURES Sheds

PICNIC AREAS

Tables* Kiosk / Sign Barbecues Specialty Barbecue Hot Coal Bin Surfacing Trash Receptacles Shade Trees

PARKING LOT

Wheel Stops Lighting Surfacing* Signage Striping

FITNESS EQUIPMENT

Equipment* Surfacing Barriers

PLAYGROUND

Equipment* Curb Surfacing Furnishings Barriers Signs Water Play Drainage

SPORTS FIELD

Surfacing* Field Striping Equipment Barriers Furnishings Signage Lighting Scoreboard Irrigation Drainage

SPORTS COURT

Surfacing* Field Striping Equipment Barriers Furnishings Signage Lighting Scoreboard Irrigation Drainage

TRAILS

Trailhead Sign Distance Marker Surfacing* Furnishings Barriers

DOG PARK

Surfacing Drinking Fountain Barriers* Benches Trash Receptacles Signage

SKATE PARK

Surfacing* Skate Features Barriers Furnishings

BIKE PUMP

TRACK Surfacing* Barriers Furnishings

WATER FEATURE

Barriers Lighting Docks Boat Ramps Mechanical Pump Surfacing Furnishings

SPRAYGROUND

Equipment* Surfacing Shade Furnishings Barriers

COMMUNITY GARDENS

Barriers* Surfacing Storage Irrigation Raised Beds Furnishings

RANKING METHODOLOGY

This Report provides an overall ranking of each park that is represented by a weighted average of four categories: condition, level of recreation programming, play value, and degree of accessibility. The ranking can be used to compare a park's level of priority against other parks within the City's park system. The lower the park ranking, the higher the priority it is for improvements. The overall priority ranking is a weighted average of the four priority ranking categories; condition is weighted at 70%, while recreation programming, play value, and accessibility are each weighted at 10%, see Figure 4.

Rankings for roadway landscapes are exclusively based on the condition ranking due to the fact that rankings within the three other categories do not vary when applied to roadway settings. Figure 5 represents the ranking system for each priority ranking category and how they impact the overall park rank. The supplemental categories provide additional information for each park amenity that do not impact the overall park ranking, this includes a cost estimate for the replacement of each amenity and the estimated life span remaining for each amenity.

OVERALL PRIORITY RANKING =





Figure 4: Priority Ranking Weighted Values

Similar to the conditions assessment, assets such as buildings, swimming pools, shade structures, bridges, and riparian areas were not taken into account when calculating the results for the priority ranking categories or supplemental categories. Buildings, swimming pools, shade structures, and bridges were not taken into account for the priority ranking categories or supplemental categories because they were already evaluated in the Facilities Condition Assessment (2018). Riparian areas were not taken in account because riparian areas are never completely replaced, and instead require mitigation.






Figure 5: Park and Roadway Categories

	High Priority	+		Low Priority
Condition	Poor	00	345	New
Accessibility	Compliant	12	345	Hazardous
Recreation Programming	High	12	345	Low
Play Value	High	12	345	Low

Figure 6: Priority Ranking Categories

PRIORITY RANKING CATEGORIES Condition

The condition ranking of each park and roadway landscape is the average of the condition of all amenity ratings assigned to each site. The condition ranking compares sites to a "new" site, and not sites to each other. The condition ranking contributes the most to the overall park rank at a weighted value of 70% of the total park ranking. Condition is the primary driver for how a park should rank relative to other parks due to condition being the best indicator for a park's need for improvements. The other ranking categories are intended to distinguish the priority between parks with similar condition rankings.

Recreation Programming


Recreation programming was used to evaluate how frequently an amenity is utilized by the community. The data used to develop the ranking method was the amount of revenue generated by the amenities within a park. The City does not have available data collected to quantify park usage, therefore revenue amounts generated at the parks provide quantifiable data to evaluate the level of programming that occurs, as well as the frequency of use of an amenity. Revenue generation fee data from 2019 is used in this report to generation the recreation programming ranking.

Park rankings and individual amenity rankings for recreational programming used a one through five numerical ranking system with a revenue range for each rank. The table below identifies the range of revenue generation associated with each rank:

RECREATION PROGRAMMING RANKING	REVENUE GENERATION AMOUNT		
1	OVER \$50K		
2	\$10K TO \$50K		
3	\$5K TO \$10K		
4	\$1 TO \$5K		
5	\$0		

Figure 7: Recreation Programming Ranking





Condition Rating Criteria

G	eneral
5 4 3 2 1	New or near new condition, no visible defects No longer new, light / normal signs of wear, superficial damage / no major defects Functioning as intended, noticeable signs of deterioration, some minor repairs are required Multiple major defects, Signs of excessive wear, not fully functioning, needs substantial repair Not functional, unsafe to use, replacement is required
Ha	ardscape / Surfacing
5	New or near new condition, no visible defects
4	No longer new, light / normal signs of wear, superficial damage / no major defects. Sand, gravel or mulch with light weed growth.
3	Surface is moderately worn with limited cracking and lifting, markings need maintenance. Sand, gravel or mulch with significant weed growth
2	Surface is heavily worn and uneven throughout, with major cracking and lifting, markings worn or absent. Sand, gravel or mulch is thin / bare in spots, weedy
1	Hazardous: major holes, buckling or erosion. Sand, gravel or mulch is missing / heavily eroded.
Si	gnage
5 4 3 2 1	New or near new condition, no visible defects, fully legible No longer new, light / normal signs of wear, fully legible Functioning as intended, noticeable signs of deterioration, some minor repairs are required Multiple major defects, signs of excessive wear, not fully legible, needs substantial repair Not functional, unsafe to use, replacement is required, illegible
Tu	urf / Ornamental Landscape
5 4 3 2 1	Vigorous and healthy, no signs of defect Moderate levels of annual weeds and gaps / dieback can be addressed with regular maintenance Weedy, significant gaps / dieback requiring rehabilitation Major defects, rehabilitation not expected Dead or missing plant material, potentially hazardous
Ur	nplanted Landscape
5 4 3 2 1	Fresh mulch, little to no weed growth Mostly mulched with moderate weed growth, needs regular maintenance Patchy mulch with significant weed growth, needs significant work Little to no mulch present, very weedy No mulch present, noxious weeds observed, potential fire hazard
Tr	ees
5 4 3 2	All trees appear vigorous and healthy, with no obvious structural damage. Most trees appear vigorous and healthy, with limited signs of structural damage and dieback. Mixed canopy with up to 25% of trees showing signs of significant structural damage or dieback. More than half of trees appear unhealthy or have significant signs of structural damage and dieback. Most trees have significant damage or dieback, or are dead; trees should be assessed for hazards.
	ghting
5	City Standard, new LED fixtures
4	LED fixtures, not new but fully functional and in good condition
3	Fixtures not LED, but system is fully functional and in good condition
2 1	Fixtures not LED; parts of the system are damaged or not functional Lighting not functional

Figure 9: Condition Rating Criteria

Irri	igation
	New system, equipment meets current City standards and is designed for MWELO Equipment meets current City standards and is water efficient, normal maintenance needs with no major problems.
2	Outdated equipment doesn't meet City standards, system functional but not water efficient Outdated equipment, parts of system are not functional, has multiple minor leaks, coverage problems apparent from plant dieback Major system breaks / not functional

Figure 9 (continued): Condition Rating Criteria

Condition Rating Examples



Figure 10: Condition Rating Examples

Play Value

Play value identifies high-touch amenities that are associated with active uses such as exercise, recreation, and organized activities. Such amenities frequently experience rigorous use and therefore accelerated wear. Examples of high play value amenities include playgrounds, sports fields, and sports courts. Amenities with minimal or no play value are associated with passive use amenities or park infrastructure amenities that are not high-touch surfaces. Examples of low park value amenities include drainage, irrigation, and lighting. Each amenity received a play value ranking based on the play value ranking table in Figure 11. Each park's play value ranking is the same as its lowest value play value ranking amenity.

Accessibility

An ADA assessment is an evaluation of an existing condition's compliance with the American with Disabilities Act (ADA) regulations, which establishes accessibility standards for properties to serve people with disabilities. ADA assessments were

F	
AMENITY	PLAY VALUE RANKING
Playground	1
Sports Field	1
Sports Court	1
Skate Park	2
Sprayground	2
Fitness Equipment	3
Dog Park	3
Community Garden	3
Picnic Areas	4
Trails	4
Parking Lot	5
Water Feature	5
General Furnishings	5
General Landscape	5
General Trees	5
General Hardscape	5
General Irrigation	5
General Lighting	5
General Barriers	5
General Signage	5
General Drainage	5
General Structures	5

Figure 11: Play Value Ranking



Figure 12: ADA Ranking Scale

conducted in 2013 and 2016 for the City's parks system, which identified ADA deficiencies for the majority of parks. As part of this report, the existing 2013 and 2016 assessments were reviewed and evaluated on-site to verify whether or not items within those reports have been addressed.

The accessibility rankings in this Report are to not be utilized independently as the only source for ADA compliance information for parks.

ADA items were ranked based off of how hazardous an item is and how much the item impedes someone's ability to access park amenities, see Figure 13 for examples. Deficiencies that are more hazardous to users would result in a lower rank, implying the priority for replacement of this amenity is greater. **Amenities receiving a lower rank on this scale will be elevated in priority for replacement.** ADA items pertaining to restrooms, interior of buildings, or face of buildings were not evaluated as part of this Report.

The average rank of all the ADA accessibility deficiencies found within an asset will be used to determine the rank of each amenity. The total park rank is determined by using a weighted average

Ranking	Examples of ADA Deficiencies
5	ADA assessment reports did not identify any deficiencies or deficiencies have been addressed
4	Door or gate not in compliance (requires >5lbs of force to operate or is missing kick plate) Sign: present but is not in compliance (mounting height, text size, location, content) Striping faded (crosswalks, ADA parking stalls)
3	Obstruction of overhead clearance Some accessible furnishings or companion seating provided, but the minimum is not met Required sign or striping missing Play Areas: No transfer system or transfer system not in compliance with ADA Diameter of handrails at ramps not between 1.25" and 1.5"
2	No landing, landing too short, or landing slopes along path of travel No accessible furnishing, companion seating, or other accessible space is provided Distance between accessible access points is not compliant Drinking fountain not high/low Transfer system does not serve at least 50% of elevated play components Minimum number of ground level play components on accessible route not met Non-compliant play area path width (36" < 60") Play Equipment is not in compliance with ADA; not a safety hazard*
1	Lifting, cracks, or gaps in pavement Non-compliant slope or cross-slope Surfacing is not accessible Missing truncated domes Curb ramp not in compliance Play Equipment is not in compliance with ADA; safety hazard*

ADA ranking examples

Figure 13: ADA Ranking Examples

of all amenity rankings. The weighted average takes into account the quantity of ADA deficiencies within an amenity along with its average rank.

In the situation that ADA reports were not available for a park, the ADA ranking matches the condition ranking. This approach was determined using the rationale that ADA deficiencies are assumed to be more prevalent at parks that are in poor condition and compliance with ADA standards are assumed to be more likely met at parks in newer and better condition.

SUPPLEMENTAL CATEGORIES Life Span

The life span category provides an approximate duration of time remaining until an amenity needs to be replaced. Approximate total life spans were determined through research, consultation with manufacturers, and professional opinions. The remaining life span of an amenity is calculated by taking a percentage of the total life span. The percentage is based off the amenity's conditions ranking, see Figure 14 and 15.

CONDITION RATING	
5	% OF USEFUL LIFE SPAN REMAINING
5	100%
4	75%
3	50%
2	25%
1	0%

Figure 14: Useful Life Span Remaining

For general park categories, such as general furnishings, each category is given an average life span based upon its most common or prevalent components. In the case of furnishings, the prevalent components include benches and tables.

For amenities with a mixture of elements with different life spans, the life span for the amenity is based on its "critical item." If the critical item is in poor condition, then the amenity itself is no longer usable or cannot be properly used, and the condition cannot be adequately resolved through repair. For example:

Tennis courts: The critical item is surfacing. If the surfacing has a lot of cracks and bumps, then the tennis court cannot be used properly. Even if the net and fence are in pristine condition, play will be hindered by the condition of the surface. It is assumed that once surfacing has reached the end of its useful life, the extent of work required to repair it will justify improvement of the entire amenity.

Playgrounds: The critical item is the play equipment. Even though surfacing is critical to playground safety and function, it is reasonable to expect to repair or replace surfacing without replacing the entire amenity. Replacement of equipment, however, would require replacement of the whole amenity, including surfacing.



Figure 15: Life Span Calculation

Cost Estimate

The cost estimate process for determining a replacement cost for each amenity, as well as for the total park, required a two-step process. Step one involved extracting the square footage of each amenity within the park using data provided by the City's GIS database. Step two involved determining a unit cost per square foot for each amenity using recent bid results.

Bid results from the past few years were compiled to determine the average unit cost per square foot for each amenity. Each unit cost number acquired from a bid result was adjusted to accommodate inflation to reflect anticipated 2022 bid costs. The unit costs for construction were then adjusted to account for soft costs including design, surveying, engineering, testing, inspections, and City administration across the board.

The square footage for each amenity is multiplied by the unit cost to generate an estimate of combined construction costs and soft costs required to replace each amenity. The sum of all amenity replacement costs amounts to the total estimated cost to replace all the amenities in the park.

Structures, including community centers and restrooms, swimming pool facilities, shade structures and bridges, in addition to riparian zones within parks, were excluded from the estimated replacement costs.

Park Amenity	Estimated Design + Construction Cost (Unit Cost per SF)
General Furnishings	\$0.75
General Landscape	\$3.66
General Trees	\$0.38
General Hardscape	\$46.82
General Irrigation	\$4.76
General Lighting	\$0.80
General Barriers	\$0.31
General Signage	\$0.32
General Drainage	\$1.97
General Structures	\$279.72
Picnic Areas	\$74.36
Parking Lot	\$26.38
Fitness Equipment	\$77.57
Playground	\$124.22
Tennis Court	\$31.84
Pickleball Court	\$22.72
Bocce/Horseshoe Court	\$45.99
Basketball Court / Handball	\$24.43
Volleyball Court	\$33.57
Soccer Field	\$7.76
Softball/Baseball Field	\$32.83
Football Field	\$6.45
Track and Field	\$23.40
Trails	\$12.50
Dog Park	\$20.32
Skate Park	\$56.70
Bike Pump Track	\$41.44
Water Feature	\$207.20
Sprayground	\$1,165.10
Community Gardens	\$54.23

Figure 16: Estimated Unit Cost Table



Figure 17: Asset Areas Extracted from GIS

FUNDING SOURCES

As this Report provides a holistic overview on the City's parks and roadway landscapes, and the prioritization of their need for improvement, this chapter reviews the available funding sources. The funding sources available for capital projects excludes the department's funds that are dedicated for operations and maintenance. Funding sources for capital projects include the Measure M -Parks for All sales tax, park development impact (PDI) fees, and grant funding. General Fund contributions are typically not available for capital improvements, however, they do contribute toward maintenance and operation efforts for parks. All revenue generated by park facilities is directed to the General Fund and not to the Recreation & Parks Department.

Measure M

24

Measure M – Parks for All is a sales tax that supports Sonoma County's regional and city parks, and is estimated to provide \$1.9 million to Santa Rosa between the years of 2019 and 2029. Santa Rosa's City Council has approved the following allocation of Measure M funding: utilize approximately 50% of funds for capital improvements, utilize approximately 40% of funds for park maintenance enhancements, utilize approximately 10% of funds for recreation programming enhancements. This approved funding plan allocates \$950k annually to capital improvements that follow the specific allowable uses as defined in the Sonoma County Measure M Expenditure Plan. Allowable capital improvements include improving and developing athletic fields, playgrounds, restrooms, picnic areas and visitor amenities; creating and expanding parks, trails, bikeways, public art, and recreation and historical facilities; and planning and developing bike paths and trails with connections to schools, community spaces and regional trails; and improving trails along waterways and riparian areas to benefit fish, wildlife, habitat, and water quality.

Park Development Impact Fees

Park Development Impact (PDI) fees are revenue sources for capital projects. PDI fees are one-time fees paid by developers in-lieu of park land dedication, for the City to utilize for development of new parks or improvements to existing park facilities. PDI fees collected for each quadrant must be utilized on capital projects within the same quadrant and must be used for the development of new amenities or complete replacement of existing amenities and cannot be used for minor repair or maintenance. PDI revenue is dependent on the development market and varies year to year.

Grant Revenue


Grants are another important source of funding for building new, and renovating existing park facilities. Grant funding is available from various sources and is subject to wide variance from year to year. Grant funding is commonly received on a reimbursement basis and may be subject to a local match requirement where local funds must be utilized from an appropriate funding source.

PARK RANKING



PARK RANKING

The park ranking chapter consists of the ranking results for each park and roadway landscape. The parks and roadway landscapes are organized into subchapters based on park type or roadway landscape, which include:



At the beginning of each sub-chapter, a summary matrix is provided as an overview of each park that is included within the given park type. Within each sub-chapter, the parks are organized in alphabetical order. The following represents the color coding found within the ranking matrix of each park and roadway landscape based on each amenities rank, where 1 is the highest priority and 5 is the lowest priority.

1.0 to 1.9, highest priority
2.0 to 2.9
3.0 to 3.9
4.0 to 4.9
5.0, lowest priority





COMMUNITY PARKS

Twelve community parks that are owned and maintained by the City were evaluated as part of this report. This section evaluates the priority ranking of each community park based on condition, recreation programming, play value, and accessibility. In addition, the approximate lifespan and the estimated replacement cost is provided for each amenity as well as the overall park. Parks with a priority ranking closer to one (1) are identified as having a higher priority for new improvements, while parks that rank closer to five (5) have a lower priority for improvement needs. The table below identifies the community parks in order of priority ranking, the parks identified in gray were not assessed by this Report.

Co	Community Parks - Ranked by Priority Ranking									
Rank	Park	Priority Ranking	Lifespan	Area (Acres)	Estimated Replacement Cost	Quadrant	Park Type			
1	Youth Community Park	2.5	15.1	73.8	\$ 44,837,076	NW	СР			
2	Northwest Community Park	2.5	14.0	35.1	\$ 27,127,956	NW	CP			
3	Southwest Community Park	2.5	11.7	19.8	\$ 17,767,728	SW	CP			
4	Doyle Community Park	2.5	14.2	21.8	\$ 18,209,391	NE	CP			
5	Rincon Valley Community Park	2.5	12.7	18.9	\$ 14,774,691	NE	CP			
6	Howarth Community Park	2.6	14.4	137.8	\$ 86,874,681	SE	CP			
7	Finley Community Park	2.6	14.3	12.2	\$ 12,823,091	NW	CP			
8	A Place to Play Community Park	2.7	13.6	77.2	\$ 51,368,135	NW	CP			
9	Franklin Community Park	2.8	14.8	13.4	\$ 10,426,680	NE	CP			
10	Galvin Community Park	2.8	16.1	23.4	\$ 26,267,160	SE	CP			
11	Skyhawk Community Park	3.1	16.2	20.8	\$ 13,173,720	NE	СР			
12	Nagasawa Community Park	3.4	13.8	33.2	\$ 32,663,391	NE	СР			
-	Kawana Spring Community Park (Future)	-	-	20.0	-	SE	СР			
-	Roseland Creek Community Park (Future)	-	-	19.1	-	SW	CP			





PARK TYPE





SIZE (ACRES) 77.2

ADDRESS 2375 West Third Street

PRIORITY OUT OF 12 COMMUNITY PARKS 8

SUMMARY

A Place to Play Community Park is a 77.2 acre community park located in the northeast quadrant of Santa Rosa, CA. The park contains picnic areas, a parking lot, playgrounds, athletic fields, trails, a dog park, and a remote-control car race track.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. A Place to Play Community Park has a high level of recreation programming, very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the general hardscape and signage. Concrete pavement is cracked and uneven in places and the decomposed granite has significant weeds. There are park rules signs in poor locations and interpretive signs that are damaged and illegible.

PRIORITY RANK

RANKING MATRIX - A PLACE TO PLAY

		Priority Rankin	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	3.1	2.0	1.0	1.8	13.6	\$ 51,368,135
General Furnishings	3.0	5.0	5.0	2.0	10.0	\$ 1,703,514
General Landscape	3.0	4.0	5.0	-	12.5	\$ 7,002,907
General Trees	3.0	5.0	5.0	-	25.0	\$ 729,298
General Hardscape	1.5	4.0	5.0	1.0	2.5	\$ 4,612,380
General Irrigation	4.0	5.0	5.0	-	18.8	\$ 9,117,996
General Barriers	4.0	5.0	5.0	-	22.5	\$ 969,582
General Signage	2.3	5.0	5.0	4.0	6.7	\$ 991,510
General Drainage	4.0	5.0	5.0	-	26.3	\$ 6,140,912
General Structures	3.0	5.0	5.0	-	15.0	\$ 35,043
Picnic Areas	3.0	5.0	4.0	1.5	10.0	\$ 780,706
Parking Lot	3.5	4.0	5.0	3.0	11.3	\$ 6,716,857
Playground	3.3	5.0	1.0	1.0	15.0	\$ 517,118
Sports Field: Baseball	3.0	4.0	1.0	-	7.5	\$ 1,425,551
Sports Field: Baseball	2.0	4.0	1.0	2.0	3.8	\$ 4,228,891
Sports Field: Soccer	3.0	2.0	1.0	-	10.0	\$ 4,641,668
Trails	4.0	5.0	4.0	-	11.3	-
Dog Park	3.2	5.0	3.0	4.0	30.0	\$ 691,907
Remote Control Car Race Track	2.5	5.0	3.0	-	7.5	\$ 1,062,297

Note: See the appendices for asset rankings



DOYLE COMMUNITY PARK



PARK TYPE





SIZE (ACRES) 21.8

ADDRESS 700 Doyle Park Dr

PRIORITY OUT OF 12 COMMUNITY PARKS 4

SUMMARY

Doyle Park is a 21.8 acre community park located in the northeast quadrant of Santa Rosa, CA. The park contains athletic fields, multiple picnic areas, playgrounds, a dog park, horseshoe courts, and fitness equipment stations along the park's walking path.

The overall condition of the park is adequate, with a majority of the amenities functional and a few in need of servicing. Doyle Park has a very high level of recreation programming, very high play value, and has a number of significantly non-compliant ADA features.

The critical condition amenities within the park are the fitness equipment, parking lot, and storage sheds. The fitness equipment is damaged due to excessive wear and is unsafe to use, the parking lot has substantial cracking and undulations throughout the asphalt pavement, and the storage shed has signs of severe deterioration.

RANKING MATRIX - DOYLE COMMUNITY PARK

		Priority Rankir	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	3.1	1.0	1.0	1.8	14.2	\$ 18,209,391
General Furnishings	3.0	5.0	5.0	2.0	10.0	\$ 450,492
General Landscape	3.0	4.0	5.0	-	12.5	\$ 1,674,144
General Trees	4.0	5.0	5.0	-	37.5	\$ 174,349
General Hardscape	3.5	1.0	5.0	1.0	12.5	\$ 2,140,809
General Irrigation	4.0	5.0	5.0	-	18.8	\$ 2,179,786
General Barriers	3.0	5.0	5.0	2.0	15.0	\$ 247,850
General Signage	4.5	5.0	5.0	4.0	17.5	\$ 253,456
General Drainage	3.0	5.0	5.0	-	17.5	\$ 1,569,776
General Structures	2.0	5.0	5.0	-	7.5	\$ 72,619
Picnic Areas	4.0	4.0	4.0	2.0	15.0	\$ 1,218,345
Parking Lot	2.0	5.0	5.0	1.5	3.8	\$ 2,507,497
Fitness Equipment	1.0	5.0	3.0	-	0.0	\$ 77,569
Playground	3.3	5.0	1.0	3.0	15.0	\$ 712,848
Sports Field: Baseball	3.0	3.0	1.0	2.0	7.5	\$ 3,373,876
Sports Court: Horseshoe	3.9	5.0	1.0	1.5	11.3	\$ 349,879
Dog Park	3.0	5.0	3.0	3.0	20.0	\$ 568,835

Note: See the appendices for asset rankings





PARK TYPE





SIZE (ACRES) 12.2

ADDRESS 2060 West College Ave

PRIORITY OUT OF 12 COMMUNITY PARKS 7

SUMMARY

Finley Community Park is a 12.2 acre community park located in the northwest quadrant of Santa Rosa, CA. The park contains picnic areas, a parking lot, playgrounds, and multiple sport courts.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Finley Community Park has a high level of recreation programming, high play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the playground and volleyball court. The playground rubber surfacing is deteriorating and peeling back in some areas and the playground equipment is showing significant wear. At the volleyball court, the net is missing and the sand surfacing has significant weed growth.





	Priority Ranking Categories				Supplemental Categories	
Amenities	Condition	Recreation Programming	Play Value		Lifespan	Cost Estimate
	3.1	2.0	2.0	1.7	14.3	\$ 12,823,091
General Furnishings	3.8	5.0	5.0	2.0	13.8	\$ 352,991
General Landscape	3.0	4.0	5.0	-	12.5	\$ 1,345,071
General Trees	4.0	5.0	5.0	-	37.5	\$ 140,079
General Hardscape	3.3	5.0	5.0	1.0	11.7	\$ 2,773,311
General Irrigation	3.5	5.0	5.0	-	15.6	\$ 1,751,322
General Lighting	3.0	5.0	5.0	-	20.0	\$ 425,466
General Barriers	4.0	5.0	5.0	-	22.5	\$ 165,476
General Signage	2.5	5.0	5.0	4.0	7.5	\$ 169,219
General Drainage	4.0	5.0	5.0	-	26.3	\$ 1,048,056
General Structures	3.0	5.0	5.0	-	15.0	\$ 26,333
Picnic Areas	3.0	2.0	4.0	2.0	10.0	\$ 1,018,790
Picnic Areas (in Turf)	3.0	5.0	4.0	-	10.0	\$ 281,656
Parking Lot	3.0	4.0	5.0	-	7.5	\$ 1,030,836
Playground	2.0	5.0	1.0	2.0	5.0	\$ 912,703
Sports Court: Tennis/Pickleball	3.0	4.0	1.0	4.0	10.0	\$ 827,114
Sports Court: Basketball	3.8	5.0	1.0	2.0	18.8	\$ 111,605
Sports Court: Horseshoe	2.0	5.0	1.0	4.0	3.8	\$ 77,907
Sports Court: Volleyball	2.7	5.0	1.0	-	10.0	\$ 365,158

Note: See the appendices for asset rankings



FRANKLIN COMMUNITY PARK



PARK TYPE





SIZE (ACRES) 13.4

ADDRESS 2095 Franklin Ave

PRIORITY OUT OF 12 COMMUNITY PARKS 9

SUMMARY

Franklin Community Park is a 13.4 acre community park located in the northeast quadrant of Santa Rosa, CA. The park contains picnic areas, a parking lot, playgrounds, and athletic fields.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Franklin Community Park has a moderate level of recreation programming, very high play value, and has a few significantly non-compliant ADA features.

There are no critical condition amenities within the park, though the presence of temporary trash receptacles indicates a demand for more permanent receptacles.





Amenities	Priority Ranking Categories				Supplemental Categories	
	Condition	Recreation Programming	Play Value		Lifespan	Cost Estimate
	3.1	3.0	1.0	2.4	14.8	\$ 10,426,680
General Furnishings	2.0	5.0	5.0	-	5.0	\$ 348,158
General Landscape	3.0	5.0	5.0	-	12.5	\$ 1,485,127
General Trees	4.0	5.0	5.0	-	37.5	\$ 154,664
General Hardscape	3.0	5.0	5.0	1.0	10.0	\$ 260,873
General Irrigation	3.0	5.0	5.0	-	12.5	\$ 1,933,680
General Lighting	3.0	5.0	5.0	-	20.0	\$ 460,377
General Barriers	4.0	5.0	5.0	-	22.5	\$ 179,055
General Signage	3.0	5.0	5.0	3.7	10.0	\$ 183,104
General Drainage	4.0	5.0	5.0	-	26.3	\$ 1,134,054
General Structures	3.0	5.0	5.0	-	15.0	\$ 85,593
Picnic Areas	2.8	4.0	4.0	2.8	10.0	\$ 527,027
Parking Lot	3.0	4.0	5.0	2.5	7.5	\$ 1,360,679
Playground	3.0	5.0	1.0	2.5	15.0	\$ 1,287,459
Sports Field: Soccer	4.0	3.0	1.0	-	15.0	\$ 635,742
Sports Field: Softball	2.0	3.0	1.0	-	3.8	\$ 391,088

RANKING MATRIX - FRANKLIN COMMUNITY PARK

Note: See the appendices for asset rankings



GALVIN COMMUNITY PARK



PARK TYPE





SIZE (ACRES) 23.4

ADDRESS 3330 Yulupa Ave

PRIORITY OUT OF 12 COMMUNITY PARKS 10

SUMMARY

Galvin Park is a 23.4 acre neighborhood park located in the southeast quadrant of Santa Rosa, CA. The park contains picnic areas, playgrounds, athletic fields, a dog park, and a casting pool.

The overall condition of the park is good, with a majority of the amenities in good condition. Galvin Park has a very high level of recreation programming, very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the tennis courts and structures. Tennis courts #9 and #10 have cracking throughout the court surfacing. The storage shed near tennis court #1 has been vandalized.





38 Park Ranking | Community Parks

RANKING MATRIX - GALVIN COMMUNITY PARK Г

Т

	Priority Ranking Categories				Supplemental Categories	
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	3.5	1.0	1.0	1.8	16.1	\$ 26,267,160
General Furnishings	4.0	5.0	5.0	-	15.0	\$ 477,751
General Landscape	3.0	5.0	5.0	-	12.5	\$ 1,949,541
General Trees	4.0	5.0	5.0	-	37.5	\$ 203,029
General Hardscape	3.0	5.0	5.0	1.0	10.0	\$ 1,925,366
General Irrigation	4.0	5.0	5.0	-	18.8	\$ 2,538,361
General Lighting	4.0	5.0	5.0	-	30.0	\$ 803,463
General Barriers	3.0	5.0	5.0	-	15.0	\$ 312,491
General Signage	4.0	5.0	5.0	-	15.0	\$ 319,558
General Drainage	3.0	5.0	5.0	-	17.5	\$ 1,979,182
General Structures	2.0	5.0	5.0	4.0	7.5	\$ 130,400
Picnic Areas	3.7	4.0	4.0	2.0	15.0	\$ 1,117,177
Parking Lot	3.0	4.0	5.0	2.0	7.5	\$ 1,620,410
Playground	3.9	5.0	1.0	2.7	15.0	\$ 515,250
Sports Field: Soccer	4.0	3.0	1.0	2.0	15.0	\$ 3,492,924
Sports Court: Tennis (Courts 1-6)	4.0	4.0	1.0	-	15.0	\$ 1,468,831
Sports Court: Tennis (Courts 7-8, 11-12)	4.0	4.0	1.0	-	15.0	\$ 979,221
Sports Court: Youth Tennis (Courts 9-10)	2.0	4.0	1.0	-	5.0	\$ 489,610
Sports Field: Baseball	4.0	2.0	1.0	-	11.3	\$ 1,839,705
Dog Park	3.4	5.0	3.0	-	30.0	\$ 395,006
Water Feature	3.5	5.0	5.0	-	15.0	\$ 3,709,884

Note: See the appendices for asset rankings









PARK TYPE





SIZE (ACRES) 137.8

ADDRESS 630 Summerfield Road

PRIORITY OUT OF 12 COMMUNITY PARKS 6

SUMMARY

Howarth Park, home of camp Wa-Tam, is a 137.8 acre community park located in the southeast quadrant of Santa Rosa, CA. The park contains various amenities including, but not limited to, picnic areas, playgrounds, athletic fields, sport courts, trails, and a lake with a boat launch.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Howarth Park has a very high level of recreation programming, very high play value, and has a number of significantly non-compliant ADA elements.

The critical condition amenities within the park are the playgrounds and tennis courts. The sand play areas have low levels of sand and portions of the tennis court surfacing have substantial cracking, making those areas unplayable.






71

RANKING MATRIX - HOWARTH COMMUNITY PARK

	Priority Ranking Categories				Supplemental Categories	
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	X		A.	G	Ŀ	S
	3.2	1.0	1.0	1.8	14.4	\$ 86,874,681
General Furnishings	3.2	5.0	5.0	2.0	10.8	\$ 3,607,233
General Landscape	3.3	4.0	5.0	-	14.6	\$ 15,971,966
General Trees	4.0	5.0	5.0	-	37.5	\$ 1,663,355
General Hardscape	3.5	1.0	5.0	1.0	12.5	\$ 12,950,780
General Irrigation	3.0	5.0	5.0	-	12.5	\$ 20,795,981
General Lighting	3.0	5.0	5.0	-	20.0	\$ 3,999,350
General Barriers	4.1	5.0	5.0	-	23.4	\$ 1,555,468
General Signage	3.7	5.0	5.0	4.0	13.3	\$ 1,590,646
General Drainage	3.0	5.0	5.0	-	17.5	\$ 9,851,661
General Structures	3.0	5.0	5.0	-	15.0	\$ 121,360
Picnic Areas:	3.4	3.0	4.0	2.0	15.0	\$ 685,245
Party Areas A-D	5.4	3.0	4.0	2.0	15.0	⊅ 005,245
Picnic Areas: Near Gazebo	3.0	3.0	4.0	2.0	10.0	\$ 528,496
Picnic Areas: Lower & Upper Oak	3.1	3.0	4.0	2.7	15.0	\$ 2,802,541
Picnic Areas: Cypress Point	3.0	4.0	4.0	2.0	10.0	\$ 641,765
Parking Lot	3.0	4.0	5.0	1.0	7.5	\$ 4,176,215
Playground: 1, Land of Imagination	2.5	5.0	1.0	-	15.0	\$ 1,580,005
Playground: 2	3.3	5.0	1.0	-	15.0	\$ 501,028
Sports Field: Baseball/Softball	3.5	4.0	1.0	3.5	11.3	\$ 2,271,391
Sports Court: Pickleball	4.0	4.0	1.0	-	15.0	\$ 214,880
Sports Court: Tennis	1.0	4.0	1.0	4.0	0.0	\$ 1,074,402
Trails	4.0	4.0	4.0	-	11.3	*see note
Water Feature	3.5	5.0	5.0	1.5	15.0	\$ 290,914

*A cost estimate is not provided due to square footage data being unavailable. Note: See the appendices for asset rankings



PARK TYPE





SIZE (ACRES) 33.2

ADDRESS 1313 Fountaingrove Parkway

PRIORITY OUT OF 12 COMMUNITY PARKS 12

SUMMARY

Nagasawa Community Park is a 33.2 acre community park located in the northeast quadrant of Santa Rosa, CA. The park contains a parking lot, trails and a boat launch into Fountaingrove Lake.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Nagasawa Community Park does not have recreation programming, has moderate play value, and has a few significantly non-compliant ADA features.

The critical condition amenity within the park is the irrigation system, which was damaged by the 2017 wildfire.





		Priority Rankin	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	3.3	5.0	4.0	1.4	13.8	\$ 32,663,391
General Furnishings	2.7	5.0	5.0	2.0	8.3	\$ 638,752
General Landscape	4.0	5.0	5.0	-	18.8	\$ 2,916,325
General Trees	3.0	5.0	5.0	-	25.0	\$ 303,712
General Hardscape	4.0	5.0	5.0	1.0	15.0	\$ 365,296
General Irrigation	1.0	5.0	5.0	-	0.0	\$ 3,797,143
General Barriers	3.8	5.0	5.0	-	20.6	\$ 296,457
General Signage	3.0	5.0	5.0	4.0	10.0	\$ 303,161
General Drainage	4.0	5.0	5.0	-	26.3	\$ 1,877,628
Parking Lot	3.8	5.0	5.0	-	10.5	\$ 1,192,464
Trails	2.0	5.0	4.0	-	3.8	*see note
Water Feature	5.0	5.0	5.0	-	-	\$ 20,972,453

RANKING MATRIX - NAGASAWA COMMUNITY PARK

*A cost estimate is not provided due to square footage data being unavailable. Note: See the appendices for asset rankings



NORTHWEST COMMUNITY PARK



PARK TYPE





SIZE (ACRES) 35.1

ADDRESS 2880 West Steele Ln

PRIORITY OUT OF 12 COMMUNITY PARKS 2

SUMMARY

Northwest Community Park is a 35.1 acre community park located in the northwest quadrant of Santa Rosa, CA. The park contains picnic areas, a parking lot, playgrounds, athletic fields, a dog park, and a bike pump track.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Northwest Community Park has a very high level of recreation programming, very high play value, and a number of significantly non-compliant ADA features.

The critical condition amenities within the park are the landscape, hardscape, and rugby field. The landscape has a substantial amount of weeds, the hardscape has deterioration in the asphalt pavement, and the rugby field has issues with irrigation coverage and furnishings that are worn.




44 Park Ranking | Community Parks

		Priority Rankir	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	3.1	1.0	1.0	1.4	14.0	\$ 27,127,956
General Furnishings	2.3	5.0	5.0	2.0	6.7	\$ 681,342
General Landscape	2.0	5.0	5.0	-	6.3	\$ 2,911,839
General Trees	4.0	5.0	5.0	-	37.5	\$ 303,245
General Hardscape	2.0	4.0	5.0	1.0	5.0	\$ 2,323,783
General Irrigation	3.0	5.0	5.0	-	12.5	\$ 3,791,302
General Lighting	3.0	5.0	5.0	-	20.0	\$ 1,195,636
General Barriers	3.0	5.0	5.0	-	15.0	\$ 465,019
General Signage	2.7	5.0	5.0	-	8.3	\$ 475,536
General Drainage	4.0	5.0	5.0	-	26.3	\$ 2,945,228
General Structures	4.0	5.0	5.0	-	22.5	\$ 223,623
Picnic Areas	2.8	5.0	4.0	1.7	10.0	\$ 379,669
Parking Lot	4.0	5.0	5.0	-	11.3	\$ 448,047
Playground	3.0	5.0	1.0	2.3	10.0	\$ 684,095
Sports Field: Softball	3.2	1.0	1.0	-	11.3	\$ 6,066,025
Sports Field: Soccer	4.0	3.0	1.0	-	15.0	\$ 1,647,906
Sports Field: Track & Field	3.0	5.0	1.0	-	9.0	\$ 939,374
Sports Field: Rugby	2.8	5.0	1.0	-	10.0	\$ 479,453
Dog Park	2.8	5.0	3.0	-	20.0	\$ 612,648
Bike Pump Track	3.0	5.0	2.0	-	10.0	\$ 554,184

Note: See the appendices for asset rankings



RINCON VALLEY COMMUNITY PARK



PARK TYPE





SIZE (ACRES) 18.9

ADDRESS 5108 Badger Rd

PRIORITY OUT OF 12 COMMUNITY PARKS 5

SUMMARY

Rincon Valley Community Park is an 18.9 acre community park located in the northeast quadrant of Santa Rosa, CA. The park contains picnic areas, parking lots, playgrounds, a soccer field, horseshoe pits, a softball field, and a dog park.

The overall condition of the park is adequate, with a majority of the amenities fully functional, while a few are in poor condition. Rincon Valley Community Park has a high level of recreation programming, very high play value, and has a number of significantly non-compliant ADA elements.


The critical condition amenities within the park are the playground and the dog park. The playground equipment has splintering wood, corrosion on metal surfaces, paint deterioration and substantial damage to the rubber tile surfacing. The dog park fence and gate have minor damage, the site furnishings are aged and deficient in quantity, and the drinking fountain is leaking.

	Priority Ranking Categories				Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate	
	2.9	2.0	1.0	2.0	12.7	\$ 14,774,691	
General Landscape	3.0	4.0	5.0	-	12.5	\$ 2,054,513	
General Trees	4.0	5.0	5.0	-	37.5	\$ 213,961	
General Hardscape	3.7	5.0	5.0	1.0	13.3	\$ 1,697,591	
General Irrigation	3.0	5.0	5.0	-	12.5	\$ 2,675,038	
General Barriers	4.0	5.0	5.0	-	22.5	\$ 247,770	
General Signage	3.7	5.0	5.0	3.5	13.3	\$ 253,373	
General Drainage	3.0	5.0	5.0	-	17.5	\$ 1,569,266	
General Structures	3.0	5.0	5.0	3.0	15.0	\$ 61,742	
Picnic Areas: North	3.0	4.0	4.0	1.5	10.0	\$ 54,010	
Picnic Areas: South	3.1	4.0	4.0	2.3	15.0	\$ 60,632	
Parking Lot	3.0	4.0	5.0	2.3	7.5	\$ 1,224,758	
Playground	2.0	5.0	1.0	1.5	5.0	\$ 650,593	
Sports Field: Soccer	3.0	4.0	1.0	2.0	10.0	\$ 1,672,736	
Sports Court: Horseshoe	1.0	5.0	1.0	-	0.0	\$ 107,985	
Sports Field: Softball	3.0	4.0	1.0	-	7.5	\$ 1,188,156	
Dog Park	2.0	5.0	3.0	4.0	10.0	\$ 530,038	

RANKING MATRIX - RINCON VALLEY COMMUNITY PARK

Note: See the appendices for asset rankings





PARK TYPE





SIZE (ACRES) 20.8

ADDRESS 5750 Mountain Hawk

PRIORITY OUT OF 12 COMMUNITY PARKS 11

SUMMARY

Skyhawk Community Park is a 20.8 acre community park located in the northeast quadrant of Santa Rosa, CA. The park contains playgrounds, soccer fields, softball fields, and trails.

The overall condition of the park is good and a majority of the amenities are in good condition. Skyhawk Community Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenity is the park's trail, which has significant cracking in the asphalt, moderate weed growth, and damaged fencing.





		Priority Rankir	ig Catego	ories	Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate	
	3.4	5.0	1.0	1.3	16.2	\$ 13,173,720	
General Furnishings	3.7	5.0	5.0	2.0	13.3	\$ 578,608	
General Landscape	3.0	5.0	5.0	-	12.5	\$ 2,687,037	
General Trees	4.0	5.0	5.0	-	37.5	\$ 279,834	
General Hardscape	4.0	5.0	5.0	1.0	15.0	\$ 1,667,547	
General Irrigation	4.0	5.0	5.0	-	18.8	\$ 3,498,603	
General Lighting	3.0	5.0	5.0	-	20.0	\$ 677,346	
General Barriers	3.0	5.0	5.0	-	15.0	\$ 263,440	
General Signage	3.7	5.0	5.0	-	13.3	\$ 269,398	
General Drainage	4.0	5.0	5.0	-	26.3	\$ 1,668,517	
Playground	3.0	5.0	1.0	1.5	10.0	\$ 291,950	
Sports Field: Soccer/Softball	3.0	5.0	1.0	-	10.0	\$ 833,993	
Sports Field: Soccer	3.8	5.0	1.0	-	15.0	\$ 224,336	
Trails	2.0	5.0	4.0	-	3.8	\$ 233,112	

RANKING MATRIX - SKYHAWK COMMUNITY PARK

Note: See the appendices for asset rankings



SOUTHWEST COMMUNITY PARK



PARK TYPE





SIZE (ACRES) 19.8

ADDRESS 1698 Hearn Ave

PRIORITY OUT OF 12 COMMUNITY PARKS 3

SUMMARY

Southwest Park is a 19.8 acre community park located in the southwest quadrant of Santa Rosa, CA. The park contains picnic areas, a playground, basketball courts, soccer fields, a softball field, and a parking lot.

The overall condition of the park is below adequate, with a majority of the amenities fully functional, while a few others are in critical condition. Southwest Park has a moderate level of recreation programming, very high play value, and has several significantly non-compliant ADA elements.

The critical condition amenities within the park are the general hardscape and the gravel parking lot. The asphalt has major cracking, while the parking lot has uneven surfacing and substantial pot holes.



		Priority Rankir	ıg Catego	ries	Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate	
	2.8	3.0	1.0	1.6	11.7	\$ 17,767,728	
General Furnishings	3.5	5.0	5.0	-	12.5	\$ 550,613	
General Landscape	2.5	5.0	5.0	-	9.4	\$ 2,077,887	
General Trees	4.0	5.0	5.0	-	37.5	\$ 216,396	
General Hardscape	1.0	4.0	5.0	1.0	0.0	\$ 5,382,594	
General Irrigation	3.5	5.0	5.0	-	15.6	\$ 2,705,472	
General Barriers	3.5	5.0	5.0	1.0	18.8	\$ 267,736	
General Signage	3.0	5.0	5.0	4.0	10.0	\$ 273,791	
General Drainage	3.3	5.0	5.0	-	19.7	\$ 1,695,724	
Picnic Areas	3.0	4.0	4.0	2.0	10.0	\$ 795,069	
Parking Lot: #1	3.0	4.0	5.0	1.0	7.5	\$ 853,582	
Parking Lot: #2	1.0	5.0	5.0	-	0.0	\$ 464,580	
Playground	3.0	5.0	1.0	1.3	10.0	\$ 478,578	
Sports Court: Basketball	2.0	5.0	1.0	-	6.3	\$ 257,776	
Sports Field: Soccer	3.2	4.0	1.0	-	15.0	\$ 488,420	
Sports Field: Softball	2.0	5.0	1.0	-	3.8	\$ 1,259,509	

RANKING MATRIX - SOUTHWEST COMMUNITY PARK

Note: See the appendices for asset rankings



YOUTH COMMUNITY PARK



PARK TYPE





SIZE (ACRES) 73.8

ADDRESS 1701 Fulton Rd

PRIORITY OUT OF 12 COMMUNITY PARKS

SUMMARY

Youth Community Park, home of camp Yu-Chi, is a 73.8 acre park located in the northwest quadrant of Santa Rosa, CA. The park contains picnic areas, playgrounds, trails, and a skate park. There are also a temporary disc golf course and a temporary bike pump track on site that are not operated by the Recreation and Parks Department and a miniature gauge train on site that is maintained by a community group.

The overall condition of the park is adequate, with a majority of the amenities fully functional, while a few others are in critical condition. Youth Community Park has a very high level of recreation programming, very high play value, and has a number of significantly non-compliant ADA elements.

The critical condition amenity within the park is the trail, which has uneven surfacing throughout.



		Priority Rankir	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	3.1	1.0	1.0	1.2	15.1	\$ 44,837,076
General Furnishings	4.0	5.0	5.0	2.0	15.0	\$ 2,321,200
General Landscape	3.0	4.0	5.0	-	12.5	\$ 11,007,970
General Trees	4.0	5.0	5.0	-	37.5	\$ 1,146,394
General Hardscape	3.0	1.0	5.0	1.0	10.0	\$ 1,917,016
General Irrigation	4.0	5.0	5.0	-	18.8	\$ 14,332,709
General Lighting	3.0	5.0	5.0	-	20.0	\$ 2,499,776
General Barriers	2.7	5.0	5.0	-	12.5	\$ 972,238
General Signage	3.0	5.0	5.0	-	10.0	\$ 994,226
General Drainage	4.0	5.0	5.0	-	26.3	\$ 6,157,736
General Structures	4.0	5.0	5.0	-	22.5	\$ 112,357
Picnic Areas	3.0	4.0	4.0	1.0	10.0	\$ 250,770
Parking Lot	3.0	4.0	5.0	1.0	7.5	\$ 1,031,087
Playground	3.2	5.0	1.0	1.5	15.0	\$ 1,023,845
*Sports Field: Disc Golf	1.0	5.0	1.0	-	0.0	_
Trails	1.5	5.0	4.0	-	3.8	**see note
Skate Park	2.8	5.0	2.0	-	20.0	\$ 1,069,754
*Bike Pump Track	4.0	5.0	2.0	-	15.0	-

RANKING MATRIX - YOUTH COMMUNITY PARK

*Disc Golf Course and Bike Pump Track are temporary amenities and are not operated by the Recreation and Parks Department. **A cost estimate is not provided due to square footage data being unavailable. Note: See the appendices for asset rankings



NEIGHBORHOOD PARKS



Fifty neighborhood parks that are owned and maintained by the City were evaluated as part of this report. This section evaluates the priority ranking of each neighborhood

NEIGHBORHOOD PARKS

park based on condition, recreation programming, play value, and accessibility. In addition, the approximate lifespan and the estimated replacement cost is provided for each amenity as well as the overall park. Parks with a priority ranking closer to one (1) are identified as having a higher priority for new improvements, while parks that rank closer to five (5) have a lower priority for improvement needs. The table below identifies the neighborhood parks in order of priority ranking, the parks identified in gray were not assessed by this Report.

Ne	eighborhood Parks - Ranked by Priority Rank	ing					
Rank	Park	Priority Ranking	Lifespan	Area (Acres)	Estimated Replacement Cost	Quadrant	Park Type
1	Jacobs Park (Lincoln School)	2.3	9.5	6.9	\$ 5,089,625	NW	NP
2	South Davis Park	2.6	13.6	1.3	\$ 1,418,918	SW	NP
3	Martin Luther King Jr. Park	2.7	13.4	5.4	\$ 5,146,137	SE	NP
4	Live Oak Park	2.7	14.7	4.9	\$ 3,456,191	NW	NP
5	Bicentennial Park	2.8	14.8	5.3	\$ 6,025,186	NW	NP
6	Peterson Lane Park	2.8	13.6	4.0	\$ 3,281,990	NW	NP
7	Juilliard Park	2.8	16.0	9.1	\$ 10,187,312	NE	NP
8	Hidden Valley Park	2.8	15.4	8.2	\$ 5,053,685	NE	NP
9	Brendon Park	2.9	15.1	1.4	\$ 1,925,815	NW	NP
10	Tanglewood Park	2.9	14.0	7.8	\$ 5,334,531	NE	NP
11	Jennings Park	2.9	15.0	6.6	\$ 3,922,385	NW	NP
12	Pioneer Park	2.9	15.3	4.5	\$ 4,668,338	NW	NP
13	Cook School Park	3.0	15.9	0.9	\$ 1,363,826	SW	NP
14	DeMeo Park	3.0	17.2	1.0	\$ 1,437,841	NW	NP
15	Humboldt Park	3.0	16.4	0.5	\$ 709,544	NE	NP
16	Eastside Park	3.0	16.8	0.4	\$ 962,609	NE	NP
17	North Park	3.0	15.2	1.0	\$ 961,376	NE	NP
18	Steele Lane Park	3.0	15.9	2.4	\$ 2,361,427	NE	NP
19	Westgate Park	3.0	16.5	2.4	\$ 1,753,464	NW	NP
20	Oaklake Green Park	3.1	16.4	3.7	\$ 2,650,452	NE	NP
21	Pearblossom Park	3.1	16.3	3.1	\$ 3,161,271	SW	NP
22	Rinconada Park	3.1	14.7	2.2	\$ 1,290,982	NE	NP
23	Brush Creek Park	3.1	15.7	2.2	\$ 2,774,595	NE	NP
24	Colgan Creek Park	3.1	16.2	2.8	\$ 3,034,739	SE	NP
25	Flat Rock Park	3.1	13.2	5.4	\$ 1,981,199	SE	NP

Ne	eighborhood Parks - Ranked by Priority R	anking					
Rank	Lar A Lar A	Priority Ranking	Lifespan	Area (Acres)	Estimated Replacement Cost	Quadrant	Park Type
26	Sonoma Avenue Park	3.1	14.7	1.8	\$ 1,646,397	NE	NP
27	Village Green Park	3.1	15.0	2.0	\$ 2,081,640	SW	NP
28	Peter Springs Park	3.1	16.9	1.2	\$ 923,826	SE	NP
29	Rae Street Park	3.1	17.1	0.8	\$ 841,822	NE	NP
30	Olive Park	3.1	17.3	0.9	\$ 1,347,291	NW	NP
31	Bellevue Ranch Park	3.1	16.6	3.5	\$ 3,758,003	SW	NP
32	Mesquite Park	3.1	18.1	4.0	\$ 2,682,854	SE	NP
33	Harvest Park	3.2	16.9	3.3	\$ 3,882,737	SE	NP
34	Fremont Park	3.2	13.7	1.7	\$ 1,941,379	NE	NP
35	Matanzas Park	3.2	18.8	1.1	\$ 1,139,441	SE	NP
36	Red Hawk Park	3.2	17.5	0.4	\$ 770,932	SE	NP
37	Frances Nielsen Ranch Park	3.3	16.7	6.0	\$ 3,043,018	NE	NP
38	Haydn Village Park	3.3	18.1	0.1	\$ 168,614	NW	NP
39	DeTurk Park	3.4	18.8	1.0	\$ 1,031,358	NW	NP
40	Airfield Park	3.4	19.0	3.9	\$ 2,911,833	SW	NP
41	Railroad Depot Park	3.6	17.3	0.3	\$ 291,744	NW	NP
42	Bayer Park and Gardens	3.7	21.7	6.0	\$ 10,124,418	SW	NP
43	Finali Park	3.7	22.1	2.8	\$ 3,060,027	NW	NP
44	Strawberry Park	3.8	16.9	5.8	\$ 2,796,006	SE	NP
45	Trailhead Park	3.8	17.2	4.2	\$ 2,191,514	SE	NP
46	Prince Memorial Greenway	3.8	18.8	4.1	\$ 6,071,503	NW	NP
47	Triangle Park	3.8	20.6	0.1	\$ 52,205	NE	NP
48	Dauenhauer Park	3.9	25.9	2.5	\$ 2,398,128	SE	NP
49	Prince Gateway Park	3.9	21.8	0.5	\$ 1,060,495	NE	NP
50	Coffey Park	4.4	25.8	5.9	\$ 5,966,960	NW	NP
-	Dutch Flohr (In Design)	-	-	2.4	-	NW	NP
-	Fir Ridge Park	-	-	1.1	-	NE	NP
-	Jack London Park (Future)	-	-	2.2	-	NW	NP
-	Kawana Tokay Park (Future)	-	-	0.6	-	SE	NP
-	Lower Colgan Creek Park (Future)	-	-	1.8	-	SW	NP
-	Meadows Park (Future)	-	-	3.7	-	SW	NP
-	Piedra Park (Future)	-	-	0.2	-	NE	NP
-	Rincon Ridge Park	-	-	10.1	-	NE	NP
-	Tenth Street Park (Future)	-	-	0.1	-	NW	NP

Parks Prioritization Report

Page is Intentionally Blank





PARK TYPE



SIZE (ACRES) 3.1

ADDRESS 4051 Fresno Ave

PRIORITY OUT OF 50 COMMUNITY PARKS 40

SUMMARY

Airfield Park is a 3.1 acre neighborhood park located in the southwest quadrant of Santa Rosa, CA. The park contains picnic areas, a playground and a basketball court.

The overall condition of the park is good and a majority of the amenities are in good condition. Airfield Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

There are no critical condition amenities within the park. However, the playground has missing signage and the trees around the picnic areas have died or been removed.





RANKING MATRIX - AIRFIELD PARK

	I	Supplemental Categories						
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	C	Cost Estimate	
	3.8	5.0	1.0	1.6	19.0	\$	2,911,833	
General Furnishings	4.0	5.0	5.0	-	15.0	\$	92,568	
General Landscape	3.3	5.0	5.0	-	14.6	\$	399,769	
General Trees	4.0	5.0	5.0	-	37.5	\$	41,633	
General Hardscape	3.3	5.0	5.0	1.0	11.7	\$	652,336	
General Irrigation	3.5	5.0	5.0	-	15.6	\$	520,511	
General Barriers	4.0	5.0	5.0	-	22.5	\$	42,017	
General Signage	4.5	5.0	5.0	4.0	17.5	\$	42,968	
General Drainage	4.0	5.0	5.0	-	26.3	\$	266,120	
Picnic Areas	3.0	5.0	4.0	-	15.0	\$	145,910	
Playground	3.7	5.0	1.0	-	15.0	\$	587,203	
Sports Court: Basketball	4.0	5.0	1.0	-	18.8	\$	120,798	

Note: See the appendices for asset rankings



BAYER PARK AND GARDENS



PARK TYPE

Neighborhood Park



SIZE (ACRES) 6.0

ADDRESS 1550 West Ave

PRIORITY OUT OF 50 COMMUNITY PARKS 42

SUMMARY

Bayer Park and Gardens is a 6.0 acre neighborhood park located in the southwest quadrant of Santa Rosa, CA. The park contains a skate park, picnic areas, a parking lot, fitness equipment, playgrounds, sport courts, and a community garden.

The overall condition of the park is very good, a majority of the amenities are functional, and the park is not anticipated to need major improvements in the near-term. Bayer Park and Gardens has a high level of recreation programming, very high play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

There are no critical condition amenities within the park. However, the playground mulch will soon need replenishing and the volleyball court does not have a net.



		Priority Rankin	ig Catego	ories	Supplem	ental Categories
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	4.2	2.0	1.0	4.2	21.7	\$ 10,124,418
General Furnishings	4.3	5.0	5.0	-	16.7	\$ 109,225
General Landscape	3.5	4.0	5.0	-	15.6	\$ 349,805
General Trees	4.0	5.0	5.0	-	37.5	\$ 36,429
General Hardscape	5.0	4.0	5.0	-	20.0	\$ 2,058,947
General Irrigation	4.0	5.0	5.0	-	18.8	\$ 455,457
General Lighting	5.0	5.0	5.0	-	40.0	\$ 199,571
General Barriers	3.7	5.0	5.0	-	20.0	\$ 77,619
General Signage	4.7	5.0	5.0	-	18.3	\$ 79,374
General Drainage	4.0	5.0	5.0	-	26.3	\$ 491,605
General Structures	4.0	5.0	5.0	-	22.5	\$ 61,752
Picnic Areas	4.4	4.0	4.0	-	20.0	\$ 1,195,955
Parking Lot	5.0	5.0	5.0	-	15.0	\$ 125,403
Fitness Equipment	4.0	5.0	3.0	-	15.0	\$ 64,069
Playground 1	3.0	5.0	1.0	-	10.0	\$ 322,579
Playground 2	4.5	5.0	1.0	-	20.0	\$ 47,320
Sports Court: Basketball	5.0	5.0	1.0	-	25.0	\$ 23,844
Sports Court: Volleyball	3.0	5.0	1.0	-	10.0	\$ 61,828
Skate Park	5.0	5.0	2.0	-	40.0	\$ 174,867
Community Gardens	4.0	5.0	3.0	-	22.5	\$ 4,188,769

RANKING MATRIX - BAYER PARK AND GARDENS

Note: See the appendices for asset rankings



BELLEVUE RANCH PARK



PARK TYPE

Neighborhood Park



SIZE (ACRES) 3.5

ADDRESS 2646 Arrowhead Dr

PRIORITY OUT OF 50 COMMUNITY PARKS 31

SUMMARY

Bellevue Ranch Park is a 3.5 acre neighborhood park located in the southwest quadrant of Santa Rosa, CA. The park contains a playground, a basketball court and a handball court.

The overall condition of the park is good and a majority of the amenities are fully functional. Bellevue Rank Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the ornamental landscape areas, which have large gaps in vegetation, significant weeds and no mulch, and furnishings where there is a deficient quantity of trash receptacles.



overall priority rank **3.1**

RANKING MATRIX - BELLEVUE RANCH PARK

		Priority Ranking Categories					Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate			
	3.4	5.0	1.0	1.6	16.6	\$	3,758,003		
General Furnishings	3.4	5.0	5.0	-	12.0	\$	107,557		
General Landscape	2.7	5.0	5.0	-	10.4	\$	420,506		
General Trees	4.0	5.0	5.0	-	37.5	\$	43,792		
General Hardscape	3.5	5.0	5.0	1.0	12.5	\$	1,321,249		
General Irrigation	4.0	5.0	5.0	-	18.8	\$	547,512		
General Barriers	4.0	5.0	5.0	-	22.5	\$	47,663		
General Signage	3.5	5.0	5.0	4.0	12.5	\$	48,741		
General Drainage	3.5	5.0	5.0	-	21.9	\$	301,876		
Playground	3.2	5.0	1.0	2.0	15.0	\$	846,088		
Sports Court: Basketball	3.0	5.0	1.0	-	12.5	\$	51,251		
Sports Court: Handball	3.0	5.0	1.0	-	7.5	\$	21,768		

Note: See the appendices for asset rankings





PARK TYPE

Neighborhood Park



SIZE (ACRES) 5.3

ADDRESS 974 Russell Ave

PRIORITY OUT OF 50 COMMUNITY PARKS

5

SUMMARY

Bicentennial Park is a 5.3 acre neighborhood park located in the northwest quadrant of Santa Rosa, CA. The park contains picnic areas, a playground, basketball court and horseshoe court.

The overall condition of the park is adequate, aside from a number of deficient amenities. Bicentennial Park has minimal recreation programming, very high play value, and a few significantly non-compliant ADA features.

The critical condition amenities within the park are the playground and horseshoe pit. The playground equipment is missing components and the wood fiber surfacing requires replenishing. The horseshoe pit has damaged equipment and excessive wear in the sand and paver surfacing.





PRIORITY RANK

RANKING MATRIX - BICENTENNIAL PARK

		Priority Rankin	Supplemental Categories				
Amenities	Condition	Recreation Programming	Play Value		Lifespan	Cost Estimate	
	3.0	4.0	1.0	1.8	14.8	\$ 6,025,186	
General Furnishings	2.5	5.0	5.0	2.0	7.5	\$ 157,678	
General Landscape	3.0	5.0	5.0	-	12.5	\$ 647,011	
General Trees	4.0	5.0	5.0	-	37.5	\$ 67,381	
General Hardscape	3.0	4.0	5.0	1.0	10.0	\$ 1,545,814	
General Irrigation	3.0	5.0	5.0	-	12.5	\$ 842,428	
General Lighting	3.0	5.0	5.0	-	20.0	\$ 186,432	
General Barriers	3.5	5.0	5.0	-	18.8	\$ 72,509	
General Signage	3.0	5.0	5.0	4.0	10.0	\$ 74,149	
General Drainage	4.0	5.0	5.0	-	26.3	\$ 459,240	
Picnic Areas	3.0	5.0	4.0	-	10.0	\$ 505,013	
Playground	2.0	5.0	1.0	2.0	5.0	\$ 1,305,953	
Sports Court: Basketball	3.3	5.0	1.0	-	18.8	\$ 104,721	
Sports Court: Horseshoe	2.0	5.0	1.0	1.0	3.8	\$ 56,857	

Note: See the appendices for asset rankings



BRENDON PARK



PARK TYPE





SIZE (ACRES)

ADDRESS 1743 Greeneich Ave

PRIORITY OUT OF 50 COMMUNITY PARKS 9

SUMMARY

Brendon Park is a 1.4 acre neighborhood park located in the northwest quadrant of Santa Rosa, CA. The park contains picnic areas, a playground, and a volleyball court.

The overall condition of the park is adequate, with a few amenities broken and not functioning. Brendon Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the playground, volleyball court and hardscape. The playground has sand surfacing that is weedy and heavily compacted and play equipment that is showing excessive wear. The volleyball court net is missing and therefore unplayable. Asphalt and concrete pavement throughout the site have severe cracking, and there is a deficient quantity of trash receptacles.



Parks Prioritization Report

RANKING MATRIX - BRENDON PARK

		Supplemental Categories					
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	C	ost Estimate
	3.0	5.0	1.0	1.6	15.1	\$	1,925,815
General Furnishings	1.5	5.0	5.0	-	2.5	\$	36,353
General Landscape	3.0	5.0	5.0	-	12.5	\$	147,597
General Trees	4.0	5.0	5.0	-	37.5	\$	15,371
General Hardscape	2.0	5.0	5.0	1.0	5.0	\$	376,542
General Irrigation	4.0	5.0	5.0	-	18.8	\$	192,176
General Lighting	3.0	5.0	5.0	-	20.0	\$	48,669
General Barriers	3.5	5.0	5.0	-	18.8	\$	18,929
General Signage	3.0	5.0	5.0	4.0	10.0	\$	19,357
General Drainage	4.0	5.0	5.0	-	26.3	\$	119,887
Picnic Areas	3.0	5.0	4.0	-	15.0	\$	65,088
Playground	2.0	5.0	1.0	1.5	5.0	\$	753,369
Sports Court: Volleyball	3.0	5.0	1.0	-	10.0	\$	132,476

Note: See the appendices for asset rankings



BRUSH CREEK PARK



PARK TYPE





SIZE (ACRES)

ADDRESS 1180 Brush Creek Rd

PRIORITY OUT OF 50 COMMUNITY PARKS 23

SUMMARY

Brush Creek Park is a 2.2 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains picnic areas, a playground, handball court and basketball court.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Brush Creek Park has minimal recreation programming, very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the picnic areas, which have uneven surfacing within the concrete pavement and pavers.





overall priority rank **3.1**

RANKING MATRIX - BRUSH CREEK PARK

		Supplemental Categories					
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Co	ost Estimate
	3.3	4.0	1.0	2.6	15.7	\$	2,774,595
General Furnishings	3.5	5.0	5.0	2.0	12.5	\$	63,829
General Landscape	3.0	5.0	5.0	-	12.5	\$	242,223
General Trees	4.0	5.0	5.0	-	37.5	\$	25,226
General Hardscape	3.0	4.0	5.0	-	10.0	\$	877,873
General Irrigation	4.0	5.0	5.0	-	18.8	\$	315,381
General Lighting	3.0	5.0	5.0	-	20.0	\$	76,562
General Barriers	3.3	5.0	5.0	-	16.9	\$	29,777
General Signage	3.0	5.0	5.0	4.0	10.0	\$	30,451
General Drainage	4.0	5.0	5.0	-	26.3	\$	188,595
Picnic Areas	3.0	5.0	4.0	1.0	10.0	\$	198,435
Playground	3.0	5.0	1.0	2.0	10.0	\$	662,680
Sports Court: Handball	3.0	5.0	1.0	-	7.5	\$	12,110
Sports Court: Basketball	3.0	5.0	1.0	-	12.5	\$	51,455

Note: See the appendices for asset rankings



COFFEY PARK



PARK TYPE

Neighborhood Park



SIZE (ACRES) 5.9

ADDRESS 1524 Amanda Pl

PRIORITY OUT OF 50 COMMUNITY PARKS 50

SUMMARY

Coffey Park is a 5.9 acre neighborhood park located in the northwest quadrant of Santa Rosa, CA. The park contains picnic areas, playgrounds, fitness equipment and a dog park.

The overall condition of the park is very good, a majority of the amenities are functional, and the park is not anticipated to need major improvements in the near-term. Coffey Park does not have recreation programming, has very high play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

There are no critical condition amenities within the park, though portions of dried turf imply there is deficient coverage by the irrigation system.





RANKING MATRIX - COFFEY PARK

		Supplemental Categories					
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Co	ost Estimate
	4.7	5.0	1.0	4.7	25.8	\$	5,966,960
General Furnishings	5.0	5.0	5.0	-	20.0	\$	172,903
General Landscape	3.7	5.0	5.0	-	16.7	\$	764,359
General Trees	5.0	5.0	5.0	-	50.0	\$	79,602
General Hardscape	5.0	5.0	5.0	-	20.0	\$	861,428
General Irrigation	3.0	5.0	5.0	-	12.5	\$	995,219
General Lighting	5.0	5.0	5.0	-	40.0	\$	204,168
General Barriers	5.0	5.0	5.0	-	30.0	\$	79,407
General Signage	5.0	5.0	5.0	-	20.0	\$	81,203
General Drainage	4.0	5.0	5.0	-	26.3	\$	502,930
Picnic Areas	5.0	5.0	4.0	-	20.0	\$	371,824
Fitness Equipment	5.0	5.0	3.0	-	20.0	\$	217,192
Playground	5.0	5.0	1.0	-	20.0	\$	1,478,233
Dog Park	5.0	5.0	3.0	-	40.0	\$	158,491

Note: See the appendices for asset rankings





PARK TYPE

Neighborhood Park



SIZE (ACRES) 2.8

ADDRESS 2036 Bedford St

PRIORITY OUT OF 50 COMMUNITY PARKS 24

SUMMARY

Colgan Creek Park is a 2.8 acre neighborhood park located in the southeast quadrant of Santa Rosa, CA. The park contains picnic areas, playgrounds, a basketball court, and a trail.

The overall condition of the park is adequate aside from a few deficient amenities. Colgan Creek Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the playground and trails. The playground equipment shows signs of excessive wear and broken components with weeds growing in the sand surfacing. The trails have major cracking throughout the asphalt pavement.





RANKING MATRIX - COLGAN CREEK PARK

		Priority Rankin	Supplemental Categories				
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate	
	3.3	5.0	1.0	1.6	16.2	\$ 3,034,73	39
General Furnishings	3.4	5.0	5.0	2.0	12.0	\$ 67,2	77
General Landscape	3.3	5.0	5.0	-	14.6	\$ 281,20	01
General Trees	4.0	5.0	5.0	-	37.5	\$ 29,28	85
General Hardscape	4.0	5.0	5.0	1.0	15.0	\$ 593,70	62
General Irrigation	4.0	5.0	5.0	-	18.8	\$ 366,13	32
General Lighting	2.0	5.0	5.0	-	10.0	\$ 96,5	79
General Barriers	3.0	5.0	5.0	-	15.0	\$ 37,50	63
General Signage	3.5	5.0	5.0	4.0	12.5	\$ 38,4	12
General Drainage	4.0	5.0	5.0	-	26.3	\$ 237,90	05
Picnic Areas	4.0	5.0	4.0	-	15.0	\$ 102,94	41
Playground	2.0	5.0	1.0	2.0	5.0	\$ 861,3	51
Sports Court: Basketball	4.3	5.0	1.0	1.0	25.0	\$ 79,40	07
Trails	2.0	5.0	4.0	-	3.8	\$ 242,92	23

Note: See the appendices for asset rankings



COOK SCHOOL PARK



PARK TYPE



SIZE (ACRES)

ADDRESS 2525 Gardner Ave

PRIORITY OUT OF 50 COMMUNITY PARKS 13

SUMMARY

Cook School Park is a 0.9 acre neighborhood park located in the southwest quadrant of Santa Rosa, CA. The park contains a playground, a dog park, and natural turf.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Cook School Park does not have recreation programming, has low play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the signage, which is illegible due to wear, and a deficient quantity of trash receptacles.





OVERALL PRIORITY RANK

RANKING MATRIX - COOK SCHOOL PARK

		Supplemental Categories					
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Co	ost Estimate
	3.1	5.0	1.0	1.9	15.9	\$	1,363,826
General Furnishings	2.0	5.0	5.0	-	5.0	\$	17,692
General Landscape	3.0	5.0	5.0	-	12.5	\$	53,256
General Trees	4.0	5.0	5.0	-	37.5	\$	5,546
General Hardscape	3.0	5.0	5.0	1.0	10.0	\$	421,061
General Irrigation	3.5	5.0	5.0	-	15.6	\$	69,341
General Barriers	4.0	5.0	5.0	-	22.5	\$	11,519
General Signage	2.0	5.0	5.0	4.0	5.0	\$	11,779
General Drainage	3.3	5.0	5.0	-	20.4	\$	72,954
Playground	3.0	5.0	1.0	2.0	10.0	\$	511,630
Dog Park	3.2	5.0	3.0	3.0	20.0	\$	189,049

Note: See the appendices for asset rankings



DAUENHAUER PARK



PARK TYPE

Neighborhood Park



SIZE (ACRES) 2.5

ADDRESS 1700 Allan Way

PRIORITY OUT OF 50 COMMUNITY PARKS 48

SUMMARY

Dauenhauer Park is a 2.5 acre neighborhood park located in the southeast quadrant of Santa Rosa, CA. The park contains playgrounds, a basketball court, and natural turf.

The overall condition of the park is very good, a majority of the amenities are functional, and the park is not anticipated to need major improvements in the near-term. Dauenhauer Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

There are no critical condition amenities at the park, though the basketball court lacks court striping.



OVERALL PRIORITY RANK **3.9**

RANKING MATRIX - DAUENHAUER PARK

		Priority Ranking Categories					Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate			
	4.4	5.0	1.0	1.7	25.9	\$	2,398,128		
General Furnishings	4.3	5.0	5.0	2.0	16.3	\$	78,603		
General Landscape	4.0	5.0	5.0	-	18.8	\$	316,099		
General Trees	5.0	5.0	5.0	-	50.0	\$	32,919		
General Hardscape	4.0	5.0	5.0	1.0	15.0	\$	853,006		
General Irrigation	5.0	5.0	5.0	-	25.0	\$	411,570		
General Lighting	5.0	5.0	5.0	-	40.0	\$	87,807		
General Barriers	4.0	5.0	5.0	-	22.5	\$	34,151		
General Signage	4.5	5.0	5.0	4.0	17.5	\$	34,923		
General Drainage	5.0	5.0	5.0	-	35.0	\$	216,297		
Playground	4.3	5.0	1.0	-	20.0	\$	262,948		
Sports Court: Basketball	3.3	5.0	1.0	-	25.0	\$	69,807		

Note: See the appendices for asset rankings



DEMEO PARK



PARK TYPE





SIZE (ACRES) 1.0

ADDRESS 610 Polk St

PRIORITY OUT OF 50 COMMUNITY PARKS 14

SUMMARY

DeMeo Park is a 1.0 acre neighborhood park located in the northwest quadrant of Santa Rosa, CA. The park contains a playground, a basketball court and bocce courts.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. DeMeo Park has minimal recreation programming, very high play value, and has a few significantly non-compliant ADA features.

There are no critical condition amenities within the park, though there appears to be a deficient quantity of trash receptacles.





RANKING MATRIX - DEMEO PARK

	Priority Ranking Categories				Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Со	st Estimate
	3.4	4.0	1.0	1.1	17.2	\$	1,437,841
General Furnishings	2.3	5.0	5.0	-	6.7	\$	25,242
General Landscape	3.0	5.0	5.0	-	12.5	\$	94,918
General Trees	4.0	5.0	5.0	-	37.5	\$	9,885
General Hardscape	3.0	4.0	5.0	1.0	10.0	\$	358,340
General Irrigation	3.0	5.0	5.0	-	12.5	\$	123,586
General Lighting	4.0	5.0	5.0	-	30.0	\$	33,627
General Barriers	4.0	5.0	5.0	-	22.5	\$	13,078
General Signage	3.0	5.0	5.0	-	10.0	\$	13,374
General Drainage	4.0	5.0	5.0	-	26.3	\$	82,833
Picnic Areas	3.2	5.0	4.0	-	15.0	\$	91,759
Playground	4.0	5.0	1.0	1.5	15.0	\$	477,709
Sports Court: Basketball	3.3	5.0	1.0	-	18.8	\$	43,175
Sports Court: Bocce	3.9	5.0	1.0	-	7.5	\$	70,315

Note: See the appendices for asset rankings



DETURK PARK



PARK TYPE

Neighborhood Park



SIZE (ACRES) 1.0

ADDRESS 819 Donahue St

PRIORITY OUT OF 50 COMMUNITY PARKS 39

SUMMARY

DeTurk Park is a 1.0 acre neighborhood park located in the northwest quadrant of Santa Rosa, CA. The park contains a dog park, natural turf, and also features the DeTurk Round Barn, which was not evaluated as part of this assessment.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. DeTurk Park does not have recreation programming apart from the barn, has moderate play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the signage, which is illegible due to wear, and a deficient quantity of trash receptacles.





Parks Prioritization Report

RANKING MATRIX - DETURK PARK

	Priority Ranking Categories				Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Co	ost Estimate
	3.4	5.0	3.0	1.7	18.8	\$	1,031,358
General Furnishings	2.8	5.0	5.0	2.0	8.8	\$	25,871
General Landscape	4.0	5.0	5.0	-	18.8	\$	84,462
General Trees	4.0	5.0	5.0	-	37.5	\$	8,796
General Hardscape	3.0	5.0	5.0	1.0	10.0	\$	501,759
General Irrigation	3.5	5.0	5.0	-	15.6	\$	109,972
General Lighting	3.0	5.0	5.0	-	20.0	\$	33,653
General Signage	3.0	5.0	5.0	4.0	10.0	\$	13,385
General Drainage	4.0	5.0	5.0	-	26.3	\$	82,898
Parking Lot	3.8	5.0	5.0	-	11.3	\$	16,707
Dog Park	3.3	5.0	3.0	1.0	30.0	\$	153,858

Note: See the appendices for asset rankings



EASTSIDE PARK



PARK TYPE





SIZE (ACRES) 0.4

82

ADDRESS 169 Alderbrook Dr

PRIORITY OUT OF 50 COMMUNITY PARKS 16

SUMMARY

Eastside Park is a 0.4 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains a playground, natural turf, and picnic tables.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Eastside Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the signage, which is illegible due to wear, and a deficient quantity of trash receptacles.



OVERALL PRIORITY RANK

RANKING MATRIX - EASTSIDE PARK

		ories	Supplemental Categories				
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Со	st Estimate
	3.2	5.0	1.0	2.0	16.8	\$	962,609
General Furnishings	2.0	5.0	5.0	-	5.0	\$	9,094
General Landscape	2.7	5.0	5.0	-	10.4	\$	30,753
General Trees	4.0	5.0	5.0	-	37.5	\$	3,203
General Hardscape	3.5	5.0	5.0	1.0	12.5	\$	173,191
General Irrigation	4.5	5.0	5.0	-	21.9	\$	40,041
General Lighting	3.0	5.0	5.0	-	20.0	\$	13,872
General Barriers	3.0	5.0	5.0	-	15.0	\$	5,395
General Signage	2.0	5.0	5.0	4.0	5.0	\$	5,517
General Drainage	4.5	5.0	5.0	-	30.6	\$	34,170
Playground	3.0	5.0	1.0	2.0	10.0	\$	647,372

Note: See the appendices for asset rankings







PARK TYPE

NEIGHBORHOOD PARKS





SIZE (ACRES) 2.8

ADDRESS 1420 Range Ave

PRIORITY OUT OF 50 COMMUNITY PARKS 43

SUMMARY

Finali Park is a 2.8 acre neighborhood park located in the northwest quadrant of Santa Rosa, CA. The park contains picnic areas, a playground, a dog park and a community garden.

The overall condition of the park is very good, a majority of the amenities are functional, and the park is not anticipated to need major improvements in the near-term. Finali Park does not have recreation programming, has very high play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

There are no critical conditions amenities at this park. However, the wood fiber at the playgrounds will soon require replenishing and the ornamental planting areas have weeds and require additional mulch.



Parks Prioritization Report


RANKING MATRIX - FINALI PARK

	Priority Ranking Categories				Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate	
	3.9	5.0	1.0	3.9	22.1	\$ 3,060,027	
General Furnishings	4.8	5.0	5.0	-	18.8	\$ 77,641	
General Landscape	2.7	5.0	5.0	-	10.4	\$ 307,058	
General Trees	4.0	5.0	5.0	-	37.5	\$ 31,978	
General Hardscape	4.0	5.0	5.0	-	15.0	\$ 908,815	
General Irrigation	4.0	5.0	5.0	-	18.8	\$ 399,799	
General Lighting	4.0	5.0	5.0	-	30.0	\$ 96,233	
General Barriers	4.0	5.0	5.0	-	22.5	\$ 37,428	
General Signage	4.0	5.0	5.0	-	15.0	\$ 38,274	
General Drainage	4.0	5.0	5.0	-	26.3	\$ 237,052	
Picnic Areas	3.8	5.0	4.0	-	20.0	\$ 98,141	
Playground	4.0	5.0	1.0	-	20.0	\$ 453,573	
Dog Park	4.0	5.0	3.0	-	30.0	\$ 159,493	
Community Gardens	4.0	5.0	3.0	-	22.5	\$ 214,541	

Note: See the appendices for asset rankings



FLAT ROCK PARK



PARK TYPE





SIZE (ACRES) 5.4

ADDRESS 4230 Flat Rock Circle

PRIORITY OUT OF 50 COMMUNITY PARKS 25

SUMMARY

Flat Rock Park is a 5.4 acre neighborhood park located in the southeast quadrant of Santa Rosa, CA. The park contains trails alongside a riparian habitat.

The overall condition of the park is poor. Flat Rock Park does not have recreation programming, has low play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park include deficient trash receptacles, dense weeds in the natural landscapes, missing bollards, deficient signage and significant cracking in the asphalt pavement.

Flat Rock Park is identified by the City as a neighborhood park, though many of the park's characteristics closely resemble a typical trail park.





overall priority rank **3.1**

RANKING MATRIX - FLAT ROCK PARK

	Priority Ranking Categories				Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value		Lifespan	Co	ost Estimate
	2.6	5.0	5.0	2.6	13.2	\$	1,981,199
General Furnishings	1.0	5.0	5.0	-	0.0	\$	150,795
General Landscape	2.0	5.0	5.0	-	6.3	\$	691,743
General Trees	4.0	5.0	5.0	-	37.5	\$	72,040
General Hardscape	2.0	5.0	5.0	-	5.0	\$	543,992
General Barriers	2.0	5.0	5.0	-	7.5	\$	62,544
General Signage	3.0	5.0	5.0	-	10.0	\$	63,959
General Drainage	4.0	5.0	5.0	-	26.3	\$	396,127

Note: See the appendices for asset rankings



FRANCES NIELSEN RANCH PARK



PARK TYPE





SIZE (ACRES) 6.0

ADDRESS 3565 Lake **Park Drive**

88

PRIORITY OUT OF 50 COMMUNITY PARKS 37

SUMMARY

Frances Nielsen Rank Park is a 6.0 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains picnic areas, playgrounds, a basketball court, trails and a lake.

The overall condition of the park is good, with a majority of the amenities in good condition. Frances Nielsen Ranch Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

There are no critical condition amenities within the park, though the required signage at the playground is deficient.





Parks Prioritization Report

	Priority Ranking Categories				Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Co	ost Estimate
	3.8	5.0	1.0	1.6	19.0	\$	2,911,833
General Furnishings	4.0	5.0	5.0	-	15.0	\$	92,568
General Landscape	3.3	5.0	5.0	-	14.6	\$	399,769
General Trees	4.0	5.0	5.0	-	37.5	\$	41,633
General Hardscape	3.3	5.0	5.0	1.0	11.7	\$	652,336
General Irrigation	3.5	5.0	5.0	-	15.6	\$	520,511
General Barriers	4.0	5.0	5.0	-	22.5	\$	42,017
General Signage	4.5	5.0	5.0	4.0	17.5	\$	42,968
General Drainage	4.0	5.0	5.0	-	26.3	\$	266,120
Picnic Areas	3.0	5.0	4.0	-	15.0	\$	145,910
Playground	3.7	5.0	1.0	-	15.0	\$	587,203
Sports Court: Basketball	4.0	5.0	1.0	-	18.8	\$	120,798

RANKING MATRIX - FRANCES NIELSEN RANCH PARK

Note: See the appendices for asset rankings



FREMONT PARK



PARK TYPE





SIZE (ACRES)

ADDRESS 860 Fifth Street

PRIORITY OUT OF 50 COMMUNITY PARKS 34

SUMMARY

Fremont Park is a 1.7 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains a water feature and natural turf.

The overall condition of the park is below adequate, with a few of the amenities broken and not functioning. Fremont Park does not have recreation programming, has low play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the turf areas, which are experiencing significant dieback, the irrigation system, which does not appear to be operating, and the water feature, which is not functioning.



RANKING MATRIX - FREMONT PARK

		ries	Supplemental Categories				
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	C	ost Estimate
	2.9	5.0	5.0	1.6	13.7	\$	1,941,379
General Furnishings	4.0	5.0	5.0	2.0	15.0	\$	55,002
General Landscape	2.5	5.0	5.0	-	9.4	\$	192,995
General Trees	4.0	5.0	5.0	-	37.5	\$	20,099
General Hardscape	3.3	5.0	5.0	1.0	11.7	\$	957,860
General Irrigation	3.0	5.0	5.0	-	12.5	\$	251,286
General Lighting	2.0	5.0	5.0	-	10.0	\$	59,560
General Signage	3.0	5.0	5.0	4.0	10.0	\$	23,689
General Drainage	3.0	5.0	5.0	-	17.5	\$	146,715
Water Feature	1.0	5.0	5.0	-	0.0	\$	234,175

Note: See the appendices for asset rankings



💼 HARVEST PARK



PARK TYPE

Neighborhood Park



SIZE (ACRES) 3.3

ADDRESS 245 Burt St

PRIORITY OUT OF 50 COMMUNITY PARKS 33

SUMMARY

Harvest Park is a 3.3 acre neighborhood park located in the southeast quadrant of Santa Rosa, CA. The park contains picnic areas, a playground, and a dog park.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Harvest Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenity within the park is the dog park, which has substantial weeds and holes in the mulch surfacing, broken components within the gate, and a deficient quantity of trash receptacles. The playgrounds also have a deficient level of wood fiber surfacing.



RANKING MATRIX - HARVEST PARK

		Priority Ranking Categories S					Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	С	ost Estimate		
	3.3	5.0	1.0	2.6	16.9	\$	3,882,737		
General Furnishings	4.0	5.0	5.0	2.0	15.0	\$	92,060		
General Landscape	2.7	5.0	5.0	-	10.4	\$	363,466		
General Hardscape	4.0	5.0	5.0	1.0	15.0	\$	1,085,471		
General Irrigation	3.0	5.0	5.0	-	12.5	\$	473,243		
General Lighting	4.0	5.0	5.0	-	30.0	\$	116,370		
General Barriers	4.0	5.0	5.0	-	22.5	\$	45,260		
General Signage	3.0	5.0	5.0	4.0	10.0	\$	46,284		
General Drainage	3.3	5.0	5.0	-	20.4	\$	286,657		
Picnic Areas	3.8	5.0	4.0	-	15.0	\$	425,626		
Playground	2.9	5.0	1.0	2.3	15.0	\$	675,560		
Dog Park	1.0	5.0	3.0	4.0	0.0	\$	234,889		

Note: See the appendices for asset rankings



HAYDN VILLAGE PARK



PARK TYPE



SIZE (ACRES) 0.1

ADDRESS 1400 Tammy Way

PRIORITY OUT OF 50 COMMUNITY PARKS 38

SUMMARY

Haydn Park is a 0.1 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains a playground and natural turf.

The overall condition of the park is good, and a majority of the amenities are fully functional. Hadyn Park does not have recreation programming, has low play value, and has a few noncompliant ADA features.

The critical condition amenity within the park is the playground equipment, which is showing excessive wear due to its age.




OVERALL PRIORITY RANK 3.3

		Priority Ranking Categories					Supplemental Categories				
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Co	ost Estimate				
General Furnishings	2.7	5.0	5.0	2.0	8.3	\$	2,978				
General Landscape	2.5	5.0	5.0	-	9.4	\$	10,221				
General Trees	4.0	5.0	5.0	-	37.5	\$	1,064				
General Hardscape	4.0	5.0	5.0	-	15.0	\$	54,765				
General Irrigation	4.0	5.0	5.0	-	18.8	\$	13,308				
General Barriers	4.0	5.0	5.0	-	22.5	\$	1,422				
General Signage	5.0	5.0	5.0	-	20.0	\$	1,454				
General Drainage	4.0	5.0	5.0	-	26.3	\$	9,004				
Playground	2.0	5.0	1.0	2.0	5.0	\$	74,399				
late. Can the annealized for each reali-											

RANKING MATRIX - HAYDN VILLAGE PARK

Note: See the appendices for asset rankings



HIDDEN VALLEY PARK



PARK TYPE





SIZE (ACRES) 8.2

ADDRESS 3455 Bonita Vista Ln

PRIORITY OUT OF 50 COMMUNITY PARKS 8

SUMMARY

Hidden Valley Park is a 8.2 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains picnic areas, a playground, and trails.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Hidden Valley Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

There are no critical condition amenities within the park, though the gravel paths on the trails have uneven surfacing, noxious weeds were found within the natural landscape, and trash receptacles appear to be deficient.



PRIORITY RANK

		ries	Supplemental Categories				
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	С	ost Estimate
	3.3	5.0	1.0	1.4	15.4	\$	5,053,685
General Furnishings	2.0	5.0	5.0	-	5.0	\$	232,648
General Landscape	2.0	5.0	5.0	-	6.3	\$	1,077,464
General Trees	4.0	5.0	5.0	-	37.5	\$	112,209
General Hardscape	2.3	5.0	5.0	1.0	6.7	\$	708,222
General Irrigation	3.0	5.0	5.0	-	12.5	\$	1,402,891
General Lighting	3.0	5.0	5.0	-	20.0	\$	251,299
General Barriers	3.0	5.0	5.0	-	15.0	\$	97,738
General Signage	3.0	5.0	5.0	4.0	10.0	\$	99,948
General Drainage	4.0	5.0	5.0	-	26.3	\$	619,029
Picnic Areas	3.6	5.0	4.0	2.0	15.0	\$	65,686
Playground	3.4	5.0	1.0	-	15.0	\$	386,550

Note: See the appendices for asset rankings



HUMBOLDT PARK



PARK TYPE





SIZE (ACRES)

98

ADDRESS 1172 Humboldt St

PRIORITY OUT OF 50 COMMUNITY PARKS 15

SUMMARY

Humboldt Park is a 0.5 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains a playground and natural turf.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Humboldt Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

There are no critical condition amenities within the park, though the presence of temporary trash receptacles indicates a deficient number of permanent receptacles in the park.




RANKING MATRIX - HUMBOLDT PARK

		Priority Rankir	ıg Catego	ories	Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Co	ost Estimate
	3.2	5.0	1.0	1.8	16.4	\$	709,544
General Furnishings	2.5	5.0	5.0	2.0	7.5	\$	15,785
General Landscape	2.3	5.0	5.0	-	8.3	\$	61,333
General Trees	4.0	5.0	5.0	-	37.5	\$	6,387
General Hardscape	3.0	5.0	5.0	1.0	10.0	\$	198,753
General Irrigation	3.0	5.0	5.0	-	12.5	\$	79,858
General Lighting	3.0	5.0	5.0	-	20.0	\$	18,610
General Signage	3.3	5.0	5.0	4.0	11.7	\$	7,402
General Drainage	4.0	5.0	5.0	-	26.3	\$	45,841
General Structures	3.0	5.0	5.0	-	15.0	*	see note
Playground	3.9	5.0	1.0	-	15.0	\$	275,575

*A cost estimate is not provided due to square footage data being unavailable. Note: See the appendices for asset rankings



JACOBS PARK (LINCOLN SCHOOL)



PARK TYPE





SIZE (ACRES) 6.9

ADDRESS 828 W Ninth St

PRIORITY OUT OF 50 COMMUNITY PARKS

SUMMARY

Jacobs Park (Lincoln School) is a 6.9 acre neighborhood park located in the northwest quadrant of Santa Rosa, CA. The park contains picnic areas, a playground, and athletic fields.

The overall condition of the park is poor, with a number of the amenities being excessively worn and having missing or damaged components. Jacobs Park has minimal recreation programming, very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the playground, baseball field, and volleyball court. The playground equipment is heavily worn and is missing components, and the playground rubber tile is deteriorating and creates a tripping hazard. The baseball field has weeds throughout the infield and illegible signage. The volleyball court surfacing is dead turf, the net posts are damaged, and the net is missing.

	Priority Ranking Categories				Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estim	nate
	2.3	4.0	1.0	2.0	9.5	\$ 5,089,	625
General Furnishings	1.0	5.0	5.0	-	0.0	\$ 160	,912
General Landscape	2.0	5.0	5.0	-	6.3	\$ 758	,717
General Trees	4.0	5.0	5.0	-	37.5	\$ 79	,014
General Hardscape	3.0	4.0	5.0	1.0	10.0	\$ 315	,207
General Irrigation	3.0	5.0	5.0	-	12.5	\$ 987	,873
General Lighting	1.0	5.0	5.0	-	0.0	\$ 242	,019
General Barriers	3.0	5.0	5.0	-	15.0	\$ 94	,129
General Signage	2.5	5.0	5.0	4.0	7.5	\$ 96	,257
General Drainage	2.5	5.0	5.0	-	13.1	\$ 596	,170
General Structures	3.0	5.0	5.0	-	15.0	\$ 11	,695
Picnic Areas	2.0	5.0	4.0	-	5.0	\$ 89	,473
Playground	2.0	5.0	1.0	-	5.0	\$ 736	,102
Sports Field: Baseball	1.0	5.0	1.0	-	0.0	\$ 277	,846
Sports Field: Soccer	3.0	4.0	1.0	-	10.0	\$ 507	,362
Sports Court: Volleyball	2.0	5.0	1.0	-	5.0	\$ 136	,847

RANKING MATRIX - JACOBS PARK (LINCOLN SCHOOL)

Note: See the appendices for asset rankings



JENNINGS PARK AT HELEN LEHMAN ELEMENTARY SCHOOL



PARK TYPE

Neighborhood Park



SIZE (ACRES) 6.6

ADDRESS 1688 Clover Ln

PRIORITY OUT OF 50 COMMUNITY PARKS

SUMMARY

Jennings Park at Helen Lehman Elementary School is a 6.6 acre neighborhood park located in the northwest quadrant of Santa Rosa, CA. The park contains softball fields and soccer fields.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Jennings Park has minimal recreation programming, very high play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

The critical condition amenity within the park is the irrigation system, where extensive dieback is observable within the natural turf. Temporary trash receptacles are present, which suggests a deficient number of permanent receptacles in the park.



Parks Prioritization Report

overall priority rank **2.9**

RANKING MATRIX - JENNINGS PARK AT HELEN LEHMAN ELEMENTARY SCHOOL

	Priority Ranking Categories				Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	С	ost Estimate
	3.0	4.0	1.0	3.0	15.0	\$	3,922,385
General Furnishings	1.0	5.0	5.0	-	0.0	\$	121,577
General Landscape	3.0	5.0	5.0	-	12.5	\$	581,266
General Trees	4.0	5.0	5.0	-	37.5	\$	60,534
General Hardscape	4.0	4.0	5.0	-	15.0	\$	134,419
General Irrigation	4.0	5.0	5.0	-	18.8	\$	756,826
General Barriers	3.3	5.0	5.0	-	17.5	\$	89,009
General Signage	2.0	5.0	5.0	-	5.0	\$	91,022
General Drainage	4.0	5.0	5.0	-	26.3	\$	563,744
General Structures	4.0	5.0	5.0	-	22.5	\$	15,344
Sports Field: Softball	1.0	4.0	1.0	-	0.0	\$	801,787
Sports Field: Soccer	3.0	4.0	1.0	-	10.0	\$	706,856

Note: See the appendices for asset rankings



JUILLIARD PARK



PARK TYPE





SIZE (ACRES) 9.1

ADDRESS 227 Santa Rosa Avenue

PRIORITY OUT OF 50 COMMUNITY PARKS 7

SUMMARY

Juilliard Park is a 9.1 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains a playground, bocce ball courts, and a water feature.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Julliard Park has a high level of recreation programming, very high play value, and has a few significantly non-compliant ADA features.

The park does not have critical condition amenities, though the stone pavers are cracked and damaged, and the stone veneer around the flag pole has minor damage.





RANKING MATRIX - JUILLIARD PARK

		Priority Rankin	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	3.3	2.0	1.0	1.9	16.0	\$ 10,187,312
General Furnishings	3.0	5.0	5.0	3.0	10.0	\$ 278,086
General Landscape	4.5	4.0	5.0	-	21.9	\$ 1,104,497
General Trees	4.0	5.0	5.0	-	37.5	\$ 115,025
General Hardscape	2.5	3.0	5.0	1.0	7.5	\$ 3,187,063
General Irrigation	4.5	5.0	5.0	-	21.9	\$ 1,438,089
General Lighting	3.0	5.0	5.0	-	20.0	\$ 315,960
General Barriers	4.0	5.0	5.0	-	22.5	\$ 122,886
General Signage	2.5	5.0	5.0	3.7	7.5	\$ 125,666
General Drainage	3.0	5.0	5.0	-	17.5	\$ 778,309
General Structures	2.0	5.0	5.0	-	7.5	\$ 45,981
Playground	3.0	5.0	1.0	-	10.0	\$ 240,888
Sports Court: Bocce	3.7	4.0	1.0	2.0	10.0	\$ 211,079
Water Feature	4.0	5.0	5.0	-	15.0	\$ 2,009,524
Community Gardens	3.0	5.0	3.0	1.0	15.0	\$ 214,261

Note: See the appendices for asset rankings



LIVE OAK PARK



PARK TYPE

Neighborhood Park



SIZE (ACRES)

ADDRESS 2490 Darla Dr

PRIORITY OUT OF 50 COMMUNITY PARKS

SUMMARY

Live Oak Park is a 4.9 acre neighborhood park located in the northwest quadrant of Santa Rosa, CA. The park contains a playground and natural turf.

The overall condition of the park is below adequate, with a few of the amenities broken and not functioning. Live Oak Park has minimal recreation programming, very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenity within the park is the playground, which has a damaged equipment component and is unsafe to use.





RANKING MATRIX - LIVE OAK PARK

	Priority Ranking Categories				Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	C	ost Estimate
	2.9	4.0	1.0	2.1	14.7	\$	3,456,191
General Furnishings	3.3	5.0	5.0	2.0	11.3	\$	155,950
General Landscape	3.3	5.0	5.0	-	14.6	\$	734,000
General Trees	4.0	5.0	5.0	-	37.5	\$	76,440
General Hardscape	3.0	4.0	5.0	1.0	10.0	\$	324,331
General Irrigation	3.0	5.0	5.0	-	12.5	\$	955,691
General Lighting	3.0	5.0	5.0	-	20.0	\$	169,464
General Barriers	2.0	5.0	5.0	-	7.5	\$	65,910
General Signage	2.5	5.0	5.0	4.0	7.5	\$	67,400
General Drainage	4.0	5.0	5.0	-	26.3	\$	417,444
Playground	1.0	5.0	1.0	2.0	0.0	\$	489,560

Note: See the appendices for asset rankings



MARTIN LUTHER KING JR. PARK



PARK TYPE

Reighborhood Park



SIZE (ACRES) 5.4

ADDRESS 1208 South Hendley St

PRIORITY OUT OF 50 COMMUNITY PARKS 2

SUMMARY

Martin Luther King Jr. Park is a 5.4 acre neighborhood park located in the southeast quadrant of Santa Rosa, CA. The park contains picnic areas, a parking lot, a playground, a basketball court and soccer fields.

The overall condition of the park is below adequate, with some amenities in poor condition, while others remain fully functional. Martin Luther King Jr. Park has minimal recreation programming, very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the landscape, hardscape, sheds, parking lot, and basketball court. The landscape is weedy and a portion of the turf is damaged, the hardscape has large holes in the asphalt pavement, the storage shed and parking lot surface have excessive wear, and the basketball surfacing has major cracking and weed growth. The decomposed granite surfacing in the picnic area also has substantial weed growth.

		Priority Rankir	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	2.9	4.0	1.0	1.6	13.4	\$ 5,146,137
General Furnishings	2.8	5.0	5.0	2.0	8.8	\$ 139,164
General Landscape	2.3	5.0	5.0	-	8.3	\$ 558,396
General Trees	4.0	5.0	5.0	-	37.5	\$ 58,153
General Hardscape	2.0	4.0	5.0	1.0	5.0	\$ 1,457,057
General Irrigation	3.5	5.0	5.0	-	15.6	\$ 727,049
General Lighting	3.0	5.0	5.0	-	20.0	\$ 186,951
General Barriers	4.0	5.0	5.0	-	22.5	\$ 72,711
General Signage	2.5	5.0	5.0	4.0	7.5	\$ 74,355
General Drainage	3.0	5.0	5.0	-	17.5	\$ 460,518
Picnic Areas	2.8	5.0	4.0	2.0	10.0	\$ 285,921
Parking Lot	2.0	5.0	5.0	-	3.8	\$ 38,968
Playground	3.0	5.0	1.0	-	10.0	\$ 670,091
Sports Court: Basketball	2.0	5.0	1.0	-	6.3	\$ 168,408
Sports Field: Soccer	3.5	4.0	1.0	-	15.0	\$ 248,396

RANKING MATRIX - MARTIN LUTHER KING JR. PARK

Note: See the appendices for asset rankings



MATANZAS PARK



PARK TYPE





SIZE (ACRES)

ADDRESS 1900 Woodward Dr

PRIORITY OUT OF 50 COMMUNITY PARKS 35

SUMMARY

Matanzas Park is a 1.1 acre neighborhood park located in the southeast quadrant of Santa Rosa, CA. The park contains a playground and natural turf.

The overall condition of the park is good, and a majority of the amenities are in good condition. Matanzas Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the site furnishings. The presence of temporary trash receptacles suggest a deficient number of permanent receptacles in the park.





RANKING MATRIX - MATANZAS PARK

		Priority Rankir	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	3.5	5.0	1.0	1.4	18.8	\$ 1,139,441
General Furnishings	1.0	5.0	5.0	2.0	0.0	\$ 33,820
General Landscape	4.0	5.0	5.0	-	18.8	\$ 141,966
General Trees	4.0	5.0	5.0	-	37.5	\$ 14,785
General Hardscape	4.0	5.0	5.0	1.0	15.0	\$ 290,707
General Irrigation	4.0	5.0	5.0	-	18.8	\$ 184,844
General Drainage	4.0	5.0	5.0	-	26.3	\$ 94,852
Playground	3.6	5.0	1.0	2.0	15.0	\$ 378,466

Note: See the appendices for asset rankings



MESQUITE PARK



PARK TYPE





SIZE (ACRES)

ADDRESS 2250 Mesquite Dr

PRIORITY OUT OF 50 COMMUNITY PARKS 32

SUMMARY

Mesquite Park is a 4.0 acre neighborhood park located in the southeast quadrant of Santa Rosa, CA. The park contains a playground and natural turf.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Mesquite Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

There are no amenities in critical condition at the park. However, the rubber surfacing at the playground is experiencing wear, and the irrigation for the natural turf has coverage issues.





RANKING MATRIX - MESQUITE PARK

		Supplemental Categories					
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	C	ost Estimate
	3.4	5.0	1.0	1.6	18.1	\$	2,682,854
General Furnishings	2.7	5.0	5.0	-	8.3	\$	128,355
General Landscape	2.5	5.0	5.0	-	9.4	\$	601,160
General Trees	4.0	5.0	5.0	-	37.5	\$	62,606
General Hardscape	3.0	5.0	5.0	1.0	10.0	\$	304,834
General Irrigation	3.0	5.0	5.0	-	12.5	\$	782,728
General Lighting	4.0	5.0	5.0	-	30.0	\$	138,269
General Barriers	3.3	5.0	5.0	-	17.5	\$	53,777
General Signage	4.0	5.0	5.0	4.0	15.0	\$	54,993
General Drainage	4.0	5.0	5.0	-	26.3	\$	340,601
Playground	3.7	5.0	1.0	2.0	15.0	\$	215,529

Note: See the appendices for asset rankings



NORTH PARK



PARK TYPE





SIZE (ACRES)

ADDRESS 921 North St

PRIORITY OUT OF 50 COMMUNITY PARKS 17

SUMMARY

North Park is a 1.0 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains a playground and natural turf.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. North Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenity within the park is the hardscape, which has significant cracking and uneven surfaces.





RANKING MATRIX - NORTH PARK

		Priority Rankin	Supplemental Categories				
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Es	stimate
	3.2	5.0	1.0	2.0	15.2	\$ 9	61,376
General Furnishings	3.5	5.0	5.0	2.0	12.5	\$	29,745
General Landscape	2.5	5.0	5.0	-	9.4	\$ 1	24,516
General Trees	4.0	5.0	5.0	-	37.5	\$	12,967
General Hardscape	2.0	5.0	5.0	1.0	5.0	\$ 2	260,093
General Irrigation	3.0	5.0	5.0	-	12.5	\$ 1	62,123
General Signage	3.5	5.0	5.0	4.0	12.5	\$	13,324
General Drainage	3.0	5.0	5.0	-	17.5	\$	82,522
Playground	3.9	5.0	1.0	-	15.0	\$ 2	276,086

Note: See the appendices for asset rankings





PARK TYPE





SIZE (ACRES) 3.7

ADDRESS 429 Garfield Park Avenue

PRIORITY OUT OF 50 COMMUNITY PARKS 20

SUMMARY

Oaklake Green Park is a 3.7 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains a playground, natural turf, and riparian habitat.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Oaklake Green Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the furnishings due to graffiti and deficiency. A number of light poles have been damaged. The playground is below adequate due to insufficient mulch surfacing, damaged play area curb, and drainage issues.



overall priority rank **3.1**

RANKING MATRIX - OAKLAKE GREEN PARK

		Priority Rankir	Supplemental Categories				
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	C	ost Estimate
	3.2	5.0	1.0	2.2	16.4	\$	2,650,452
General Furnishings	2.0	5.0	5.0	2.0	5.0	\$	111,331
General Landscape	3.5	5.0	5.0	-	15.6	\$	524,720
General Trees	4.0	5.0	5.0	-	37.5	\$	54,645
General Hardscape	3.5	5.0	5.0	1.0	12.5	\$	222,239
General Irrigation	3.0	5.0	5.0	-	12.5	\$	683,201
General Lighting	2.0	5.0	5.0	-	10.0	\$	122,175
General Barriers	4.0	5.0	5.0	-	22.5	\$	47,517
General Signage	3.5	5.0	5.0	4.0	12.5	\$	48,592
General Drainage	4.0	5.0	5.0	-	26.3	\$	300,955
Playground	2.7	5.0	1.0	2.0	10.0	\$	535,077

Note: See the appendices for asset rankings



OLIVE PARK



PARK TYPE





SIZE (ACRES) 0.9

ADDRESS 105 Orange St

PRIORITY OUT OF 50 COMMUNITY PARKS 30

SUMMARY

Olive Park is a 0.9 acre neighborhood park located in the northwest quadrant of Santa Rosa, CA. The park contains a playground, natural turf, and a shade structure.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Olive Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the site furnishings, due to non-operational drinking fountains and a deficient quantity of trash receptacles.





NEIGHBORHOOD PARKS

RANKING MATRIX - OLIVE PARK

		Priority Ranking Categories					Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	C	ost Estimate		
	3.4	5.0	1.0	1.4	17.3	\$	1,347,291		
General Furnishings	1.5	5.0	5.0	-	2.5	\$	25,358		
General Landscape	2.5	5.0	5.0	-	9.4	\$	77,511		
General Trees	4.0	5.0	5.0	-	37.5	\$	8,072		
General Hardscape	4.0	5.0	5.0	1.0	15.0	\$	588,427		
General Irrigation	3.0	5.0	5.0	-	12.5	\$	100,922		
General Lighting	3.0	5.0	5.0	-	20.0	\$	29,753		
General Barriers	4.0	5.0	5.0	-	22.5	\$	11,572		
General Signage	3.5	5.0	5.0	4.0	12.5	\$	11,834		
General Drainage	4.0	5.0	5.0	-	26.3	\$	73,292		
Playground	4.0	5.0	1.0	2.0	15.0	\$	420,550		

Note: See the appendices for asset rankings



PEARBLOSSOM PARK



PARK TYPE





SIZE (ACRES) 3.1

ADDRESS 2850 Edgewater Dr

PRIORITY OUT OF 50 COMMUNITY PARKS 21

SUMMARY

Pearblossom Park is a 3.1 acre neighborhood park located in the southwest quadrant of Santa Rosa, CA. The park contains picnic areas, a playground and a basketball court.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Pearblossom Park does not have recreation programming, has very high play value, and has a number of significantly non-compliant ADA features.

The park does not have critical condition amenities, though there are portions of the ornamental landscape that are dead or missing and the spray irrigation for the natural turf has coverage issues.



overall priority rank **3.1**

RANKING MATRIX - PEARBLOSSOM PARK

		Priority Rankin	Supplemental Categories				
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	C	ost Estimate
	3.3	5.0	1.0	1.5	16.3	\$	3,161,271
General Furnishings	3.4	5.0	5.0	-	12.0	\$	90,596
General Landscape	2.0	5.0	5.0	-	6.3	\$	361,024
General Trees	4.0	5.0	5.0	-	37.5	\$	37,598
General Hardscape	3.0	5.0	5.0	1.0	10.0	\$	1,025,462
General Irrigation	3.0	5.0	5.0	-	12.5	\$	470,064
General Barriers	4.0	5.0	5.0	-	22.5	\$	41,296
General Signage	3.0	5.0	5.0	4.0	10.0	\$	42,230
General Drainage	4.0	5.0	5.0	-	26.3	\$	261,551
Picnic Areas	3.0	5.0	4.0	-	15.0	\$	353,301
Playground	3.4	5.0	1.0	1.0	15.0	\$	376,470
Sports Court: Basketball	3.0	5.0	1.0	-	12.5	\$	101,680

Note: See the appendices for asset rankings





PARK TYPE

Neighborhood Park



SIZE (ACRES)

ADDRESS 1719 Peterson Ln

PRIORITY OUT OF 50 COMMUNITY PARKS

SUMMARY

Peterson Lane Park is a 4.0 acre neighborhood park located in the northwest quadrant of Santa Rosa, CA. The park contains picnic areas, fitness equipment and playgrounds.

The overall condition of the park is poor, with a majority of the amenities experiencing excessive wear and deterioration. Peterson Lane Park does not have recreation programming, has very high play value, and has a number of significantly noncompliant ADA features.

The critical condition amenities within the park are the barriers, playground, picnic area, and fitness equipment. The barriers have missing bollards, the playground has low levels of mulch surfacing, the fitness equipment has excessive wear, and the picnic areas have damaged furnishings.



PRIORITY RANK


		Supplemental Categories					
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Est	imate
	2.8	5.0	1.0	2.3	13.6	\$ 3,28	1,990
General Furnishings	2.5	5.0	5.0	2.0	7.5	\$ 1 [°]	13,528
General Landscape	2.8	5.0	5.0	-	10.9	\$ 49	91,950
General Trees	4.0	5.0	5.0	-	37.5	\$!	51,233
General Hardscape	2.0	5.0	5.0	1.0	5.0	\$ 68	33,110
General Irrigation	4.0	5.0	5.0	-	18.8	\$ 64	40,534
General Lighting	3.0	5.0	5.0	-	20.0	\$ 12	25,336
General Barriers	2.0	5.0	5.0	-	7.5	\$ 4	48,747
General Signage	3.0	5.0	5.0	4.0	10.0	\$ 4	49,849
General Drainage	4.0	5.0	5.0	-	26.3	\$ 30	08,741
Picnic Areas	2.0	5.0	4.0	2.0	5.0	\$ 7	76,806
Fitness Equipment	2.0	5.0	3.0	-	5.0	\$ 15	58,540
Playground	2.3	5.0	1.0	-	10.0	\$ 53	33,615

RANKING MATRIX - PETERSON LANE PARK

Note: See the appendices for asset rankings



PETER SPRINGS PARK



PARK TYPE





SIZE (ACRES)

ADDRESS 819 Carley Rd

PRIORITY OUT OF 50 COMMUNITY PARKS 28

SUMMARY

Peter Springs Park is a 1.2 acre neighborhood park located in the southeast quadrant of Santa Rosa, CA. The park contains a playground and natural turf.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Peter Springs Park has minimal recreation programming, very high play value, and has a few non-compliant ADA features.

The critical condition amenity within the park is the playground, due to the play equipment missing a swing and experiencing excessive wear and the sand surfacing level being low and having weeds.



overall priority rank **3.1**

RANKING MATRIX - PETER SPRINGS PARK

		Priority Rankin	ig Catego	ories	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Со	st Estimate	
	3.4	4.0	1.0	2.2	16.9	\$	923,826	
General Furnishings	2.3	5.0	5.0	2.0	6.7	\$	39,560	
General Landscape	4.0	5.0	5.0	-	18.8	\$	178,748	
General Trees	4.0	5.0	5.0	-	37.5	\$	18,615	
General Hardscape	4.0	4.0	5.0	1.0	15.0	\$	177,629	
General Irrigation	3.0	5.0	5.0	-	12.5	\$	232,735	
General Barriers	3.0	5.0	5.0	-	15.0	\$	16,750	
General Signage	4.0	5.0	5.0	4.0	15.0	\$	17,129	
General Drainage	4.0	5.0	5.0	-	26.3	\$	106,090	
Playground	2.0	5.0	1.0	2.0	5.0	\$	136,569	

Note: See the appendices for asset rankings



PIONEER PARK



PARK TYPE

Neighborhood Park



SIZE (ACRES)

ADDRESS 2062 Peterson Ln

PRIORITY OUT OF 50 COMMUNITY PARKS

SUMMARY

Pioneer Park is a 4.5 acre neighborhood park located in the northwest quadrant of Santa Rosa, CA. The park contains playgrounds, multiple sport courts, and natural turf.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Pioneer Park has minimal recreation programming, very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenity within the park is the horseshoe pit, which has deteriorating lumber, aged surfacing, and pavement uplifting due to tree roots.



RANKING MATRIX - PIONEER PARK

		Priority Rankin	Supplemental Categories				
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Co	st Estimate
	3.2	4.0	1.0	1.7	15.3	\$	4,668,338
General Furnishings	3.4	5.0	5.0	-	12.0	\$	138,760
General Landscape	3.0	5.0	5.0	-	12.5	\$	548,597
General Trees	4.0	5.0	5.0	-	37.5	\$	57,132
General Hardscape	3.0	4.0	5.0	1.0	10.0	\$	1,626,484
General Irrigation	4.0	5.0	5.0	-	18.8	\$	714,290
General Lighting	3.0	5.0	5.0	-	20.0	\$	158,067
General Barriers	3.5	5.0	5.0	-	18.8	\$	61,477
General Signage	3.0	5.0	5.0	4.0	10.0	\$	62,867
General Drainage	4.0	5.0	5.0	-	26.3	\$	389,369
Picnic Areas	3.4	5.0	4.0	1.0	15.0	\$	129,224
Playground	3.0	5.0	1.0	2.0	10.0	\$	643,199
Sports Court: Horseshoe	2.0	5.0	1.0	-	3.8	\$	17,859
Sports Court: Basketball	3.0	5.0	1.0	1.0	12.5	\$	101,600
Sports Court: Handball	3.0	5.0	1.0	-	7.5	\$	19,411

Note: See the appendices for asset rankings



PRINCE GATEWAY PARK



PARK TYPE





SIZE (ACRES) 0.5

ADDRESS 171 Santa Rosa Ave

PRIORITY OUT OF 50 COMMUNITY PARKS 49

SUMMARY

Prince Gateway Park is a 0.5 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains a sprayground and interpretive signage.

The overall condition of the park is good, with a majority of the amenities being fully functional and fairly new. Prince Gateway Park does not have recreation programming, has moderate play value, and has a minor non-compliant ADA element.

The park does not have critical condition amenities, though the sprayground's UV light was identified as outdated.





RANKING MATRIX - PRINCE GATEWAY PARK

		Priority Ranking Categories				Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	C	ost Estimate		
	4.0	5.0	2.0	4.0	21.8	\$	1,060,495		
General Furnishings	3.7	5.0	5.0	-	13.3	\$	15,735		
General Landscape	4.5	5.0	5.0	-	21.9	\$	36,877		
General Trees	5.0	5.0	5.0	-	50.0	\$	3,840		
General Hardscape	4.7	5.0	5.0	-	18.3	\$	508,763		
General Irrigation	4.0	5.0	5.0	-	18.8	\$	48,015		
General Lighting	3.0	5.0	5.0	-	20.0	\$	17,037		
General Barriers	4.3	5.0	5.0	-	25.0	\$	6,626		
General Signage	4.0	5.0	5.0	4.0	15.0	\$	6,776		
General Drainage	4.5	5.0	5.0	-	30.6	\$	41,968		
Sprayground	2.0	5.0	2.0	-	5.0	\$	374,857		

Note: See the appendices for asset rankings



PRINCE MEMORIAL GREENWAY



PARK TYPE

Neighborhood Park



SIZE (ACRES)

ADDRESS 151 Santa Rosa Ave

PRIORITY OUT OF 50 COMMUNITY PARKS 46

SUMMARY

Prince Memorial Greenway is a 4.1 acre neighborhood park located in the northwest quadrant of Santa Rosa, CA. The park contains a walking path along a creek with occasional seating and landscape areas.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Prince Memorial Greenway does not have recreation programming, has low play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

The critical condition amenity within the park is the irrigation system, which was indicated to be non-operational due to the lack of mainline and backflow installation.






		Priority Rankin	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	3.5	5.0	5.0	3.5	18.8	\$ 6,071,503
General Furnishings	3.0	5.0	5.0	-	10.0	\$ 133,767
General Landscape	3.5	5.0	5.0	-	15.6	\$ 289,283
General Trees	4.0	5.0	5.0	-	37.5	\$ 30,127
General Hardscape	4.0	5.0	5.0	-	15.0	\$ 4,635,407
General Irrigation	2.5	5.0	5.0	-	9.4	\$ 376,655
General Lighting	3.0	5.0	5.0	-	20.0	\$ 142,651
General Barriers	4.0	5.0	5.0	-	22.5	\$ 55,481
General Signage	3.7	5.0	5.0	-	13.3	\$ 56,736
General Drainage	4.0	5.0	5.0	-	26.3	\$ 351,396

RANKING MATRIX - PRINCE MEMORIAL GREENWAY

Note: See the appendices for asset rankings



RAE STREET PARK



PARK TYPE





SIZE (ACRES)

ADDRESS 715 Rae St

PRIORITY OUT OF 50 COMMUNITY PARKS 29

SUMMARY

Rae Street Park is a 0.8 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains playgrounds and natural turf.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Rae Street Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

There are no critical condition amenities within the park, though the irrigation system is identified by maintenance staff as below adequate.



RANKING MATRIX - RAE STREET PARK

	l	Priority Ranking Categories					Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Co	ost Estimate		
	3.3	5.0	1.0	2.0	17.1	\$	841,822		
General Furnishings	3.0	5.0	5.0	2.0	10.0	\$	25,323		
General Landscape	3.0	5.0	5.0	-	12.5	\$	115,190		
General Trees	4.0	5.0	5.0	-	37.5	\$	11,996		
General Hardscape	4.0	5.0	5.0	1.0	15.0	\$	103,838		
General Irrigation	2.5	5.0	5.0	-	9.4	\$	149,981		
General Lighting	3.0	5.0	5.0	-	20.0	\$	29,018		
General Barriers	3.0	5.0	5.0	-	15.0	\$	11,286		
General Signage	3.0	5.0	5.0	4.0	10.0	\$	11,541		
General Drainage	4.0	5.0	5.0	-	26.3	\$	71,479		
Playground	3.9	5.0	1.0	-	15.0	\$	312,171		

Note: See the appendices for asset rankings



RAILROAD DEPOT PARK



PARK TYPE

Neighborhood Park



SIZE (ACRES) 0.3

ADDRESS 9 4th St

PRIORITY OUT OF 50 COMMUNITY PARKS 41

SUMMARY

Railroad Depot Park is a 0.3 acre neighborhood park located in the northwest quadrant of Santa Rosa, CA. The park contains natural turf, a few site furnishings, and several art pieces.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Railroad Depot Park does not have recreation programming, has low play value, and has a few significantly non-compliant ADA features.

There are no critical condition amenities within the park, though the park rules sign is in a poor location. The monument sign is frequently vandalized.





OVERALL PRIORITY RANK **3.6**

RANKING MATRIX - RAILROAD DEPOT PARK

	I	Priority Rankin	g Catego	ories	Supplem	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Со	st Estimate		
	3.4	5.0	5.0	1.8	17.3	\$	291,744		
General Furnishings	4.0	5.0	5.0	-	15.0	\$	8,544		
General Landscape	3.3	5.0	5.0	-	14.6	\$	27,718		
General Trees	3.0	5.0	5.0	-	25.0	\$	2,887		
General Hardscape	3.0	5.0	5.0	1.0	10.0	\$	177,781		
General Irrigation	3.0	5.0	5.0	-	12.5	\$	36,089		
General Lighting	3.0	5.0	5.0	-	20.0	\$	9,112		
General Barriers	4.0	5.0	5.0	-	22.5	\$	3,544		
General Signage	3.0	5.0	5.0	4.0	10.0	\$	3,624		
General Drainage	4.0	5.0	5.0	-	26.3	\$	22,445		

Note: See the appendices for asset rankings



RED HAWK PARK



PARK TYPE





SIZE (ACRES)

ADDRESS 3000 Terrimay Ln

PRIORITY OUT OF 50 COMMUNITY PARKS 36

SUMMARY

Red Hawk Park is a 0.4 acre neighborhood park located in the southeast quadrant of Santa Rosa, CA. The park contains playgrounds and natural turf.

The overall condition of the park is good, and a majority of the amenities are in good condition. Red Hawk Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA features.

There are no critical condition amenities within the park though the presence of temporary trash receptacles suggests a deficient number of permanent receptacles in the park.





RANKING MATRIX - RED HAWK PARK

	I	Priority Rankin	ıg Catego	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value		Lifespan	Co	ost Estimate
	3.5	5.0	1.0	1.9	17.5	\$	770,932
General Furnishings	3.0	5.0	5.0	-	10.0	\$	12,567
General Landscape	3.0	5.0	5.0	-	12.5	\$	36,056
General Trees	4.0	5.0	5.0	-	37.5	\$	3,755
General Hardscape	4.0	5.0	5.0	1.0	15.0	\$	321,795
General Irrigation	4.0	5.0	5.0	-	18.8	\$	46,946
General Barriers	3.0	5.0	5.0	-	15.0	\$	5,964
General Signage	3.5	5.0	5.0	4.0	12.5	\$	6,099
General Drainage	4.0	5.0	5.0	-	26.3	\$	37,776
Playground	3.0	5.0	1.0	2.0	10.0	\$	299,974

Note: See the appendices for asset rankings



RINCONADA PARK



PARK TYPE

Neighborhood Park



SIZE (ACRES) 2.2

ADDRESS 4459 Yukon Dr

PRIORITY OUT OF 50 COMMUNITY PARKS 22

SUMMARY

Rinconada Park is a 2.2 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains natural turf and trails alongside riparian habitat.

The overall condition of the park is below adequate, with a few amenities broken and not functioning. Rinconada Park does not have recreation programming, has moderate play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the general hardscape, trail surfacing, and site furnishings. The hardscape has cracking and lifting and there is a deficient number of benches and trash receptacles.



overall priority rank **3.1**

RANKING MATRIX - RINCONADA PARK

		Priority Rankin	ig Catego	ories Supplemental Catego			l Categories
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	C	ost Estimate
	2.8	5.0	4.0	2.0	14.7	\$	1,290,982
General Furnishings	1.0	5.0	5.0	-	0.0	\$	68,322
General Landscape	4.0	5.0	5.0	-	18.8	\$	327,095
General Trees	4.0	5.0	5.0	-	37.5	\$	34,064
General Hardscape	2.0	5.0	5.0	1.0	5.0	\$	71,271
General Irrigation	3.5	5.0	5.0	-	15.6	\$	425,888
General Lighting	3.0	5.0	5.0	-	20.0	\$	75,614
General Barriers	3.5	5.0	5.0	-	18.8	\$	29,409
General Signage	2.0	5.0	5.0	4.0	5.0	\$	30,074
General Drainage	4.0	5.0	5.0	-	26.3	\$	186,261
Trails	1.0	5.0	4.0	-	0.0	\$	42,984

Note: See the appendices for asset rankings



SONOMA AVENUE PARK



PARK TYPE

Neighborhood Park



SIZE (ACRES)

140

ADDRESS 729 Sonoma Ave

PRIORITY OUT OF 50 COMMUNITY PARKS 26

SUMMARY

Sonoma Avenue Park is a 1.8 acre park located in the northeast quadrant of Santa Rosa, CA. The park contains a water feature with a pedestrian bridge, landscaping, and walking paths.

The overall condition of the park is adequate, with some amenities being functional and others being deficient. Sonoma Avenue Park does not have recreation programming, has low play value, and has a number of significantly non-compliant ADA elements.

The critical condition amenities within the park are the irrigation system and the water feature. The irrigation system uses battery powered nodes and has coverage issues, while the water feature is functioning but the water and basin are polluted.



arks

overall priority rank **3.1**

		Priority Rankin	ıg Catego	ries	Supplem	Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	C	ost Estimate	
	2.8	5.0	5.0	1.2	14.7	\$	1,646,397	
General Furnishings	2.0	5.0	5.0	2.0	5.0	\$	55,385	
General Landscape	2.7	5.0	5.0	-	10.4	\$	201,557	
General Trees	4.0	5.0	5.0	-	37.5	\$	20,991	
General Hardscape	3.0	5.0	5.0	1.0	10.0	\$	867,870	
General Irrigation	1.0	5.0	5.0	-	0.0	\$	262,434	
General Drainage	5.0	5.0	5.0	-	35.0	\$	146,126	
General Structures	3.0	5.0	5.0	-	15.0	\$	25,323	
Water Feature	2.0	5.0	5.0	-	5.0	\$	66,710	

RANKING MATRIX - SONOMA AVENUE PARK

Note: See the appendices for asset rankings



SOUTH DAVIS PARK



PARK TYPE





SIZE (ACRES)

ADDRESS 712 S Davis St

PRIORITY OUT OF 50 COMMUNITY PARKS 2

SUMMARY

South Davis Park is a 1.3 acre park located in the southwest quadrant of Santa Rosa, CA. The park contains a playground and a basketball court.

The overall condition of the park is below adequate, with a number of the amenities nearing critical condition. South Davis Park has minimal recreation programming, very high play value, and a number of significantly non-compliant ADA elements.

The critical condition amenity is the basketball court due to the uneven and cracking asphalt surfacing and the heavilyweathered equipment.



PRIORITY RANK

RANKING MATRIX - SOUTH DAVIS PARK

		Priority Rankin	ig Catego	ries	Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	С	ost Estimate
	2.8	4.0	1.0	1.5	13.6	\$	1,418,918
General Furnishings	2.3	5.0	5.0	2.0	6.7	\$	40,810
General Landscape	2.5	5.0	5.0	-	9.4	\$	170,869
General Trees	4.0	5.0	5.0	-	37.5	\$	17,795
General Hardscape	3.0	4.0	5.0	1.0	10.0	\$	356,400
General Irrigation	3.5	5.0	5.0	-	15.6	\$	222,476
General Lighting	3.0	5.0	5.0	-	20.0	\$	46,893
General Barriers	3.0	5.0	5.0	-	15.0	\$	18,238
General Signage	2.0	5.0	5.0	4.0	5.0	\$	18,650
General Drainage	2.0	5.0	5.0	-	8.8	\$	115,511
Playground	4.0	5.0	1.0	2.0	15.0	\$	383,902
Sports Court: Basketball	2.0	5.0	1.0	-	6.3	\$	27,375

Note: See the appendices for asset rankings



STEELE LANE PARK



PARK TYPE

Neighborhood Park



SIZE (ACRES) 2.4

144

ADDRESS 130 Schurman Dr

PRIORITY OUT OF 50 COMMUNITY PARKS 18

SUMMARY

Steele Lane Park is a 2.4 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains a playground, natural turf, and walking paths.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Steele Lane Park does not have recreation programming, has very high play value, and generally complies with ADA standards with the exception of having a few non-compliant items.

There are no critical condition amenities within the park, but the general irrigation and general landscape are in below adequate condition. The irrigation overspray causes weed growth within the play area, and there are substantial weeds in the landscape areas.





OVERALL PRIORITY RANK

RANKING MATRIX - STEELE LANE PARK

		Priority Rankin	ig Catego	ories	Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	С	ost Estimate
	3.2	5.0	1.0	1.5	15.9	\$	2,361,427
General Furnishings	3.0	5.0	5.0	-	10.0	\$	71,261
General Landscape	2.7	5.0	5.0	-	10.4	\$	323,533
General Trees	4.0	5.0	5.0	-	37.5	\$	33,693
General Hardscape	3.0	5.0	5.0	2.0	10.0	\$	300,149
General Irrigation	2.5	5.0	5.0	-	9.4	\$	421,250
General Lighting	3.0	5.0	5.0	-	20.0	\$	82,292
General Barriers	3.0	5.0	5.0	-	15.0	\$	32,006
General Signage	3.7	5.0	5.0	4.0	13.3	\$	32,730
General Drainage	4.0	5.0	5.0	-	26.3	\$	202,712
Playground	3.0	5.0	1.0	1.0	15.0	\$	848,925
Trails	3.5	5.0	4.0	1.0	7.5	\$	12,876

Note: See the appendices for asset rankings



STRAWBERRY PARK



PARK TYPE

Neighborhood Park



SIZE (ACRES) 5.8

ADDRESS 2311 Horseshoe Dr

PRIORITY OUT OF 50 COMMUNITY PARKS 44

SUMMARY

Strawberry Park is a 5.8 acre neighborhood park located in the southeast quadrant of Santa Rosa, CA. The park contains a natural turf area and a trail alongside a riparian habitat.

The overall condition of the park is good, and a majority of the amenities are in good condition. Strawberry Park does not have recreation programming, has moderate play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

There are no critical condition amenities within the park, but the general hardscape is in below adequate condition due to cracking in both the concrete and asphalt pavement.






OVERALL PRIORITY RANK

RANKING MATRIX - STRAWBERRY PARK

		Priority Rankin	ig Catego	gories Supplemental Catego			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Co	ost Estimate
	3.6	5.0	4.0	3.6	16.9	\$	2,796,006
General Furnishings	4.5	5.0	5.0	-	17.5	\$	147,008
General Landscape	4.0	5.0	5.0	-	18.8	\$	700,035
General Trees	3.0	5.0	5.0	-	25.0	\$	72,903
General Hardscape	2.5	5.0	5.0	-	7.5	\$	201,742
General Irrigation	3.0	5.0	5.0	-	12.5	\$	911,466
General Barriers	4.0	5.0	5.0	-	22.5	\$	66,200
General Signage	4.0	5.0	5.0	-	15.0	\$	67,697
General Drainage	4.0	5.0	5.0	-	26.3	\$	419,281
Trails	3.0	5.0	4.0	-	7.5	\$	209,674

Note: See the appendices for asset rankings





PARK TYPE





SIZE (ACRES) 7.8

ADDRESS 5174 Oak Pk Way

PRIORITY OUT OF 50 COMMUNITY PARKS 10

SUMMARY

Tanglewood Park is a 7.8 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains a playground, a basketball court, and lengthy walking paths along a riparian habitat.

The overall condition of the park is adequate, with a majority of the amenities being functional and a few being in need of servicing. Tanglewood Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA elements.

The critical condition amenity within the park is the basketball court, which has major cracking, uneven pavement, faded striping, and severe weed growth within the surfacing.






overall priority rank **2.9**

		Priority Rankin	ig Catego	Categories Supplemental Categ			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	С	ost Estimate
	3.0	5.0	1.0	1.6	14.0	\$	5,334,531
General Furnishings	2.0	5.0	5.0	-	5.0	\$	217,443
General Landscape	3.5	5.0	5.0	-	15.6	\$	957,692
General Trees	4.0	5.0	5.0	-	37.5	\$	99,736
General Hardscape	4.0	5.0	5.0	1.0	15.0	\$	1,293,838
General Irrigation	3.5	5.0	5.0	-	15.6	\$	1,246,944
General Lighting	2.0	5.0	5.0	-	10.0	\$	236,831
General Barriers	3.0	5.0	5.0	-	15.0	\$	92,111
General Signage	3.5	5.0	5.0	4.0	12.5	\$	94,194
General Drainage	3.0	5.0	5.0	-	17.5	\$	583,390
Playground	3.0	5.0	1.0	2.0	10.0	\$	449,968
Sports Court: Basketball	1.0	5.0	1.0	1.0	0.0	\$	62,382

Note: See the appendices for asset rankings





PARK TYPE





SIZE (ACRES)

ADDRESS 4684 Quigg Dr

PRIORITY OUT OF 50 COMMUNITY PARKS 45

SUMMARY

Trailhead Park is a 4.2 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains picnic areas and trails along a riparian habitat.

The overall condition of the park is good, and a majority of the amenities are in good condition. Trailhead Park does not have recreation programming, has moderate play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

There are no amenities in critical condition at the park. However, the landscape areas require mulch replenishing.



RANKING MATRIX - TRAILHEAD PARK

		Priority Rankin	ıg Catego	ories	Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	C	ost Estimate
	3.6	5.0	4.0	3.6	17.2	\$	2,191,514
General Furnishings	3.3	5.0	5.0	-	11.3	\$	90,133
General Landscape	2.5	5.0	5.0	-	9.4	\$	413,625
General Trees	4.0	5.0	5.0	-	37.5	\$	43,076
General Hardscape	4.0	5.0	5.0	-	15.0	\$	323,168
General Irrigation	4.0	5.0	5.0	-	18.8	\$	538,552
General Barriers	3.8	5.0	5.0	-	20.6	\$	44,182
General Signage	3.3	5.0	5.0	-	11.7	\$	45,181
General Drainage	4.0	5.0	5.0	-	26.3	\$	279,828
Picnic Areas	3.0	5.0	4.0	-	10.0	\$	169,538
Trails	4.0	5.0	4.0	-	11.3	\$	244,231

Note: See the appendices for asset rankings



TRIANGLE PARK



PARK TYPE





SIZE (ACRES) 0.1

ADDRESS 0 Clyde Ave

PRIORITY OUT OF 50 COMMUNITY PARKS 47

SUMMARY

Triangle Park is a 0.1 acre neighborhood park located in the northeast quadrant of Santa Rosa, CA. The park contains a small natural turf area and a few benches.

The overall condition of the park is good, and a majority of the amenities are in good condition. Triangle Park does not have recreation programming, has low play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

There are no critical condition amenities within the park, but the natural turf is dead, potentially due to drought measures.





OVERALL PRIORITY RANK

RANKING MATRIX - TRIANGLE PARK

		Priority Rankir	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	3.5	5.0	5.0	3.5	20.6	\$ 52,205
General Furnishings	4.0	5.0	5.0	-	15.0	\$ 3,403
General Landscape	2.0	5.0	5.0	-	6.3	\$ 16,568
General Trees	4.0	5.0	5.0	-	37.5	\$ 1,725
General Irrigation	2.5	5.0	5.0	-	9.4	\$ 21,571
General Drainage	5.0	5.0	5.0	-	35.0	\$ 8,938

Note: See the appendices for asset rankings





PARK TYPE

Neighborhood Park



SIZE (ACRES) 2.0

ADDRESS 3945 New Zealand Ave

PRIORITY OUT OF 50 COMMUNITY PARKS 27

SUMMARY

Village Green Park is a 2.0 acre neighborhood park located in the southwest quadrant of Santa Rosa, CA. The park contains picnic areas, a playground, and a basketball court.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Village Green Park does not have recreation programming, has very high play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessment.

There are no critical condition amenities within the park, though a portion of the concrete pavement has significant cracking, and the quantity of trash receptacles throughout the park is deficient.



Parks Prioritization Report

overall priority rank **3.1**

RANKING MATRIX - VILLAGE GREEN PARK

		Supplemental Categories					
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	С	ost Estimate
	3.1	5.0	1.0	3.1	15.0	\$	2,081,640
General Furnishings	2.7	5.0	5.0	-	8.3	\$	57,496
General Landscape	2.7	5.0	5.0	-	10.4	\$	233,817
General Trees	4.0	5.0	5.0	-	37.5	\$	24,350
General Hardscape	3.0	5.0	5.0	-	10.0	\$	590,707
General Irrigation	3.0	5.0	5.0	-	12.5	\$	304,436
General Barriers	3.5	5.0	5.0	-	18.8	\$	26,552
General Signage	3.5	5.0	5.0	-	12.5	\$	27,153
General Drainage	3.0	5.0	5.0	-	17.5	\$	168,172
Picnic Areas	2.3	5.0	4.0	-	10.0	\$	232,053
Playground	3.1	5.0	1.0	-	15.0	\$	349,752
Sports Court: Basketball	3.0	5.0	1.0	-	12.5	\$	67,152

Note: See the appendices for asset rankings



WESTGATE PARK



PARK TYPE





SIZE (ACRES) 2.4

ADDRESS 209 Westbrook Dr

PRIORITY OUT OF 50 COMMUNITY PARKS 18

SUMMARY

Westgate Park is a 2.4 acre park located in the northwest quadrant of Santa Rosa, CA. The park contains a playground, a large natural turf field, and a basketball half-court.

The overall condition of the park is adequate. Westgate Park does not have recreation programming, has very high play value, and has a few significantly non-compliant ADA elements.

There are no critical condition amenities within the park, though there are a few general amenities that are nearing the end of their life span, such as the bollards and park signage.



OVERALL PRIORITY RANK

RANKING MATRIX - WESTGATE PARK

		Priority Rankin	ig Catego	ories	Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	C	ost Estimate
	3.2	5.0	1.0	2.0	16.5	\$	1,753,464
General Furnishings	2.7	5.0	5.0	-	8.3	\$	74,830
General Landscape	3.0	5.0	5.0	-	12.5	\$	351,999
General Trees	4.0	5.0	5.0	-	37.5	\$	36,658
General Hardscape	4.0	5.0	5.0	1.0	15.0	\$	158,176
General Irrigation	3.0	5.0	5.0	-	12.5	\$	458,313
General Barriers	2.0	5.0	5.0	-	7.5	\$	32,583
General Signage	2.0	5.0	5.0	4.0	5.0	\$	33,320
General Drainage	4.0	5.0	5.0	-	26.3	\$	206,369
Playground	3.6	5.0	1.0	2.0	15.0	\$	348,447
Sports Court: Basketball	3.4	5.0	1.0	-	25.0	\$	52,770

Note: See the appendices for asset rankings



OPEN SPACES



OPEN SPACES

Twelve open spaces that are owned and maintained by the City were evaluated as part of this report. This section evaluates the priority ranking of each open space based on condition, recreation programming, play value, and accessibility. In addition, the approximate lifespan and the estimated replacement cost is provided for each amenity as well as the overall park. Parks with a priority ranking closer to one (1) are identified as having a higher priority for new improvements, while parks that rank closer to five (5) have a lower priority for improvement needs. The table below identifies the open spaces in order of priority ranking, the parks identified in gray were not assessed by this Report.

0	pen Spaces - Ranked by Priority Ranking						
Rank	Park	Priority Ranking	Lifespan	Area (Acres)	Estimated Replacement Cost	Quadrant	Park Type
1	Frances Nielsen Open Space	2.7	10.8	7.9	\$ 2,028,790	NE	OS
2	Parktrail Open Space	3.1	13.5	24.9	\$ 7,462,667	SE	OS
3	Owls Nest Open Space	3.2	18.3	15.0	\$ 3,134,127	NE	OS
4	Parker Hill Open Space	3.2	14.2	4.3	\$ 1,099,983	NE	OS
5	Fravel Lane Open Space	3.2	16.5	2.9	\$ 827,794.25	NE	OS
6	Vietnam Vets Memorial Trail Open Space	3.4	15.2	11.4	\$ 3,720,669	SE	OS
7	Thomas Lake Harris Open Space	3.4	16.0	6.2	\$ 2,275,898	NE	OS
8	Skyhawk Creek Open Space	3.6	19.8	2.6	\$ 595,816	SE	OS
9	Boas Village Creek Open Space	3.9	20.3	0.5	\$ 225,963	SE	OS
10	Mary Traverso Open Space	4.0	21.0	3.6	\$ 497,761	SE	OS
11	Skyhawk Open Space	4.0	17.5	21.7	\$ 8,493,984	NE	OS
12	Airfield Fresno Mitigation Open Space	4.1	18.4	3.1	\$ 1,134,647	SW	OS
-	Rincon Ridge Open Space	-	-	1.8	-	NE	OS

AIRFIELD FRESNO MITIGATION OPEN SPACE



PARK TYPE





SIZE (ACRES) 3.9

ADDRESS 5020 Yeager Dr

PRIORITY OUT OF 12 OPEN SPACE PARKS 12

SUMMARY

Airfield Fresno Open Space is a 3.9 acre park located in the southwest quadrant of Santa Rosa, CA. The area is not accessible to the general public for it is an important migration corridor managed by the Recreation and Parks Department for the California Tiger Salamander.

The overall condition of the park is good. Airfield Fresno Open Space does not have recreation programming, has low play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessment.

There are no critical condition amenities within the park. However, the locking mechanism for the entry gate is damaged.






		Priority Rankin	ıg Catego	ries	Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	С	ost Estimate
	3.9	5.0	5.0	3.9	18.4	\$	1,134,647
General Landscape	3.5	5.0	5.0	-	15.6	\$	614,988
General Hardscape	4.0	5.0	5.0	-	15.0	\$	77,594
General Barriers	3.0	5.0	5.0	-	15.0	\$	52,903
General Signage	5.0	5.0	5.0	-	20.0	\$	54,099
General Drainage	4.0	5.0	5.0	-	26.3	\$	335,063

RANKING MATRIX - AIRFIELD FRESNO MITIGATION OPEN SPACE

Note: See the appendices for asset rankings



BOASVILLAGE CREEK OPEN SPACE



PARK TYPE





SIZE (ACRES) 0.5

ADDRESS 0 Santa Rosa Creek Dr

PRIORITY OUT OF 12 OPEN SPACE PARKS 9

SUMMARY

Boas Village Creek Open Space is a 0.5 acre open space park located in the southeast quadrant of Santa Rosa, CA.

The overall condition of the park is adequate. Boas Village Creek Open Space does not have recreation programming, has low play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessment.

The critical condition amenities within the park is the irrigated groundcover landscape, which is weedy and partially dead.



		Supplemental Categories					
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost E	Estimate
	3.6	5.0	5.0	3.6	20.3	\$ 2	225,963
General Landscape	3.0	5.0	5.0	-	12.5	\$	61,839
General Trees	4.0	5.0	5.0	-	37.5	\$	6,440
General Hardscape	4.0	5.0	5.0	-	15.0	\$	42,033
General Irrigation	4.0	5.0	5.0	-	18.8	\$	80,516
General Drainage	3.0	5.0	5.0	-	17.5	\$	35,134

RANKING MATRIX - BOAS VILLAGE CREEK OPEN SPACE

Note: See the appendices for asset rankings



FRANCES NIELSEN OPEN SPACE



PARK TYPE





SIZE (ACRES) 7.9

ADDRESS 0 Altruria Dr

PRIORITY OUT OF 12 OPEN SPACE PARKS

1

SUMMARY

Frances Nielsen Open Space is 7.9 acre open space park located in the northeast quadrant of Santa Rosa, CA.

The overall condition of the park is poor. Frances Nielsen Open Space does not have recreation programming, has moderate play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessment.

The critical condition amenities within the park are the natural landscape and signage. There were noxious weeds and a deficient amount of park signage.





		Priority Ranking Categories					Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	С	ost Estimate		
	2.3	5.0	4.0	2.3	10.8	\$	2,028,790		
General Landscape	1.0	5.0	5.0	-	0.0	\$	1,066,876		
General Trees	3.0	5.0	5.0	-	25.0	\$	111,107		
General Barriers	3.0	5.0	5.0	-	15.0	\$	92,765		
General Signage	1.0	5.0	5.0	-	0.0	\$	94,863		
General Drainage	3.0	5.0	5.0	-	17.5	\$	587,535		
Trails	3.0	5.0	4.0	-	7.5	\$	75,642		

RANKING MATRIX - FRANCES NIELSEN OPEN SPACE

Note: See the appendices for asset rankings







PARK TYPE





SIZE (ACRES) 2.6

ADDRESS 0 Fravel Ln

PRIORITY OUT OF 12 OPEN SPACE PARKS 5

SUMMARY

Fravel Lane Open Space is a 2.6 acre open space park located in the northeast quadrant of Santa Rosa, CA.

The overall condition of the park is below adequate. Fravel Lane Open Space does not have recreation programming, has low play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessment.

The critical condition amenity within the park is the asphalt pavement, which has major buckling across the surface.




		Supplemental Categories					
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Co	ost Estimate
	2.8	5.0	5.0	2.8	16.5	\$	827,794
General Landscape	3.0	5.0	5.0	-	12.5	\$	408,437
General Trees	4.0	5.0	5.0	-	37.5	\$	42,536
General Hardscape	1.0	5.0	5.0	-	0.0	\$	116,012
General Barriers	3.0	5.0	5.0	-	15.0	\$	35,564
General Drainage	3.0	5.0	5.0	-	17.5	\$	225,245

RANKING MATRIX - FRAVEL LANE OPEN SPACE

Note: See the appendices for asset rankings



MARY TRAVERSO OPEN SPACE



PARK TYPE





SIZE (ACRES) 3.6

ADDRESS 0 Creekside Rd

PRIORITY OUT OF 12 OPEN SPACE PARKS 10

SUMMARY

Mary Traverso Open Space, formerly Creekside Open Space, is a 3.6 acre open space park located in the southeast quadrant of Santa Rosa, CA.

The overall condition of the park is good. Mary Traverso Open Space does not have recreation programming, has low play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessment.

The park does not have critical condition amenities, though a trash receptacle has been damaged and is no longer functional.





		Priority Rankin	ıg Catego	ries	Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Co	ost Estimate
	3.7	5.0	5.0	3.7	21.0	\$	497,761
General Furnishings	3.5	5.0	5.0	-	12.5	\$	38,737
General Landscape	4.0	5.0	5.0	-	18.8	\$	175,879
General Trees	4.0	5.0	5.0	-	37.5	\$	18,316
General Hardscape	3.0	5.0	5.0	-	10.0	\$	163,068
General Drainage	4.0	5.0	5.0	-	26.3	\$	101,760

RANKING MATRIX - MARY TRAVERSO OPEN SPACE

Note: See the appendices for asset rankings





PARK TYPE





SIZE (ACRES) 15.0

ADDRESS 0 Owls Nest Dr

PRIORITY OUT OF 12 OPEN SPACE PARKS 3

SUMMARY

Owls Nest Open Space is a 15.0 acre open space park located in the northeast quadrant of Santa Rosa, CA.

The overall condition of the park is below adequate. Owls Nest Open Space does not have recreation programming, has low play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessment.

The critical condition amenity within the park is the natural landscape, which include portions of tall, overgrown grasses that pose a fire hazard and require mowing.





overall priority rank **3.2**

		Priority Rankin	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	2.7	5.0	5.0	2.7	18.3	\$ 3,134,127
General Landscape	1.0	5.0	5.0	-	0.0	\$ 1,906,803
General Trees	4.0	5.0	5.0	-	37.5	\$ 198,579
General Drainage	3.0	5.0	5.0	-	17.5	\$ 1,028,745

RANKING MATRIX - OWLS NEST OPEN SPACE

Note: See the appendices for asset rankings





PARK TYPE





SIZE (ACRES) 4.3

ADDRESS 3881 Parker Hill Rd

PRIORITY OUT OF 12 OPEN SPACE PARKS 4

SUMMARY

Parker Hill Open Space is a 4.3 acre open space park located in the northeast quadrant of Santa Rosa, CA.

The overall condition of the park is below adequate. Parker Hill Open Space does not have recreation programming, has low play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessment.

There are no amenities in critical condition at the park. However, a number of trees and portions of the landscape have been impacted due to fire damage from the 2017 wildfires.





overall priority rank **3.2**

		Priority Rankir	Supplemental Categories				
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate	e
	2.7	5.0	5.0	2.7	14.2	\$ 1,099,98	33
General Landscape	3.0	5.0	5.0	-	12.5	\$ 669,23	30
General Trees	2.0	5.0	5.0	-	12.5	\$ 69,69	95
General Drainage	3.0	5.0	5.0	-	17.5	\$ 361,05	58

RANKING MATRIX - PARKER HILL OPEN SPACE

Note: See the appendices for asset rankings





PARK TYPE





SIZE (ACRES) 24.9

ADDRESS 4837 Parktrail Dr

PRIORITY OUT OF 12 OPEN SPACE PARKS 2

SUMMARY

Parktrail Open Space is a 24.9 acre open space park located in the southeast quadrant of Santa Rosa, CA. The park contains trails that meander through large swaths of natural areas.

The overall condition of the park is below adequate, primarily due to the trail condition. Parktrail Open Space does not have recreation programming, has moderate play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessment.

The critical condition amenities within the park are the trail and the site furnishings. The trail surface is uneven with frequent rocks and boulder obstructing the path, the site furnishings are severely worn, and the quantity of trash receptacles is deficient.



Parks Prioritization Report

overall priority rank **3.1**

		Priority Rankin	Supplemental Categories				
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate	
	2.8	2.8 5.0		2.8	13.5	\$ 7,462,667	
General Furnishings	1.5	5.0	5.0	-	2.5	\$ 758,250	
General Landscape	3.0	5.0	5.0	-	12.5	\$ 3,691,966	
General Trees	3.0	5.0	5.0	-	25.0	\$ 384,489	
General Barriers	3.3	5.0	5.0	-	16.9	\$ 314,493	
General Signage	2.5	5.0	5.0	-	7.5	\$ 321,606	
General Drainage	4.0	5.0	5.0	-	26.3	\$ 1,991,863	
Trails	2.0	5.0	4.0	-	3.8	*see note	

RANKING MATRIX - PARK TRAIL OPEN SPACE

*A cost estimate is not provided due to square footage data being unavailable. Note: See the appendices for asset rankings



SKYHAWK CREEK OPEN SPACE



PARK TYPE





SIZE (ACRES) 2.6

ADDRESS 0 Diane Way

PRIORITY OUT OF 12 OPEN SPACE PARKS 8

SUMMARY

Skyhawk Creek Open Space is a 2.6 acre open space park located in the southeast quadrant of Santa Rosa, CA.

The overall condition of the park is adequate. Skyhawk Creek Open Space does not have recreation programming, has low play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

There are no amenities in critical or poor condition at the park. However, a number of trees have been impacted due to fire damage from the 2017 wildfires.



		Priority Rankir	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	3.3	5.0	5.0	3.3	19.8	\$ 595,816
General Landscape	4.0	5.0	5.0	-	18.8	\$ 344,634
General Trees	3.0	5.0	5.0	-	25.0	\$ 35,891
General Barriers	3.0	5.0	5.0	-	15.0	\$ 29,357
General Drainage	3.3	5.0	5.0	-	20.4	\$ 185,934

RANKING MATRIX - SKYHAWK CREEK OPEN SPACE

Note: See the appendices for asset rankings





PARK TYPE





SIZE (ACRES) 21.7

ADDRESS 0 Mountain Hawk

PRIORITY OUT OF 12 OPEN SPACE PARKS 11

SUMMARY

Skyhawk Open Space is a 21.7 acre open space park located in the northeast quadrant of Santa Rosa, CA.

The overall condition of the park is good. Skyhawk Open Space does not have recreation programming, has low play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

There are no amenities in critical or poor condition at the park. However, a number of trees have been impacted due to fire damage from the 2017 wildfires.



overall priority rank **4.0**


		Priority Rankin	Supplemental Categories				
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate	
	3.7	5.0	5.0	3.7	17.5	\$ 8,493,984	
General Landscape	4.0	5.0	5.0	-	-	\$ 2,996,387	
General Trees	2.0	5.0	5.0	-	12.5	\$ 312,050	
General Hardscape	4.0	5.0	5.0	-	15.0	\$ 2,891,929	
General Barriers	4.0	5.0	5.0	-	22.5	\$ 274,482	
General Signage	5.0	5.0	5.0	-	20.0	\$ 280,689	
General Drainage	3.0	5.0	5.0	-	17.5	\$ 1,738,447	

RANKING MATRIX - SKYHAWK OPEN SPACE

Note: See the appendices for asset rankings



THOMAS LAKE HARRIS OPEN SPACE



PARK TYPE





SIZE (ACRES) 6.2

ADDRESS 700 Doyle Park Dr

PRIORITY OUT OF 12 OPEN SPACE PARKS 7

SUMMARY

Thomas Lake Harris Open Space is a 6.2 acre open space park located in the northeast quadrant of Santa Rosa, CA. The park only has general amenities.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Thomas Lake Harris Open does not have recreation programming, has low play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

The critical condition amenity within the park is the general landscape due to the dense invasive plants observed within the natural landscape.





		Supplemental Categories						
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	С	Cost Estimate	
	3.0	5.0	5.0	3.0	16.0	\$	2,275,898	
General Landscape	1.0	5.0	5.0	-	0.0	\$	944,985	
General Trees	3.0	5.0	5.0	-	25.0	\$	98,413	
General Hardscape	4.0	5.0	5.0	-	15.0	\$	612,298	
General Barriers	4.0	5.0	5.0	-	22.5	\$	84,570	
General Drainage	3.0	5.0	5.0	-	17.5	\$	535,632	

RANKING MATRIX - THOMAS LAKE HARRIS OPEN SPACE

Note: See the appendices for asset rankings



VIETNAM VETERANS MEMORIAL TRAIL



PARK TYPE





SIZE (ACRES) 11.4

ADDRESS 4776 Carissa Ave

PRIORITY OUT OF 12 OPEN SPACE PARKS



SUMMARY

The Vietnam Veterans Memorial Trail is a 11.4 acre open space park located in the southeast quadrant of Santa Rosa, CA. The park contains trails that meander through large swaths of natural areas.

The overall condition of the park is adequate, a with a few site furnishings in poor condition. Vietnam Veterans Memorial Trail does not have recreation programming, has moderate play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessment.

The critical condition amenities within the park are the site furnishings. Site furnishings are severely worn, and the quantity of trash receptacles is deficient.



		Supplemental Categories						
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Co	Cost Estimate	
	3.1	5.0	4.0	3.1	15.2	\$ 3,720,669		
General Furnishings	1.5	5.0	5.0	-	2.5	\$	373,054	
General Landscape	4.0	5.0	5.0	-	18.8	\$	1,812,224	
General Trees	4.0	5.0	5.0	-	37.5	\$	188,729	
General Hardscape	4.0	5.0	5.0	-	15.0	\$	53,724	
General Barriers	2.5	5.0	5.0	-	11.3	\$	154,728	
General Signage	3.5	5.0	5.0	-	12.5	\$	158,228	
General Drainage	3.3	5.0	5.0	-	20.4	\$	979,982	
Trails	2.0 5.0 4.0 - 3.8		3.8	,	*see note			

RANKING MATRIX - VIETNAM VETERANS MEMORIAL TRAIL

*A cost estimate is not provided due to square footage data being unavailable. Note: See the appendices for asset rankings



PUBLIC GATHERING AREAS & PLAZAS



PUBLIC GATHERING AREAS & PLAZAS

Three public gathering areas & plazas that are owned and maintained by the City were evaluated as part of this report. This section evaluates the priority ranking of each public gathering areas & plazas based on condition, recreation programming, play value, and accessibility. In addition, the approximate lifespan and the estimated replacement cost is provided for each amenity as well as the overall park. Parks with a priority ranking closer to one (1) are identified as having a higher priority for new improvements, while parks that rank closer to five (5) have a lower priority for improvement needs. The table below identifies the public gathering areas & plazas in order of priority ranking, the parks identified in gray were not assessed by this Report.

Ρι	Public Gathering Areas and Plazas - Ranked by Priority Ranking										
Rank	Park	Priority Ranking	Lifespan	Area (Acres)		Estimated Replacement Cost	Quadrant	Park Type			
1	Jeju Way	3.5	15.6	0.1	\$	214,309	NE	PA			
2	Comstock Mall Park	3.7	17.4	0.4	\$	763,071	NE	PA			
3	Courthouse Square	4.8	25.8	2.7	\$	4,859,650	NE	PA			

COMSTOCK MALL



PARK TYPE

Public Gathering Areas & Plazas



SIZE (ACRES) 0.4

ADDRESS 2nd Street

PRIORITY OUT OF 3 PUBLIC GATHERING AREAS & PLAZAS

2

SUMMARY

Comstock Mall is a 0.4 acre public gathering area located in the northeast quadrant of Santa Rosa, CA. The park contains a hardscape plaza between buildings with seating and a water feature.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Comstock Mall does not have recreation programming, has low play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

The critical condition amenity within the park is the irrigation system, which does not appear to be operational.



186 Park Ranking | Public Gathering Areas & Plazas

RANKING MATRIX - COMSTOCK MALL

	Priority Ranking Categories Supp						oplemental Categories		
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Со	st Estimate		
	3.4	5.0	5.0	3.4	17.4	\$	763,071		
General Furnishings	4.0	5.0	5.0	-	15.0	\$	11,792		
General Landscape	3.0	5.0	5.0	-	12.5	\$	12,199		
General Trees	4.0	5.0	5.0	-	37.5	\$	1,270		
General Hardscape	3.0	5.0	5.0	-	10.0	\$	578,941		
General Irrigation	1.0	5.0	5.0	-	0.0	\$	15,884		
General Lighting	3.0	5.0	5.0	-	20.0	\$	12,916		
General Barriers	4.0	5.0	5.0	-	22.5	\$	5,023		
General Signage	4.0	5.0	5.0	-	15.0	\$	5,137		
General Drainage	4.0	5.0	5.0	-	26.3	\$	31,815		
Water Feature	3.5	5.0	5.0	-	15.0	\$	88,093		

Note: See the appendices for asset rankings



Park Ranking | Public Gathering Areas & Plazas 187

COURTHOUSE SQUARE



PARK TYPE

Public Gathering Areas & Plazas



SIZE (ACRES) 2.7

ADDRESS 69 Old Courthouse Square

PRIORITY OUT OF 3 PUBLIC GATHERING AREAS & PLAZAS

-

3

SUMMARY

Courthouse Square is a 2.7 acre public gathering area located in the northeast quadrant of Santa Rosa, CA. The park contains a plaza area, tables and benches, and two parking areas.

The overall condition of the park is very good, a majority of the amenities are functional, and the park is not anticipated to need major improvements in the near-term. Courthouse Square does not have recreation programming, has low play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

There are no critical condition amenities at the park.



RANKING MATRIX - COURTHOUSE SQUARE

		Priority Rankin	g Catego	ories	Supplem	enta	l Categories
Amenities	Condition	Recreation Programming	Play Value		Lifespan	Co	ost Estimate
	4.7	5.0	5.0	4.7	25.8	\$	4,859,650
General Furnishings	4.7	5.0	5.0	-	18.3	\$	87,598
General Landscape	5.0	5.0	5.0	-	25.0	\$	59,762
General Trees	5.0	5.0	5.0	-	50.0	\$	6,224
General Hardscape	5.0	5.0	5.0	-	20.0	\$	3,481,250
General Irrigation	5.0	5.0	5.0	-	25.0	\$	77,812
General Lighting	4.0	5.0	5.0	-	30.0	\$	93,416
General Barriers	4.0	5.0	5.0	-	22.5	\$	36,332
General Signage	5.0	5.0	5.0	-	20.0	\$	37,154
General Drainage	5.0	5.0	5.0	-	35.0	\$	230,114
General Structures	4.0	5.0	5.0	-	22.5	\$	72,315
Parking Lot	5.0	5.0	5.0	-	15.0	\$	677,672

Note: See the appendices for asset rankings



Park Ranking | Public Gathering Areas & Plazas 189





PARK TYPE

Public Gathering Areas & Plazas



SIZE (ACRES) 0.1

ADDRESS 717 4th Street

PRIORITY OUT OF 3 PUBLIC GATHERING AREAS & PLAZAS

1

SUMMARY

Jeju Way is a 0.1 acre public gathering area located in the northeast quadrant of Santa Rosa, CA. The park contains a walking path and landscape area between buildings with murals.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Jeju Way does not have recreation programming, has low play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

The park does not have critical condition amenities, though a number of broken irrigation heads were identified and do not appear to be functional.





RANKING MATRIX - JEJU WAY

		Supplemental Categories					
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Co	ost Estimate
	3.1	5.0	5.0	3.1	15.6	\$	214,309
General Furnishings	4.0	5.0	5.0	-	15.0	\$	2,862
General Landscape	3.0	5.0	5.0	-	12.5	\$	4,747
General Trees	4.0	5.0	5.0	-	37.5	\$	494
General Hardscape	3.0	5.0	5.0	-	10.0	\$	117,648
General Lighting	3.0	5.0	5.0	-	20.0	\$	3,321
General Signage	4.0	5.0	5.0	-	15.0	\$	1,321
General Drainage	3.0	5.0	5.0	-	17.5	\$	8,181
Water Feature	1.0	5.0	5.0	-	0.0	\$	69,554

Note: See the appendices for asset rankings



Park Ranking | Public Gathering Areas & Plazas 191

SPECIAL PURPOSE PARKS



SPECIAL PURPOSE PARKS

Three special purpose parks that are owned and maintained by the City were evaluated as part of this report. This section evaluates the priority ranking of each special purpose park based on condition, recreation programming, play value, and accessibility. In addition, the approximate lifespan and the estimated replacement cost is provided for each amenity as well as the overall park. Parks with a priority ranking closer to one₉ (1) are identified as having a higher priority for new improvements, while parks that rank closer to five (5) have a lower priority for improvement needs. The table below identifies the special purpose parks in order of priority ranking, the parks identified in gray were not assessed by this Report.

Sp	Special Purpose Parks - Ranked by Priority Ranking										
Rank	Park	Priority Ranking	Lifespan	Area (Acres)		Estimated Replacement Cost	Quadrant	Park Type			
1	Bennett Valley Golf Course	2.9	14.2	153.0	\$	85,194,416	SE	SP			
2	Luther Burbank Home and Gardens	3.2	17.4	1.6	\$	2,834,273	NE	SP			
3	Santa Rosa Rural Cemetery	3.9	19.6	15.8	\$	6,687,387	NE	SP			

BENNETT VALLEY GOLF COURSE



PARK TYPE





SIZE (ACRES) 153.0

ADDRESS 3330 Yulupa Ave

PRIORITY OUT OF 3 SPECIAL PURPOSE PARKS

SUMMARY

Bennett Valley Golf Course is a 153.0 acre special purpose park located in the southeast quadrant of Santa Rosa, CA. The park is an 18-hole golf course and contains natural turf, trees, pathways, and golf equipment.

The overall condition of the park is very good. Bennett Valley Golf Course does not have recreation programming managed by the Recreation and Parks Department, has very high play value, and has a few significantly non-compliant ADA features.

The critical condition amenities within the park are the irrigation and lighting. The irrigation is outdated and does not meet current best practices, and there are a few light posts that have been damaged.





		Priority Rankir	ng Catego	ories	Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value		Lifespan	Cost Estimate	
	3.1	5.0	1.0	1.7	14.2	\$ 85,194,416	
General Furnishings	4.0	5.0	5.0	2.0	15.0	\$ 2,484,580	
General Landscape	3.7	5.0	5.0	-	16.7	\$ 10,904,355	
General Trees	4.0	5.0	5.0	-	37.5	\$ 1,135,603	
General Hardscape	3.7	5.0	5.0	1.0	13.3	\$ 10,174,879	
General Irrigation	1.0	5.0	5.0	-	0.0	\$ 14,197,800	
General Lighting	2.0	5.0	5.0	-	10.0	\$ 4,954,247	
General Barriers	3.5	5.0	5.0	-	18.8	\$ 1,926,856	
General Signage	3.0	5.0	5.0	4.0	10.0	\$ 1,970,434	
General Drainage	1.0	5.0	5.0	-	0.0	\$ 12,203,872	
General Structures	4.0	5.0	5.0	-	22.5	\$ 27,117	
Parking Lot	3.8	5.0	5.0	2.5	11.3	\$ 2,873,003	
Sports Field: Golf Course	3.0	5.0	1.0	1.5	15.0	\$ 19,962,725	
Sports Field: Driving Range	3.1	5.0	1.0	2.0	15.0	\$ 2,378,945	

RANKING MATRIX - BENNETT VALLEY GOLF COURSE

Note: See the appendices for asset rankings



LUTHER BURBANK HOME AND GARDENS



PARK TYPE





SIZE (ACRES) 1.6

ADDRESS 204 Santa Rosa Avenue

PRIORITY OUT OF 3 SPECIAL PURPOSE PARKS 2

SUMMARY

Luther Burbank Home and Gardens is a 1.6 acre special purpose park that is registered as a National, State, City, and Horticultural Historic Landmark. The gardens are located in the northeast quadrant of Santa Rosa, CA. The park contains ornamental landscapes, garden beds, and a water feature. The park also includes a restaurant and event building that were assessed within the Facilities Condition Assessment (2018). Luther Burbank Home and Gardens is maintained and operated by the namesake nonprofit organization.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Luther Burbank Home and Garden does not have recreation programming managed by the Recreation and Parks Department, has moderate play value, and has a few significantly non-compliant ADA features.

The park does not have critical condition items, though the brick paver pathways have areas with uneven surfaces.


		Priority Rankin	ıg Catego	ries	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate		
	3.3	5.0	3.0	1.1	17.4	\$	2,834,273	
General Furnishings	3.2	5.0	5.0	2.0	11.0	\$	40,694	
General Landscape	3.0	5.0	5.0	2.0	12.5	\$	93,393	
General Trees	4.0	5.0	5.0	-	37.5	\$	9,726	
General Hardscape	2.5	5.0	5.0	1.0	7.5	\$	1,336,871	
General Irrigation	2.5	5.0	5.0	-	9.4	\$	121,601	
General Lighting	3.0	5.0	5.0	-	20.0	\$	56,090	
General Barriers	4.0	5.0	5.0	-	22.5	\$	21,815	
General Signage	4.3	5.0	5.0	-	16.7	\$	22,308	
General Drainage	4.0	5.0	5.0	-	26.3	\$	138,166	
General Structures	3.0	5.0	5.0	-	15.0	\$	25,622	
Water Feature	3.5	5.0	5.0	-	15.0	\$	146,880	
Community Gardens	3.0	5.0	3.0	-	15.0	\$	821,107	

RANKING MATRIX - LUTHER BURBANK HOME AND GARDENS

Note: See the appendices for asset rankings



SANTA ROSA RURAL CEMETERY



PARK TYPE

Special Purpose Parks



SIZE (ACRES) 15.8

ADDRESS

1600 Franklin Avenue

PRIORITY OUT OF 3 SPECIAL PURPOSE PARKS 3

SUMMARY

Santa Rosa Rural Cemetery is a 15.8 acre special purpose park that is registered as a historic landmark. The cemetery is located in the northeast quadrant of Santa Rosa, CA. The park contains general park infrastructure such as landscape, pathways, and furnishings but no additional amenities.

The overall condition of the park is good, and a majority of the amenities are in good condition. Santa Rosa Rural Cemetery does not have recreation programming, has low play value, and generally complies with ADA standards with only a few minor non-compliant items.

There are no amenities in critical condition except for the general furnishings due to a deficient quantity of trash receptacles.



SPECIAL PURPOSE PARKS

		Priority Rankin	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate
	3.6	5.0	5.0	3.5	19.6	\$ 6,687,387
General Furnishings	2.0	5.0	5.0	-	5.0	\$ 406,733
General Landscape	3.5	5.0	5.0	-	15.6	\$ 1,970,237
General Trees	4.0	5.0	5.0	-	37.5	\$ 205,185
General Hardscape	3.0	5.0	5.0	-	10.0	\$ 130,258
General Irrigation	4.0	5.0	5.0	-	18.8	\$ 2,565,307
General Barriers	3.7	5.0	5.0	-	20.0	\$ 168,697
General Signage	4.0	5.0	5.0	3.5	15.0	\$ 172,513
General Drainage	5.0	5.0	5.0	-	35.0	\$ 1,068,457

RANKING MATRIX - SANTA ROSA RURAL CEMETERY

Note: See the appendices for asset rankings



TRAIL PARKS



TRAIL PARKS

Five trail parks that are owned and maintained by the City were evaluated as part of this report. This section evaluates the priority ranking of each trail park based on condition, recreation programming, play value, and accessibility. In addition, the approximate lifespan and the estimated replacement cost is provided for each amenity as well as the overall park. Parks with a priority ranking closer to one (1) are identified as having a higher priority for new improvements, while parks that rank closer to five (5) have a lower priority for improvement needs. The table below identifies the trail parks in order of priority ranking, the parks identified in gray were not assessed by this Report.

Tr	ail Parks - Ranked by Priority Ranking						
Rank	Park	Priority Ranking	Lifespan	Area (Acres)	Estimated Replacement Cost	Quadrant	Park Type
1	Newhall Bike Trail	3.1	14.4	1.0	\$ 479,668	SE	TR
2	Hampton Woods Trail	3.2	14.7	11.2	\$ 4,941,373	SE	TR
3	Pearblossom Trail	3.4	17.9	2.4	\$ 1,681,990	SW	TR
4	Fourth and Farmers Creek Trail	3.5	19.8	3.0	\$ 615,687	SE	TR
5	Upper Brush Creek Trail Park	3.5	16.5	11.7	\$ 3,053,911	NE	TR

FOURTH AND FARMERS CREEK TRAIL



PARK TYPE





SIZE (ACRES) 3.0

ADDRESS 0 Hwy 12

PRIORITY OUT OF 5 TRAIL PARKS 4

SUMMARY

Fourth and Farmers Creek Trail is a 3.0 acre trail park located in the southeast quadrant of Santa Rosa, CA.

The overall condition of the park is adequate, aside from a few deficient amenities. Fourth and Farmers Creek Trail does not have recreation programming, has moderate play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessment.

The critical condition amenity within the park is the trail, where portions of the dirt surfacing are substantially uneven and concrete debris obstructs the path.





Parks Prioritization Report

		Supplemental Categories					
Amenities	Condition	Recreation Programming	Play Value		Lifespan	Cos	st Estimate
	3.2	5.0	4.0	3.2	19.8	\$	615,687
General Landscape	3.0	5.0	5.0	-	12.5	\$	348,738
General Trees	4.0	5.0	5.0	-	37.5	\$	36,318
General Barriers	4.0	5.0	5.0	-	22.5	\$	29,976
General Drainage	4.0	5.0	5.0	-	26.3	\$	189,854
Trails	1.0	5.0	4.0	-	0.0	\$	10,801

RANKING MATRIX - FOURTH AND FARMERS CREEK TRAIL


Note: See the appendices for asset rankings



Parks Prioritization Report

Park Ranking | Trail Parks 203

HAMPTON WOODS TRAIL



PARK TYPE



SIZE (ACRES)

ADDRESS 0 Yulupa Cir

PRIORITY OUT OF 5 TRAIL PARKS 2

SUMMARY

Hampton Woods Trail is a 11.2 acre trail park located in the southeast quadrant of Santa Rosa, CA.

The overall condition of the park is below adequate. Hampton Woods Trail does not have recreation programming, has moderate play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessment.

The critical condition amenities within the park are the site furnishings due to a deficient quantity of trash receptacles, and the irrigation, which does not appear to be operational.






RANKING MATRIX - HAMPTON WOODS TRAIL

		Priority Rankir	ries	Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	Cost Estimate	
	2.9	5.0	4.0	2.9	14.7	\$ 4,941,373	
General Furnishings	2.5	5.0	5.0	-	7.5	\$ 291,368	
General Landscape	3.0	5.0	5.0	-	12.5	\$ 1,418,686	
General Trees	4.0	5.0	5.0	-	37.5	\$ 147,745	
General Irrigation	2.0	5.0	5.0	-	6.3	\$ 1,847,172	
General Barriers	3.0	5.0	5.0	-	15.0	\$ 125,522	
General Signage	2.0	5.0	5.0	-	5.0	\$ 128,361	
General Drainage	4.0	5.0	5.0	-	26.3	\$ 795,003	
Trails	3.0	5.0	4.0	-	7.5	\$ 187,516	

Note: See the appendices for asset rankings





PARK TYPE





SIZE (ACRES)

ADDRESS 0 Newhall St

PRIORITY OUT OF 5 TRAIL PARKS

1

SUMMARY

Newhall Bike Trail is a 1.0 acre trail park located in the southeast quadrant of Santa Rosa, CA.

The overall condition of the park is below adequate due to the trail condition. Newhall Bike Trail does not have recreation programming, has moderate play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

The critical condition amenity within the park is the hardscape, which has severe cracking and weed growth within the pavement.



TRAIL PARKS

overall priority rank **3.1**

RANKING MATRIX - NEWHALL BIKE TRAIL

		Priority Ranking Categories Su				Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value		Lifespan	Cost Estimate		
	2.8	5.0	4.0	2.8	14.4	\$	479,668	
General Landscape	4.0	5.0	5.0	-	18.8	\$	118,097	
General Trees	4.0	5.0	5.0	-	37.5	\$	12,299	
General Hardscape	2.0	5.0	5.0	-	5.0	\$	49,898	
General Lighting	3.0	5.0	5.0	-	20.0	\$	36,079	
General Barriers	3.0	5.0	5.0	-	15.0	\$	14,032	
General Signage	3.0	5.0	5.0	-	10.0	\$	14,349	
General Drainage	2.0	5.0	5.0	-	8.8	\$	88,873	
Trails	1.0	5.0	4.0	-	0.0	\$	146,041	

Note: See the appendices for asset rankings



PEARBLOSSOM TRAIL



PARK TYPE





SIZE (ACRES) 2.4

ADDRESS 0 Edgewater Dr

PRIORITY OUT OF 5 TRAIL PARKS 3

SUMMARY

Pearblossom Trail is a 2.4 acre trail park located in the southwest quadrant of Santa Rosa, CA, and is adjacent to Pearblossom Park. The park consists of primarily general amenities and trails.

The overall condition of the park is adequate, and a majority of the amenities are fully functional. Pearblossom Trail does not have recreation programming, has moderate play value, and has moderate non-compliant ADA features based off the of the condition ranking.

The park does not have critical condition amenities, though there are portions of the ornamental landscape that are dead or missing, and the spray irrigation for the natural turf has coverage issues.



overall priority rank **3.4**

RANKING MATRIX - PEARBLOSSOM TRAIL

		Priority Ranking Categories					Supplemental Categories		
Amenities	Condition	Recreation Programming	Play Value		Lifespan	Cost Estimate			
	3.1	5.0	4.0	3.1	17.9	\$	1,681,990		
General Landscape	2.0	5.0	5.0	-	6.3	\$	252,811		
General Trees	4.0	5.0	5.0	-	37.5	\$	26,328		
General Hardscape	2.0	5.0	5.0	-	5.0	\$	432,638		
General Irrigation	3.0	5.0	5.0	-	12.5	\$	329,167		
General Lighting	4.0	5.0	5.0	-	30.0	\$	84,991		
General Drainage	4.0	5.0	5.0	-	26.3	\$	209,359		
Trails	3.0	5.0	4.0	-	7.5	\$	346,696		


Note: See the appendices for asset rankings



Parks Prioritization Report

Park Ranking | Trail Parks 209

UPPER BRUSH CREEK TRAIL PARK



PARK TYPE



QUADRANT Northeast

SIZE (ACRES) 11.7

ADDRESS 0 Brush Creek Rd

PRIORITY OUT OF 5 TRAIL PARKS

SUMMARY

Upper Brush Creek Trail Park is a 11.7 acre trail park located in the northeast quadrant of Santa Rosa, CA. The park contains natural landscape and packed earth trails.

The overall condition of the park is adequate. Upper Brush Creek Trail Park does not have recreation programming, has moderate play value, and does not have non-compliant features identified by the 2013 and 2016 ADA assessments.

The critical condition amenity within the park is the trail due to a number of holes throughout the park, a lack of signage, and the informal bike jumps created near Wild Lilac Lane.



Parks Prioritization Report

	Priority Ranking Categories			Supplemental Categories			
Amenities	Condition	Recreation Programming	Play Value	Accessibility	Lifespan	C	ost Estimate
	3.2	5.0	4.0	3.2	16.5	\$	3,053,911
General Landscape	4.0	5.0	5.0	-	18.8	\$	1,651,762
General Trees	4.0	5.0	5.0	-	37.5	\$	172,018
General Hardscape	3.0	5.0	5.0	-	10.0	\$	185,997
General Signage	4.0	5.0	5.0	-	15.0	\$	145,150
General Drainage	3.0	5.0	5.0	-	17.5	\$	898,984
Trails	1.0	5.0	4.0	-	0.0		-

RANKING MATRIX - UPPER BRUSH CREEK TRAIL PARK

Note: See the appendices for asset rankings



ROADWAY LANDSCAPES



Park Ranking | Roadway Landscapes 213

ROADWAY LANDSCAPES

Fifty-six roadway landscapes that are owned and maintained by the Recreation and Parks Department were evaluated as part of this report. This section evaluates the priority ranking of each roadway based on condition. In additional, the approximate lifespan and the estimated replacement cost is provided for each amenity as well as the overall roadway landscapes. Roadway landscapes with a priority ranking closer to one (1) are identified as having a higher priority for new improvements, while roadway landscapes that rank closer to five (5) have a lower priority for improvement needs. The table below identifies the roadway landscapes in order of priority ranking.

Roa	dway Landscape	es - Ran	ked by	Prior	ity Ranking	Road	dway Landscape	es - Rar	ked by	Prior	ity Ranking
Rank	Roadway Landscape	Priority ranking	Lifespan		Estimated Replacement Cost	Rank	Roadway Landscape	Priority ranking	Lifespan		Estimated Replacement Cost
1	100020NW	1.0	0.0	\$	12,765	39	M00049NE	3.4	20.3	\$	142,888
2	100023NW	1.0	0.0	\$	19,326	29	C00012SE	3.5	18.1	\$	8,718
3	100011NW	1.7	8.3	\$	36,079	30	C00053NE	3.5	16.3	\$	24,332
4	100003NW	2.0	12.5	\$	8,739	31	M00001SW	3.5	19.4	\$	134,637
5	100032NE	2.0	7.9	\$	15,185	32	M00006SE	3.5	20.6	\$	673,072
7	M00010NW	2.3	11.9	\$	85,907	33	M00008NE	3.5	19.6	\$	16,761
8	100008NE	2.3	14.6	\$	8,250	34	M00007SE	3.5	20.6	\$	127,740
6	M00006SW	2.5	13.1	\$	104,664	35	M00008SE	3.5	20.6	\$	191,443
9	M00018NW	2.5	13.1	\$	259,721	42	100015SE	3.5	22.8	\$	46,847
10	M00021NW	2.5	13.1	\$	62,048	36	F00020SE	3.6	20.8	\$	46,883
11	M00028NE	2.6	14.0	\$	18,729	37	100022SE	3.6	20.3	\$	270,709
23	100005SE	2.7	17.6	\$	33,389	38	C00007NW	3.7	13.3	\$	53,575
12	F00014SW	2.8	14.7	\$	55,086	40	C00015SE	3.8	19.4	\$	12,173
18	F00016NW	2.8	14.7	\$	1,136,874	41	M00002NW	3.8	20.9	\$	208,304
13	100012SE	2.8	15.8	\$	27,055	43	100028NE	3.8	23.4	\$	2,049
14	F00005SW	2.9	15.9	\$	2,175,101	44	C00001NW	4.0	15.0	\$	8,132
15	C00003NW	3.0	10.0	\$	84,160	45	C00001SW	4.0	15.0	\$	22,556
16	C00005SW	3.0	10.0	\$	67,252	46	C00004SW	4.0	15.0	\$	19,776
17	C00006NE	3.0	10.0	\$	15,087	47	C00008SW	4.0	15.0	\$	8,246
19	F00033NE	3.0	18.4	\$	147,558	48	C00009SE	4.0	22.5	\$	104,578
20	100025NE	3.0	18.8	\$	56,758	49	C00013NW	4.0	15.0	\$	50,486
21	M00021NE	3.0	16.5	\$	821,708	50	C00017SE	4.0	15.0	\$	5,079
22	F00001SW	3.1	17.4	\$	279,585	51	C00056NE	4.0	15.0	\$	64,599
27	M00010SE	3.1	18.5	\$	100,722	52	100017NW	4.0	25.0	\$	35,251
28	B00001NE	3.2	18.8	\$	726,144	53	M00011SW	4.0	23.3	\$	143,071
26	100019SE	3.3	17.8	\$	32,656	54	M00029NW	4.2	25.0	\$	56,137
24	F00002SE	3.4	19.0	\$	489,033	55	100042NE	4.5	21.9	\$	2,172
25	F00013NE	3.4	19.0	\$	93,894	56	C00045NE	5.0	27.5	\$	18,478



overall priority rank **3.2**

TYPE





Northeast

SIZE (SF) 29,767

MEDIAN TYPE BUFFER

MATERIAL MIXED

ADDRESS

965 Sonoma Ave, Santa Rosa, CA 95404

RANK OUT OF 56 ROADWAY LANDSCAPES 28



RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
Amenities	Condition	Lifespan	Cost Estimate	
	3.2	18.8	\$	726,144
General Landscape	2.0	6	\$	69,839
General Trees	4.0	38	\$	7,273
General Hardscape	4.0	15	\$	499,377
General Irrigation	1.0	0	\$	90,933
General Drainage	5.0	35	\$	58,722





Note: See the appendices for asset rankings

ROADWAY LANDSCAPES

CO000INW

TYPE





SIZE (SF) 174

MEDIAN TYPE MEDIAN

MATERIAL IMPERMEABLE

ADDRESS W College Ave @ Maxwell Dr

RANK OUT OF 56 ROADWAY LANDSCAPES 44



RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		Categories
	Condition	Lifespan	Со	st Estimate
Amenities	×	Ð		S
	4.0	15.0	\$	8,132
General Hardscape	4.0	15	\$	8,132

Note: See the appendices for asset rankings





OVERALL PRIORITY RANK

C0000ISW

TYPE





Southwest

SIZE (SF) 482

MEDIAN TYPE MEDIAN

MATERIAL IMPERMEABLE

ADDRESS

Dutton Ave. @ HWY 12 (South side)

RANK OUT OF 56 ROADWAY LANDSCAPES 45

RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
	Condition	Lifespan	Cost Estimate	
Amenities	×		S	
	4.0	15.0	\$ 22,556	
General Hardscape	4.0	15	\$ 22,556	

Note: See the appendices for asset rankings



OVERALL PRIORITY RANK



C00003NW

TYPE





Northwest

SIZE (SF) 1,798

MEDIAN TYPE MEDIAN

MATERIAL IMPERMEABLE

ADDRESS

Guerneville Rd. @ Ridley Ave. (East side)

RANK OUT OF 56 ROADWAY LANDSCAPES 15



RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		Categories
Amenities	Condition	Lifespan	Cos	st Estimate
	3.0	10.0	\$	84,160
General Hardscape	3.0	10	\$	84,160

Note: See the appendices for asset rankings





OVERALL PRIORITY RANK

3.0

C00004SW

TYPE



QUADRANT



SIZE (SF) 422


MEDIAN TYPE MEDIAN

MATERIAL IMPERMEABLE

ADDRESS

N Wright Rd. @ Sebastopol (North side)

RANK OUT OF 56 ROADWAY LANDSCAPES 46



RANKING MATRIX

	Priority Ranking Category	Suppleme	ental	Categories
Amenities	Condition	Lifespan	Cos	st Estimate
	4.0	15.0	\$	8,246
General Hardscape	4.0	15	\$	8,246

Note: See the appendices for asset rankings



OVERALL PRIORITY RANK



🕞 C00005SW

TYPE





SIZE (SF) 1,436

MEDIAN TYPE FRONTAGE

MATERIAL IMPERMEABLE

ADDRESS

Hearn Ave. @ RR Crossing (Both sides)

RANK OUT OF 56 ROADWAY LANDSCAPES 16 LOUID ALL LOUID

RANKING MATRIX

	Priority Ranking Category	Supplemental Categories	
Amenities	Condition	Lifespan	Cost Estimate
	3.0	10.0	\$ 67,252
General Hardscape	3.0	10	\$ 67,252

Note: See the appendices for asset rankings





OVERALL PRIORITY RANK

3.0

C00006NE

OVERALL PRIORITY RANK

TYPE





Northeast

SIZE (SF) 322

MEDIAN TYPE MEDIAN

MATERIAL IMPERMEABLE

ADDRESS

Mendocino Ave. @ College Ave. (East Side)

RANK OUT OF 56 ROADWAY LANDSCAPES 17

RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
Amenities	Condition	Lifespan	Cost Estimate	
	3.0	10.0	\$ 15,087	
General Hardscape	3.0	10	\$ 15,087	

Note: See the appendices for asset rankings







COLLEGE AVE

🕞 C00007NW

TYPE



QUADRANT



SIZE (SF) 1,144

MEDIAN TYPE MEDIAN

MATERIAL IMPERMEABLE

ADDRESS

Guerneville Rd @ RR Crossing (Both Sides)

RANK OUT OF 56 ROADWAY LANDSCAPES 38



RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
Amenities	Condition	Lifespan	Cost Estimate	
	3.7	13.3	\$ 53,575	
General Hardscape	3.7	13	\$ 53,575	

Note: See the appendices for asset rankings





OVERALL PRIORITY RANK

👄 C00008SW

TYPE



QUADRANT



SIZE (SF) 176

MEDIAN TYPE MEDIAN

MATERIAL IMPERMEABLE

ADDRESS

Stony Point Rd. @ HWY 12 Ramp


RANK OUT OF 56 ROADWAY LANDSCAPES 47

RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
Amenities	Condition	Lifespan	Cost Estimate	
	×		(S)	
	4.0	15.0	\$ 8,246	
General Hardscape	4.0	15	\$ 8,246	







C00009SE

OVERALL PRIORITY RANK

TYPE



QUADRANT



SIZE (SF) 2,143

MEDIAN TYPE MEDIAN

MATERIAL IMPERMEABLE

ADDRESS

Bennett Valley Rd. @ Farmers Lane (East side)

RANK OUT OF 56 ROADWAY LANDSCAPES 48



RANKING MATRIX

	Priority Ranking Category	Suppleme	ental Categories		
Amenities	Condition	Lifespan	Cost Estimate		
	4.0	22.5	\$ 104,578		
General Hardscape	3.0	10	\$ 100,350		
General Drainage	5.0	35	\$ 4,228		





C00012SE

overall priority rank **3.5**

TYPE





Southeast

SIZE (SF) 179

MEDIAN TYPE MEDIAN

MATERIAL IMPERMEABLE

ADDRESS

Montgomery Dr. @ Mission Blvd. (All)

RANK OUT OF 56 ROADWAY LANDSCAPES 29

RANKING MATRIX

	Priority Ranking Category	Suppleme	ental Categories
	Condition	Lifespan	Cost Estimate
Amenities	*	Ŀ	S
	3.5	18.1	\$ 8,718
General Hardscape	3.0	10	\$ 8,366
General Drainage	4.0	26	\$ 353





C00013NW

TYPE





SIZE (SF) 1,078

MEDIAN TYPE MEDIAN

MATERIAL IMPERMEABLE

ADDRESS

Range Ave. @ Piner (Both sides and South)

RANK OUT OF 56 ROADWAY LANDSCAPES 49



RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		
Amonition	Condition	Lifespan	Cos	t Estimate
Amenities	×			Q
	4.0	15.0	\$	50,486
General Hardscape	4.0	15	\$	50,486

Note: See the appendices for asset rankings





C00015SE

OVERALL PRIORITY RANK **3.8**

TYPE



Southeast

SIZE (SF) 249

MEDIAN TYPE MEDIAN

MATERIAL IMPERMEABLE

ADDRESS

Mission Blvd. @ HWY 12 (East side)

RANK OUT OF 56 ROADWAY LANDSCAPES 40

RANKING MATRIX

	Priority Ranking Category	Supplemental Categori		
	Condition	Lifespan	Cost Estimate	
Amenities	*	Ŀ	S	
	3.8	19.4	\$ 12,173	
General Hardscape	3.5	13	\$ 11,680	
General Drainage	4.0	26	\$ 492	









TYPE





Southeast

SIZE (SF) 108

MEDIAN TYPE MEDIAN

MATERIAL IMPERMEABLE

ADDRESS

Montgomery Dr. @ Farmers Ln. (East side)

RANK OUT OF 56 ROADWAY LANDSCAPES 50



RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
Amenities	Condition	Lifespan	Cost E	Estimate
	4.0	15.0	\$	5,079
General Hardscape	4.0	15	\$	5,079

Note: See the appendices for asset rankings





C00045NE

TYPE





SIZE (SF) 379

MEDIAN TYPE MEDIAN

MATERIAL IMPERMEABLE

ADDRESS

3rd Rd. Street @ Brookwood Ave. (East Side)

RANK OUT OF 56 ROADWAY LANDSCAPES 56



RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		
	Condition	Lifespan	Cost Estimate	
Amenities	*	Ŀ	S	
	5.0	27.5	\$ 18,478	
General Hardscape	5.0	20	\$ 17,731	
General Drainage	5.0	35	\$ 747	

Note: See the appendices for asset rankings





C00053NE

OVERALL PRIORITY RANK

TYPE





Northeast

SIZE (SF) 499

MEDIAN TYPE MEDIAN

MATERIAL IMPERMEABLE

ADDRESS

Rieblie Rd. @ Mark West Springs Rd.

RANK OUT OF 56 ROADWAY LANDSCAPES 30



RANKING MATRIX

	Priority Ranking Category	Suppleme	ental Categories
Amenities	Condition	Lifespan	Cost Estimate
	3.5	16.3	\$ 24,332
General Hardscape	4.0	15	\$ 23,348
General Drainage	3.0	18	\$ 984





C00056NE

TYPE





Northeast

SIZE (SF) 1,380

MEDIAN TYPE MEDIAN

MATERIAL **IMPERMEABLE**

ADDRESS

Mendocino O/C @ Mendocino Ave

RANK OUT OF 56 ROADWAY LANDSCAPES 51

RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
Amenities	Condition	Lifespan	Cost	Estimate
	4.0	15.0	\$	64,599
General Hardscape	4.0	15	\$	64,599

Note: See the appendices for asset rankings







OVERALL



F0000ISW

OVERALL PRIORITY RANK

TYPE





Southwest

SIZE (SF) 17,220

MEDIAN TYPE FRONTAGE

MATERIAL MIXED

ADDRESS

Southwest corner of Sebastopol Rd. and Lombardi Ln

RANK OUT OF 56 ROADWAY LANDSCAPES 22



RANKING MATRIX

	Priority Ranking Category	Suppleme	ntal Categories		
Amenities	Condition	Lifespan	Со	st Estimate	
	3.1	17.4	\$	279,585	
General Landscape	3.0	13	\$	53,915	
General Trees	4.0	38	\$	5,615	
General Hardscape	3.0	10	\$	115,886	
General Irrigation	2.5	9	\$	70,198	
General Drainage	3.0	18	\$	33,971	





OVERALL PRIORITY RANK R

TYPE





SIZE (SF) 26,770

MEDIAN TYPE FRONTAGE

MATERIAL MIXED

ADDRESS

South side HWY 12 both sides of Queen Anne Dr.

RANK OUT OF 56 ROADWAY LANDSCAPES 24



RANKING MATRIX

	Priority Ranking Category	Suppleme	ental	Categories
Amenities	Condition	Lifespan	Со	st Estimate
	3.4	19.0	\$	489,033
General Landscape	3.0	13	\$	78,580
General Trees	4.0	38	\$	8,183
General Hardscape	4.0	15	\$	247,147
General Irrigation	3.0	13	\$	102,314
General Drainage	3.0	18	\$	52,809





🕞 F00005SW

overall priority rank **2.8**

TYPE



QUADRANT



Southwest

SIZE (SF) 129,631

MEDIAN TYPE FRONTAGE

MATERIAL MIXED

ADDRESS

Trail along E. Side of Fresno Ave & frontage on Northpoint Pkwy, E. of Yeager Dr

RANK OUT OF 56 ROADWAY LANDSCAPES

14

RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		
Amenities	Condition	Lifespan	Co	ost Estimate
	2.9	15.9	\$	2,175,101
General Landscape	2.5	9	\$	399,088
General Trees	4.0	38	\$	41,562
General Hardscape	4.0	15	\$	959,099
General Irrigation	1.0	0	\$	519,625
General Drainage	3.0	18	\$	255,727









TYPE





Northeast

SIZE (SF) 2,991

MEDIAN TYPE FRONTAGE

MATERIAL MIXED

ADDRESS

N Side of HWY 12 230 ft East of Acacia Ln

RANK OUT OF 56 ROADWAY LANDSCAPES 25



RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
Amenities	Condition	Lifespan	Со	st Estimate
	3.4	19.0	\$	93,894
General Landscape	3.0	13	\$	5,003
General Trees	4.0	38	\$	521
General Hardscape	4.0	15	\$	75,955
General Irrigation	3.0	13	\$	6,514
General Drainage	3.0	18	\$	5,900



OVERALL PRIORITY RANK



Note: See the appendices for asset rankings

ROADWAY LANDSCAPES

F00014SW

TYPE





Southwest

SIZE (SF) 1,780

MEDIAN TYPE FRONTAGE

MATERIAL MIXED

ADDRESS

NE corner of Trombetta St & Stony Point Rd across from Gardner Ave

RANK OUT OF 56 ROADWAYS 12

RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
Amenities	Condition	Lifespan	Co	ost Estimate
	2.8	14.7	\$	55,086
General Landscape	2.0	6	\$	2,717
General Trees	4.0	38	\$	283
General Hardscape	4.0	15	\$	48,548
General Irrigation	1.0	0	\$	3,538

Note: See the appendices for asset rankings







🕞 F00016NW

TYPE

Roadway



SIZE (SF) 67,116

MEDIAN TYPE FRONTAGE

MATERIAL MIXED

ADDRESS

SE Corner of Fulton Rd and Piner Rd

RANK OUT OF 56 ROADWAY LANDSCAPES 18



RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		
Amenities	Condition	Lifespan	Co	ost Estimate
	3.6	20.8	\$	46,883
General Landscape	3.0	13	\$	4,639
General Trees	4.0	38	\$	483
General Hardscape	4.0	15	\$	31,874
General Irrigation	3.0	13	\$	6,041
General Drainage	4.0	26	\$	3,846



OVERALL PRIORITY RANK





OVERALL PRIORITY RANK

TYPE





Southeast

SIZE (SF) 1,950

MEDIAN TYPE FRONTAGE

MATERIAL MIXED

ADDRESS

Public access to Annadel State Park from corner of Stonehedge Dr. & Westminster Pl

RANK OUT OF 56 ROADWAY LANDSCAPES 36

RANKING MATRIX

	Priority Ranking Category	Supplemental Categori		
Amenities	Condition	Lifespan	Cost	Estimate
	3.6	20.8	\$	46,883
General Landscape	3.0	13	\$	4,639
General Trees	4.0	38	\$	483
General Hardscape	4.0	15	\$	31,874
General Irrigation	3.0	13	\$	6,041
General Drainage	4.0	26	\$	3,846

STONEHEDGE DR







OVERALL PRIORITY RANK

TYPE





Northeast

SIZE (SF) 13,700


MEDIAN TYPE FRONTAGE

MATERIAL PERMEABLE

ADDRESS

Fountain Grove Pkwy @ Chanate Rd

RANK OUT OF 56 ROADWAY LANDSCAPES 19



RANKING MATRIX

	Priority Ranking Category	Suppleme	Supplemental Categories	
	Condition	Lifespan	Со	st Estimate
Amenities	*	L		S
	3.0	18.4	\$	147,558
General Landscape	3.0	13	\$	50,093
General Trees	4.0	38	\$	5,217
General Irrigation	2.0	6	\$	65,222
General Drainage	3.0	18	\$	27,026





👄 100003NW

OVERALL PRIORITY RANK 2.0

TYPE





SIZE (SF) 993

MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS

West 9th St. @ West 8th St. (West Side)

RANK OUT OF 56 ROADWAY LANDSCAPES 4



RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
Amenities	Condition	Lifespan	Cost Estimate	
	2.0	12.5	\$ 8,739	
General Landscape	1.0	0	\$ 3,632	
General Trees	4.0	38	\$ 378	
General Irrigation	1.0	0	\$ 4,729	





👄 100005SE

TYPE



Roadway



SIZE (SF) 3,100


MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS

Holland Dr. @ Bennett Valley Rd

RANK OUT OF 56 ROADWAY LANDSCAPES 23



RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		
	Condition	Lifespan Cost Estima		ost Estimate
Amenities	×	Ŀ		S
	2.7	17.6	\$	33,389
General Landscape	1.0	0	\$	11,335
General Trees	4.0	38	\$	1,180
General Irrigation	1.0	0	\$	14,758
General Drainage	4.8	33	\$	6,115

Note: See the appendices for asset rankings







PRIORITY RANK

TYPE

Roadway



Northeast

SIZE (SF) 938

MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS

Woodland Shadows Pl. @ Montecito Ave.

RANK OUT OF 56 ROADWAY LANDSCAPES 8



RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		
Amenities	Condition	Lifespan	Cos	t Estimate
	2.3	14.6	\$	8,250
General Landscape	2.0	6	\$	3,429
General Trees	4.0	38	\$	357
General Irrigation	1.0	0	\$	4,464





👄 100011NW

OVERALL PRIORITY RANK

TYPE





Northwest

SIZE (SF) 4,101

MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS

West 3rd St @ Darek Rd

RANK OUT OF 56 ROADWAY LANDSCAPES 3



RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		
Amenities	Condition	Lifespan	Cos	st Estimate
	1.7	8.3	\$	36,079
General Landscape	1.0	0	\$	14,994
General Trees	3.0	25	\$	1,562
General Irrigation	1.0	0	\$	19,523





👄 100012SE

OVERALL PRIORITY RANK 2.8

TYPE



QUADRANT



SIZE (SF) 2,512

MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS

Montgomery Dr @ Mission Blvd (West Side)

RANK OUT OF 56 ROADWAY LANDSCAPES 13



RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
Amenities	Condition	Lifespan	Со	st Estimate
	2.8	15.8	\$	27,055
General Landscape	1.0	0	\$	9,185
General Trees	4.0	38	\$	957
General Hardscape	4.0	15	*see note	
General Irrigation	1.0	0	\$	11,959
General Drainage	4.0	26	\$	4,955





*A cost estimate is not provided due to square footage data being unavailable. Note: See the appendices for asset rankings.



TYPE

Roadway



SIZE (SF) 4,349

MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS

Bellevue @ Terrimay Ln

RANK OUT OF 56 ROADWAY LANDSCAPES 42



RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		
	Condition	Lifespan Cost Estima		ost Estimate
Amenities	*			S
	3.5	22.8	\$	46,847
General Landscape	2.0	6	\$	15,904
General Trees	4.0	38	\$	1,656
General Irrigation	3.0	13	\$	20,707
General Drainage	5.0	35	\$	8,580

Note: See the appendices for asset rankings



OVERALL PRIORITY RANK

3.5



📥 100017NW



TYPE

Roadway



Northwest

SIZE (SF) 4,007

MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS Steele Way @ Guerneville Rd

RANK OUT OF 56 ROADWAY LANDSCAPES 52



RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		
Amenities	Condition	Lifespan	Cost	Estimate
	4.0	25.0	\$	35,251
General Landscape	4.0	19	\$	14,650
General Trees	4.0	38	\$	1,526
General Irrigation	4.0	19	\$	19,075







TYPE



QUADRANT



SIZE (SF) 3,712

MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS Baker O/C @ Santa Rosa Ave

RANK OUT OF 56 ROADWAY LANDSCAPES 26



RANKING MATRIX

	Priority Ranking Category	Suppleme	ental Categories	
Amenities	Condition	Lifespan	Со	st Estimate
	3.3	17.8	\$	32,656
General Landscape	3.0	13	\$	13,572
General Trees	4.0	38	\$	1,413
General Hardscape	4.0	15	*	see note
General Irrigation	2.0	6	\$	17,671

*A cost estimate is not provided due to square footage data being unavailable. Note: See the appendices for asset rankings





📥 100020NW

OVERALL PRIORITY RANK

TYPE



Northwest

SIZE (SF) 1,516

MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS

Guerneville Rd @ Fulton Rd. (West Side)

RANK OUT OF 56 ROADWAY LANDSCAPES

1

RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		
	Condition	Lifespan	Cost Estimate	
Amenities	*	Ŀ	S	
	1.0	0.0	\$ 12,765	
General Landscape	1.0	0	\$ 5,545	
General Irrigation	1.0	0	\$ 7,220	







OVERALL PRIORITY RANK 3.6

TYPE



QUADRANT



SIZE (SF)

MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS

Oakmont Dr. from HWY 12 to E. of Laurel Leaf Pl

RANK OUT OF 56 ROADWAY LANDSCAPES 37



RANKING MATRIX

	Priority Ranking Category	Suppleme	ental Categories	
Amenities	Condition	Lifespan	Cost Estimate	
	3.6	20.3	\$ 270,709	
General Landscape	4.0	19	\$ 91,900	
General Trees	4.0	38	\$ 9,571	
General Hardscape	4.0	15	*see note	
General Irrigation	3.0	13	\$ 119,657	
General Drainage	3.0	18	\$ 49,581	





*A cost estimate is not provided due to square footage data being unavailable. Note: See the appendices for asset rankings

Southeast 25,133

248 Park Ranking | Roadway Landscapes

👄 100023NW

TYPE





SIZE (SF) 2,296

MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS

West 3rd St. @ Darla Dr. (East side)

RANK OUT OF 56 ROADWAY LANDSCAPES 2

W 8rd 80 W 800 GO W 200 80 W806 60 W. 3RD ST 27 200 20 122 800 800 07 800 68 Wands DR DARLA

RANKING MATRIX

	Priority Ranking Category	Supplemental Categori	
	Condition	Lifespan	Cost Estimate
Amenities	*		Ś
	1.0	0.0	\$ 19,326
General Landscape	1.0	0	\$ 8,395
General Irrigation	1.0	0	\$ 10,931

Note: See the appendices for asset rankings







OVERALL PRIORITY RANK

TYPE



Roadway




SIZE (SF) 6,451

MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS Juliet Dr. @ Piedra Ln.

RANK OUT OF 56 ROADWAY LANDSCAPES 20



RANKING MATRIX

	Priority Ranking Category	Suppleme	Supplemental Categor	
Amenities	Condition	Lifespan	Cos	st Estimate
	3.0	18.8	\$	56,758
General Landscape	3.0	13	\$	23,588
General Trees	4.0	38	\$	2,457
General Irrigation	2.0	6	\$	30,713







OVERALL PRIORITY RANK

TYPE





Northeast

SIZE (SF) 341

MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS Lewis Rd @ Franklin Ave

RANK OUT OF 56 ROADWAY LANDSCAPES 43



RANKING MATRIX

	Priority Ranking Category	Suppleme	ental Categories
Amenities	Condition	Lifespan	Cost Estimate
	3.8	23.4	\$ 2,049
General Landscape	2.0	6	\$ 1,247
General Trees	4.0	38	\$ 130
General Hardscape	4.0	15	*see note
General Drainage	5.0	35	\$ 673

*A cost estimate is not provided due to square footage data being unavailable. Note: See the appendices for asset rankings







TYPE





SIZE (SF) 1,461

MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS

Los Alamos Rd @ HWY 12 (North Side)

RANK OUT OF 56 ROADWAY LANDSCAPES 5



RANKING MATRIX

	Priority Ranking Category	Suppleme	ental Categories	
Amenities	Condition	Lifespan	Cost	Estimate
	2.0	7.9	\$	15,185
General Landscape	2.0	6	\$	5,344
General Irrigation	1.0	0	\$	6,958
General Drainage	3.0	18	\$	2,883

Note: See the appendices for asset rankings











Northeast

SIZE (SF) 258

MEDIAN TYPE MEDIAN

MATERIAL PERMEABLE

ADDRESS

Benton St @ Morgan St (Circle)

RANK OUT OF 56 ROADWAY LANDSCAPES 55



RANKING MATRIX

	Priority Ranking Category	Supplemental Categor	
Amenities	Condition	Lifespan	Cost Estimate
	4.5	21.9	\$ 2,172
General Landscape	5.0	25	\$ 944
General Irrigation	4.0	19	\$ 1,229

Note: See the appendices for asset rankings





📥 M0000ISW

TYPE



Southwest

SIZE (SF) 8,363


MEDIAN TYPE MEDIAN

MATERIAL MIXED

ADDRESS

Sebastopol Rd @ Campoy St (West side)

RANK OUT OF 56 ROADWAY LANDSCAPES 31



RANKING MATRIX

	Priority Ranking Category	Suppleme	ental	Categories
Amenities	Condition	Lifespan	Co	ost Estimate
	3.5	19.4	\$	134,637
General Landscape	3.0	13	\$	24,706
General Trees	4.0	38	\$	2,573
General Hardscape	4.0	15	\$	75,191
General Irrigation	3.0	13	\$	32,168

Note: See the appendices for asset rankings



OVERALL PRIORITY RANK

3.5



TYPE

Roadway



Northwest

SIZE (SF) 10,694

MEDIAN TYPE MEDIAN

MATERIAL MIXED

ADDRESS


Guerneville Rd @ Herbert Ln (Northeast side)

RANK OUT OF 56 ROADWAY LANDSCAPES 41

RANKING MATRIX

	Priority Ranking Category	Suppleme	ental Categories
	Condition	Lifespan	Cost Estimate
Amenities	*	Ŀ	S
	3.8	20.9	\$ 208,304
General Landscape	4.0	19	\$ 28,117
General Trees	4.0	38	\$ 2,928
General Hardscape	4.0	15	\$ 140,650
General Irrigation	3.0	13	\$ 36,609

Note: See the appendices for asset rankings





OVERALL PRIORITY RANK

3.8





OVERALL PRIORITY RANK **3.5**

TYPE

Roadway



Southeast


SIZE (SF) 62,014

MEDIAN TYPE MEDIAN

MATERIAL MIXED

ADDRESS Summerfield Rd @ Bethards Rd

RANK OUT OF 56 ROADWAY LANDSCAPES 32



RANKING MATRIX

	Priority Ranking Category	Suppleme	upplemental Categorie	
Amenities	Condition	Lifespan	Со	st Estimate
	3.5	20.6	\$	673,072
General Landscape	2.0	6	\$	226,262
General Trees	4.0	38	\$	23,563
General Hardscape	4.0	15	\$	6,309
General Irrigation	2.5	9	\$	294,600
General Drainage	5.0	35	\$	122,337



📥 M00006SW

PRIORITY RANK



Roadway



Journwes

SIZE (SF) 4,699

MEDIAN TYPE MEDIAN

MATERIAL MIXED

ADDRESS

Sebastopol Rd @ N Wright Rd (East side)

RANK OUT OF 56 ROADWAY LANDSCAPES 6



RANKING MATRIX

	Priority Ranking Category	Suppleme	ental	Categories
	Condition	Lifespan	Сс	ost Estimate
Amenities	*	Ŀ		S
	2.5	13.1	\$	104,664
General Landscape	1.0	0	\$	11,090
General Trees	4.0	38	\$	1,155
General Hardscape	4.0	15	\$	77,980
General Irrigation	1.0	0	\$	14,439





👄 M00007SE

TYPE





Southeast

SIZE (SF) 11,117

MEDIAN TYPE MEDIAN

MATERIAL MIXED

ADDRESS

Summerfield Rd @ Annadel Heights Dr (South side)

RANK OUT OF 56 ROADWAY LANDSCAPES 34



RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
Amenities	Condition	Lifespan	Co	ost Estimate
	3.5	20.6	\$	127,740
General Landscape	2.0	6	\$	39,878
General Trees	4.0	38	\$	4,153
General Hardscape	4.0	15	\$	9,857
General Irrigation	2.5	9	\$	51,922
General Drainage	5.0	35	\$	21,930

OVERALL PRIORITY RANK



Note: See the appendices for asset rankings

M00008NE

TYPE





Northeast

SIZE (SF) 564

MEDIAN TYPE MEDIAN

MATERIAL MIXED

ADDRESS


Mountain Hawk Dr @ Raters Dr (North side)

RANK OUT OF 56 ROADWAY LANDSCAPES 33

RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		
Amenities	Condition	Lifespan	Co	ost Estimate
	3.5	19.6	\$	16,761
General Landscape	3.0	13	\$	1,036
General Trees	4.0	38	\$	108
General Hardscape	4.0	15	\$	13,153
General Irrigation	3.5	16	\$	1,350
General Drainage	3.0	18	\$	1,113

Note: See the appendices for asset rankings







OVERALL PRIORITY RANK



TYPE

Roadway



Southeast

SIZE (SF) 17,364

MEDIAN TYPE MEDIAN

MATERIAL MIXED

ADDRESS

Summerfield Rd @ Santa Rosita Ct (South side)

RANK OUT OF 56 ROADWAY LANDSCAPES 35



RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
Amenities	Condition	Lifespan	Co	ost Estimate
	3.5	20.6	\$	191,443
General Landscape	2.0	6	\$	63,065
General Trees	4.0	38	\$	6,568
General Hardscape	4.0	15	\$	5,444
General Irrigation	2.5	9	\$	82,113
General Drainage	5.0	35	\$	34,254

OVERALL PRIORITY RANK



Note: See the appendices for asset rankings

- M00010NW

TYPE





Northwest

SIZE (SF) 3,391

MEDIAN TYPE MEDIAN

MATERIAL MIXED

ADDRESS

Stony Point Rd. @ Finley Park (South entrance)

RANK OUT OF 56 ROADWAY LANDSCAPES 7



RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		
	Condition	Lifespan	Сс	ost Estimate
Amenities	*	Ŀ		S
	2.3	11.9	\$	85,907
General Landscape	1.0	0	\$	7,007
General Trees	4.0	38	\$	730
General Hardscape	3.0	10	\$	69,048
General Irrigation	1.0	0	\$	9,123

Note: See the appendices for asset rankings





OVERALL PRIORITY RANK

2.3

OVERALL PRIORITY RANK

M000I0SE

TYPE

Roadway



Southeas

SIZE (SF) 5,312

MEDIAN TYPE MEDIAN

MATERIAL MIXED

ADDRESS Santa Rosa Ave @ Burt St

RANK OUT OF 56 ROADWAY LANDSCAPES 27



RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		
Amenities	Condition	Lifespan	Co	ost Estimate
	3.1	18.5	\$	100,722
General Landscape	2.0	6	\$	15,239
General Trees	4.0	38	\$	1,587
General Hardscape	2.5	8	\$	53,574
General Irrigation	2.0	6	\$	19,842
General Drainage	5.0	35	\$	10,479



Note: See the appendices for asset rankings

M000IISW

TYPE





Southwest

SIZE (SF) 6,255


MEDIAN TYPE MEDIAN

MATERIAL MIXED

ADDRESS

Stony Pt Rd @ Campbell Dr (North side)

RANK OUT OF 56 ROADWAY LANDSCAPES 53



RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
Amenities	Condition	Lifespan	Со	st Estimate
	4.0	23.3	\$	143,071
General Landscape	4.0	19	\$	15,592
General Trees	4.0	38	\$	1,624
General Hardscape	4.0	15	\$	93,214
General Irrigation	4.0	19	\$	20,301
General Drainage	4.0	26	\$	12,340

Note: See the appendices for asset rankings





OVERALL PRIORITY RANK

🇀 M00018NW

TYPE

Roadway



Northwest

SIZE (SF) 11,665

MEDIAN TYPE MEDIAN

MATERIAL MIXED

ADDRESS

Guerneville Rd @ Fulton Rd (East side)

RANK OUT OF 56 ROADWAY LANDSCAPES 9



	Priority Ranking Category	Supplemental Categorie		
Amenities	Condition	Lifespan	Co	ost Estimate
	2.5	13.1	\$	259,721
General Landscape	1.0	0	\$	27,547
General Trees	4.0	38	\$	2,869
General Hardscape	4.0	15	\$	193,440
General Irrigation	1.0	0	\$	35,866

Note: See the appendices for asset rankings





OVERALL PRIORITY RANK



- M0002INE

TYPE

Roadway



Northeast


SIZE (SF) 45,200

MEDIAN TYPE MEDIAN

MATERIAL **MIXED**

ADDRESS Fountain Grove Pkwy @ Chanate Rd (West side)

RANK OUT OF 56 ROADWAY LANDSCAPES 21



RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
	Condition	Lifespan	Со	st Estimate
Amenities	×	Ŀ		S
	3.0	16.5	\$	821,708
General Landscape	3.0	13	\$	133,068
General Trees	4.0	38	\$	13,858
General Hardscape	4.0	15	\$	412,356
General Irrigation	1.0	0	\$	173,259
General Drainage	3.0	18	\$	89,167

Note: See the appendices for asset rankings





OVERALL PRIORITY RANK

3.0

📥 M0002INW

TYPE





Northwest

SIZE (SF) 3,438


MEDIAN TYPE MEDIAN

MATERIAL MIXED

ADDRESS

Marlow Rd @ Guerneville Rd

RANK OUT OF 56 ROADWAY LANDSCAPES 10



RANKING MATRIX

	Priority Ranking Category	Supplemental Categorie		
Amenities	Condition	Lifespan	Сс	ost Estimate
	2.5	13.1	\$	62,048
General Landscape	1.0	0	\$	9,513
General Trees	4.0	38	\$	991
General Hardscape	4.0	15	\$	39,157
General Irrigation	1.0	0	\$	12,387

Note: See the appendices for asset rankings



OVERALL PRIORITY RANK

2.5



M00028NE

TYPE





Northeast

SIZE (SF) 1,650

MEDIAN TYPE MEDIAN


MATERIAL MIXED

ADDRESS

Montecito Blvd @ Rincon Valley Library

RANK OUT OF 56 ROADWAY LANDSCAPES

11



RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
Amenities	Condition	Lifespan	Со	st Estimate
	2.6	14.0	\$	18,729
General Landscape	1.0	0	\$	5,942
General Trees	4.0	38	\$	619
General Hardscape	4.0	15	\$	1,176
General Irrigation	1.0	0	\$	7,737
General Drainage	3.0	18	\$	3,255



Note: See the appendices for asset rankings

OVERALL PRIORITY RANK



M00029NW

TYPE



Roadway



SIZE (SF) 2,185

MEDIAN TYPE MEDIAN

MATERIAL MIXED

ADDRESS 3rd Street @ Wilson St

RANK OUT OF 56 ROADWAY LANDSCAPES 54



RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
	Condition	Lifespan	Со	ost Estimate
Amenities	*	L		S
	4.2	25.0	\$	56,137
General Landscape	4.0	19	\$	4,852
General Trees	4.0	38	\$	505
General Hardscape	4.0	15	\$	40,151
General Irrigation	4.0	19	\$	6,318
General Drainage	5.0	35	\$	4,310

OVERALL PRIORITY RANK

4.2



Note: See the appendices for asset rankings



TYPE

Roadway



Northeast

SIZE (SF) 11,704

MEDIAN TYPE MEDIAN

MATERIAL MIXED

ADDRESS

County Center Dr @ Professional Dr (North Side)

RANK OUT OF 56 ROADWAY LANDSCAPES 39



RANKING MATRIX

	Priority Ranking Category	Supplemental Categories		
	Condition	Lifespan	Сс	ost Estimate
Amenities	*	L		S
	3.4	20.3	\$	142,888
General Landscape	3.0	13	\$	41,175
General Trees	4.0	38	\$	4,288
General Hardscape	3.0	10	\$	20,725
General Irrigation	2.0	6	\$	53,612
General Drainage	5.0	35	\$	23,088

Note: See the appendices for asset rankings





OVERALL PRIORITY RANK

ANALYSIS

270 Analysis

ALLANAAAAAAA

Parks Prioritization Report



ANALYSIS

The information generated in the park ranking chapter can be organized in various ways to analyze the needs throughout the park system. The Analysis Chapter considers various park characteristics to analyze park priority rankings through different lenses. Some examples of what this chapter identifies, includes high priority parks that are related or differentiated by quadrant, park type, City Council District, or replacement cost.

CITYWIDE ANALYSIS

The citywide analysis takes into account all 85 parks that were assessed as part of this report. The parks are organized based on priority ranking, starting with the highest priority rank to the lowest, where a rank of 1 is the park in need of the most improvements and has the highest priority ranking, while a rank of 85 is the park that needs little to no improvements and is the lowest priority ranked park. Figure 19 identifies the location of the ten highest priority parks within the City's park system. Observations made based on this analysis include, none of the ten highest priority parks fall within the southwest quadrant, and the most frequent park type that occurs within the ten highest priority parks is community park, which pertains to four of the parks.

0	All Parks - Ranked by Priority Ranking				
Rank	a F	Priority Ranking	Lifespan	Area (Acres)	Estimated Replacement Cost Quadrant Park Type
1	Jacobs Park (Lincoln School)	2.3	9.5	6.9	\$ 5,089,625 NW NF
2	Youth Community Park	2.5	15.1	73.8	\$ 44,837,076 NW CP
3	Northwest Community Park	2.5	14.0	35.1	\$ 27,127,956 NW CP
4	Southwest Community Park	2.5	11.7	19.8	\$ 17,767,728 SW CP
5	Doyle Community Park	2.5	14.2	21.8	\$ 18,209,391 NE CP
6	Rincon Valley Community Park	2.5	12.7	18.9	\$ 14,774,691 NE CP
7	South Davis Park	2.6	13.6	1.3	\$ 1,418,918 SW NF
8	Howarth Community Park	2.6	14.4	137.8	\$ 86,874,681 SE CP
9	Finley Community Park	2.6	14.3	12.2	\$ 12,823,091 NW CP
10	A Place to Play Community Park	2.7	13.6	77.2	\$ 51,368,135 NW CP
11	Martin Luther King Jr. Park	2.7	13.4	5.4	\$ 5,146,137 SE NF
12	Frances Nielsen Open Space	2.7	10.8	7.9	\$ 2,028,790 NE OS
13	Live Oak Park	2.7	14.7	4.9	\$ 3,456,191 NW NF
14	Bicentennial Park	2.8	14.8	5.3	\$ 6,025,186 NW NF
15	Peterson Lane Park	2.8	13.6	4.0	\$ 3,281,990 NW NF
16	Juilliard Park	2.8	16.0	9.1	\$ 10,187,312 NE NF
17	Franklin Community Park	2.8	14.8	13.4	\$ 10,426,680 NE CP
18	Galvin Community Park	2.8	16.1	23.4	\$ 26,267,160 SE CP
19	Hidden Valley Park	2.8	15.4	8.2	\$ 5,053,685 NE NP
20	Brendon Park	2.9	15.1	1.4	\$ 1,925,815 NW NP
21	Tanglewood Park	2.9	14.0	7.8	\$ 5,334,531 NE NP
22	Jennings Park	2.9	15.0	6.6	\$ 3,922,385 NW NP
23	Pioneer Park	2.9	15.3	4.5	\$ 4,668,338 NW NP
24	Bennett Valley Golf Course	2.9	14.2	153.0	\$ 85,194,416 SE SP
25	Cook School Park	3.0	15.9	0.9	\$ 1,363,826 SW NF
26	DeMeo Park	3.0	17.2	1.0	\$ 1,437,841 NW NF
27	Humboldt Park	3.0	16.4	0.5	\$ 709,544 NE NP

Figure 18: Citywide Analysis Table

•	All Parks - Ranked by Priority Ranking						
Rank	Park	Priority Ranking	Lifespan	Area (Acres)	Estimated Replacement Cost	Quadrant	Park Type
28	Eastside Park	3.0	16.8	0.4	\$ 962,609	NE	NP
29	North Park	3.0	15.2	1.0	\$ 961,376	NE	NP
30	Steele Lane Park	3.0	15.9	2.4	\$ 2,361,427	NE	NP
31	Westgate Park	3.0	16.5	2.4	\$ 1,753,464	NW	NP
32	Oaklake Green Park	3.1	16.4	3.7	\$ 2,650,452	NE	NP
33	Pearblossom Park	3.1	16.3	3.1	\$ 3,161,271	SW	NP
34	Rinconada Park	3.1	14.7	2.2	\$ 1,290,982	NE	NP
35	Westgate Park	3.1	15.7	2.2	\$ 2,774,595	NE	NP
36	Colgan Creek Park	3.1	16.2	2.8	\$ 3,034,739	SE	NP
37	Flat Rock Park	3.1	13.2	5.4	\$ 1,981,199	SE	NP
38	Sonoma Avenue Park	3.1	14.7	1.8	\$ 1,646,397	NE	NP
39	Village Green Park	3.1	15.0	2.0	\$ 2,081,640	SW	NP
40	Peter Springs Park	3.1	16.9	1.2	\$ 923,826	SE	NP
41	Rae Street Park	3.1	17.1	0.8	\$ 841,822	NE	NP
42	Skyhawk Community Park	3.1	16.2	20.8	\$ 13,173,720	NE	СР
43	Olive Park	3.1	17.3	0.9	\$ 1,347,291	NW	NP
44	Bellevue Ranch Park	3.1	16.6	3.5	\$ 3,758,003	SW	NP
45	Mesquite Park	3.1	18.1	4.0	\$ 2,682,854	SE	NP
46	Newhall Bike Trail	3.1	14.4	1.0	\$ 479,668	SE	TR
47	Parktrail Open Space	3.1	13.5	24.9	\$ 7,462,667	SE	OS
48	Owls Nest Open Space	3.2	18.3	15.0	\$ 3,134,127	NE	OS
49	Parker Hill Open Space	3.2	14.2	4.3	\$ 1,099,983	NE	OS
50	Harvest Park	3.2	16.9	3.3	\$ 3,882,737	SE	NP
51	Fremont Park	3.2	13.7	1.7	\$ 1,941,379	NE	NP
52	Matanzas Park	3.2	18.8	1.1	\$ 1,139,441	SE	NP
53	Hampton Woods Trail	3.2	14.7	11.2	\$ 4,941,373	SE	TR
54	Luther Burbank Home and Gardens	3.2	17.4	1.6	\$ 2,834,273	NE	SP
55	Fravel Lane Open Space	3.2	16.5	2.9	\$ 827,794.25	NE	OS
56	Red Hawk Park	3.2	17.5	0.4	\$ 770,932	SE	NP
57	Frances Nielsen Ranch Park	3.3	16.7	6.0	\$ 3,043,018	NE	NP
58	Haydn Village Park	3.3	18.1	0.1	\$ 168,614	NW	NP
59	DeTurk Park	3.4	18.8	1.0	\$ 1,031,358	NW	NP
60	Nagasawa Community Park	3.4	13.8	33.2	\$ 32,663,391	NE	СР
61	Pearblossom Trail	3.4	17.9	2.4	\$ 1,681,990	SW	TR
62	Vietnam Vets Memorial Trail Open Space	3.4	15.2	11.4	\$ 3,720,669	SE	OS
63	Thomas Lake Harris Open Space	3.4	16.0	6.2	\$ 2,275,898	NE	OS
64	Airfield Park	3.4	19.0	3.9	\$ 2,911,833	SW	NP
65	Fourth and Farmers Creek Trail	3.5	19.8	3.0	\$ 615,687	SE	TR

Figure 18 (continued): Citywide Analysis Table

0	All Parks - Ranked by Priority Ranking						
Rank	Å Å	Priority Ranking	Lifespan	Area (Acres)	Estimated Replacement Cost	Quadrant	Park Type
66	Upper Brush Creek Trail Park	3.5	16.5	11.7	\$ 3,053,911	NE	TR
67	Jeju Way	3.5	15.6	0.1	\$ 214,309	NE	PA
68	Railroad Depot Park	3.6	17.3	0.3	\$ 291,744	NW	NP
69	Skyhawk Creek Open Space	3.6	19.8	2.6	\$ 595,816	SE	OS
70	Bayer Park and Gardens	3.7	21.7	6.0	\$ 10,124,418	SW	NP
71	Comstock Mall Park	3.7	17.4	0.4	\$ 763,071	NE	PA
72	Finali Park	3.7	22.1	2.8	\$ 3,060,027	NW	NP
73	Strawberry Park	3.8	16.9	5.8	\$ 2,796,006	SE	NP
74	Trailhead Park	3.8	17.2	4.2	\$ 2,191,514	SE	NP
75	Prince Memorial Greenway	3.8	18.8	4.1	\$ 6,071,503	NW	NP
76	Triangle Park	3.8	20.6	0.1	\$ 52,205	NE	NP
77	Dauenhauer Park	3.9	25.9	2.5	\$ 2,398,128	SE	NP
78	Santa Rosa Rural Cemetery	3.9	19.6	15.8	\$ 6,687,387	NE	SP
79	Boas Village Creek Open Space	3.9	20.3	0.5	\$ 225,963	SE	OS
80	Mary Traverso Open Space	4.0	21.0	3.6	\$ 497,761	SE	OS
81	Skyhawk Open Space	4.0	17.5	21.7	\$ 8,493,984	NE	OS
82	Prince Gateway Park	3.9	21.8	0.5	\$ 1,060,495	NE	NP
83	Airfield Fresno Mitigation Open Space	4.1	18.4	3.1	\$ 1,134,647	SW	OS
84	Coffey Park	4.4	25.8	5.9	\$ 5,966,960	NW	NP
85	Courthouse Square	4.8	25.8	2.7	\$ 4,859,650	NE	PA
-	Dutch Flohr (In Design)	-	-	2.4	-	NW	NP
-	Fir Ridge Park	-	-	1.1	-	NE	NP
-	Jack London Park (Future)	-	-	2.2	-	NW	NP
-	Kawana Spring Community Park (Future)	-	-	20.0	-	SE	CP
-	Kawana Tokay Park (Future)	-	-	0.6	-	SE	NP
-	Lower Colgan Creek Park (Future)	-	-	1.8	-	SW	NP
-	Meadows Park (Future)	-	-	3.7	-	SW	NP
-	Piedra Park (Future)	-	-	0.2	-	NE	NP
-	Rincon Ridge Open Space	-	-	1.8	-	NE	OS
-	Rincon Ridge Park	-	-	10.1	-	NE	NP
-	Roseland Creek Community Park (Future)	-	-	19.1	-	SW	СР
-	Tenth Street Park (Future)	-	-	0.1	-	NW	NP

Figure 18 (continued): Citywide Analysis Table




Figure 19: Citywide Analysis Map

COST ANALYSIS

The cost estimate analysis identifies the five highest and five lowest cost parks for a full park replacement. The five highest cost parks range between \$30 million to \$90 million for replacement costs. The five lowest cost parks range between \$50,000 to \$260,000. Figure 21 identifies the location of the five highest cost parks, and five lowest cost parks.

Hi	ghest and Lowest Cost for Full Park Replace	ment					
Rank	Park	Priority Ranking	Lifespan	Area (Acres)	Estimated Replacement Cost	Quadrant	Park Type
•	5 Highest Cost for Full Park Replacement						
1	Howarth Community Park	2.6	14.2	137.8	\$ 86,874,681	SE	СР
2	Bennett Valley Golf Course	2.9	14.2	153.0	\$ 85,194,416	SE	SP
3	A Place to Play Community Park	2.7	14.1	77.2	\$ 51,368,135	NW	СР
4	Youth Community Park	2.5	16.0	73.8	\$ 44,837,076	NW	CP
5	Nagasawa Community Park	3.4	13.8	33.2	\$ 32,663,391	NE	CP
0 !	5 Lowest Cost for Full Park Replacement						
1	Triangle Park	3.8	20.63	0.1	\$ 52,205	NE	NP
2	Haydn Village Park	3.3	18.08	0.1	\$ 168,614	NW	NP
3	Jeju Way	3.5	15.56	0.1	\$ 214,309	NE	PA
4	Boas Village Creek Open Space	3.9	20.25	0.5	\$ 225,963	SE	OS
5	Railroad Depot Park	3.6	17.31	0.3	\$ 291,744	NW	NP
<u> </u>	ra 20. Cast Analysis Tabla						

Figure 20: Cost Analysis Table




Figure 21: Cost Analysis Map

QUADRANT ANALYSIS

The quadrant analysis identifies the three highest priority and three lowest priority parks within each of the four quadrants within the City, which include northwest, northeast, southwest, and southeast. The three highest priority and three lowest priority parks are relatively comparable in ranking across the four quadrants. Figure 22 and 23 identify the location of the highest priority parks within each quadrant, and Figure 24 and 25 identify the location of the lowest priority parks, regardless of park type.

Rank	d Parks in Each Quadrar				1			
	Park	Priority Ranking	Lifespan	Area (Acres)		Estimated Replacement Cost	Quadrant	Park Type
Northeast Quadrant -	Highest Priority Ranke	d Parks	;					
1 Doyle Community P	ark	2.5	14.2	21.8	\$	18,209,391	NE	СР
2 Rincon Valley Comm	nunity Park	2.5	13.4	18.9	\$	14,774,691	NE	CP
3 Frances Nielsen Ope	en Space	2.7	10.8	7.9	\$	2,028,790	NE	OS
 Northwest Quadrant Jacobs Park (Lincoln 	- Highest Priority Ranke	d Park 2.3	s 10.29	6.9	\$	5,089,625	NW	NP
2 Youth Community P		2.5	16.02	73.8	⊅ \$	44,837,076	NW	CP
3 Northwest Commun		2.5	14.08	35.1	\$	27,127,956	NW	CP
Southeast Quadrant -	Highest Priority Ranke	d Parks	i					
1 Howarth Community	y Park	2.6	14.25	137.8	\$	86,874,681	SE	СР
2 Martin Luther King J	lr. Park	2.7	13.05	5.4	\$	5,146,137	SE	NP
3 Galvin Community F	?ark	2.8	16.13	23.4	\$	26,267,160	SE	CP
Southwest Quadrant	- Highest Priority Ranke	d Park	5					
1 Southwest Commun	ity Park	2.5	11.4	19.8	\$	17,767,728	SW	СР
2 South Davis Park		2.6	13.56	1.3	\$	1,418,918	SW	NP
3 Cook School Park		3.0	15.85	0.9	\$	1,363,826	SW	NP

Figure 22: Quadrant Analysis Table - Highest Priority




Figure 23: Quadrant Analysis Map - Highest Priority

Lo	west Priority Ranked Parks in Each Quadran	t								
Rank	Park	Priority Ranking	Lifespan	Area (Acres)		Estimated Replacement Cost	Quadrant	Park Type		
0	Northeast Quadrant - Lowest Priority Rankec	l Parks			7 ¢ 4.859.650 NE					
1	Courthouse Square	4.8	25.8	2.7	\$	4,859,650	NE	PA		
2	Prince Gateway Park	4.0	21.8	0.5	\$	1,060,495	NE	NP		
3	Skyhawk Open Space	4.0	17.5	21.7	\$	8,493,984	NE	OS		
• 1	Northwest Quadrant - Lowest Priority Ranked Coffey Park	d Parks 4.4	25.8	5.9	\$	5,966,960	NW	NP		
2	Prince Memorial Greenway	3.8	18.84	4.1	\$	6,071,503	NW	NP		
3	Finali Park	3.7	22.05	2.8	\$	3,060,027	NW	NP		
	Southeast Quadrant - Lowest Priority Ranked	1	04	2 (<i>*</i>	407.7(4	65	06		
1	Mary Traverso Open Space	4.0	21	3.6	\$	497,761	SE	OS		
2	Boas Village Creek Open Space	3.9	20.25	0.5	\$	225,963	SE	OS		
3	Dauenhauer Park	3.9	25.91	2.5	\$	2,398,128	SE	NP		
•	Southwest Quadrant - Lowest Priority Ranked	d Parks								
1	Airfield Fresno Mitigation Open Space	4.1	18.4	3.1	\$	1,134,647	SW	OS		
2	Bayer Park and Gardens	3.7	21.7	6.0	\$	10,124,418	SW	NP		
3	Airfield Park	3.4	19.0	3.9	\$	2,911,833	SW	NP		

Figure 24: Quadrant Analysis Table - Lowest Priority




Figure 25: Quadrant Analysis Map - Highest Priority

CITY COUNCIL DISTRICT ANALYSIS

The City Council District analysis identifies the highest priority park within each of the seven City Council Districts across the City. The City Council Districts are based off the 2010 Census. The City is anticipating an update to the Council District boundaries based upon the 2020 Census. Figure 27 identifies the location of each park.

Ц	ghest Priority Ranked Park in Each City Cour	cil Diet	rict					
	Giest i nonty Raiked i ark in Each City Cour				1			
Rank	Park	Priority Ranking	Lifespan	Area (Acres)		Estimated Replacement Cost	Quadrant	Park Type
•	District 1 - Highest Priority Ranked Park							
1	Southwest Community Park	2.5	11.4	19.8	\$	17,767,728	SW	CP
0	District 2 - Highest Priority Ranked Park							
1	Doyle Community Park	2.5	14.19	21.8	\$	18,209,391	NE	CP
1	District 3 - Highest Priority Ranked Park Rincon Valley Community Park District 4 - Highest Priority Ranked Park	2.5	13.4	18.9	\$	14,774,691	NE	СР
1	Frances Nielsen Open Space	2.7	10.83	7.9	\$	2,028,790	NE	OS
	District 5 - Highest Priority Ranked Park	0.0	10.00		¢	E 000 / 05	N 1) 4 /	ND
1	Jacobs Park (Lincoln School)	2.3	10.29	6.9	\$	5,089,625	NW	NP
0	District 6 - Highest Priority Ranked Park							
1	Bicentennial Park	2.8	14.81	5.3	\$	6,025,186	NW	NP
0	District 7 - Highest Priority Ranked Park							
1	A Place to Play Community Park	2.7	14.05	77.2	\$	51,368,135	NW	CP
Figu	re 26: City Council District Analysis Table	-	-					

Figure 26: City Council District Analysis Table



Figure 27: City Council District Analysis Map

PARK TYPE ANALYSIS

The park type analysis identifies the three highest priority parks for each park type, which include: community parks, neighborhood parks, trail parks, open spaces, special purpose park, and public gathering areas and plazas. Figure 29 identifies the location of each parks.

н	ighest Priority Ranked Parks in Each Park Typ							
	Ignest i nonty trained Fairs in Each Fair Typ				T	I		
Rank	Park	Priority Ranking	Lifespan	Area (Acres)		Estimated Replacement Cost	Quadrant	Park Type
0	Community Parks - Highest Priority Ranked P	arks						
1	Youth Community Park	2.5	16.02	73.8	\$	44,837,076	NW	СР
2	Northwest Community Park	2.5	14.08	35.1	\$	27,127,956	NW	CP
3	Southwest Community Park	2.5	11.4	19.8	\$	17,767,728	SW	СР
	Neighborhood Parks - Highest Priority Ranke				Γ.			
1	Jacobs Park (Lincoln School)	2.3	10.29	6.9	\$	5,089,625	NW	NP
2	South Davis Park	2.6	13.56	1.3	\$	1,418,918	SW	NP
3	Martin Luther King Jr. Park	2.7	13.05	5.4	\$	5,146,137	SE	NP
	Open Spaces - Highest Priority Ranked Parks				T .			
1	Frances Nielsen Open Space	2.7	10.83	7.9	\$	2,028,790	NE	OS
2	Parktrail Open Space	3.1	13.48	24.9	\$	7,462,667	SE	OS
3	Owls Nest Open Space	3.2	18.3	15.0	\$	3,134,127	NE	OS
	Public Gathering Areas & Plazas - Highest Pri							
	Jeju Way	3.5	15.56	0.1	\$	214,309	NE	PA
71	Comstock Mall Park	3.7	17.38	0.4	\$	763,071	NE	PA
85	Courthouse Square	4.8	25.76	2.7	\$	4,859,650	NE	PA
•	Special Purpose Parks - Highest Priority Rank	ed Par	ks					
1	Bennett Valley Golf Course	2.9	14.23	153.0	\$	85,194,416	SE	SP
2	Luther Burbank Home and Gardens	3.2	17.36	1.6	\$	2,834,273	NE	SP
3	Santa Rosa Rural Cemetery	3.9	19.61	15.8	\$	6,687,387	NE	SP
0	Trail Parks - Highest Priority Ranked Parks							
1	Newhall Bike Trail	3.1	14.38	1.0	\$	479,668	SE	TR
2	Hampton Woods Trail	3.2	14.69	11.2	\$	4,941,373	SE	TR
3	Pearblossom Trail	3.4	17.86	2.4	\$	1,681,990	SW	TR
	ura 20. Darle Tura a Analysia Talala							

Figure 28: Park Type Analysis Table




Figure 29: Park Type Analysis Map

PLAYGROUND ANALYSIS

The playground analysis identifies all playgrounds found within the City parks assessed as a part of this Report. The playgrounds are categorized into each of the four quadrants and are organized by condition, from worst to best.

4	All Playgrounds by Quadrant and Ranked by Conc	ition					
Rank	Playground	Condition	Lifespan	Area (SF)	Estimated Replacement Cost	Quadrant	Park Type
No	ortheast Quadrant - Playgrounds						
1	Rincon Valley Community Park	2.0	5	5,237	\$ 650,593	NE	CP
2	Oaklake Green Park	2.7	10	4,307	\$ 535,077	NE	
3	Brush Creek Park	3.0	10	5,335	\$ 662,680	NE	NP
4	Eastside Park	3.0	10	5,211	\$ 647,372	NE	NP
5	Franklin Community Park	3.0	15	10,364	\$ 1,287,459	NE	CP
6	Juilliard Park	3.0	10	1,939	\$ 240,888	NE	NP
7	Sky Hawk Community Park	3.0	10	2,350	\$ 291,950	NE	CP
8	Steele Lane Park	3.0	15	6,834	\$ 848,925	NE	NP
9	Tanglewood Park	3.0	10	3,622	\$ 449,968	NE	NP
10	Doyle Community Park	3.3	15	5,739	\$ 712,848	NE	CP
11	Frances Nielsen Open Space	3.3	15	1,517	\$ 188,393	NE	OS
12	Hidden Valley Park	3.4	15	3,112	\$ 386,550	NE	NP
13	Rae Street Park	3.9	15	2,513	\$ 312,171	NE	NP
14	North Park	3.9	15	2,223	\$ 276,086	NE	NP
15	Humboldt Park	3.9	15	2,218	\$ 275,575	NE	NP
	orthwest Quadrant - Playgrounds				 		
1	Live Oak Park	1.0	0	3,941	\$ 489,560	NW	
2	Bicentennial Park	2.0	5	10,513	\$ 1,305,953		NP
3	Brendon Park	2.0	5	6,065	\$ 753,369		NP
4	Finley Community Park	2.0	5	7,347	\$ 912,703	NW	
5	Haydn Village Park	2.0	5	599	\$ 74,399		NP
6	Jacobs Park (Lincoln School)	2.0	5	5,926	\$ 736,102		
7	Peterson Lane Park	2.3	10	4,296	533,615		
8	Northwest Community Park	3.0	10	5,507	\$ 684,095		
9	Pioneer Park	3.0	10	5,178	\$ 643,199		
10	Youth Community Park	3.2	15	8,242	\$ 1,023,845	NW	
11	A Place to Play Community Park	3.3	15	4,163	\$ 517,118	NW	
12	Westgate Park	3.6	15	2,805	\$ 348,447		NP
13	DeMeo Park	4.0	15	3,846	\$ 477,709		NP
14	Finali Park	4.0	20	3,651	\$ 453,573		NP
15	Olive Park	4.0	15	3,385	\$ 420,550		NP
16	Coffey Park	5.0	20	11,900	\$ 1,478,233	NW	NP

Figure 30: Playground Analysis

	All Playgrounds by Quadrant and Ranked by Condi	ion					
Ή	an naygrounds by Quadrant and Kanked by Condi	T			LL		
Rank	Playground	Condition	Lifespan	Area (SF)	Estimated Replacement Cost	Quadrant	Park Type
Sc	outheast Quadrant - Playgrounds						
1	Colgan Creek Park	2.0	5	6,934	\$ 861,351	SE	NP
2	Peter Springs Park	2.0	5	1,099	\$ 136,569	SE	NP
3	Howarth Community Park #1 Land of Imagination	2.5	15	12,719	\$ 1,580,005	SE	CP
4	Harvest Park	2.9	15	5,438	\$ 675,560	SE	NP
5	Martin Luther King Jr. Park	3.0	10	5,394	\$ 670,091	SE	NP
6	Red Hawk Park	3.0	10	2,415	\$ 299,974	SE	NP
7	Howarth Community Park #2	3.3	15	4,033	\$ 501,028	SE	CP
8	Matanzas Park	3.6	15	3,047	\$ 378,466	SE	NP
9	Mesquite Park	3.7	15	1,735	\$ 215,529	SE	NP
10	Galvin Community Park	3.9	15	4,148	\$ 515,250	SE	CP
11	Dauenhauer Park	4.3	20	2,117	\$ 262,948	SE	NP
Sc	outhwest Quadrant - Playgrounds						
1	Bayer Park and Gardens #1	3.0	10	2,597	\$ 322,579	SW	NP
2	Cook School Park	3.0	10	4,119	\$ 511,630	SW	NP
3	Southwest Community Park	3.0	10	3,853	\$ 478,578	SW	CP
4	Village Green Park	3.0	15	2,816	\$ 349,752	SW	NP
5	Bellevue Ranch Park	3.2	15	6,811	\$ 846,088	SW	NP
6	Pearblossom Park	3.4	15	3,031	\$ 376,470	SW	NP
7	Airfield Park	3.7	15	4,727	\$ 587,203	SW	NP
8	South Davis Park	4.0	15	3,090	\$ 383,902	SW	NP
9	Bayer Park and Gardens #2	4.5	20	1,937	\$ 47,320	SW	NP

Figure 30 (continued): Playground Analysis

SPORTS FIELD ANALYSIS

The sports field analysis identifies all sports fields found within the City parks assessed as a part of this Report. The sports fields are categorized into each of the four quadrants and are organized by condition, from worst to best.

	All Sports Fields by Quadrant an	d Ranked by Conditi	on					
Rank	Park	Sport Type	Condition	Lifespan	Area (SF)	Estimated Replacement Cost	Quadrant	Park Type
N	ortheast Quadrant - Sports Field	s						
1	Franklin Community Park	Softball	2.0	4	11,913	\$ 391,088	NE	CP
2	Doyle Community Park	Baseball	3.0	7.5	138,131	\$ 3,373,876	NE	CP
3	Rincon Valley Community Park	Soccer	3.0	10	68,484	\$ 1,672,736	NE	CP
4	Skyhawk Community Park	Soccer / Softball	3.0	10	25,405	\$ 833,993	NE	CP
5	Rincon Valley Community Park	Softball	3.0	8	36,193	\$ 1,188,156	NE	CP
6	Skyhawk Community Park	Soccer	3.8	15	28,896	\$ 224,336	NE	CP
7	Franklin Community Park	Soccer	4.0	15	81,888	\$ 635,742	NE	CP
_	orthwest Quadrant - Sports Field	ds						
1	Youth Community Park	*Disc Golf	1.0	0	-	-	NW	CP
2	Jacobs Park (Lincoln School)	Baseball	1.0	0	11,375	\$ 277,846	NW	NP
3	Jennings Park	Softball	1.0	0	32,826	\$ 801,787	NW	NP
4	A Place to Play Community Park	Baseball (Paul Cousins)	2.0	4	128,819	\$ 4,228,891	NW	CP
5	Northwest Community Park	Rugby	2.8	10	74,307	\$ 479,453	NW	CP
6	A Place to Play Community Park	Baseball	3.0	7.5	43,425	\$ 1,425,551	NW	CP
7	A Place to Play Community Park	Soccer	3.0	10	597,882	\$ 4,641,668	NW	СР
8	Jacobs Park (Lincoln School)	Soccer	3.0	10	65,352	\$ 507,362	NW	NP
9	Jennings Park	Soccer	3.0	10	91,048	\$ 706,856	NW	NP
10	Northwest Community Park	Track & Field	3.0	9	40,150	\$ 939,374	NW	CP
11	Northwest Community Park	Softball	3.2	11	248,351	\$ 6,066,025	NW	CP
12	Northwest Community Park	Soccer	4.0	15	212,263	\$ 1,647,906	NW	CP

Figure 31: Sports Field Analysis

	All Sports Fields by Quadrant ar	nd Ranked by Condit	ion								
Rank	Park	Sport Type	Condition	Lifespan	Area (SF)	Estimated Replacement Cost	Quadrant	Park Type			
Se	outheast Quadrant - Sports Field	ls									
1	Galvin Community Park	Youth Tennis (9-10)	2.0	5	15,375	\$ 489,610	SE	CP			
2	Bennett Valley Golf Course	Golf Course	3.0	15	2,571,349	\$ 19,962,725	SE	SP			
3	Bennett Valley Golf Course	Drive Range	3.1	15	306,426	\$ 2,378,945	SE	SP			
4	Martin Luther King Jr. Park	Soccer	3.5	15	31,995	\$ 248,396	SE	NP			
5	Howarth Community Park	Baseball / Softball	3.5	11	69,190	\$ 2,271,391	SE	CP			
6	Galvin Community Park	Baseball	4.0	11	75,320	\$ 1,839,705	SE	CP			
7	Galvin Community Park	Soccer	4.0	15	143,005	\$ 3,492,924	SE	CP			
Se	Southwest Quadrant - Sports Fields										
1	Southwest Community Park	Softball	2.0	4	38,367	\$ 1,259,509	SW	CP			
					62,912	\$ 488,420	SW	CP			

Figure 31 (continued): Sports Field Analysis

SPORTS COURT ANALYSIS

The sports court analysis identifies the sports courts found within the City parks assessed as a part of this Report. The sports courts are categorized into each of the four quadrants and and are organized by condition, from worst to best.

All Sports Courts by Quadrant and Ranked by Condition												
Rank	Park	Sport Type	Condition	Lifespan	Area (SF)		Estimated Replacement Cost	Quadrant	Park Type			
Northeast Quadrant - Sports Courts												
1	Tanglewood Park	Basketball	1.0	0	2,554	\$	62,382	NE	NP			
2	Rincon Valley Community Park	Horseshoe	1.0	0	2,348	\$	107,985	NE	CP			
3	Brush Creek Park	Basketball	3.0	13	2,107	\$	51,455	NE	NP			
4	Brush Creek Park	Handball	3.0	8	496	\$	12,110	NE	NP			
5	Juilliard Park	Bocce	3.7	10	8,642	\$	211,079	NE	NP			
6	Doyle Community Park	Horseshoe	3.9	11	7,608	\$	349,879	NE	CP			
7	Frances Nielsen Ranch Park	Basketball	4.0	19	934	\$	22,807	NE	NP			
Northwest Quadrant - Sports Courts												
1	Bicentennial Park	Horseshoe	2.0	4	1,236	\$	56,857					
	Finley Community Park	Horseshoe	2.0	4	1,694	\$	77,907					
_	Pioneer Park	Horseshoe	2.0	4	731	\$	17,859					
4	Jacobs Park (Lincoln School)	Volleyball	2.0	5	4,077	\$	136,847					
5	Finley Community Park	Volleyball	2.7	10	7,940	\$	365,158					
6	Pioneer Park	Basketball	3.0	13	4,160	\$	101,600					
7	Pioneer Park	Handball	3.0	8	795	\$	19,411					
_	Finley Community Park	Tennis / Pickleball	3.0	10	25,973	\$	827,114					
9	Brendon Park	Volleyball	3.0	10	5,424	\$	132,476					
	DeMeo Park	Basketball	3.3	19	1,768	\$	43,175					
11	Bicentennial Park	Basketball	3.3	19	4,287	\$		NW				
	Westgate Park	Basketball	3.4	25	2,160	\$	52,770					
13	Finley Community Park	Basketball	3.8	19	4,569	\$	111,605	_				
14	DeMeo Park	Bocce	3.9	7.5	1,529	\$	70,315	NW	NP			

Figure 32: Sports Court Analysis

All Sports Courts by Quadrant and Ranked by Condition											
Rank	Park	Sport Type	Condition	Lifespan	Area (SF)	Estimated Replacement Cost		Quadrant	Park Type		
Southeast Quadrant - Sports Courts											
1	Howarth Community Park	Tennis	1.0	0	33,739	\$	1,074,402	SE	CP		
2	Martin Luther King Jr. Park	Basketball	2.0	6	6,895	\$	168,408	SE	NP		
3	Galvin Community Park	Youth Tennis (9-10)	2.0	5	15,375	\$	489,610	SE	CP		
4	Dauenhauer Park	Basketball	3.3	25	2,858	\$	69,807	SE	NP		
5	Howarth Community Park	Pickleball	4.0	15	6,748	\$	214,880	SE	CP		
6	Galvin Community Park	Tennis (1-6)	4.0	15	46,125	\$	1,468,831	SE	CP		
7	Galvin Community Park	Tennis (7-8, 11-12)	4.0	15	30,750	\$	979,221	SE	CP		
8	Colgan Creek Park	Basketball	4.3	25	3,251	\$	79,407	SE	NP		
Southwest Quadrant - Sports Courts											
	South Davis Park	Basketball	2.0	6	1,121	\$	-	SW			
	Southwest Community Park	Basketball	2.0	6	10,554	\$	257,776	SW			
	Bellevue Ranch Park	Basketball	3.0	13	2,098	\$	51,251	SW			
	Pearblossom Park	Basketball	3.0	13	4,163	\$	101,680	SW			
5	Village Green Park	Basketball	3.0	13	2,749	\$	67,152	SW			
6	Bellevue Ranch Park	Handball	3.0	8	891	\$	21,768	SW			
7	Bayer Park and Gardens	Volleyball	3.0	10	1,842	\$	61,828	SW			
8	Airfield Park	Basketball	4.0	19	4,946	\$	120,798	SW	NP		
9	Bayer Park and Gardens	Basketball	5.0	25	976	\$	23,844	SW	NP		

Figure 32 (continued): Sports Court Analysis

ACKNOWLEDGMENTS





CITY STAFF Recreation and Parks Department


Emily Ander, Park Planner Assistant Jen Santos, Deputy Director of Parks Terri Bladow, Research and Program Coordinator Tim Finegan, Parks Crew Supervisor Ellio Torrano, Parks Supervisor Jeff Tibbets, Deputy Director of Recreation James Castro, Park/Streets Maintenance Superintendent Amy Rocklewitz, Recreation Supervisor

Transportation & Public Works Department Jeremy Gundy, Deputy Director of Field Services Cameron Macdonald, Facilities Planning Coordinator

CONSULTANT

Callander Associates Landscape Architecture Brian Fletcher, Principal-In-Charge Grant Huang, Project Manager Kelly Kong, Project Designer

APPENDICES



Parks Prioritization Report



APPENDIX A Glossary of Terms

APPENDIX B Park Assessment Summaries

APPENDIX C Roadway Landscape Assessment Summaries

APPENDIX D Cost Estimate Table Page is Intentionally Blank





GLOSSARY OF TERMS

Page is Intentionally Blank

GLOSSARY OF TERMS

Amenities

Attributes of park that have a designated use.

Assets

Specific parts or components that make up a park amenity.

Condition Rating

The numerical value assigned to an asset based on its condition, using the Condition Rating Criteria as a common scale.

Condition Rating Criteria

Established criteria with detailed descriptions used to assign a condition rating to an asset.

Deferred Maintenance

Deferred maintenance is maintenance that has not been completed to keep facilities in an acceptable and operable condition.

General Fund

Makes up the largest portion of the City's budget and provides funding for many of the services the City offers.

Invasive Weeds

Weeds that have the ability to aggressively spread outside its natural habitat

Measure M

A sales tax that supports Sonoma County's regional and city parks, which dedicates approximately \$1.9 million to Santa Rosa each year from 2019 to 2029. The City of Santa Rosa's City Council has approved a funding strategy to utilize these funds for the park system.

Noxious Weeds

Weeds that are detrimental to public health, agriculture, recreation, wildlife, or property.

Overall Priority Ranking

The numerical value assigned to each park using weighted values of each ranking category to compare it's priority with other parks.

Park Development Impact (PDI) Fees

The City collects Park Development Impact Fees from residential housing developments in lieu of park land dedication. These funds are used to acquire and develop new parks as well as replace existing park amenities.

Ranking

The numerical value assigned to a park (or amenity) for each ranking category in order to compare priority levels between parks (or amenities).

Ranking Categories

The categories of a park that contribute to its overall priority rank, which include condition, recreation programming, play value and accessibility.

Ranking Methodology

The methodology used to derive a numerical ranking for each ranking category.

Roadway Landscape

The hardscape and landscape of a roadway frontage or median, which does not include the roadway surface or curb.

Supplemental Categories

Additional information including approximate lifespan and estimate replacement cost provided for each park that is not associated with the priority ranking. Page is Intentionally Blank





Park Assessment Summaries

—		[İ	
	Amenity	Asset	Type / Material	on	Inventory Date: 7/7/21
				Condition	Time: 1:16 - 1:42pm
Park	me		Type / Materi		Field Notes (all italicized noted are notes
ă	A	۷	μ μ		from maintenance staff)
Airfi	eld P	 Park		3.8	
				5.0	
					General Site Observations: Large group of
					people using picnic area and playground
					during time of visit, clean and well
					maintained overall, safe environment
	Gen	eral Furnishings		4.0	
		Benches	Composite	4	
		Drinking Fountains	Steel	4	Water turned off
		Trash/Recycling Receptacles	Metal	4	
	Gen	eral Landscape		3.3	
		Turf		4	Significant weed growth
		Non-Turf Ornamental Landscape		3	
		Unplanted Landscape		3	No mulch along fence line, low mulch
					throughout
	Gen	eral Trees		4.0	
		Park Trees		4	All trees in DG are dead/removed
	Gen	eral Hardscape		3.3	
		Concrete		4	
		Pavers		3	Interpretive banding within concrete path, minor lifting
		Decomposed Granite / Gravel		3	Empty tree well in the middle of DG area
	Gen	eral Irrigation		3.5	
		System operation		3	Minor coverage issues
		System type (drip / spray)	Spray		
		Controller		4	No observable problems
	Gen	eral Barriers		4.0	
		Fences / Walls	Seat wall, Concrete	4	
	Gen	eral Signage		4.5	
		Park ID	Concrete	5	On corner of North Point and Fresno
		Park Rules	Metal	4	
	Gen	eral Drainage		4.0	
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	

		ity			Inventory Date: 7/7/21
	ity		Condition	Time: 1:16 - 1:42pm	
¥	Amenity	set	Type / Material	jdi	Field Notes (all italicized noted are notes
Park	Αm	Asset	Z A	Ō	from maintenance staff)
Airfi	eld P	ark		3.8	
	Picn	ic Areas		3.0	
		Tables*	Composite	4	
		Surfacing	D.G.	3	
		Trash Receptacles		4	
		Shade Trees		1	Dead or removed
	Play	ground		3.7	
		Equipment*	Metal/Plastic	4	
		Curb	Concrete	4	
		Surfacing	Rubber	4	
		Surfacing	Sand	4	
		Barriers	Ornamental Metal	4	
		Signs		2	One structure is missing sign
		Drainage		4	No observable problems
	Spo	rts Field / Court 1		4.0	
		Sport Type:	Basketball		
		Surfacing*	Asphalt	4	
		Striping		4	
		Equipment	Metal	4	
		Drainage		4	No observable problems
		ng of the amenity shall not exceed the rat	-	asset v	vith an asterisk
Note	e: Lim	nited assessment items are highlighted in g	grey		

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/22/21 Time: 11:45 -11:57am Field Notes (all italicized noted are notes from maintenance staff)
Airfi	old E	resno Mitigation Open Space		3.9	
AIIII				3.9	General Site Observations: Large fenced off open space adjacent to new development
	Gen	eral Landscape		3.5	
		Non-Turf Ornamental Landscape		3	No mulch, major gaps
		Natural Landscape		4	Natural landscape, no noxious weeds present / annual grasses manageable by mowing
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		N/A	None observable
	Gen	eral Barriers		3.0	
		Fences / Walls	Wood posts	4	
		Entrance/Maintenance Gates		2	Latch, latching mechanism broken
		eral Signage		5.0	
		Interpretive Signage		5	Dust/dirt slightly obscuring sign graphics
	Gen	eral Drainage		4.0	
		Culvert		4	No observable problems
		Curb and Gutter		4	
		Drain inlet		4	
		Swales / Stormwater Infrastructure		4	
	1	king Lot		N/A	
		Lighting			Street lighting only
* Th	o rati	ng of the amenity shall not exceed the rat	ing of the lowest rated	asset w	l vith an asterisk
		lited assessment items are highlighted in g	-		

				-	Inventory Date: 7/8/21
	tγ		a	io	Time: 7:53am/9:46am
_	eni	et	e / teri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	Condition	from maintenance staff)
<u> </u>	4	4	<u> </u>	0	
	Place to Play Community Park			3.1	
				-	General Site Observations: Highly used by
					dog owners at time of visit, dog owners
					bring and leave their own chairs in the park,
					few individuals using soccer fields for
					personal exercise
	Gen	eral Furnishings		3.0	
		Benches	wood	4	
		Tables	metal	4	
		Bike Racks	metal	4	
		Drinking Fountains	(1) concrete (1) motol	2	Drinking fountain near baseball field is
		Drinking Fountains	(1) concrete, (1) metal	2	cracked at base, water turned off
		Trash/Recycling Receptacles	Plastic	1	Deficient
	Gen	eral Landscape		3.0	
		Turf		3	Weedy and patchy
		Non-Turf Ornamental Landscape		3	Weedy
		Unplanted Landscape		2	Weedy, no mulch
		Natural Landscape		4	
	Gen	eral Trees		3.0	
		Park Trees		3	Pears have significant dieback
		Trees in Natural Areas		3	
	Gen	eral Hardscape		1.5	
		Concrete		2	
		Decomposed Granite / Gravel		1	Weedy
	Gen	eral Irrigation		4.0	
		System operation		4	
		System type (drip / spray)	spray		
		Controller		4	No observable problems, controllers appear new
	Gen	eral Barriers		4.0	
		Entrance/Maintenance Gates	metal	4	At entry
		Handrails	metal	4	
		Bollards	metal	4	
	Gen	eral Signage		2.3	
		Park Rules	metal	2	Poor location
		Interpretive Signage	metal	2	Illegible, damaged
L		Kiosks	wood	3	At dog park

				1	Inventory Date: 7/0/21
	Ň		a	on	Inventory Date: 7/8/21
	nit	r.	eria	diti	Time: 7:53am/9:46am
Park	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized noted are notes
4	A	۷	μŻ	Ŭ	from maintenance staff)
A Pla		o Play Community Park		3.1	
		eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	
		eral Structures		3.0	
		Sheds	wood and metal	3	Wood decay on woodshed roof
		Restrooms (not assessed)			On site
	Picn	ic Areas		3.0	
		Tables*	metal	3	
		Barbecues	metal	4	
		Surfacing	DG, Concrete	4	Deficient
		Trash Receptacles		1	
		Shade Trees		4	
		Water Source		4	
	Park	king Lot		3.5	
		Lighting	metal accents	4	
		Surfacing*	asphalt	4	
		Signage	metal	4	
		Christian -		2	Missing in some locations and extremely
		Striping		2	faded in other locations
	Play	ground		3.3	
		Equipment*	metal	4	
		Curb	concrete	4	
		Surfacing	wood fiber	2	Significantly low levels
		Barriers		1	Deficient
		Signs		1	
		Shade Structures		5	
		Drainage		4	No observable problems

	<u> </u>				Inventory Date: 7/0/21
	~		Ē	Condition	Inventory Date: 7/8/21
	nit	ц.	eria	liti	Time: 7:53am/9:46am
Park	Amenity	Asset	Type / Materia	Duc	Field Notes (all italicized noted are notes
P	Ā	Ä.	ĻΣ	Ŭ	from maintenance staff)
		o Play Community Park		3.1	
	Spo	rts Field / Court 1		3.0	
		Sport Type:	Baseball		
					Maintenance appears to only occur within
		Surfacing*	infield	3	the diamond, areas not in diamond are
					weedy
		Surfacing*	outfield, turf	3	
		Surfacing*	concrete	4	
			back stop,		Overall in functioning condition, wood
		Equipment	chainlink/wood	4	panels are weathered
		Barriers	chainlink	3	Maintenance gates needs repair
		Furnishings	metal/concrete,	4	Bleachers are concrete seat walls
			benches and bleachers	•	
		Signage	concrete	4	
		Irrigation		4	Minor coverage issues within
		lingation		4	infield/diamond
		Drainage		4	No observable problems
	Spo	rts Field / Court 2		2.0	
		Sport Turpo:	Baseball (Paul Cousins		
		Sport Type:	Field)		
		Surfacing*	infield mix	4	Only within diamond/bases
		Surfacing*	+ <i>r</i> f	2	Databy (woody along backstop and dugayt
			turf	2	Patchy/weedy along backstop and dugout
		Faultament	chainlink and wood	4	
		Equipment	backstop	4	
		Fouriers	metal and netting,	-	Extremely uneven/weedy, half of structure
		Equipment	batting cage	2	missing netting
		Barriers	chainlink	3	
		Furnishings	benches and bleachers	4	
		Signage	concrete	4	
		Irrigation		4	
		Drainage		4	No observable problems, trench drain along
					backstop

			_	5	Inventory Date: 7/8/21		
	it		ria	Condition	Time: 7:53am/9:46am		
Park	Amenity	Asset	Type / Materia	pu	Field Notes (all italicized noted are notes		
Pa	An	As	Ļξ	ပိ	from maintenance staff)		
A Pla	ace to	o Play Community Park		3.1			
	Spo	rts Field / Court 3		3.0			
		Sport Type:	Soccer (all fields turf)				
		Surfacing*	turf	3	Community members have noted issues		
		Surracing	turi	5	with weedy turf, gopher holes, and bees		
		Equipment	Metal, goal posts	4			
		Barriers	chainlink	4			
		Signage	concrete/metal	4			
		Irrigation*		4			
		Drainage		4	No observable problems		
	Trai	ls		4.0			
		Surfacing*	gravel	4			
	Dog	; Park		3.2			
		Surfacing	mulch	3	Weedy		
		Drinking Fountain	metal	4	Spigot		
		Barriers*	chainlink	4	Weeds stuck in fence		
		Benches			Deficient, users bring their own benches		
		Trash Receptacles	Plastic	1	Deficient		
		Signage	Metal	4	On entry gate		
	Rem	note Control Car Race Track		2.5			
		Surfacing*	compacted earth	4	Course has some areas with carpets/fabric, light amount of weeds		
		Barriers	t-post and rope	1			
		ing of the amenity shall not exceed the ra	-	asset v	vith an asterisk		
Note	Note: Limited assessment items are highlighted in grey						

—		1			Inventory Date: 5/18/21
	itγ		ial	tio	Time: AM
×	Amenity	et	Type / Materia	Condition	Field Notes (all italicized noted are notes
Park	Am	Asset	Type / Materi	Co	from maintenance staff)
		-	• <u>-</u>		
Baye	er Pa	rk and Gardens		4.2	
					General Site Observations: Beautiful historic
					garden, friendly staff
	Gen	eral Furnishings		4.3	
		Bike Racks		5	
		Drinking Fountains		4	
		Trash/Recycling Receptacles		4	
	Gen	eral Landscape		3.5	
		Turf		4	
					Majority of landscape is not planted,
		Unplanted Landscape		3	consists of mulch and mowed natural plants,
					weedy
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		5.0	
		Concrete		5	
		Pavers		5	
		Amphitheater		5	
	Gen	eral Irrigation		4.0	
		System operation		3	Coverage problems apparent in turf
		System type (drip / spray)			Presumed new
		Controller		5	Presumed new, no observable problems
	Gen	eral Lighting		5.0	
		System Operation		5	No observable problems
	Gen	eral Barriers		3.7	
		Entrance/Maintenance Gates		4	
		Handrails		4	At central amphitheater, gazebo
		Bollards		3	Rust
	Gen	eral Signage		4.7	
		Park ID		5	
		Park Rules		4	
		Traffic Signs		5	
	Gen	eral Drainage		4.0	
		Curb and Gutter		4	Appears almost new with light damage
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	No observable problems
	Gen	eral Structures		4.0	
		Shade Structures (not assessed)			Present
		Sheds		4	Trash enclosure

					Inventory Date: 5/18/21
	ť		a	ion	Time: AM
	eni		e /	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	Condition	from maintenance staff)
	4	¥		0	
Baye	ar Pai	rk and Gardens		4.2	
Day		lic Areas		4.4	
	1 1011	Tables*		5	
		Kiosk / sign	Steel	5	
		Barbecues	Steel	4	
		Specialty Barbecue	Concrete	4	
		Hot Coal Bin	Metal	4	
			ivietai	4	
		Surfacing	Decomposed Granite	4	Minor amounts of weeds
		Trash Receptacles	Metal	4	
		Shade Trees		5	
		Shade Structures (not assessed)			Present, no observable problems
		Water Source		5	No observable problems
	Park	king Lot		5.0	
		Lighting	LED	5	No observable problems
		Surfacing*		5	
		Signage		5	
		Striping		5	
	Fitn	ess Equipment		4.0	
		Type: cluster/par course	Multiple clusters		
		Equipment*	Metal	4	
		Surfacing	Mulch	5	
	Play	vground 1	Nature Play	3.0	
		Equipment*	wood	3	Decomposing wood/stump steps
		Surfacing	mulch	2	Needs replenishment, weedy play mounds
		Surfacing	Decomposed Granite	4	
		Water play		4	Water turned off
		Drainage		3	No observable problems
	Play	vground 2		4.5	
		Equipment*	Metal and plastic	5	
		Curb		5	
		Surfacing	Poured in place rubber	4	
		Surfacing	Concrete	5	
		Furnishings		4	
		Barriers		4	
		Signs		5	
		Drainage		4	No observable problems

	l			_	Inventory Date: 5/18/21	
	Σ	*	a	ion	Time: AM	
	-in		e /	diti		
Park	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized noted are notes	
<u>⊢</u>	◄	₹	⊢ 2	0	from maintenance staff)	
Bave	er Pa	rk and Gardens		4.2		
	1	rts Field / Court 1		5.0		
		Sport Type:	Basketball (half court)			
		Surfacing*	Concrete	5		
		Surfacing*		5		
		Field striping	Ноор	5		
		Equipment		5		
	Spo	rts Field / Court 2		3.0		
		Sport Type:	Volleyball			
		Surfacing*	Mulch	3	Needs replenishment	
		Equipment	Poles and net	2	No net, tensioners stuck	
		Barriers	Concrete Curb	4		
		Drainage		4	No observable problems	
	Skat	te Park		5.0		
		Surfacing*		5		
		Skate Features		5		
		Furnishings		5		
	Con	nmunity Gardens		4.0		
		Barriers*	Wood and wire	4		
		Surfacing	Decomposed Granite	4		
		Storage	building, not assessed		No observable problems	
		Irrigation		4	Drip present, functioning	
		Raised Beds		4		
	Art			N/A		
		Surfacing (not assessed)			Present	
		Structure (not assessed)			Present	
		Mural / Mosaic (not assessed)			Present	
* Th	e rati	l ing of the amenity shall not exceed the rat	ing of the lowest rated a	isset M	l	
		nited assessment items are highlighted in g	-			
11010	iote. Limited assessment items are inginigrited in grey					

	1	İ		İ _	Inventory Date: 7/8/21
	t		a	ion	Time: 8:00 - 10:27am
l 🗸	eni	et	e / :eri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	Condition	from maintenance staff)
<u> </u>	-	· · · · · · · · · · · · · · · · · · ·			
Ben	nett '	l Valley Golf Course		3.1	
					General Site Observations: Golf course and
					driving range were both almost full on a
					weekday morning. Clean and comfortable
					golf course.
	Gen	neral Furnishings		4.0	
		Benches	Composite/Wood	4	
		Tables			
		Bike Racks		4	
		Drinking Fountains			No observable problems, not running, one
		Drinking Fountains		4	had duct tape over operation button
		Trash/Recycling Receptacles	Wood/Metal	4	
		Other: Golf Bag Rack	Metal	4	
	Gen	neral Landscape		3.7	
		Non-Turf Ornamental Landscape		3	Dieback, weedy, mulch is thin in some areas
		Unplanted Landscape		4	Light amount of weed growth, mulch is thin in some areas
		Natural Landscape		4	
	Gen	neral Trees		4.0	
		Park Trees		4	Several dead trees, several trees with dieback
		Trees in Natural Areas		4	
	Gen	eral Hardscape		3.7	
		Concrete		1	Some areas with lifting, some drainage
		Concrete		4	issues at low points
		Pavers		4	
		Decomposed Granite / Gravel		3	Few large dips
	Gen	eral Irrigation		1.0	
		System operation		1	Low per BVGC report, new POC required
		System type (drip / spray)			Unknown
		Controller		1	Not found, low per BVGC report
	Gen	eral Lighting		2.0	
		System Operation		2	Not LED, some pathway lights fallen over
	Gen	eral Barriers		3.5	
		Fences / Walls	Split rail	3	
		Fences / Walls 2	Chainlink	4	
		Fences / Walls 3	Stone & Wood	3	At entrance
		Guardrails	Metal	4	One pole was leaning
L		Bollards	Metal	4	

—	Ì			1	Inventory Date: 7/8/21
	₹		a	ion	Inventory Date: 7/8/21 Time: 8:00 - 10:27am
	eni	et	e / :eri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset Type / Material Condition	UO I	from maintenance staff)	
<u> </u>	-	7	F 6		
Beni	nett \	l Valley Golf Course		3.1	
	Gen	eral Signage		3.0	
		Park ID	Stone and Metal	3	Corners look damaged
		Park Rules		3	Poor location, not near foot traffic
		Kiosks			Could not be located
	Gen	eral Drainage		1.0	
		Culvert		1	Low rating per BVGC report
		Curb and Gutter		1	Low rating per BVGC report
		Drain inlet		1	Low rating per BVGC report
		Swales / Stormwater Infrastructure		1	Low rating per BVGC report
	Gen	eral Structures		4.0	
		Pedestrian Bridges (not assessed)	Wood		Appears functional, but extremely worn
		Sheds		4	
		Restrooms (not assessed)			Present
	Park	king Lot		3.8	
		Wheel stops		4	One damaged at ADA stall
		Lighting		3	No observable problems, can't confirm if LED
		Surfacing*	asphalt	4	
		Striping		4	Slightly faded
	Spo	rts Field / Court 1		3.0	
		Sport Type:	Golf Course		
		Surfacing*	Turf	4	Moderate gaps and yellow patches
		Surfacing*	Sand	4	
		Equipment		4	No observable problems
		Furnishings	Wood, Composite	3	Older wood benches have noticeable signs of deterioration
		Signage		4	
		Irrigation		1	Some yellow patches, rotors, irrigation low rating per BVGC report
		Drainage		1	Some flooding issues, drainage issues per BVGC report

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 7/8/21 Time: 8:00 - 10:27am Field Notes (all italicized noted are notes from maintenance staff)
		/alley Golf Course		3.1	
	Spor	rts Field / Court 2		3.1	
		Sport Type:	Driving Range		
		Surfacing*	Turf	4	Some light yellow patches
		Equipment		4	No observable problems
		Barriers	Wood	4	
		Furnishings	Composite	4	
		Signage		4	
		Irrigation		1	Some yellow patches, rotors, irrigation issues per BVGC report
		Drainage		1	No observable problems, drainage issues per BVGC report
* The	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated	asset v	vith an asterisk
Note	: Lim	ited assessment items are highlighted in g	grey		

	1		1	1	
	٧		_	u	Inventory Date: 6/22/21
	nit	Asset	eria	liti	Time: 1:10pm to 1:45pm
Park	Amenity		Type / Materia	Condition	Field Notes (all italicized noted are notes
ä	A	Ŕ	F≥	Ŭ	from maintenance staff)
Pollo		Ranch Park		3.4	
Delle	evue			5.4	
					General Site Observations: Newer park,
					unkept, appears to be popular with residents
	Gen	eral Furnishings		3.4	
		Benches	Composite/Wood	4	
		Tables	Composite/Wood	4	
		Bike Racks	Metal	4	
		Drinking Fountains		4	
		Trash/Recycling Receptacles	Rolling/Plastic	1	Deficient, only rolling trash receptacles
	Gon	eral Landscape		2.7	present
	Gen	Turf		4	Small dry patches
		Non-Turf Ornamental Landscape		2	No mulch, very weedy, large gaps
		Unplanted Landscape		2	No mulch present
	Gon	eral Trees		4.0	
	Gen	Park Trees		4.0	
	Gon	eral Hardscape		3.5	
	Gen	Asphalt		3	Cracking, lifting
		Concrete		4	
	Gon	eral Irrigation		4.0	
	Gen	System operation		4.0	No observable problems
		System type (drip / spray)	Spray	-	
		Controller	Spray	4	Would be nice if we had a remote
	Gen	eral Barriers		4.0	
	00	Fences / Walls	Plastic White Fence	4	2 minor holes in railing
		Bollards		4	
	Gen	eral Signage		3.5	
		Park ID		4	
		Park Rules		3	Sign deteriorating, legibility issues
	Gen	eral Drainage		3.5	
		Curb and Gutter		3	
		Drain inlet		4	No observable problems

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/22/21 Time: 1:10pm to 1:45pm Field Notes (all italicized noted are notes from maintenance staff)
4	4	4			
Belle	evue	Ranch Park		3.4	
	Play	ground		3.2	
		Equipment*		4	One ground play element is broken in 5-12 area, not a safety hazard
		Curb		4	
		Surfacing	Rubber	4	
		Surfacing	Sand	3	Appears to be below intended depth
		Furnishings		4	
		Barriers		3	Gate not self closing, street less than 30' from play area with no barrier
		Signs		2	5-12 age appropriateness sign missing, warning labels missing
		Water play		1	Not operating
		Drainage		4	No observable problems
	Spo	rts Field / Court 1		3.0	
		Sport Type:	Basketball		
		Surfacing*	Asphalt	3	Signs of weed growth
		Striping		4	
		Equipment		4	
		Drainage		4	No observable problems
	Spo	rts Field / Court 2		3.0	
		Sport Type:	Handball		
		Surfacing*	Asphalt	3	Sloped
		Striping		4	
	-	Equipment		3	Wood damage
		Drainage		4	No observable problems
	Art			N/A	
		Surfacing (not assessed)			Present
		Structure (not assessed)			Present
		Mural / Mosaic (not assessed)			Present, wall-ball wall
* Th	e rati	I ing of the amenity shall not exceed the rat	ting of the lowest rated	asset w	vith an asterisk
Note	: Lim	ited assessment items are highlighted in {	grey		

				1	Lauranteau Deter (122/2021
	Amenity	Asset	Type / Material	on	Inventory Date: 6/23/2021
				diti	Time: 12:45pm - 1:24pm
Park	me		yp6 lat	Condition	Field Notes (all italicized noted are notes
	A	۷	μŻ	Ŭ	from maintenance staff)
Bico	nton	nial Park		3.0	
DICC				3.0	General Site Observations: Few people
					observed at park on a weekday, some
					accumulated trash near picnic area, signs of
					encampments observed.
	Gen	eral Furnishings		2.5	
		Benches	Wood	2	
		Tables	Wood and Steel	3	Heavily used
	Gen	eral Landscape		3.0	
		Turf		4	
		Unplanted Landscape		2	
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		3.0	
		Concrete		3	
	Gen	eral Irrigation		3.0	
		System operation	Turf	2	Patchy turf dieback, coverage issues
		System type (drip / spray)	Spray		
		Controller		4	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	
	Gen	eral Barriers		3.5	
		Fences / Walls	Split Rail/Wood	3	Sections are missing for rail, signs of
					deterioration
		Bollards		4	
	Gen	eral Signage		3.0	
		Park ID	Wood	3	Boards are cupping, sign facing Range Ave
		Wayfinding	Steel		
		Park Rules	Metal	3	Some are illegible
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	

	i –		1		Inventory Date: 6/23/2021			
	₹	*	<u> </u>	io l				
	en it		eri	Condition	Time: 12:45pm - 1:24pm Field Notes (all italicized noted are notes			
Park	Amenity	Asset	Type / Material	u o				
	◄	٩	⊢ ∠	0	from maintenance staff)			
Bice	nten	nial Park		3.0				
	Picn	iic Areas		3.0				
		Tables*	Wood and Steel	3				
		Barbecues	Metal	3	One is not standard height			
		Surfacing	Pavers	3	Far right corner uplifted by roots			
		Trash Receptacles	Concrete	3				
		Shade Structures (not assessed)	Wood		Present			
	Play	/ground		2.0				
		Equipment*		2	Missing swing components			
		Curb		4	No observable problems			
		Surfacing	Mulch	1	Tot-Lot has little to no mulch, lots of weeds			
		Furnishings	Wood Benches	3				
		Barriers	Metal	3	Few leaning posts			
		Signs	Metal	3	Poor location			
		Drainage		4	No observable problems			
	Spo	rts Field / Court 1		3.3				
		Sport Type:	Basketball					
		Surfacing*	Asphalt	4				
		Surfacing*	Concrete	4				
		Striping		2				
		Equipment	Metal	3	Striping on backboard extremely faded			
		Furnishings	Wood Benches	3	Heavily used			
	Spo	rts Field / Court 2		2.0				
		Sport Type:	Horseshoe					
		Surfacing*	Sand	2				
		Surfacing*	Pavers	2				
		Equipment	Wood Backboard	2				
		Barriers	Chainlink	3	Fabric at corner peeling back			
		Drainage		4	No observable problems			
		ing of the amenity shall not exceed the ra	-	asset v	vith an asterisk			
Note	ote: Limited assessment items are highlighted in grey							

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/22/21 Time: 1:14 - 1:25pm Field Notes (all italicized noted are notes from maintenance staff)
_					
Boas		ge Creek Open Space		3.6	Concret Site Observationer Small ener anos
					General Site Observations: Small open space area at the end of a street. Adjacent to a creek
	Gen	eral Landscape		3.0	
		Non-Turf Ornamental Landscape		2	Groundcover (irrigated) partially dead
		Natural Landscape		4	No noxious weeds present / mixture of annual grasses and dense shrub growth, including blackberry, cotoneaster, ivy, willows, oaks
	Gen	eral Trees		4.0	
		Park Trees		4	
		Trees in Natural Areas		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	Sidewalk
	Gen	eral Irrigation		4.0	
		System operation		4	No observable problems
		System type (drip / spray)			Tree bubbler / drip rings
		Controller		4	No observable problems
	Gen	eral Drainage		3.0	No observable problems
		Curb and Gutter		3	
		Drain inlet		3	
		ng of the amenity shall not exceed the rat ited assessment items are highlighted in g	÷	asset v	l vith an asterisk

	İ				Inventory Date:
	ţ		a	ion	Time:
_	eni	et	e / teri	Condition	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia		from maintenance staff)
<u> </u>					
Bren	Brendon Park			3.0	
					General Site Observations: Well maintained
					site, safe surroundings overall
	Gen	eral Furnishings		1.5	
		Benches	Wood	2	
		Trash/Recycling Receptacles		1	Deficient
	Gen	eral Landscape		3.0	
		Turf		4	
		Unplanted Landscape		2	
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		2.0	
		Asphalt		2	
		Concrete	Ped. Path	2	Half on east side cracked
	Gen	eral Irrigation		4.0	
		System operation		4	
		System type (drip / spray)	Spray		
		Controller		4	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	No observable problems
	Gen	eral Barriers		3.5	
		Entrance/Maintenance Gates		4	
		Bollards	Wood and Metal	3	
	Gen	eral Signage		3.0	
		Park ID	Wood	4	Front of park
		Park Rules	Metal	2	
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	
		Swales / Stormwater Infrastructure		4	
	Picn	ic Areas		3.0	
		Tables*		4	
		Barbecues		4	
		Surfacing	Concrete	2	
		Trash Receptacles	Plastic	1	1 rolling bin
		Shade Trees		4	

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: Time: Field Notes (all italicized noted are notes from maintenance staff)
Bren	don	Park		3.0	
	Play	ground		2.0	
		Equipment*		2	Extensive wear
		Curb	Asphalt	2	
		Surfacing	Sand	1	Full of weeds, compacted
		Surfacing	Concrete	3	Picnic table pad is cracked
		Furnishings	Tables	3	
		Signs		3	
		Drainage		4	No observable problems
	Spo	rts Field / Court 1		3.0	
		Sport Type:	Volleyball		
		Surfacing*	Turf	3	
		Equipment	Metal Posts	2	Missing net
		Irrigation		4	
		Drainage		4	No observable problems
* The	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated	asset v	vith an asterisk
Note	: Lim	nited assessment items are highlighted in g	grey		

	l			_	Inventory Date: 6/24/2021
	₹		a	ion	Time: 8:06am - 8:39am
	eni	t.	e / :eri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	Condition	from maintenance staff)
<u> </u>	4	Υ	F 2		
Brus	h Cra	eek Park		3.3	
Dius				5.5	General Site Observations: Clean & well
					maintained overall, safe environment
	Gon	leral Furnishings		3.5	
	Gen	Benches	Wood	3	Signs of weathering
		Tables	Wood	3	Signs of weathering
		Bike Racks	Metal	5	
			Concrete	3	
	Car	Trash/Recycling Receptacles	Concrete		
<u> </u>	Gen	eral Landscape		3.0	
<u> </u>		Turf		4	
┣──		Non-Turf Ornamental Landscape		3	
		Unplanted Landscape		2	
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		3.0	
		Asphalt			
		Concrete		3	Minor lifting, sidewalk is buckled, heavily worn and uneven.
<u> </u>	Gen	leral Irrigation		4.0	
	Gen	System operation		4	No observable problems
		System type (drip / spray)	Spray		
		Controller	Spray	4	No observable problems
	Gon	eral Lighting		3.0	
	Gen	System Operation		3	
	Gon	eral Barriers		3.3	
	Gen	Fences / Walls	Walls/Stone	3.3	Some stones are missing
<u> </u>		Fences / Walls 2	Wood and Wire	4	
		Entrance/Maintenance Gates/Fence	Split rail/wood	3	Signs of weathering
		Bollards		3	
┣──	Gar		Metal	3.0	
┣──	Gen	eral Signage	Engraved on stone	3.0	
		Park ID	pillar	3	Difficult to read
		Park Rules		3	
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure	Gravel, boulders,	4	
		Swales / Stormwater initiastructure	unplanted swale	4	

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/24/2021 Time: 8:06am - 8:39am Field Notes (all italicized noted are notes from maintenance staff)
srus	h Cre	eek Park		3.3	
		eral Structures		N/A	
		Shade Structures (not assessed)	Wood with Steel		Gazebo
	Picn	nic Areas		3.0	
		Tables*	Wood	3	Heavily used and weathered/deteriorating
		Barbecues	Steel	4	
		Surfacing	Concrete	2	Extremely uneven, lifting near trees
		Surfacing	Paver	2	Extremely uneven, lifting near trees
		Trash Receptacles	Concrete	3	
		Shade Trees		4	
		Shade Structures (not assessed)			Present, Gazebo
	Play	/ground		3.0	
		Equipment*	Plastic and Metal	3	Signs of weathering
		Curb	Concrete	4	
		Surfacing	Sand	4	
		Surfacing	Rubber	4	
		Surfacing	Concrete	3	Minor lifting and cracks
		Furnishings	Wood and Concrete	3	Wood benches and concrete trash receptacles, 2 benches show major weathering
		Barriers	Wood	3	Shows weathering
		Signs		1	On structure for tot-lot only, large structur is deficient
		Water play		3	Spigot turned off, no observable problems, Water faucet off
		Shade Structures (not assessed)	Wood and Steel		Present, shows significant signs of weathering
		Drainage		3	No observable problems.
	Spo	rts Field / Court 1		3.0	
		Sport Type:	Handball Court		
		Surfacing*	Asphalt	3	
		Equipment	Wood with Steel	3	Wall - heavily used
		Drainage		4	No observable problems

Park	Amenity	Asset	Type / Material	ā	Inventory Date: 6/24/2021 Time: 8:06am - 8:39am Field Notes (all italicized noted are notes from maintenance staff)		
Brus	h Cre	ek Park		3.3			
	Spor	ts Field / Court 2		3.0			
		Sport Type:	Basketball Court				
		Surfacing*	Asphalt	3			
		Striping		2			
		Equipment	Metal Hoop	4			
		Furnishings	Wood and Concrete	3	Bench and trash can		
		Drainage		4	No observable problems		
* Th	* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk						
Note	e: Lim	ited assessment items are highlighted in g	grey				

	İ 🗌			_	Inventory Date: 5/19/21
	Amenity	et	Type / Material	Condition	Time:
¥					Field Notes (all italicized noted are notes
Park	Am	Asset		Č	from maintenance staff)
		-			
Coff	ey Pa	ark		4.7	
					General Site Observations: Relatively new
					park
	Gen	eral Furnishings		5.0	
		Benches	concrete	5	
		Tables	concrete	5	
		Bike Racks	metal	5	
		Drinking Fountains	metal	5	
		Trash/Recycling Receptacles	metal	5	
	Gen	eral Landscape		3.7	
		Turf		3	Significant dry spots, green stripes indicating
		luri		5	soil/irrigation issues
		Non-Turf Ornamental Landscape		4	Healthy planting, weedy
		Unplanted Landscape		4	Weedy, missing mulch in some areas
	Gen	eral Trees		5.0	
		Park Trees		5	
	Gen	eral Hardscape		5.0	
		Concrete	gray, integral color	5	
		Pavers	tile veneer paving	5	
		Other:	permeable paving	5	
	Gen	eral Irrigation		3.0	
				2	Turf issues signify irrigation functionality
		System operation		2	problems
		System type (drip / spray)			Spray for turf, drip for planting
		Controller		4	Present, no visible issues
	Gen	eral Lighting		5.0	
		System Operation	metal, phillips domus	5	
	Gen	eral Barriers		5.0	
		Fences / Walls	wood split rail	5	
		Bollards	metal, black, removable	5	
	Gen	l leral Signage	Terriovable	5.0	
		Park ID	corten steel	5	
		Park Rules	metal, new graphic	5	
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	No visible issues, appears functional

		et	Type / Material	Condition	Inventory Date: 5/19/21	
	īτ				Time:	
_	Amenity				Field Notes (all italicized noted are notes	
Park	Am	Asset	Ma	Cor	from maintenance staff)	
			·			
Coff	ey Pa	rk		4.7		
	Picn	ic Areas		5.0		
		Tables*	concrete	5		
		Barbecues	concrete/metal	5		
		Surfacing	concrete	5		
		Trash Receptacles	metal	5		
		Shade Trees		5		
	Fitn	ess Equipment		5.0		
		Type: cluster/par course	par course			
		Equipment*	dynamic and fixed	5		
		Surfacing	concrete	5		
		ground		5.0		
		Equipment*		5		
		Curb	wood fiber	5		
		Surfacing		5		
		Surfacing	concrete			
		Furnishings	wood top rail, metal wire	5		
		Barriers		5		
		Signs		5		
		Shade Structures (not assessed)	shade sails		Present	
		Drainage		5	No observable problems	
	Dog	Park		5.0		
		Surfacing	wood mulch	5		
		Drinking Fountain	spout/bowl filler	5		
		Barriers*	wood rail, metal mesh	5		
		Benches	concrete	5		
		Signage		5		
	Art			N/A		
		Structure (not assessed)			Present, water droplet shaped seats	
		Mural / Mosaic (not assessed)			Present, on ground adjacent to water droplet shaped seats	
	* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk					
Note: Limited assessment items are highlighted in grey						

	1	İ		<u> </u>	Inventory Data: 5/19/21 7/7/21
	~	÷	a	Condition	Inventory Date: 5/18/21, 7/7/21
	snit		e/ eri		Time:
Park	Amenity	Asset	Type / Materia	ů O	Field Notes (all italicized noted are notes
	◄	٤	⊢ 2	0	from maintenance staff)
Colg	olgan Creek Park			3.3	
018				0.0	General Site Observations: Quaint park, large
					shade trees
	Gen	leral Furnishings		3.4	
		Tables	Metal	4	
		Bike Racks	Metal	4	
		Drinking Fountains	Concrete/Metal	4	
		Trash/Recycling Receptacles		1	Deficient
		Other: Tree Grates	Metal	4	
	Gen	eral Landscape		3.3	
		Turf		4	
		Non-Turf Ornamental Landscape		3	Weedy, overgrown
		Unplanted Landscape		3	Weedy
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete	Gray/Integral Color	4	
	Gen	eral Irrigation		4.0	
		System operation		4	No observable problems
		System type (drip / spray)			Turf appears to have complete coverage
		Controller		4	
	Gen	eral Lighting		2.0	
		System Operation		2	Not LED, appears to be in good condition
	Gen	eral Barriers		3.0	
		Bollards	Metal/Concrete	3	Visibly worn, crooked
	Gen	eral Signage		3.5	
		Park ID	Wooden	4	
		Park Rules	metal	3	Legibility issues due to age
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	Clogged with debris
	Picn	nic Areas		4.0	
		Tables*	Metal	4	
		Surfacing	Integral Color	4	
		Water Source		4	

X	Amenity	et	Type / Material	Condition	Inventory Date: 5/18/21, 7/7/21 Time: Field Notes (all italicized noted are notes	
Park	Am	Asset	Type / Mater	Con	from maintenance staff)	
	-		· -			
Colg	an Cr	reek Park		3.3		
	Play	ground		2.0		
		Equipment*	Tot and Youth	2	Needs repair, excessive wear	
		Curb		4	Normal, no issues	
		Surfacing	Sand	2	Excessive weeds, low elevation	
		Surfacing	Rubber	3	Worn, minor cracking	
		Furnishings	Metal benches	3	Broken mounting	
		Barriers	Metal clad fence around tot	3	Deterioration	
		Signs		1	Deficient	
		Water play	Spigot	1	Broken handle	
		Shade Structures (not assessed)		1		
		Drainage		1	No observable problems	
	Spo	rts Field / Court 1		4.3		
		Sport Type:	Basketball		Half court	
		Surfacing*	Grey Concrete	5	Smooth	
		Striping	White paint	4	Minor fading	
		Equipment	Backboard, hoop, net	4	Normal wear	
		Furnishings	Metal table	4	Single table, normal wear, no issues	
	Trai	ls		2.0		
		Surfacing*	Asphalt	2	Deterioration	
		Barriers	Bollards	3	Paint chipping, visibly worn	
* Th	* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk					
	Note: Limited assessment items are highlighted in grey					

				<u> </u>	Inventory Date: 7/7/21	
	Σ	Asset	Type / Material	ion	Inventory Date: 7/7/21 Time: 4:30 - 4:50pm	
	eni			dit	Field Notes (all italicized noted are notes	
Park	Amenity		Type / Materi	Condition		
–	٩	4	⊢ ∠	0	from maintenance staff)	
Com	stock	Mall Park		3.4		
Com	SLUCE			5.4	General Site Observations: Main path into	
					most neighboring buildings & parking	
					garage, a lot of tree liter, suspicious activity	
					occurring in darker areas/corners near	
					parking garage	
	Gen	eral Furnishings		4.0		
		Trash/Recycling Receptacles	metal	4		
	Gen	eral Landscape		3.0		
		Non-Turf Ornamental Landscape		3		
<u> </u>		eral Trees		4.0		
		Park Trees		4		
		eral Hardscape		3.0		
	Gen	Concrete		3.0	Uneven throughout	
	Gon	eral Irrigation		1.0		
					Function questionable	
		System operation System type (drip / spray)	c prov	1		
		Controller	spray	1	Not found, no observable problems	
	Gan	eral Lighting		3.0		
		System Operation		3.0	Multiple lights missing	
		eral Barriers		4.0	Multiple lights missing	
			cost walls, concrete			
		Fences / Walls Bollards	seat walls, concrete metal	4		
			metai			
		eral Signage	motal	4.0		
		Park Rules	metal	4		
	Gen	eral Drainage Culvert		4.0		
		Curvert Curb and Gutter		4		
		Drain inlet		4	No observable problems	
	\A/at	er Feature				
<u> </u>	vval	Mechanical water feature	concrete fountain	3.5 3	Operating fine, no observable problems	
┣──		Surfacing*		3 4		
	Art					
<u> </u>		Mural (Masais (not account)		N/A	Masais hanshas an sita	
		Mural / Mosaic (not assessed)			Mosaic benches on site	
* Th	The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk					
	Note: Limited assessment items are highlighted in grey					
INOLE	אטנב. בוווונבע מספסווופות ונפוווס מופ וווצווווצוונפע ווו צופץ					

	1			_	Inventory Date: 5/19/21
	ity		a	ior	Time: Morning
_	eni	et	e / teri	Condition	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	Son	from maintenance staff)
<u> </u>		· · · · · · · · · · · · · · · · · · ·		0	
Cour	rthou	i ise Square		4.7	
cou				4.7	General Site Observations: Large clean plaza
					in the heart of downtown
	Gen	leral Furnishings		4.7	
<u> </u>		Benches	Metal	5	
		Tables	Metal	5	
-		Bike Racks	Metal	5	
		Drinking Fountains	Metal with bottle filler	4	
		Trash/Recycling Receptacles	Metal	4	
		Other:	Metal Tree grates	5	
	Gen	eral Landscape		5.0	
		Turf		5	
		Unplanted Landscape		5	
	Gen	eral Trees		5.0	
		Park Trees		5	
	Gen	eral Hardscape		5.0	
		Concrete		5	
		Pavers		5	
		Decomposed Granite / Gravel		5	
	Gen	eral Irrigation		5.0	
		System operation		5	No observable problems
		System type (drip / spray)			Recent installation
		Controller		5	Presumed City standard
	Gen	eral Lighting		4.0	
	1	System Operation		4	
	Gen	eral Barriers		4.0	
		Fences / Walls	Concrete seat wall	4	
		Bollards		4	
	Gen	eral Signage		5.0	
		Park ID		5	
	Gen	eral Drainage		5.0	
		Culvert		5	
		Curb and Gutter		5	New, no observable problems
		Drain inlet		5	New, no observable problems
		Swales / Stormwater Infrastructure		5	
	Gen	eral Structures		4.0	
		Sheds		4	Site-built kiosks

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 5/19/21 Time: Morning Field Notes (all italicized noted are notes from maintenance staff)
Cour	thou	se Square		4.7	
	Park	king Lot		5.0	Parking meters
		Lighting		5	
		Surfacing*		5	
		Signage		5	
		Striping		5	Metal medallions
	Art			N/A	
		Structure (not assessed)			Present
* Th	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated	asset v	vith an asterisk
Note	: Lim	ited assessment items are highlighted in g	grey		

					Inventory Date: 7/7/21
	ity		ial	tio	Time: 2:30 - 2:52pm
×	eni	Amenity Asset Type / Material	Condition	Field Notes (all italicized noted are notes	
Park	Am	Ass	Ma	C	from maintenance staff)
	-				,
Cook	c Sch	ool Park		3.1	
					General Site Observations: Park was filled
					with people using playground and dog park,
					dog owners bring their own furnishings and
					leave them in park, clean overall, safe
					environment
	Gen	eral Furnishings		2.0	
		Tables	Metal	3	Vinyl coating peeling
		Drinking Fountains			Removed 10 years ago
		Trash/Recycling Receptacles	Plastic	1	Deficient
	Gen	eral Landscape		3.0	
		Turf		3	Patchy
		Non-Turf Ornamental Landscape		3	
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		3.0	
		Concrete		3	Lifting and cracking throughout
	Gen	eral Irrigation		3.5	
		System operation		3	No observable problems
		System type (drip / spray)	Spray		Spray
		Controller		4	No observable problems
	Gen	eral Barriers		4.0	
		Fences / Walls	Chainlink	4	
	Gen	eral Signage		2.0	
		Park Rules	Metal	2	
	Gen	eral Drainage		3.3	
		Curb and Gutter		3	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		3	

	ty		a	Condition	Inventory Date: 7/7/21 Time: 2:30 - 2:52pm
_	Amenity	et	Type / Materia	ldit	Field Notes (all italicized noted are notes
Park	Am	Asset	Type / Materi	Con	from maintenance staff)
-				•	
Cool	c Sch	ool Park		3.1	
	Play	ground		3.0	
		Equipment*	Metal	3	Heavily weathered
		Curb	Concrete	3	Back of play structures, curb is lifting and separating
		Surfacing	Sand	4	
		Surfacing	Rubber	4	
		Furnishings	Coated metal Benches	3	
		Barriers	Chainlink	4	
		Signs		1	Deficient
		Shade Structures (not assessed)			Old
		Drainage		4	No observable problems
	Dog	Park		3.2	
		Surfacing	Turf	3	Patchy
		Surfacing	Concrete	4	Water turned off
		Drinking Fountain	Steel	3	
		Barriers*	Chainlink	4	
		Trash Receptacles	Steel	1	Deficient
		Signage	Metal	4	
		ng of the amenity shall not exceed the rat	-	isset v	vith an asterisk
Note	e: Lim	ited assessment items are highlighted in §	grey		

				-	Inventory Date: 6/22/21
	tγ		a	ion	Time: 3:16 - 3:46pm
	eni	et	e / :eri	Condition	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	Con	from maintenance staff)
<u> </u>	1	7		0	
Dau	enha	l uer Park		4.4	
Duu					General Site Observations: Relatively new
					park, topography adds interest, play area
					fenced off for some reason
<u> </u>	Gen	eral Furnishings		4.3	
		Benches	Metal	4	
<u> </u>		Tables	Metal	4	
		Drinking Fountains		5	New, 1 out of 2 not operational
<u> </u>		Trash/Recycling Receptacles		4	
<u> </u>	Gen	eral Landscape		4.0	
├──		Turf		4	
		Non-Turf Ornamental Landscape		4	
		Unplanted Landscape	Gravel	4	Landscape strip
<u> </u>	Gon	eral Trees	Clavel	5.0	
<u> </u>	Gen	Park Trees		5.0	
	Gon	eral Hardscape		4.0	
	Gen	Concrete		4.0	
		Decomposed Granite / Gravel		4	
<u> </u>	Gon	eral Irrigation		5.0	
<u> </u>	Gen	System operation		5	No observable problems
<u> </u>		System type (drip / spray)	Spray	5	
		Controller	Spidy	5	No observable problems
	Gon	eral Lighting		5.0	
		System Operation	Metal	5	Domus
	Gon	eral Barriers	Wietai	4.0	
	Gen	Fences / Walls	Split Rail	4.0	
		Fences / Walls 2	Block wall	4	Retaining wall
		·	DIOCK Wall	-	
		Fences / Walls 3	Boulder Retaining Wall	4	
		Handrails	Metal	4	
		Bollards	Metal	4	
	Gen	eral Signage		4.5	
		Park ID	Stone and Metal	5	
		Park Rules	Metal	4	Blocked by shrubs
	Gen	eral Drainage		5.0	
		Culvert		5	No observable problems
		Curb and Gutter		5	
		Drain inlet		5	No observable problems
		Swales / Stormwater Infrastructure		5	

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/22/21 Time: 3:16 - 3:46pm Field Notes (all italicized noted are notes from maintenance staff)
Dau	anhai	uer Park		4.4	
Dau		ground		4.4	
	гау	Equipment*	Metal	5	
		Curb	Concrete	5	
		Surfacing	Rubber	5	
		Surfacing	Sand	5	
		Furnishings		4	
		Barriers	Metal	4	No gates, minor damage
		Signs		1	Lacking signage
		Shade Structures (not assessed)			Present
		Drainage		5	No observable problems
	Spor	rts Field / Court 1		3.3	
		Sport Type:	Basketball		
		Surfacing*	Concrete	5	
		Field striping		1	None
		Equipment		4	Metal net broken
		Drainage			No observable problems
* Th	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated a	asset w	vith an asterisk
		ited assessment items are highlighted in g	-		

	ĺ			_	Inventory Date: 7/8/21
	₹		a	ion	Time: 1:25 - 1:48pm
	eni	t .	e / :eri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	Condition	from maintenance staff)
	٩	₹	F 2		
Dol	leo P	lark		3.4	
Delv				5.4	
					General Site Observations: Observed a few
					individuals utilizing shaded seating areas on
					site, park provides perimeter fencing
					throughout, signs of encampments near
					picnic area & behind the bocce courts
	Gen	eral Furnishings		2.3	
		Tables	wood and metal	4	
		Drinking Fountains		2	
		Trash/Recycling Receptacles	plastic	1	Deficient
	Gen	eral Landscape		3.0	
		Turf		4	Dry patches
		Non-Turf Ornamental Landscape		3	Significant gaps
		Unplanted Landscape		2	Little to no mulch
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		3.0	
		Concrete		3	Sidewalk needs repair
	Gen	eral Irrigation		3.0	
		System operation		3	Coverage issues
		System type (drip / spray)	spray		
		Controller		3	No observable problems
	Gen	eral Lighting		4.0	
		System Operation		4	
	Gen	eral Barriers		4.0	
		Fences / Walls	wood, split rail	4	
		Fences / Walls 2	wood, picket	4	
		Bollards	metal	4	
	Gen	eral Signage		3.0	
		Park Rules		3	
		Kiosks	wood	3	
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	
		Swales / Stormwater Infrastructure		4	
	Gen	eral Structures		N/A	
		Shade Structures (not assessed)	Steel, Trellis		Present

				_	Inventory Date: 7/8/21
	ť		a	•—	Time: 1:25 - 1:48pm
~	eni	et	e / :eri		Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	UO U	from maintenance staff)
<u> </u>	4	۷	μ	0	
DeM	leo P	ark		3.4	
		ic Areas		3.2	
		Tables*	metal	4	
		Barbecues	metal	3	
		Surfacing	concrete	4	
		Trash Receptacles	plastic	1	Deficient
		Shade Trees			
			concrete, drinking		Nie obere oble en ble en
		Water Source	fountain	4	No observable problems
	Play	ground		4.0	
		Equipment*		4	
		Curb	concrete	4	
		Surfacing	sand	4	
		Surfacing	rubber	4	
		Furnishings	concrete	4	Seat wall facing playground
		Signs	metal	4	
		Drainage		4	No observable problems
		rts Field / Court 1		3.3	
		Sport Type:	Basketball		
		Surfacing*	concrete	4	
		Striping		2	
		Equipment	metal hoop	3	Very rusted
		Drainage		4	No observable problems
	Spo	rts Field / Court 2		3.9	
		Sport Type:	Bocce		
		Surfacing*	oyster shell	4	Minor leaf litter and holes
		Surfacing*	concrete	4	
			curb/bumper,	4	
		Equipment	concrete and wood	4	
		Barriers	chainlink	4	Some peeling paint
		Furnishings	wood benches	3	Heavily worn
		Signage	metal	4	
		Drainage		4	No observable problems
		ing of the amenity shall not exceed the rat	-	asset v	vith an asterisk
Note	e: Lim	nited assessment items are highlighted in g	rey		

<u> </u>	İ				Inventory Data 7/9/21
	≥		a	ion	Inventory Date:7/8/21 Time: 1:55 - 2:00pm
	enit	t.	e / :eri	diti	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	Condition	from maintenance staff)
<u> </u>	4	۲	F 6	0	
DeT	urk P	l Park		3.4	
Der				5.4	
					General Site Observations: Sections of the
					landscape have died and some sections of
					turf are full of weeds, safe environment
	Gen	eral Furnishings		2.8	
		Benches	wood	2	Missing plank
		Tables	metal	4	
		Bike Racks	metal	4	
		Trash/Recycling Receptacles	plastic	1	Deficient
	Gen	eral Landscape		4.0	
		Turf		4	
		Non-Turf Ornamental Landscape		4	
		Unplanted Landscape		4	
	Gen	ieral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		3.0	
		Concrete		4	
		Decomposed Granite / Gravel		2	
	Gen	eral Irrigation		3.5	
		System operation		3	Coverage issues
		System type (drip / spray)	spray		
		Controller		4	No observable problems
	Gen	eral Lighting		3.0	
		System Operation	metal	3	Acorn lights
	Gen	eral Signage		3.0	
		Park Rules	metal	2	Illegible, poor location
		Kiosks	composite	4	
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
	<u> </u>	Drain inlet		4	
		Swales / Stormwater Infrastructure		4	
	Parl	king Lot		3.8	
		Wheel stops	concrete	4	
		Lighting		4	
		Surfacing*	asphalt	4	
		Signage	metal	4	
		Striping		3	Faded

Park	Amenity	Asset	Type / Material	Condition	Inventory Date:7/8/21 Time: 1:55 - 2:00pm Field Notes (all italicized noted are notes from maintenance staff)
DeTu	urk Pa	ark		3.4	
	Dog	Park		3.3	
		Surfacing	packed earth	3	Very weedy
		Drinking Fountain	metal	4	Spigot
		Barriers*	ornamental metal	4	
		Benches	composite	4	
		Trash Receptacles	plastic	1	Deficient
		Signage	Metal	4	At main entrance
* Th	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated a	asset v	vith an asterisk
Note	e: Lim	ited assessment items are highlighted in g	rey		

	Ì				Inventory Date: 5/19/21
	₹		a	ior	Time: Early afternoon
_	eni	et	e / ter	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	Condition	from maintenance staff)
┝━	`				
Doy	le Co	mmunity Park		3.1	
<u> </u>					General Site Observations: Spacious park,
					decent number of park users during time of
					second visit, who were all there for the dog
					park
	Gen	eral Furnishings		3.0	
		Benches	Wood, Composite	4	
		Tables		2	
		Drinking Fountains		4	Multiple fountains at ballfield, mixed
		Drinking Fountains		4	condition, some turned off
		Flag Pole		4	
		Trash/Recycling Receptacles		1	Deficient, plastic bins
	Gen	eral Landscape		3.0	
		Turf		4	
		Unplanted Landscape		2	Little to no mulch
	Gen	eral Trees		4.0	
		Park Trees		4	
		Trees in Natural Areas		4	
	Gen	eral Hardscape		3.5	
		Asphalt		3	
		Concrete		4	
	Gen	eral Irrigation		4.0	
		System operation		4	No observable problems
		System type (drip / spray)	Spray		
		Controller		4	
	Gen	eral Lighting		3.0	
		System Operation	Luminaire on wood post	3	Mixed luminaries on wood posts, not LED
	Gen	eral Barriers		3.0	
		Fences / Walls	Chainlink	3	
		Fences / Walls 2	Split Rail	4	
		Handrails		2	
		Bollards		3	
	Gen	eral Signage		4.5	
		Park Rules		5	
		Traffic Signs		4	
	Gen	eral Drainage		3.0	No observable problems
		Culvert		3	
		Curb and Gutter		3	
		Drain inlet		3	

	İ				Inventory Data: E/10/21
	≥		a	on	Inventory Date: 5/19/21
	init	t t	eri		Time: Early afternoon
Park	Amenity	Asset	Type / Material	o u o	Field Notes (all italicized noted are notes
٦	◄	۸	<u>⊢ 2</u>	Ŭ	from maintenance staff)
Dov		mmunity Park		3.1	
-		eral Structures		2.0	
	Gen			2.0	Present, needs paint, 1" gaps between
		Pedestrian Bridges (not assessed)			boards
					In rough shape, shed at baseball field with
		Sheds		2	decaying roof
		Restrooms (not assessed)			present
	Dicn	lic Areas		4.0	
	FICI	Tables*	Wood and Metal	4.0	
		Kiosk / sign	Concrete	5	
		Barbecues	Metal	4	
			Metal	4	
		Specialty Barbecue		3	
		Surfacing	Concrete pads in packed earth	4	
		Trash Receptacles		4	
		Shade Trees		4	
	Park	king Lot		2.0	
		Wheel stops		3	
		Lighting		4	
		Surfacing*		2	Pavement in horrible shape
		Signage		2	
		Striping			
	Fitn	ess Equipment		1.0	
		Type: cluster/par course	Par Course, wood		Decaying posts, unstable
		Equipment*		1	
	Play	ground		3.3	
		Equipment*		4	
		Curb	Plastic	2	Temporary curb
		Surfacing	Sand	2	Weedy, low
		Surfacing	PIP Rubber	2	Cracking, excessive wear
		Furnishings		4	
		Barriers	Chainlink	4	
		Signs		5	
		Drainage		3	No observable problems

	Amenity		Type / Material	Condition	Inventory Date: 5/19/21 Time: Early afternoon
Park	ner	Asset	Type / Materi	pu	Field Notes (all italicized noted are notes
Ра	An	As	Υ Υ	ပိ	from maintenance staff)
<u> </u>		mmunity Park		3.1	
	Spo	rts Field / Court 1		3.0	
		Sport Type:	Baseball		
		Surfacing*	Infield	3	Weedy near backstop
		Surfacing*	Turf	4	
		Field striping	Temporary		
		Equipment	Foul poles, dugouts	3	
		Barriers		3	Wood deteriorating on backstop
		Furnishings	Bleachers	3	
		Field Lighting		4	
		Irrigation		4	No observable problems
		Drainage		4	No observable problems
	Spo	rts Field / Court 2		3.9	
		Sport Type:	Horseshoe		
		Surfacing*	Turf	4	
		Surfacing*	Concrete	4	
		Equipment	Wooden stops	4	
		Barriers	Chainlink	4	
		Furnishings		3	
		Signage			
		Irrigation		4	No observable problems
		Drainage		4	No observable problems
	Dog	Park		3.0	
		Surfacing	Natural/Mulch	4	
		Drinking Fountain		4	Spigot
		Barriers*	Chainlink	3	
		Trash Receptacles			Deficient
		Signage		5	
		Kiosk		4	
* Th	e rati	ing of the amenity shall not exceed the rat	ing of the lowest rated a	asset v	vith an asterisk
Note	e: Lim	nited assessment items are highlighted in g	grey		

					Inventory Date: 6/23/2021
	ity		<u>a</u>	lior	Time: 4:15pm - 4:30pm
×	eni	et	e / ter	hdit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	Condition	from maintenance staff)
-					
East	side I	Park		3.2	
					General Site Observations: Very small park,
					observed a few people using the playground,
					clean overall
		eral Furnishings		2.0	
		Drinking Fountains	Concrete	3	Turned off
		Trash/Recycling Receptacles		1	Deficient
	Gen	eral Landscape		2.7	
		Turf		3	Minor spotting
		Non-Turf Ornamental Landscape		3	
		Unplanted Landscape		2	
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		3.5	
		Asphalt		2	Major cracking and uneven
		Concrete		5	
	Gen	eral Irrigation		4.5	
		System operation		4	No observable problems
		System type (drip / spray)	Spray		
		Controller		5	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	
	Gen	eral Barriers		3.0	
		Bollards		3	Missing one
		eral Signage		2.0	
		Park Rules	Metal	2	
	Gen	eral Drainage		4.5	
		Curb and Gutter		5	
		Drain inlet		4	

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/23/2021 Time: 4:15pm - 4:30pm Field Notes (all italicized noted are notes from maintenance staff)			
	<mark>side F</mark>			3.2				
		ground		3.0				
		Equipment*		3	Excludes new structure			
		Curb	Concrete	2				
		Surfacing	Mulch	4				
		Surfacing	Sand	3				
		Furnishings	Metal, Composite and Wood	4	Bench and table			
		Surfacing*	Rubber	4				
		Drainage		3	No observable problems			
	The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk Note: Limited assessment items are highlighted in grey							

	Ì				Inventory Date:
	tγ		a	itio	Time:
	eni	et	e / :eri		Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	U N	from maintenance staff)
<u> </u>	4	7	F 2	<u>۲</u>	
Fina	li Par	k		3.9	
					General Site Observations: Reasonably new
					park, a lot of people on site during a
					weekday using playground, overall very well
					maintained
	Gen	eral Furnishings		4.8	
		Benches		5	
		Tables		5	
		Bike Racks		5	
		Trash/Recycling Receptacles	Metal	4	
	Gen	eral Landscape		2.7	
		Turf		4	
		Non-Turf Ornamental Landscape		2	
		Unplanted Landscape		2	
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
		Decomposed Granite / Gravel		4	
		eral Irrigation		4.0	
		System operation		4	Some possible coverage issues
		System type (drip / spray)	Drip		
		Controller		4	No observable problems
		eral Lighting		4.0	
		System Operation	Metal	4	
	Gen	eral Barriers	-	4.0	
		Fences / Walls	Split Rail/Wood	4	
	Gen	eral Signage		4.0	
<u> </u>		Park ID		5	Front corner of park
<u> </u>		Park Rules		3	Missing Spanish version
<u> </u>	Gen	eral Drainage		4.0	
<u> </u>		Culvert		4	
		Curb and Gutter		4	
<u> </u>		Drain inlet		4	
		Swales / Stormwater Infrastructure		4	

			_	Ę	Inventory Date:			
	ity		/ rial	itio	Time:			
Park	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized noted are notes			
Ра	An	As	лу Т	ပိ	from maintenance staff)			
Fina	li Par	k		3.9				
	Picn	ic Areas		3.8				
		Tables*		5				
		Barbecues		4				
		Surfacing	DG. With Stabilizer	4	Uneven weathering			
		Trash Receptacles		4				
		Shade Trees		1	Only 1 dead plum tree for entire picnic area			
		Shade Structures (not assessed)			Present			
		Water Source		5				
	Play	ground		4.0				
		Equipment*	Metal/Plastic	5				
		Curb		4				
		Surfacing	wood fiber	2	Uneven/thin surface at both structures			
		Furnishings	Bench/Composite	5				
		Barriers	Chainlink	3	At tot lot fabric falling off support			
		Drainage		5	No observable problems			
	Dog	Park		4.0				
		Surfacing	Mulch	3				
		Barriers*	Chainlink	4				
		Benches	Composite	5				
		Trash Receptacles	Metal	4				
		Signage	Metal	5				
	Com	nmunity Gardens		4.0				
		Barriers*	Chainlink	4	Gate fabric pushed in			
		Surfacing	D.G.	4				
		Irrigation		4	None found, hose bib only			
		Raised Beds		4				
		Furnishings	Composite	5				
* -	·				ith on estavial			
		ing of the amenity shall not exceed the rat	-	asset v	vith an asterisk			
ινοτε	ote: Limited assessment items are highlighted in grey							

	1			Ì	Inventory Data:
	≥		a	Condition	Inventory Date:
	init	r r	eris		Time:
Park	Amenity	Asset	Type / Material	ouc	Field Notes (all italicized noted are notes
<u> </u>	◄	Δ	μŻ	Ŭ	from maintenance staff)
Finle	ev Co	mmunity Park		3.1	
	Í	•			
					General Site Observations: Highly used park,
					all amenities were in use on a weekday
					morning, safe environment overall
	Gen	eral Furnishings		3.8	
		Benches	Wood//Metal	3	
		Bike Racks	Metal	4	Paint chipping
		Drinking Fountains		4	
		Trash/Recycling Receptacles	Metal	4	
	Gen	eral Landscape		3.0	
		Turf		4	
		Non-Turf Ornamental Landscape		3	
		Unplanted Landscape		2	No mulch
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		3.3	
		Concrete		4	
		Pavers		2	Wavy, uneven, dipping
		Other: Stage in Sheltered Picnic Area	Concrete	4	
	Gen	eral Irrigation		3.5	
		System operation		4	Old irrigation clocks - update
		System type (drip / spray)	Spray		Spray, popups -rotors
		Controller		3	Old irrigation clocks
	Gen	eral Lighting		3.0	
		System Operation		3	
	Gen	eral Barriers		4.0	
		Fences / Walls	Wood	4	Split rail
		Fences / Walls 2	Stone	4	At picnic area #1 (low r. wall)
		Entrance/Maintenance Gates	Metal	4	At back parking lot
		Handrails		4	At Stony Pt. Road, at Sidewalk
		Bollards		4	
	Gen	eral Signage		2.5	
		Park ID			No Park ID sign
	<u> </u>	Park Rules		3	
		Interpretive Signage		2	1 missing, 1 illegible, 1 ok

	İ	1		6	Inventory Date:
	ť		ial	_	Time:
_	eni	et	Type / Materia		Field Notes (all italicized noted are notes
Park	Amenity	Asset	A Z		from maintenance staff)
_					
Finle	ev Co	mmunity Park		3.1	
	1	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	
	Gen	eral Structures		3.0	
		Shade Structures (not assessed)			Gazebos
		Sheds	Wood	3	Rot on roof, near tennis courts
	1	Restrooms (not assessed)			On-site
	Picr	nic Areas		3.0	
		Tables*		3	
		Specialty Barbecue	Metal/Concrete	3	Some rust, warped metal edging, grill lid not
					level
<u> </u>		Surfacing	Pavers		Uneven, tree roots uplifting
		Trash Receptacles		3	
		Shade Structures (not assessed)	Wood gazebo	<u> </u>	Present, no observable problems
<u> </u>		Water Source	Stucco	4	Drinking fountain
	Picr	nic Areas (in Turf)		3.0	
		Tables*	Concrete with wood	3	Worn
		Barbecues	Metal	3	Rusted post
		Surfacing	Concrete	4	
		Trash Receptacles	Metal	4	
		Shade Trees		4	
	Parl	king Lot		3.0	
		Wheel stops		5	
		Lighting		3	No observable problems
		Surfacing*	Asphalt	3	Cracking in middle
		Signage		4	
		Striping		4	
	Play	/ground		2.0	
<u> </u>		Equipment*		2	For accessibility
 		Curb	Concrete	4	
		Surfacing	Sand	4	
		Surfacing	Rubber	1	Pulling back at transition bridge, rubber might not meet fall requirements
		Furnishings	Wood	3	Bench
	1	Signs		1	No rules sign
	İ	Drainage		3	

					Inventory Date:		
	Amenity	Asset	a	ion	Time:		
~			Type / Material	dit	Field Notes (all italicized noted are notes		
Park	Ĩ,			Condition	from maintenance staff)		
<u>a</u>	4	٩	F 2				
Finle	ev Co	mmunity Park		3.1			
	-	rts Field / Court 1		3.0			
	_	Sport Type:	Tennis/Pickleball				
		Surfacing*	Court Surfacing	3	Crack at edges, outside play area		
		Surfacing*	Pavers	3	Exercise sitting area		
		Field striping		4			
		Equipment		4			
		Barriers	Chainlink	3	Windscreen is ripped and moldy		
		Furnishings	Composite	5	Bench		
		Signage		4	Has a mix of new and old signs		
		Drainage		4	No observable problems		
	Spo	rts Field / Court 2		3.8			
		Sport Type:	Basketball Court				
		Surfacing*	Asphalt	4			
		Striping		4			
		Equipment		4	Hoops		
		Furnishings	bench, wood	3	Trash receptacle is deficient		
	Spo	rts Field / Court 3		2.0			
		Sport Type:	Horseshoe				
		Surfacing*	D.G.	2	Weedy and heavily worn		
		Surfacing*	Sand	2	Border deteriorating and weedy		
		Equipment	Wood	4	Backboards appear to be new		
		Barriers	Chainlink	3	Fence is warped, gate (D) needs ADA kick		
		Darriers	Chairmink		plate		
		Drainage		4	No observable problems		
	Spo	rts Field / Court 4		2.7			
		Sport Type:	Volleyball				
		Surfacing	Sand	3	Significant weed growth		
		Surfacing	Concrete	4	Missing netting, attachments missing		
		Equipment*		1			
		ing of the amenity shall not exceed the rat	-	asset v	vith an asterisk		
Note	ote: Limited assessment items are highlighted in grey						

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/24/2021 Time: 1:45PM - 1:58PM Field Notes (all italicized noted are notes from maintenance staff)
Flat	Rock	Park		2.6	
	Itoek			2.0	General Site Observations: Hard to identify as park, overall trail is maintained and highly used by locals
	Gen	eral Furnishings		1.0	
		Trash/Recycling Receptacles		1	Deficient
	Gen	eral Landscape		2.0	
		Natural Landscape		2	Dense growth with significant weeds
	Gen	eral Trees		4.0	
		Trees in Natural Areas		4	
	Gen	eral Hardscape		2.0	
		Asphalt		2	
	Gen	eral Barriers		2.0	
		Bollards	Steel	2	2 curb ramps missing bollards
	Gen	eral Signage		3.0	
		Wayfinding	Metal	5	Creek trail signage
		Park Rules		1	Deficient
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	
		ng of the amenity shall not exceed the rat	-	asset v	l vith an asterisk
Note	e: Lim	ited assessment items are highlighted in g	grey		

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/24/2021 Time: 2:30pm - 2:58pm Field Notes (all italicized noted are notes from maintenance staff)
Four	th an	d Farmers Creek Trail		3.2	
					General Site Observations: Entrance off of Farmers Ln was difficult to locate, Stair down to trail was unsafe and deteriorating, large amounts of accumulated trash and dumping near bridge, possible encampments within site
	Gen	eral Landscape		3.0	
		Natural Areas		3	
	Gen	eral Trees		4.0	
		Trees in Natural Areas		4	
	Gen	eral Barriers		4.0	
		Fences / Walls	Stone	4	
	Gen	eral Drainage		4.0	
	Trail	ls		1.0	
		Trailhead Sign/Kiosk	Wood	3	
		Distance Marker	Metal	5	Attached to kiosk
		Surfacing*		1	Impassible dirt and concrete chunks
		Barriers	Wood	1	Wooden handrails have collapsed at railroad ties on stairs at fourth and farmers entrance
		ng of the amenity shall not exceed the rat ited assessment items are highlighted in g	-	l asset v	vith an asterisk

					Inventory Dates C/24/2021
	λ		le	on	Inventory Date: 6/24/2021
	nit	Asset	liti	Time: 11:30AM - 11:50AM	
Park	Amenity	Asset	Type / Mater	Condition	Field Notes (all italicized noted are notes
ä	A	A:	ĘΣ	Ŭ	from maintenance staff)
Fran	ces N	lielsen Open Space		2.3	
					General Site Observations: Dense noxious
					weeds throughout park. Some spots have
					fire damage.
	Gen	eral Landscape		1.0	
		Natural Areas		1	Dense noxious weeds
	Gen	eral Trees		3.0	
		Trees in Natural Areas		3	Fire damaged, especially in southern parcel
	Gen	eral Barriers		3.0	
		Bollards	Steel	3	Unpainted Pipe w/cap
	Gen	eral Signage		1.0	
		Park Rules		1	Deficient
	Gen	eral Drainage		3.0	
		Culvert		3	
		Curb and Gutter		3	
		Drain inlet		3	
		Swales / Stormwater Infrastructure		3	
	Gen	eral Structures		N/A	
		Pedestrian Bridges (not assessed)			Present
	Trai	ls		3.0	
		Trailhead Sign		3	Creek sign
		Surfacing*	Asphalt	3	Noxious weeds growing in asphalt cracks and buried in duff
		ng of the amenity shall not exceed the rat		asset v	vith an asterisk
Note	e: Lim	ited assessment items are highlighted in g	grey		

	1				Inventory Date: 6/24/2021
	₹		a	ion	Time: 10:50AM - 11:29AM
×	eni	et	e / teri	Condition	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material		from maintenance staff)
Fran	rances Nielsen Ranch Park			3.6	
					General Site Observations: Few people
					observed on site during a weekday, well
					maintained overall
	Gen	neral Furnishings		3.0	
		Tables	Wood	3	
		Drinking Fountains	Concrete	3	Turned off, No observable problems
		Trash/Recycling Receptacles	Composite	3	
	Gen	neral Landscape		3.3	
		Turf		4	
		Non-Turf Ornamental Landscape		3	
		Unplanted Landscape		2	
		Natural Areas		4	
	Gen	neral Trees		4.0	
		Park Trees		4	
		Trees in Natural Areas		4	
	Gen	neral Hardscape		4.0	
		Asphalt		4	
		Concrete		4	
	Gen	neral Irrigation		4.0	
		System operation		4	No observable problems
		System type (drip / spray)	spray		
		Controller		4	No observable problems
	Gen	neral Barriers		3.3	
		Fences / Walls	Chainlink	3	
		Handrails	Metal	4	
		Bollards	Metal	3	
	Gen	neral Signage		3.5	
		Park ID	Wood	4	On Lake Park Dr. signs of fading
		Park Rules	Metal	3	Shows weathering
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	
	Picn	nic Areas		3.0	
		Tables*	Wood	3	
		Barbecues	Steel	3	Major rusting
		Surfacing	Concrete	4	Minor cracking

	Amenity	et	Type / Material	Condition	Inventory Date: 6/24/2021 Time: 10:50AM - 11:29AM
Park	Ame	Asset	Type / Mater	Con	Field Notes (all italicized noted are notes from maintenance staff)
Fran	ces N	lielsen Ranch Park		3.6	
	Play	ground		3.3	
		Equipment*	Plastic and Metal	4	
		Surfacing	Sand	4	
		Surfacing	Rubber	4	
		Furnishings	Benches/Composite	4	Mix match
		Signs		1	Deficient
		Drainage		3	No observable problems
	Spo	rts Field / Court 1		4.0	
		Sport Type:	Basketball		
		Surfacing*	Asphalt	4	
		Equipment	Metal Hoop	4	
		Drainage		4	No observable problems
	Trai	ls		4.0	
		Trailhead Sign			Opportunities for additional connections to Kirk Ridge St.
		Surfacing*	Packed Earth	4	Also has metal headerboards
	Wat	er Feature		3.0	
		Barriers	Deck Railing/Wood	3	
		Lighting		3	
		Docks		3	
		Mechanical water feature*		3	Pond aerators, Pump for Lake Aerator
		Surfacing	Wooden Viewing Deck	3	
		Furnishings	Wood Bench	3	
		Dams (not assessed)			On site
		ng of the amenity shall not exceed the rat	-	sset v	vith an asterisk
Note	e: Lim	nited assessment items are highlighted in g	grey		

<u> </u>	İ		1		Investory Data (122/2021
	~		<u> </u>	uo	Inventory Date: 6/23/2021
	nit	t t	eria	liti	Time: 2:00pm - 2:50pm
Park	Amenity	Asset	Type / Materia		Field Notes (all italicized noted are notes
ă	Ā	Ň Ň	ĘΣ	Ŭ	from maintenance staff)
Fran	klin (Community Park		3.1	
					General Site Observations: Few people
					observed at park on weekday using
					playground, overall well maintained
	Gen	eral Furnishings		2.0	
		Drinking Fountains		3	Water turned off
		Trash/Recycling Receptacles		1	Deficient
	Gen	ieral Landscape		3.0	
		Turf		4	
		Non-Turf Ornamental Landscape		3	
		Unplanted Landscape		2	
	Gen	ieral Trees		4.0	
		Park Trees		4	
		eral Hardscape		3.0	
		Concrete		4	
<u> </u>					Moderate cracking, some stones falling off
		Amphitheater		2	wall, weed growth between cracks, no
				-	apparent drainage
	Gen	eral Irrigation		3.0	
		System operation		3	
		System type (drip / spray)	Spray		
		Controller		3	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	
		eral Barriers		4.0	
		Bollards		4	
	Gen	neral Signage		3.0	
		Park ID	Wood	4	On Franklin Rd., entire sign is leaning
		Park Rules		2	Poor location
<u> </u>	Gen	neral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
<u> </u>		Drain inlet		4	No observable problems
┣──		Swales / Stormwater Infrastructure		4	
<u> </u>	Gon	eral Structures		3.0	
┣──	Gen	Sheds	Wood	3.0	Rotten panels and roof
┣		Restrooms (not assessed)	vvoou	3	Present
		nestrooms (not assessed)	l		r i escut

				Í	Inventory Data: C/22/2021
	<u>></u>	Amenity Asset Type / Material	a	on	Inventory Date: 6/23/2021
	snit		diti	Time: 2:00pm - 2:50pm	
Park	me	ISSE	ype Aat	Condition	Field Notes (all italicized noted are notes
_	٩	4	F 2	0	from maintenance staff)
Fran	klin (Community Park		3.1	
	I	ic Areas		2.8	
		Tables*	Steel	3	1 missing
		Kiosk / sign	Metal	3	Noticeable weathering
		Barbecues	Metal	3	Broken grills near play area
		Surfacing	Packed Earth	3	Sand from play area gets in this area
		Trash Receptacles		1	Deficient
		Shade Trees		4	
	Park	king Lot		3.0	
		Lighting		3	No observable problems
		Surfacing*	Asphalt	3	moderate cracking
		Signage		4	
		Striping		2	Needs to be redone
	Play	ground		3.0	
		Equipment*		4	
		Curb		2	Buried or missing on west side
		Surfacing	Sand	2	Low sand
		Surfacing	Rubber	3	Peeling and cracks
		Furnishings	Bench	5	
		Barriers	Chainlink	4	Top rail bent at one section
		Signs		3	Poor location
		Water play		1	Not functioning
		Drainage		3	No observable problems
		rts Field / Court 1		4.0	
		Sport Type:	Soccer		
		Surfacing*	Turf	4	
		Surfacing*	Concrete	4	
		Equipment	Metal Goal	5	
		Furnishings	Steel Bleachers	4	
		Signage		4	
		Irrigation		4	Some spot issues
		Drainage		4	No observable problems

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/23/2021 Time: 2:00pm - 2:50pm Field Notes (all italicized noted are notes from maintenance staff)		
Fran	klin (Community Park		3.1			
	Spo	rts Field / Court 2		2.0			
		Sport Type:	Softball				
		Surfacing*	Asphalt	2			
		Surfacing*	Infield	4	Minor weeds		
		Striping	Outfield Turf	4			
		Equipment	Backstop/Wood & Chainlink	3	Wood deteriorating		
		Barriers	Chainlink	4			
		Furnishings	Bleachers/Bench/Woo d	4			
		Signage	Metal	4			
		Lighting		3			
		Irrigation		3	No observable problems		
		Drainage		3	No observable problems		
	* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk Note: Limited assessment items are highlighted in grey						

	ţ		Б	uo	Inventory Date: 6/22/21
	Amenity	st	Asset Type / Materia	Condition	Time: 2:45 - 3:00pm Field Notes (all italicized noted are notes
Park	me	Asset	Type / Mater	ŭ	from maintenance staff)
┣┻	A	A	⊢ ∠	0	from maintenance starry
Frav	el Lai	ne Open Space		2.8	
					General Site Observations: Trail is in bad
					condition
	Gen	eral Landscape		3.0	
					No noxious weeds present / areas of dense
					shrub growth, including Himalayan black
		Natural Areas		3	berry, privet, oak trees, willows. Planting
					strips adjacent to street are weedy and need
					mulch
	Gen	eral Trees		4.0	
		Park Trees			Natural Riparian
	Gen	eral Hardscape		1.0	
		Asphalt		1	Major buckling
	Gen	eral Irrigation		N/A	
		System operation			None observed
	Gen	eral Barriers		3.0	
		Fences / Walls	Split Rail	3	Worn
	Gen	eral Signage		N/A	
		Park ID			"Austin Creek"
	Gen	eral Drainage		3.0	No observable problems
		Curb and Gutter		3	
		Drain inlet		3	
		ng of the amenity shall not exceed the rat	-	asset v	vith an asterisk
Note	e: Lim	ited assessment items are highlighted in g	rey		

	İ			<u> </u>	Inventory Data: E/10/21
	iť			ion	Inventory Date: 5/19/21 Time: 2:20pm to 2:34pm
	en it	*	eri	diti	
Park	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized noted are notes
┣┻	◄	<pre></pre>	⊢ ∠	0	from maintenance staff)
From		Park		2.0	
Fren	nont	Park		2.9	General Site Observations:
					Coverage/irrigation issues throughout turf
	Con	l eral Furnishings		4.0	areas, park looks worn
	Gen		matalwood	4.0	
		Benches	metal, wood, composite wood	4	Some near new, some worn with graffiti
		Trash/Recycling Receptacles	Metal	4	Normal wear
	Gen	eral Landscape		2.5	
		Turf		2	Significant dieback, rehabilitation not expected
		Non-Turf Ornamental Landscape		3	Gaps, weedy
<u> </u>	Gen	eral Trees		4.0	
	001	Park Trees		4	
	Gon	eral Hardscape		3.3	
	Gen	Asphalt		2	
		Concrete		5	Major cracking
			briek odgo bando	3	
	Corr	Pavers	brick edge bands	3.0	Near entrance, new
	Gen	eral Irrigation			Dishaak
		System operation		2	Dieback
		System type (drip / spray)	spray for turf		
<u> </u>	•	Controller		4	Present, no visible issues
	Gen	eral Lighting		2.0	
		System Operation		2	Worn, few damaged
<u> </u>	Gen	eral Signage		3.0	
		Park ID	stone veneer monument	4	
		Park Rules	wood posts	2	Barely legible
	Gen	eral Drainage		3.0	No observable problems
		Culvert		3	
		Curb and Gutter		3	
		Drain inlet		3	
		Swales / Stormwater Infrastructure		3	
	Gen	eral Structures		N/A	
		Shade Structures (not assessed)	wood trellis		Present, normal view
	Wat	ter Feature		1.0	
		Lighting		1	
		Mechanical water feature	fountain	2	Dry, not operational
	1	Surfacing*		1	

Park	Amenity	Asset	Type / Material		Inventory Date: 5/19/21 Time: 2:20pm to 2:34pm Field Notes (all italicized noted are notes from maintenance staff)	
Fren	nont	Park		2.9		
	Art			N/A		
		Surfacing (not assessed)			Present	
		Structure (not assessed)	metal		Present, light wear	
* Th	* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk					
Note	e: Lim	ited assessment items are highlighted in g	grey			

				r	Inventory Data: 5/0/21 (incomplete) Deviait
	٢		Type / Material		Inventory Date: 5/8/21 (incomplete), Revisit
				Condition	7/8/21 Time: AM
_	Amenity	et			Field Notes (all italicized noted are notes
Park	4m	Asset Type / Materi	l o	from maintenance staff)	
-	4	7	– – –		General Site Observations: Decent number
					of park users for a weekday morning, overall
					well maintained
Galv	in Co	ommunity Park		3.5	
		•			
	Gen	eral Furnishings		4.0	
		Benches	wood	4	
		Tables	wood	4	
		Drinking Fountains		4	Water turned off
		Trash/Recycling Receptacles		4	
	Gen	eral Landscape		3.0	
		Turf		4	
		Unplanted Landscape		2	Weedy, little to no mulch
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		3.0	
		Asphalt		1	
		Concrete		4	
		Decomposed Granite / Gravel		4	
	Gen	eral Irrigation		4.0	
		System operation		4	
		Controller		4	
	Gen	eral Lighting		4.0	
		System Operation	Luminaire on wood post	4	
	Gen	eral Barriers		3.0	
		Fences / Walls	Split rail	3	
		Fences / Walls 2	Chain link	3	
		Bollards	wood and removable metal	3	
	Gen	eral Signage		4.0	
		Park Rules		4	
	Gen	eral Drainage		3.0	
		Culvert		3	
		Curb and Gutter		4	
		Drain inlet		3	
		Swales / Stormwater Infrastructure		2	
	Gen	eral Structures		2.0	
		Sheds	Wood storage shed	2	Latch broken, vandalized
		Restrooms (not assessed)			Present

				1	
			Type / Material		Inventory Date: 5/8/21 (incomplete), Revisit
	λ			Condition	7/8/21
	nit				Time: AM
Park	Amenity	Asset	Type / Materi	on o	Field Notes (all italicized noted are notes
ä	٩	A	ĘΣ	Ŭ	from maintenance staff)
					General Site Observations: Decent number
					of park users for a weekday morning, overall
					well maintained
Galv		mmunity Park		3.5	
	Picn	ic Areas		3.7	
		Tables*	Wood, metal	4	
		Kiosk / sign	Steel posts	4	
		Barbecues	Metal	4	
		Specialty Barbecue	Concrete, stone	2	Broken concrete, grill mechanisms
		Surfacing		4	
		Trash Receptacles	metal	4	
		Shade Trees		4	
	Park	sing Lot		3.0	
		Wheel stops		5	
		Lighting		3	
		Surfacing*		3	
		Signage		4	
		Striping		4	
	Play	ground		3.9	
		Equipment*		4	
		Curb		4	
		Surfacing	sand	3	Needs replenishment
		Surfacing	rubber	3	Worn, patched
		Furnishings	Wood, metal	4	
		Barriers		4	
		Signs		5	
		Drainage		4	No observable problems
	Spor	rts Field / Court 1		4.0	
		Sport Type:	Soccer	1	
		Surfacing*	Turf	4	
		Field striping	Temporary		
		Equipment	Goals	5	
		Furnishings	Wood	4	
		Irrigation*		4	Possible coverage issues
		Drainage		3	No observable problems

					Inventory Datas 5/8/21 (incomplete) Devisit
		÷	Type / Material		Inventory Date: 5/8/21 (incomplete), Revisit
	≥			Condition	7/8/21
	Amenity			diti	Time: AM
Park	Ű,	Asset	Type / Materi	u o	Field Notes (all italicized noted are notes from maintenance staff)
┣┻	◄	٩	⊢ ∠	0	General Site Observations: Decent number
					of park users for a weekday morning, overall
					well maintained
Galv	in Co	l ommunity Park		3.5	
Gaiv		rts Field / Court 2		4.0	
	Sho			4.0	Most courts ok but some could be
		Sport Type:	Tennis Courts (1-6)		resurfaced
		Surfacing*		4	
<u> </u>		Striping		4	
<u> </u>		Equipment	nets	4	
		· ·	Chain link		
		Barriers		4	
		Furnishings	benches	4	
		Signage		5	
		Lighting		4	No observable problems
	-	Drainage		4	No observable problems
	Spo	rts Field / Court 3		4.0	
		Sport Type:	Tennis Courts (7-8, 11-		
			12)		
		Surfacing*		4	
		Striping		4	
		Equipment	nets	4	
		Barriers	Chain link	5	
		Furnishings	benches	4	
		Drainage		4	No observable problems
	Spo	rts Field / Court 4		2.0	
		Sport Type:	Youth Tennis Courts (9- 10)		
		Surfacing*		2	
		Striping		4	
		Equipment	nets	3	
		Barriers	Chain link	4	
		Furnishings	benches	5	
		Signage		5	
		Lighting		4	No observable problems
		Drainage		4	No observable problems
	I	Diamage		+	

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 5/8/21 (incomplete), Revisit 7/8/21 Time: AM Field Notes (all italicized noted are notes from maintenance staff)
					General Site Observations: Decent number of park users for a weekday morning, overall well maintained
Galv		ommunity Park		3.5	
	Spo	rts Field / Court 5		4.0	
		Sport Type:	Baseball		
		Surfacing*	Turf	4	
		Surfacing*	Infield	5	
		Equipment		4	
		Barriers		4	
		Furnishings	benches, bleachers	4	
		Lighting		4	No observable problems
		Scoreboard		3	Function unknown
		Irrigation		4	No observable problems
		Drainage		4	No observable problems
	Dog	Park		3.4	No accessible seating
		Surfacing	Mulch/natural	4	
		Barriers*	Chain link	4	
		Benches	synthetic	5	
		Trash Receptacles	varies	2	Aluminum and site built wood
		Signage	varies	2	Wooden kiosk and steel kiosk
	Wat	er Feature	Casting Pool	3.5	
		Surfacing*	Concrete	4	
		Furnishings	Wooden picnic table	3	
* The	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated a	isset v	l vith an asterisk
-		ited assessment items are highlighted in g	-		

_	Amenity	et	Type / Material	Condition	Inventory Date:6/24/2021 Time: 2:00pm - 2:19pm Field Notes (all italicized noted are notes
Park	Ame	Asset	Type / Materi	Con	from maintenance staff)
	,				
Ham	pton	Woods Trail		2.9	
					General Site Observations: Hard to identify
					as park, overall trail is maintained and highly
					used by locals
		eral Furnishings		2.5	
		Trash/Recycling Receptacles		1	Deficient
		eral Landscape		3.0	
		Natural Areas		3	Some invasive weed growth
	Gen	eral Trees		4.0	
		Trees in Natural Areas		4	
	Gen	eral Irrigation		2.0	
		System operation		1	Appears to not be used
		System type (drip / spray)	Drip		
		Controller		3	No observable problems
	Gen	eral Barriers		3.0	
		Bollards	Steel	3	
	Gen	eral Signage		2.0	
		Park Rules		1	Deficient
		Interpretive Signage		3	
	Gen	eral Drainage		4.0	
	Gen	eral Structures		N/A	Not new / No observable problems
		Pedestrian Bridges (not assessed)	Metal and Wood		Present
	Trai	ls		3.0	
		Distance Marker		5	Creek trail signage
		Surfacing*	Asphalt	3	
		Mural / Mosaic (not assessed)			On-site throughout trail
		ng of the amenity shall not exceed the rat	-	asset v	vith an asterisk
Note	e: Lim	ited assessment items are highlighted in g	grey		

			1		Inventory Date: 6/22/21
	ľζ		ia	Condition	Time: 2:30 - 3:05pm
×	Amenity	et	e / ter	dit	Field Notes (all italicized noted are notes
Park	Am	Asset	Type / Material	Co	from maintenance staff)
			· _		
Harv	vest F	Park		3.3	
					General Site Observations: Looks relatively
					new, but amenities look worn/unkept. Play
					area surfacing missing
	Gen	eral Furnishings		4.0	
		Benches	Metal	4	
		Tables	Metal	4	
		Bike Racks	Metal	4	
		Drinking Fountains	Concrete	4	Not operational
		Trash/Recycling Receptacles	Metal	4	
	Gen	eral Landscape		2.7	
		Turf		4	
		Non-Turf Ornamental Landscape		3	Weedy, plants dead
		Unplanted Landscape		1	Extremely weedy
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		3.0	
		System operation		2	No observable problems
		System type (drip / spray)	Spray		
		Controller		4	No observable problems
	Gen	eral Lighting		4.0	
		System Operation		4	Look new
	Gen	eral Barriers		4.0	
		Fences / Walls	Split Rail	4	
	Gen	eral Signage		3.0	
		Park ID		4	
		Park Rules		2	
	Gen	eral Drainage		3.3	
		Curb and Gutter		2	
		Drain inlet		4	
		Swales / Stormwater Infrastructure		4	
	Picn	nic Areas		3.8	
		Tables*		4	
		Barbecues		4	
		Surfacing	DG	3	Significant weed growth
		Trash Receptacles		4	
		Shade Trees		4	
		Water Source		4	Not operating

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/22/21 Time: 2:30 - 3:05pm Field Notes (all italicized noted are notes from maintenance staff)
┝╩	1				
Harv	vest P	ark		3.3	
	Play	ground		2.9	
		Equipment*		4	
		Curb		4	
		Surfacing		1	Missing wood fiber
		Furnishings		4	
		Barriers		4	Gate missing
		Signs		1	Missing
		Shade Structures (not assessed)			Present, major tears and holes
		Drainage		2	No observable problems
	Dog	Park		1.0	
		Surfacing		1	Mulch, very weedy, major cracks and holes
		Barriers*		1	Gates not self closing, one missing handles
		Benches		4	
		Trash Receptacles		1	Deficient, plastic bin
		Signage		2	Not legible in some areas
		ng of the amenity shall not exceed the rat ited assessment items are highlighted in g		asset v	l vith an asterisk

	n Village Park General Furnishings Benches Tables Trash/Recycling Receptacles General Landscape Turf Unplanted Landscape	Wood Wood	3.6 2.7 3 4	General Site Observations: Tiny park, appears to be highly used by neighbors
	General Furnishings Benches Tables Trash/Recycling Receptacles General Landscape Turf		2.7 3	
(Benches Tables Trash/Recycling Receptacles General Landscape Turf		3	
(Benches Tables Trash/Recycling Receptacles General Landscape Turf		3	
(Benches Tables Trash/Recycling Receptacles General Landscape Turf		-	
-	Trash/Recycling Receptacles General Landscape Turf	Wood	4	
-	General Landscape Turf			
-	Turf		1	
			2.5	
(Unplanted Landscape		3	
C			2	No mulch
	General Trees		4.0	
	Park Trees		4	
(General Hardscape		4.0	
	Concrete		4	
C	General Irrigation		4.0	
	System operation		4	No observable problems
	System type (drip / spray)	Spray		
	Controller		4	No observable problems
C	General Lighting		N/A	
	System Operation			
(General Barriers		4.0	
	Fences / Walls	Chainlink	4	
C	General Signage		5.0	
	Park ID			No park ID
	Park Rules		5	At main entrance
C	General Drainage		4.0	
	Culvert		4	
	Curb and Gutter		4	
	Drain inlet		4	
	Swales / Stormwater Infrastructure		4	
F	Playground		2.0	
	Equipment*	Plastic	2	Tot-Lot, aged, excessive wear
	Curb/Seat wall	Concrete	4	
	Surfacing	Rubber	3	
	Surfacing	Sand	4	
	Signs		1	Deficient
	Drainage		4	No observable problems
	e rating of the amenity shall not exceed the rat : Limited assessment items are highlighted in g	-	ed asset v	vith an asterisk

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/24/2021 Time: 11:58AM - 12:22PM Field Notes (all italicized noted are notes
4	◄	۲	⊨ ≥	0	from maintenance staff)
Hidd	len V	alley Park		3.0	
nac				3.0	General Site Observations: Park felt safe and
					well maintained overall
	Gen	eral Furnishings		2.0	
		Drinking Fountains	Concrete	3	Turned off, no observable problems
		Trash/Recycling Receptacles		1	Deficient
	Gen	eral Landscape		2.0	
		Turf		3	Patchy
		Natural Areas		1	No mulch and noxious weeds in natural are
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		2.3	
	••••	Asphalt		1	Serious lifting
		Concrete		4	
		Decomposed Granite / Gravel	Gravel	2	
	Gen	eral Irrigation		3.0	
		System operation		3	Coverage problems on turf
		System type (drip / spray)	Spray		
		Controller		3	No observable problems
	Gen	eral Lighting		3.0	No observable problems
		System Operation		3	Only one by play area
		eral Barriers		3.0	
		Fences / Walls	Chain link	3	Weeds growing through
		Bollards	Wood and Steel	3	
		eral Signage		3.0	
		Park ID	Wood	3	Facing street, poor visibility
		Park Rules	Metal	3	Mix match
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	
		Swales / Stormwater Infrastructure		4	
	Gen	eral Structures		N/A	
		Pedestrian Bridges (not assessed)	Concrete and Wood		#1 Concrete, #2 Wood, planks on wood bridge are loose

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/24/2021 Time: 11:58AM - 12:22PM Field Notes (all italicized noted are notes from maintenance staff)
Hidd	en V	alley Park		3.0	
	Picn	ic Areas		3.6	
		Tables*	Steel	4	
		Barbecues	Metal	4	
		Surfacing	Concrete	5	
		Trash Receptacles	Plastic Bin	1	Deficient
		Water Source		4	
	Play	ground		3.4	
		Equipment*	Metal and Plastic	4	
		Curb	Concrete	3	Minor breaks and cracks
		Surfacing	Rubber	4	
		Surfacing	Sand	4	
		Furnishings	Metal	4	
		Signs		1	Deficient
		Drainage		4	
* The	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated a	asset v	vith an asterisk
Note	e: Lim	ited assessment items are highlighted in g	rey		

	i			İ	
	7		-	uo	Inventory Date: 6/23/21
	nit	ц.	eria	liti	Time: 8:15 - 11:30am
Park	Amenity	Asset	Type / Materia	Condition	Field Notes (all italicized noted are notes
P	A	A:	Ϋ́	ŭ	from maintenance staff)
How	arth	Community Park		3.2	
					General Site Observations: Quiet in the morning, quickly became extremely busy by 11am with a lot of families. Few unhoused folks hanging around the baseball field. Pickleball courts very crowded.
	Gen	eral Furnishings		3.2	
		Benches	Wood and Metal	4	
		Tables	Concrete, Composite, Metal	4	
		Bike Racks	Metal	4	
		Drinking Fountains	Weta	2	4 fountains, some good, others not
		Flag Pole		4	
		Trash/Recycling Receptacles	Metal, plastic	1	Deficient
	Gen	eral Landscape		3.3	
		Turf		4	
		Unplanted Landscape		2	Mowed, dead grass, mulch thin in some areas
		Natural Areas		4	
	Gen	eral Trees		4.0	
		Park Trees		4	
		Trees in Natural Areas		4	
	Gen	eral Hardscape		3.5	
		Asphalt		3	Some areas with severe cracking or unevenness
		Concrete		4	
	Gen	eral Irrigation		3.0	
		System operation		2	Coverage issues in lower lawn, patchy area
		System type (drip / spray)	Spray		
		Controller		4	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	No observable problems, not LED

				_	Inventory Data: 6/22/21
	Ň		a	uo	Inventory Date: 6/23/21
	'ni	r.	eri	diti	Time: 8:15 - 11:30am
Park	Amenity	Asset	Type / Materia	Condition	Field Notes (all italicized noted are notes
<u>م</u>	A	Δ	μ Έ	Ŭ	from maintenance staff)
	e ut h	Community Dark		3.2	
		Community Park eral Barriers		3.2 4.1	
	Gen		Calit Dail		
		Fences / Walls	Split Rail	4	
		Fences / Walls 2	Chainlink, 1/2" Fabric	4	
		Fences / Walls 3	Brick retaining wall	4	
		Guardrails	Wood and Wire	5	
		Fences / Walls 5	Metal	4	
		Entrance/Maintenance Gates	Metal, Brick	4	
		Handrails	Metal	4	By picnic area A -C
		Bollards	Metal	4	
	Gen	eral Signage		3.7	
		Park ID	Wood, Stone	4	
		Wayfinding	Metal	3	Entrance/exit sign slightly faded by carousel
		Park Rules		4	
		Traffic Signs		4	
		Interpretive Signage		3	Some illegible
		Kiosks		4	
	Gen	eral Drainage		3.0	
		Culvert		3	
		Curb and Gutter		3	
		Drain inlet		3	No observable problems
		Swales / Stormwater Infrastructure		3	
	Gen	eral Structures		3.0	
		Pedestrian Bridges (not assessed)			Present
		Sheds	Wood	3	Near pickleball courts, major wood rot,
		Sheus	wood	5	cracks, broken sections
		Restrooms (not assessed)			Present
		Animal Barn			Present
		Play Land Stone			Present
		Train Area			Present
		Carousel			Present
		Boathouse			Present

				_	Inventory Date: 6/23/21
	ť		<u>ਰ</u>	itio	Time: 8:15 - 11:30am
	eni	et	e / :eri		Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	UO I	from maintenance staff)
<u> </u>	1	4			
How	arth	Community Park		3.2	
		nic Areas (Party Areas A-D)		3.4	
		Tables*	Wood	4	One table severely worn, majority new
		Kiosk / sign	Metal & Plastic	3	Cloudy cover, dirt obscures legibility
		Barbecues	Concrete & Metal	4	
				-	
		Surfacing	Concrete & Turf	3	Minor crack on concrete, dirt patches on turf
		Shade Trees		3	Experiencing dieback
	Picn	iic Areas (Near Gazebo)		3.0	
		Tables*		3	Worn, lifting
		Kiosk / sign		4	
		Specialty Barbecue	Wood/Stone/Metal	2	Corroded, missing BBQ section, stone chipped/falling
		Surfacing	Concrete	4	
		Trash Receptacles		1	Deficient, none found
		Shade Trees		4	
		Water Source/Surfacing	Sink	3	Corroded, wood splitting
	Picn	ic Areas (Lower and Upper Oak)		3.1	
		Tables*	Wood	4	Large amounts of bird poop
		Kiosk / sign	Metal/Plastic	4	
		Barbecues		4	
		Specialty Barbecue	Concrete/Metal	3	Warped metal
		Surfacing		2	Mulch thin, weedy
		Trash Receptacles	Plastic	1	Deficient
		Shade Trees		4	
	Picn	ic Areas (Cypress Point)		3.0	
		Tables*	Wood	3	Some broken, large holes near bolts
		Kiosk / sign	Metal/Plastic	4	
		Barbecues		4	
		Surfacing	Mulch	2	
		Trash Receptacles		1	Deficient
		Shade Trees		4	
	Parl	king Lot		3.0	
		Wheel stops		4	
		Lighting		3	LED, older, only one light for all three lots
		Surfacing*	Concrete/Asphalt	3	Some cracking
		Signage		4	
		Striping		3	Extremely faded

	1	İ	ĺ	İ _	Inventory Date: 6/23/21
	₹		a	ion	Time: 8:15 - 11:30am
_	eni	G	e / teri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	Condition	from maintenance staff)
	~	· · · · · · · · · · · · · · · · · · ·			
Ном	l /arth	Community Park		3.2	
		ground 1 (Land of Imagination)		2.5	
	,	Equipment*		3	Some parts missing, signs of deterioration
		Curb		4	
		Surfacing	Sand/Mulch	1	Low, not functioning as intended
		Surfacing	Rubber	2	Large splitting, tears
		Furnishings	Wood/Mulch	3	Benches and trash receptacles are worn
		Barriers	Split Rail/Retaining Wall	4	
		Signs		1	Safety signs missing, archway appears to be in good condition
		Water play		1	Not functioning / operable
		Drainage		3	No observable problems
	Play	/ground 2		3.3	
	1 lay	Equipment*		4	
		Curb		4	
		Surfacing	Rubber	4	
		Surfacing	Mulch/Sand	2	Low
				2	Wood table has deep cracks, metal trash
		Furnishings		3	receptacle
		Barriers			Need barrier to protect from road
		Signs		3	Safety signs missing
		Drainage		3	No observable problems
	Spo	rts Field / Court 1		3.5	
		Sport Type:	Baseball / Softball		
		Surfacing*	Turf	5	
		Surfacing*	Infield Mix	4	
		Field striping		4	
		Equipment		3	Backstop worn, minor repairs needed
		Barriers	Chainlink	3	Leaning, crooked rails, midrails not connected
		Furnishings		3	Bleachers, signs of deterioration
		Signage		3	Illegible
		Lighting		3	No observable problems, can't confirm if LED
		Scoreboard		3	Trees slightly covering
				4	
				4	
		Signage Lighting		3 3 3 4	Illegible No observable problems, can't co LED

Apple Apple <th< th=""><th></th><th>Ì</th><th></th><th></th><th></th><th>Inventory Date: 6/23/21</th></th<>		Ì				Inventory Date: 6/23/21
Howarkt Community Park 3.2 Sports Field / Court 2 4.0 Sports Field / Court 2 4.0 Sports Field / Court 2 4.0 Striping 4.1 Equipment 4.1 Barriers 4.1 Uighting 4.0 No observable problems, appear to be LED Drainage 4.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sport Type: Tennis Surfacing* Sports Surfacing Surfacing* Sports Surfacing Surfacing* A Signage 4 Lequipment Net/Pole Barriers Chainlink Signage 4 Lequipment Net/Pole Lighting 4 No observable problems, appears to be LED, not new Drainage 4		₹		a	ion	
Howarkt Community Park 3.2 Sports Field / Court 2 4.0 Sports Field / Court 2 4.0 Sports Field / Court 2 4.0 Striping 4.1 Equipment 4.1 Barriers 4.1 Uighting 4.0 No observable problems, appear to be LED Drainage 4.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sport Type: Tennis Surfacing* Sports Surfacing Surfacing* Sports Surfacing Surfacing* A Signage 4 Lequipment Net/Pole Barriers Chainlink Signage 4 Lequipment Net/Pole Lighting 4 No observable problems, appears to be LED, not new Drainage 4	_	eni	et	e / teri	dit	
Howarkt Community Park 3.2 Sports Field / Court 2 4.0 Sports Field / Court 2 4.0 Sports Field / Court 2 4.0 Striping 4.1 Equipment 4.1 Barriers 4.1 Uighting 4.0 No observable problems, appear to be LED Drainage 4.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sport Type: Tennis Surfacing* Sports Surfacing Surfacing* Sports Surfacing Surfacing* A Signage 4 Lequipment Net/Pole Barriers Chainlink Signage 4 Lequipment Net/Pole Lighting 4 No observable problems, appears to be LED, not new Drainage 4	arl	Ĩ,	Ass	Vat	l o	
Sports Field / Court 2 4.0 Sport Type: Pickleball Surfacing* Sports Surfacing 4 Equipment 4 Barriers 4 Signage 5 Lighting 4 No observable problems, appear to be LED Drainage 4 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Surfacing* Substantial cracking / delamination on some Surfacing* Sports Surfacing Striping 4 Equipment Net/Pole Striping 4 Equipment Net/Pole Signage 4 Uighting 4 Equipment Net/Pole Signage 4 Lighting 4 Striping 4 Equipment Net/Pole Barriers Chainlink Barriers Chainlink Signage 4 Lighting 4 Surfacing* 4		~	· · · · · · · · · · · · · · · · · · ·			
Sports Field / Court 2 4.0 Sport Type: Pickleball Surfacing* Sports Surfacing 4 Equipment 4 Barriers 4 Signage 5 Lighting 4 No observable problems, appear to be LED Drainage 4 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Surfacing* Substantial cracking / delamination on some Surfacing* Sports Surfacing Striping 4 Equipment Net/Pole Striping 4 Equipment Net/Pole Signage 4 Uighting 4 Equipment Net/Pole Signage 4 Lighting 4 Striping 4 Equipment Net/Pole Barriers Chainlink Barriers Chainlink Signage 4 Lighting 4 Surfacing* 4	How	l /arth	Community Park		3.2	
Sport Type: Pickleball Minor cracking Striping 4 Minor cracking Equipment 4 Barriers 4 Signage 5 Lighting 4 Drainage 4 Sport Siefd / Court 3 1.0 Sport Siefd / Court 3 1.0 Sport Siefd / Court 3 1.0 Sport Siefd / Court 3 1.0 Suffacing* Sports Suffacing Suffacing* Sport Suffacing Striping 4 Equipment 8 Striping 4 Equipment Net/Pole Barriers Chainlink Signage 4 Lighting 4 Signage 4 No observable problems, appears to be LED, not new Barriers Chainlink Signage 4 Lighting 4 No observable problems, appears to be LED, not new Drainage 4 Mater Feature 3.5 Surfacing* Gravel, Natural & Asphalt No ob			· · · · · · · · · · · · · · · · · · ·		-	
Surfacing* Sports Surfacing 4 Minor cracking Striping 4 4 Equipment 4 4 Barriers 4 4 Signage 5 5 Lighting 4 No observable problems, appear to be LED Drainage 4 No observable problems Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 5 Sports Field / Court 3 5 Sports Surfacing* 1 Suffacing* Sports Surfacing 1 Suffacing* Sports Surfacing 1 Equipment Net/Pole 3 Signs of deterioration Barriers Chainlink 3 Bent pole, warped fabric Furnishings 4 No observable problems, appears to be LED, not new Drainage 4 No observable problems, appears to be LED, not new Drainage 4 No observable problems, appears to be LED, not new Drainage 4 Asphalt Asphalt has minor cracks				Pickleball		
Striping 4 Equipment 4 Barriers 4 Signage 5 Lighting 4 Drainage 4 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Syntacing* Tennis Surfacing* Sports Surfacing Striping 4 Equipment Net/Pole Striping 4 Equipment Net/Pole Signage 4 Signage 4 Signage 4 Striping 4 Signage 4 Signage 4 Signage 4 Value Net/Pole 3 Signage 4 Value No observable problems, appears to be LED, not new Drainage 4 Signage 4 Lighting 4 No observable problems, appears to be LED, not new Drainage 4 No observable problems, appears to be LED, not new Surfacing* Aco					4	Minor cracking
Equipment 4 Barriers 4 Signage 5 Lighting 4 Drainage 4 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sport Type: Tennis Suffacing* Sports Surfacing Striping 4 Equipment Net/Pole Striping 4 Equipment Net/Pole Signage 4 Vertifying 4 Striping 4 Equipment Net/Pole Signage 4 Uphting 4 Vertifying 4 No observable problems, appears to be LED, not new Drainage 4 No observable problems, appears to be LED, not new Drainage 4.0 Verter Feature 3.5 Barriers Metal 4 Asphalt 4 No observable problems, can't confirm if LED Docks 2 Dock damaged by low lake levels						
Barriers 4 Signage 5 Lighting 4 No observable problems, appear to be LED Drainage 4 No observable problems Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Systantial cracking / defamination on some Substantial cracking / defamination on some Suffacing* Sports Surfacing 1 Equipment Net/Pole 3 Signs of deterioration Barriers Chainlink 3 Bent pole, warped fabric Furnishings 4 No observable problems, appears to be LED, not new Drainage 4 No observable problems, appears to be LED, not new Drainage 4 No observable problems, appears to be LED, not new Drainage 4 No observable problems, appears to be LED, not new Drainage 4.0 No observable problems Trails 4.0 No observable problems Daringe 4.1 No observable problems Daringe 4.1 No observable problems, can't confirm if LED Datramps 4.2 Suphalt					4	
Signage 5 Lighting 4 No observable problems, appear to be LED Drainage 4 No observable problems Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Sports Field / Court 3 1.0 Surfacing* Sports Surfacing Surfacing* Sports Surfacing Striping 4 Equipment Net/Pole Barriers Chainlink Signage 4 Lighting 4 Signage 4 Drainage 4 Signage 4 Kurpishings 4 Surfacing* 4 Signage 4 Drainage 4 Drainage 4 Signage 4 Lighting 4 Drainage 4 No observable problems, appears to be LED, not new Drainage 4.0 Surfacing* 4.0 Surfacing* 5 Barriers Metal			· · ·		4	
Lighting 4 No observable problems, appear to be LED Drainage 4 No observable problems Sports Field / Court 3 1.0 Sport Type: Tennis Surfacing* Sports Surfacing Striping 4 Equipment Net/Pole Barriers Chainlink Signage 4 Lighting 4 No observable problems, appear to be LED Signage 4 Lighting 4 Surfacing* Sports Surfacing Signage 4 Lighting 4 Drainage 4 Drainage 4 No observable problems, appears to be LED, not new Drainage 4 No observable problems, appears to be LED, not new Drainage 4.0 Surfacing* Gravel, Natural & Asphalt Asphalt 4 No observable problems, can't confirm if LED Docks 2 Bock damaged by low lake levels Boat ramps 4 Surfacing* Concrete						
Sports Field / Court 3 1.0 Sport Type: Tennis Surfacing* Sports Surfacing Surfacing* Sports Surfacing Striping 4 Equipment Net/Pole Barriers Chainlink Signage 4 Lighting 4 Drainage 4 Surfacing* Gravel, Natural & Asphalt Surfacing* Metal Mater Feature 3.5 Barriers Metal Lighting 3.5 Drainage 4 No observable problems Trails 4.0 Surfacing* Gravel, Natural & Asphalt Water Feature 3.5 Barriers Metal Lighting 3 Surfacing* Concrete Asphalt 4 No observable problems, can't confirm if LED Docks 2 Dock damaged by low lake levels Boat ramps 4 Surfacing* Concrete 4 Dams (not assessed) Present <tr< td=""><td></td><td></td><td></td><td></td><td></td><td>No observable problems, appear to be LED</td></tr<>						No observable problems, appear to be LED
Sports Field / Court 3 1.0 Sport Type: Tennis Surfacing* Sports Surfacing Surfacing* Sports Surfacing Striping 4 Equipment Net/Pole Barriers Chainlink Signage 4 Lighting 4 Drainage 4 Surfacing* Gravel, Natural & Asphalt Surfacing* Metal Mater Feature 3.5 Barriers Metal Lighting 3.5 Drainage 4 No observable problems Trails 4.0 Surfacing* Gravel, Natural & Asphalt Water Feature 3.5 Barriers Metal Lighting 3 Surfacing* Concrete Asphalt 4 No observable problems, can't confirm if LED Docks 2 Dock damaged by low lake levels Boat ramps 4 Surfacing* Concrete 4 Dams (not assessed) Present <tr< td=""><td></td><td></td><td>Drainage</td><td></td><td>4</td><td>No observable problems</td></tr<>			Drainage		4	No observable problems
Sport Type: Tennis Sustantial cracking / delamination on some curbs, not playable. Major crack, surface deterioration in play area Striping 4 Equipment Net/Pole 3 Signs of deterioration Barriers Chainlink 3 Bent pole, warped fabric Ighting 4 Drainage 4 Vater Feature 3.5 Barriers Metal Ighting 3.5 Drainage 4 No observable problems, can't confirm if LED Docks 2 Docks 2 Boat ramps 4 Surfacing* 4 Surfacing * Concrete Boat ramps 4 Drainsge 4 Docks 2 Dock 2 Docks 2 Dock damaged by low lake levels Boat ramps 4 Dams (not assessed) Metal, Wood Metal, Wood 4 Furnishings Metal, Wood Metal, Wood 4 Furnishings Metal, Wood Metal, Wood		Spo	-		-	
Surfacing* Sports Surfacing Substantial cracking / delamination on some curbs, not playable. Major crack, surface deterioration in play area Striping 4 Equipment Net/Pole 3 Barriers Chainlink 3 Bent pole, warped fabric Image 4 1 Signage 4 1 Image 4 1 Drainage 4 1 Surfacing* 4 1 Surfacing* 4 1 Surfacing* 4 1 Surfacing* 4 1 Instruct 1 1 1 Surfacing* 1 4 1 Motoservable problems, appears to be LED, not new 1 1 Matrix 4 1 1 Mutation on some cacks 3 1 1 Mutation on some cacks 3 1 1 Instruct 4 1 1 1 Instruct 5 1 1 1 Mutation on some cacks 3 1 1				Tennis		
Surfacing*Sports Surfacing1curbs, not playable. Major crack, surface deterioration in play areaStriping44EquipmentNet/Pole3Signs of deteriorationBarriersChainlink3Bent pole, warped fabricFurnishings44Lighting4No observable problems, appears to be LED, not newDrainage4No observable problemsTrais4.0Surfacing*Gravel, Natural & Asphalt4Surfacing*Metal4Docks2Dock damaged by low lake levelsBoat ramps4No observable problems, can't confirm if LEDDocks2Dock damaged by low lake levelsBoat ramps4PresentSurfacing*Concrete4FurnishingsMetal, Wood4Surfacing*Concrete4Surfacing*Concrete4Surfacing*Concrete4Surfacing*Concrete4Surfacing*Metal, Wood4FurnishingsMetal, Wood4Surfacing*Concrete4Surfacing*Concrete4Surfacing*Concrete4Surfacing*Concrete4Surfacing*Concrete4Surfacing*Concrete4Surfacing*Concrete4Surfacing*Concrete4Surfacing*Concrete4Surfacing*Concrete4 <t< td=""><td></td><td></td><td></td><td></td><td></td><td>Substantial cracking / delamination on some</td></t<>						Substantial cracking / delamination on some
Image: Stripping Image: Stripping <td< td=""><td></td><td></td><td>Surfacing*</td><td>Sports Surfacing</td><td>1</td><td></td></td<>			Surfacing*	Sports Surfacing	1	
Striping4EquipmentNet/Pole3Signs of deteriorationBarriersChainlink3Bent pole, warped fabricFurnishings44Signage44Lighting4No observable problems, appears to be LED, not newDrainage4No observable problemsTrails4.04.0Water Feature3.5BarriersMetal4Lighting3.5BarriersMetal4Docks2Dock damaged by low lake levelsBoat ramps44Surfacing*Concrete4Dams (not assessed)Metal, Wood4Dams (not assessed)FurnishingsMetal asterisk* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk			5			
Barriers Chainlink 3 Bent pole, warped fabric Furnishings 4 Signage 4 Lighting 4 Drainage 4 Trails 40 Surfacing* 40 Water Feature 35 Barriers Metal 4 Ighting 35 Water Feature 35 Barriers Metal 4 Surfacing* Metal 4 Surfacing* Metal 4 Barriers Metal 4 Surfacing* Metal 4 Barriers Metal 4 Surfacing* Concrete 4 Docks 2 Dock damaged by low lake levels Surfacing* Concrete 4 Surfacing* Concrete 4 Dams (not assessed) Present Metal, Wood 4 Present * The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk			Striping		4	
Barriers Chainlink 3 Bent pole, warped fabric Furnishings 4 Signage 1 4 Ighting 1 No observable problems, appears to be LED, not new Drainage 4 No observable problems, appears to be LED, not new Trit 4 No observable problems Vaturals 4 No observable problems Water Feature 4.0 Asphalt Barriers Metal 4 Ighting Metal 4 Vater Feature 3.5 Asphalt Ighting Metal 4 No observable problems, can't confirm if LED Ighting 1 Surfacing* Metal 4 No observable problems, can't confirm if LED Docks 2 Dock damaged by low lake levels Ighting 1 Concrete 4 4 Surfacing* Concrete 4 4 Ightings Metal, Wood 4 4 Ightings Metal, Wood 4 4 Ightings Metal, Wood 4 4			Equipment	Net/Pole	3	Signs of deterioration
Signage 4 Signage 4 Lighting 4 Drainage 4 Trails 4.0 Surfacing* 4.0 Water Feature 3.5 Barriers Metal 4 Lighting 3.5 Docks 2 Dock damaged by low lake levels Boat ramps 4 No observable problems, can't confirm if LED Surfacing* Concrete 4 Docks 2 Dock damaged by low lake levels Surfacing* Concrete 4 Docks 4 Present Doms (not assessed) 4 Present * The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk 1				Chainlink	3	Bent pole, warped fabric
Image A No observable problems, appears to be LED, not new Image A No observable problems Image A No observable problems Image A No observable problems Image A No observable problems Image Image A No observable problems Image Image A Asphalt Image Image Image A Image Image Image A Image Image Image Image Image Image Image Image Image Image Image Image Image Image Image Image Image Image Image			Furnishings		4	
Lighting Image			Signage		4	
Trails 4.0 Surfacing* Gravel, Natural & Asphalt 4 Water Feature 3.5 Barriers Metal 4 Lighting 1 No observable problems, can't confirm if LED Docks 2 Dock damaged by low lake levels Boat ramps 4 4 Surfacing* Concrete 4 Surfacing* Metal, Wood 4 Docks Metal, Wood 4 Dams (not assessed) Metal, Wood 4 * The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk 4			Lighting		4	
Trails 4.0 Surfacing* Gravel, Natural & Asphalt 4 Water Feature 3.5 Barriers Metal 4 Lighting 1 No observable problems, can't confirm if LED Docks 2 Dock damaged by low lake levels Boat ramps 4 4 Surfacing* Concrete 4 Surfacing* Metal, Wood 4 Docks Metal, Wood 4 Dams (not assessed) Metal, Wood 4 Trails of the amenity shall not exceed the rating of the lowest rated asset with an asterisk 4			Drainage		4	No observable problems
Surfacing*Asphalt4Asphalt has minor cracksWater Feature3.53.5BarriersMetal4LightingMetal4Docks3No observable problems, can't confirm if LDBoat ramps2Dock damaged by low lake levelsSurfacing*Concrete4Surfacing*Concrete4FurnishingsMetal, Wood4Dams (not assessed)Metal, Wood4The rativg of the amenity shall not exceed the rating of the lowest rated asset with an asterisk		Trai	ls		4.0	
Barriers Metal 4 Lighting Integration of the amenity shall not exceed the ratios of the lowest rated asset with an asterisk No observable problems, can't confirm if LD Docks Docks 2 Dock damaged by low lake levels Boat ramps 4 Dock damaged by low lake levels Surfacing* Concrete 4 Integration of the lowest rated asset with an asterisk			Surfacing*	,	4	Asphalt has minor cracks
Lighting No observable problems, can't confirm if LED Docks 2 Boat ramps 2 Surfacing* Concrete 4 Surfacings Metal, Wood 4 Dams (not assessed) Metal, Wood 4 Dams of the amenity shall not exceed the rating of the lowest rated asset with an asterisk		Wat	ter Feature		3.5	
Lighting Image: Second sec			Barriers	Metal	4	
Boat ramps 4 Surfacing* Concrete 4 Furnishings Metal, Wood 4 Dams (not assessed) Present Dams (not assessed) Image: Concrete in the amenity shall not exceed the rating of the lowest rated asset with an asterisk			Lighting		3	•
Surfacing* Concrete 4 Furnishings Metal, Wood 4 Dams (not assessed) Present Dams of the amenity shall not exceed the rating of the lowest rated asset with an asterisk			Docks		2	Dock damaged by low lake levels
Furnishings Metal, Wood 4 Dams (not assessed) Present The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk			Boat ramps		4	
Dams (not assessed) Present Image: Dams (not assessed) Image: Dams (not assessed) Image: The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk			Surfacing*	Concrete	4	
* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk			Furnishings	Metal, Wood	4	
			Dams (not assessed)			Present
Note: Limited assessment items are highlighted in grey	* Th	e rati	ing of the amenity shall not exceed the rat	ting of the lowest rated	asset v	vith an asterisk
	Note	e: Lim	nited assessment items are highlighted in a	grey		

				1	Inventory Date: 6/22/2021
	Y		a	o U	Inventory Date: 6/23/2021
	hin	Asset Type / Materia	eri	diti	Time: 3:28pm - 3:42pm
Park	Amenity		Condition	Field Notes (all italicized noted are notes	
4	A	۲۲	<u> </u>	U	from maintenance staff)
		t Daula		2.2	
Hum	ibola	lt Park		3.2	
					General Site Observations: Few people
<u> </u>	C			2.5	observed on site, clean & safe overall
	Gen	eral Furnishings		2.5	
		Benches		4	
		Trash/Recycling Receptacles		1	Deficient
	Gen	eral Landscape		2.3	
		Turf		3	Bald Spot
		Non-Turf Ornamental Landscape		2	Need to be redone
		Unplanted Landscape		2	
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		3.0	
		Concrete		3	
	Gen	eral Irrigation		3.0	
		System operation		3	No observable problems
		System type (drip / spray)	Spray		
		Controller		3	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	
	Gen	eral Signage		3.3	
		Park ID		4	Attached to kiosk
		Park Rules		3	Poor location
		Kiosks	Wood	3	Missing cover on bulletin board
	Gen	eral Drainage		4.0	
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
	Gen	eral Structures		3.0	
		Sheds	Wood	3	Near playground, panels near bottom deteriorating

			_	Ę	Inventory Date: 6/23/2021
	liity	Condition	Time: 3:28pm - 3:42pm		
ž	Amenity	Asset	Type / Material	pu	Field Notes (all italicized noted are notes
Park	An	As	۶۳ ۲	ပိ	from maintenance staff)
Hum	bold	t Park		3.2	
	Play	ground		3.9	
		Equipment*	Metal/Plastic	4	
		Curb	Concrete	4	
		Surfacing	Sand	4	
		Surfacing	Rubber	4	
		Furnishings	Metal Bench	4	
		Barriers	Chainlink	4	
		Signs		3	On structure
		Surface*	Concrete	4	
		Drainage		4	No observable problems
* The	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated	asset v	vith an asterisk
Note	: Lim	ited assessment items are highlighted in g	grey		

	>		=	u	Inventory Date: 7/8/21
	nit,		/	iti	Time: 11:20AM - 11:51AM
Park	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized noted are notes
Ра	Ar	As	ĻΣ	č	from maintenance staff)
laca	ha Da			2.2	
Jaco	DS Pa	rk (Lincoln School)		2.3	
					General Site Observations: Large open turf field, has great potential if amenities were updated, safe environment overall
	Gen	eral Furnishings		1.0	
		Trash/Recycling Receptacles		1	Deficient
	Gen	eral Landscape		2.0	
		Turf		2	Lots of dieback, under irrigated
	Gen	eral Trees		4.0	
		Park Trees		4	Most trees on street are missing
	Gen	eral Hardscape		3.0	
		Concrete		3	Sidewalk
	Gen	eral Irrigation		3.0	
		System operation		2	
		System type (drip / spray)	spray		
		Controller		4	No observable problems
	Gen	eral Lighting		1.0	
		System Operation		1	No observable problems
	Gen	eral Barriers		3.0	
		Bollards	wood	3	Heavily worn
	Gen	eral Signage		2.5	
		Park ID	wood	3	
		Park Rules	metal	2	
	Gen	eral Drainage		2.5	
		Curb and Gutter		1	
		Drain inlet		4	No observable problems
		eral Structures		3.0	
		Sheds		3	
	Picn	ic Areas		2.0	
		Tables*	wood	2	Deteriorating
		Barbecues	metal	3	Major rusting
		Surfacing	concrete	4	
		Surfacing	pavers	3	Sinking at corners
		Trash Receptacles	plastic	1	Deficient
		Shade Trees		4	

<u> </u>									
	~		-	uo	Inventory Date: 7/8/21				
	nit	t	eria	liti	Time: 11:20AM - 11:51AM				
Park	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized noted are notes				
ä	Ā	A	ΈΣ	Ŭ	from maintenance staff)				
	he De	rk (Lincoln School)		2.3					
Jaco	1	rk (Lincoln School)							
	Рау	ground	ulastia and usatal	2.0					
		Equipment*	plastic and metal	2	Heavily worn and missing slide				
		Curb	concrete	4					
		Surfacing	rubber	1	Peeling tiles, tripping hazard				
		Surfacing	wood fiber	3	Low level				
		Surfacing	concrete	3	Low level				
		Signs		1	Deficient				
		Drainage		4	No observable problems				
	Spo	rts Field / Court 1		1.0					
		Sport Type:	Baseball						
		Surfacing*	Infield Mix	1	Extremely weedy, material missing				
		Surfacing*	Outfield, Turf	3	Patchy				
		Equipment	chanlink and wood, backstop	3	Heavily worn				
		Signage	metal	2	Not legible				
		Irrigation	spray	4	No observable problems, outfield only				
		Drainage		3	No observable problems				
	Spo	rts Field / Court 2		3.0					
		Sport Type:	Soccer						
		Surfacing*	turf	3	Patchy				
		Equipment	metal goal posts	5					
		Irrigation		4	Coverage issues				
		Drainage		3	No observable problems				
	Spo	rts Field / Court 3		2.0					
		Sport Type:	Volleyball						
		Surfacing*	turf	2	Dead				
		Equipment	metal posts	2	Missing net, tensioners missing and broken				
		Irrigation		3	Coverage issues				
		Drainage		4	No observable problems, inlet is extremely close to play space				
* Th	o rati	ng of the amenity shall not exceed the rat	ing of the lowest rated		vith an asterisk				
		-	-	asset V					
NOLE	ote: Limited assessment items are highlighted in grey								

	1				Inventory Date: 7/7/21		
	ty		a	ion	Time: 4:15 - 4:26pm		
_	eni	et	e / teri	dit	Field Notes (all italicized noted are notes		
Park	Amenity	Asset	Type / Materia	Condition	from maintenance staff)		
<u> </u>							
Jeju	Way			3.1			
					General Site Observations: Highly used for		
					those parked behind 4th St., possible		
					encampments in the evenings		
	Gen	eral Furnishings		4.0			
		Benches	wood	4			
		Trash/Recycling Receptacles	metal	4			
	Gen	eral Landscape		3.0			
		Non-Turf Ornamental Landscape		2			
		Unplanted Landscape		4			
	Gen	eral Trees		4.0			
		Park Trees		4			
	Gen	eral Hardscape		3.0			
		Concrete	aggregate	3			
	Gen	eral Irrigation		3.0			
		System operation		2	Broken heads, assume non operational		
		System type (drip / spray)	spray				
		Controller		4	No observable problems, not found		
	Gen	eral Lighting		3.0			
		System Operation		3			
	Gen	eral Signage		4.0			
		Park ID	metal	4	"Street sign"		
	Gen	eral Drainage		3.0			
		Drain inlet		2			
		Swales / Stormwater Infrastructure		4			
	Wat	er Feature		1.0			
		Lighting		4			
		Mechanical water feature*	concrete	1	Fountain on 4th St., water turned off		
	Art			N/A			
		Surfacing (not assessed)			Present		
<u> </u>		Structure (not assessed)			Present		
		Mural / Mosaic (not assessed)			Murals on a building		
L_							
		ng of the amenity shall not exceed the rat	-	d asset v	vith an asterisk		
Note	ote: Limited assessment items are highlighted in grey						

					Inventory Date:
	tγ		a	Condition	Time:
	eni	t .	e / :eri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	U U	from maintenance staff)
<u> </u>	4	₹	ΗZ	0	
lonn	inge	Park		3.0	
Jeini	ings			3.0	General Site Observations: Maintenance
					team on site, possible encampment in
					parking lot provided for park, overall safe
					environment with a lot of potential
	Gon	neral Furnishings		1.0	
	Gen	Trash/Recycling Receptacles	Plastic	1.0	Deficient
	Gon	eral Landscape	riastic	3.0	
	Gen				
	•			3	
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		4.0	
		System operation			Refer to sports fields
		System type (drip / spray)	Spray		
		Controller		4	No observable problems
	Gen	eral Barriers		3.3	
		Fences / Walls	Chainlink	2	Some sections need substantial repair
		Entrance/Maintenance Gates	Metal	4	
		Bollards		4	
	Gen	ieral Signage		2.0	
		Park Rules		2	Spanish signs missing
		eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	
	Gen	eral Structures		4.0	
		Sheds	Wood	4	Roof has mold
	Spo	rts Field / Court 1		1.0	
		Sport Type:	Softball		
		Surfacing*	Turf	1	Missing, weeds
		Surfacing*		1	Uneven surface, large dead patches
		Equipment	Wood	3	Wood needs replacement
		Barriers	Chainlink	3	Leaning posts & fabric
		Furnishings		3	Benches in dugout
		Signage	Metal	4	
		Irrigation		2	Extensive turf dieback
		Drainage		4	No observable problems

Amenity	Asset	Type / Material	Condition	Inventory Date: Time: Field Notes (all italicized noted are notes from maintenance staff)			
inge	Dork		2.0				
			3.0				
	Sport Type:	Soccer					
	Surfacing*	Turf	3				
	Equipment		4				
	Irrigation		2	Extensive dieback			
	Drainage		4	No observable problems			
* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk							
	ings Spoi	ings Park Sports Field / Court 2 Sport Type: Surfacing* Equipment Irrigation Drainage e rating of the amenity shall not exceed the rat	ings Park Sports Field / Court 2 Sport Type: Soccer Surfacing* Turf Equipment Irrigation Drainage	ings Park 3.0 Sports Field / Court 2 3.0 Sport Type: Soccer Surfacing* Turf Equipment 4 Irrigation 2 Drainage 4 e rating of the amenity shall not exceed the rating of the lowest rated asset v			

	1			_	Inventory Date: 5/18/2021
	₹		a	<u> </u>	Time: n/a
	eni	t .	e / :eri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	u o	from maintenance staff)
	٩	۷		0	
1111	iilliard Park General Furnishings			3.3	
Juin				3.3	General Site Observations: Artwork adds a
					unique character to the park
<u> </u>	Gon	oral Eurnishings		3.0	
	Gen		wood/ composite	5.0	
		Benches	wood slats	4	Some near new, some damaged
		Bike Racks		4	
		Drinking Fountains	concrete	1	Leaking not functioning
		Flag Pole	stone veneer	2	Stone veneer damaged
		Trash/Recycling Receptacles	metal	4	Normal wear
	Gen	eral Landscape		4.5	
		Turf		5	Vigorous, green
		Non-Turf Ornamental Landscape		4	Moderately weedy
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		2.5	
		Asphalt		3	Areas with cracking and lifting
		Pavers	stone pavers	2	Cracked, missing pavers
	Gen	eral Irrigation		4.5	
		System operation		4	No observable problems, grass is green
		System type (drip / spray)	spray at turf		
		Controller		5	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	Not LED
	Gen	eral Barriers		4.0	
		Fences / Walls	wood split rail	4	Normal wear
		Bollards		4	Near bridge, normal view
	Gen	eral Signage		2.5	
		Park ID	wood	2	Wood post rotting
		Wayfinding			
		Park Rules		3	Worn, not easily legible
	Gen	eral Drainage		3.0	
		Culvert		4	
		Curb and Gutter		2	
		Drain inlet		3	
	Gen	eral Structures		2.0	
		Pedestrian Bridges (not assessed)	pavement cracking		Present, not accessible, steep
		Sheds		2	

		I		_	Inventory Date: 5/18/2021
	tγ		a	ion	Time: n/a
~	eni	t di di di di di di di di di di di di di	e / :eri	Condition	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	Lo D	from maintenance staff)
<u>а</u>	1	۲		0	
uilli	ard F	l Park		3.3	
	Play	/ground		3.0	
		Equipment*		3	Ropes are deteriorating
		Curb		4	Normal wear
		Surfacing	rubber	3	Requires wear at edges
		Surfacing	sand	3	Elevation low
		Furnishings	wood slat bench	4	
		Barriers	wood post, metal clad	4	
		Signs		4	
		Water play	elephant spout	2	Not functioning, significant wear
		Drainage		4	No observable problems
	Spo	rts Field / Court 1		3.7	
	•	Sport Type:	Bocce		
		Surfacing*	Clay	5	
		Barriers	Frames	3	
		Furnishings	wood benches	5	
		Signage	kiosk	4	
		Scoreboard		1	Removed/missing
		Drainage		4	No observable problems
	Wat	ter Feature		4.0	
		Mechanical water feature*	stream	4	No observable problems
	Con	nmunity Gardens		3.0	
		Barriers*		3	
		Surfacing	Mulch / Packed Earth	2	Mulch thin, weedy
		Storage		4	
		Shade Structures (not assessed)			Present
		Irrigation		4	
		Raised Beds		2	
	Art			N/A	
		Surfacing (not assessed)	brick band around mural		Broken, missing pavers
		Structure (not assessed)	metal		1 at each end of park, normal wear
		Mural / Mosaic (not assessed)	floor painted mural		Faded, paint chipping
		ing of the amenity shall not exceed the r		sset v	vith an asterisk
ote	: Lin	nited assessment items are highlighted ir	ngrey		

Vec Vec Vec Vec Time: 10:17 - 10:47am Field Notes (all italicized noted are notes from maintance staff) Field Notes (all italicized noted are notes from maintance staff) Live Oak Park 2.9 General Site Observations: Observed a fee people on site using playground, clean an well maintained overall, safe & friendly environment General Furnishings 3.3 General Site Observations: Observed a fee people on site using playground, clean an well maintained overall, safe & friendly environment Benches (1) 4 Tables wood (1), composite (1) 4 Drinking Fountains concrete 4 Tarsh/Recycling Receptacles plastic 1 Deficient General Iandscape 3.3 Turf 4 Under irrigated Non-Turf Ornamental Landscape 2 Very weedy, no mulch General Trees 4.0 Very weedy, no mulch General Hardscape 3.0 Uneven and lifting General Hardscape 3.0 Uneven and lifting General Hardscape 3.0 System type (drip / spray) Spray System type (drip / spray) Spray No observable problems General Lighting <th>r</th> <th>i</th> <th></th> <th>1</th> <th>i</th> <th></th>	r	i		1	i	
Live Oak Park 2.9 Live Oak Park 2.9 General Furnishings 3.3 Benches (1) Tables wood (1), composite (1) Tables (1) Tables wood (1), composite (1) Tables (1) Tables wood (1), composite (1) Tables (1) Tables wood (1), composite (1) Tables (1) Tables wood (1), composite (1) Mon-Turf Fountains concrete Turf 4 Non-Turf Ornamental Landscape 3.3 Turf 4 Non-Turf Ornamental Landscape 4 Very weedy, no mulch (2) General Hardscape 3.0 Concrete 3 Unplanted Landscape 4.0 Park Trees 4.0 General Hardscape 3.0 Concrete 3 General Hardscape 3.0 System operation 2 System operation 3.0 System Operation 3.0 Sy		>		_	uo	Inventory Date: 7/8/21
Live Oak Park 2.9 Live Oak Park 2.9 General Furnishings 3.3 Benches (1) Tables wood (1), composite (1) Tables (1) Tables wood (1), composite (1) Tables (1) Tables wood (1), composite (1) Tables (1) Tables wood (1), composite (1) Tables (1) Tables wood (1), composite (1) Mon-Turf Fountains concrete Turf 4 Non-Turf Ornamental Landscape 3.3 Turf 4 Non-Turf Ornamental Landscape 4 Very weedy, no mulch (2) General Hardscape 3.0 Concrete 3 Unplanted Landscape 4.0 Park Trees 4.0 General Hardscape 3.0 Concrete 3 General Hardscape 3.0 System operation 2 System operation 3.0 System Operation 3.0 Sy		nit	<u>ب</u>	eria	liti	
Live Oak Park 2.9 Live Oak Park 2.9 General Furnishings 3.3 Benches (1) Tables wood (1), composite (1) Tables (1) Tables wood (1), composite (1) Tables (1) Tables wood (1), composite (1) Tables (1) Tables wood (1), composite (1) Tables (1) Tables wood (1), composite (1) Mon-Turf Fountains concrete Turf 4 Non-Turf Ornamental Landscape 3.3 Turf 4 Non-Turf Ornamental Landscape 4 Very weedy, no mulch (2) General Hardscape 3.0 Concrete 3 Unplanted Landscape 4.0 Park Trees 4.0 General Hardscape 3.0 Concrete 3 General Hardscape 3.0 System operation 2 System operation 3.0 System Operation 3.0 Sy	۲.	ne	l se	/pe late	Duc	
General Site Observations: Observed a fexpeople on site using playground, clean anwell maintained overall, safe & friendly environment General Furnishings 3.3 Benches (1) Tables wood (1), composite (1) Trash/Recycling Receptacles plastic Image: Concrete 4 Mon-Turf Ornamental Landscape 3.3 Image: Concrete 4 Non-Turf Ornamental Landscape 4.0 Image: Concrete 4.0 General Trees 4.0 General Irrigation 3.0 Concrete 3.0 Concrete 3.0 Concrete 3.0 Concrete 3.0 Concrete 3.0 System operation 2. Coverage issues 2. System type (drip / spray) spray Controller 3.0 General Barriers 2.0 Bollards wood General Signage 2.5 Park ID wood System Operation 3. Wooden posts are worn 2.0 Bollards wood	Ğ	Ā	ŠĀ	fΣ	ŭ	from maintenance staff)
General Site Observations: Observed a fexpeople on site using playground, clean anwell maintained overall, safe & friendly environment General Furnishings 3.3 Benches (1) Tables wood (1), composite (1) Trash/Recycling Receptacles plastic Image: Concrete 4 Mon-Turf Ornamental Landscape 3.3 Image: Concrete 4 Non-Turf Ornamental Landscape 4.0 Image: Concrete 4.0 General Trees 4.0 General Irrigation 3.0 Concrete 3.0 Concrete 3.0 Concrete 3.0 Concrete 3.0 Concrete 3.0 System operation 2. Coverage issues 2. System type (drip / spray) spray Controller 3.0 General Barriers 2.0 Bollards wood General Signage 2.5 Park ID wood System Operation 3. Wooden posts are worn 2.0 Bollards wood						
General Furnishings 3.3 Benches (1) Tables wood Drinking Fountains concrete Trash/Recycling Receptacles plastic Turf 4 Mon-Turf Ornamental Landscape 3.3 Turf 4 Unplanted Landscape 2 Very weedy, no mulch 6 General Trees 4.0 Vunplanted Landscape 3.0 Concrete 3.0 General Trees 4.0 Optiking Fountains concrete 4.0 Under irrigated Non-Turf Ornamental Landscape 2 Very weedy, no mulch 6 General Trees 4.0 Concrete 3.0 System operation 2 System operation 2 System type (drip / spray) spray Controller 4 No observable problems General Barriers 2.00 Bollards wood 2 Deteriorating 3.0 System Operation 3 4	Live	Oak	Park		2.9	
General Furnishings 3.3 Benches Wood (1), composite (1) Tables wood (1), composite (1) Tables wood (1), composite (1) Drinking Fountains concrete Trash/Recycling Receptacles plastic Turf 4 Mon-Turf Ornamental Landscape 3.3 Turf 4 Unplanted Landscape 2 Very weedy, no mulch 9 General Trees 4.0 General Hrigation 3.0 Concrete 3 Unplanted Landscape 4 General Trees 4.0 General Irrigation 3.0 Concrete 3 Uneven and lifting Gontroller 4 No observable problems System operation 2 System Operation 3 Wooden posts are worn General Barriers 2.0 Bollards wood 2 Deteriorating 3 General Signage 2.5 Park ID wood 3 Act co						
General Furnishings 3.3 Benches wood (1), composite (1) Tables wood Drinking Fountains concrete Trash/Recycling Receptacles plastic General Landscape 3.3 Turf 4 Non-Turf Ornamental Landscape 4 Non-Turf Ornamental Landscape 4.0 Park Trees 4.0 General Hardscape 3.0 Concrete 3.0 Concrete 3.0 General Hardscape 3.0 Concrete 3.0 System operation 3.0 System operation 2.0 Controller 4 No observable problems General Lighting 3.0 System Operation 3.0 System Operation 3.0 System Operation 3.0 System Operation 3.0 System Operation 3.0 System Operation 3.0 System Operation 3.0 System Operation 3.0 Bollards wood 2.0						
General Furnishings 3.3 Benches wood (1), composite (1) 4 Tables wood 4 Trash/Recycling Receptacles plastic 1 Deficient General Landscape 3.3 Turf 4 Under irrigated Non-Turf Ornamental Landscape 4 Near park ID only Unplanted Landscape 2 Very weedy, no mulch General Trees 4.0 General Hardscape Concrete 3 Uneven and lifting General Irrigation 3.0 Uneven and lifting System type (drip / spray) spray Coverage issues System type (drip / spray) spray 2.0 General Barriers 2.0 Wooden posts are worn General Signage 2.0 Deteriorating General Signage 2.5 Park ID Bollards wood 2 Deteriorating General Signage 2.5 Park ID wood Park ID wood 3 At corner of Darla and Tracy Park ID wood 3 At corner of Darla and Tracy						
Benches wood (1), composite (1) 4 Tables wood 4 Tables wood 4 Drinking Fountains concrete 4 Trash/Recycling Receptacles plastic 1 Deficient General Landscape 3.3						environment
Benches(1)4Tableswood4Wood benchDrinking Fountainsconcrete4Trash/Recycling Receptaclesplastic1DeficientGeneral Landscape3.311Turf4Under irrigatedNon-Turf Ornamental Landscape2Very weedy, no mulchGeneral Trees4.0Park Trees4.0General Hardscape3.0Concrete3Uneven and liftingGeneral Irrigation3.0System operation2System type (drip / spray)sprayController4No observable problemsGeneral Barriers2.0BollardswoodQeneral Signage2.5Park IDwoodAt corner of Darla and TracyPark RulesmetalQuivert4Curb and GutterQuivert4Curb and GutterQuivert4QuivertQuivert4Quivert </th <th>L</th> <th>Gen</th> <th>eral Furnishings</th> <th>1.(4)</th> <th>3.3</th> <th></th>	L	Gen	eral Furnishings	1.(4)	3.3	
Drinking Fountainsconcrete4Trash/Recycling Receptaclesplastic1DeficientGeneral Landscape3.33.3Turf4Under irrigatedNon-Turf Ornamental Landscape4Near park ID onlyUnplanted Landscape2Very weedy, no mulchGeneral Trees4.0Park Trees4General Hardscape3.0Concrete3.0Concrete3.0System operation2.0System operation3.0System operation3.0System operation3.0System operation3.0General Lighting3.0System operation3.0System operation3.0System operation3.0System type (drip / spray)sprayController4No observable problemsGeneral Lighting3.0System Operation3Wooden posts are wornGeneral Signage2.5Park IDwoodPark RulesmetalCurer of Darla and TracyPark RulesmetalCurb and Gutter4Curb and Gutter4Curb and Gutter4Curb and Gutter4Curb and Gutter4Curb and Gutter4Curb and Gutter4Curb and Gutter4Curb and Gutter4Curb and Gutter4Curb and SubservableCurb and SubservableCurb a			Benches		4	
Trash/Recycling Receptacles plastic 1 beficient General Landscape 3.3 3.3 Turf 4 Under irrigated Non-Turf Ornamental Landscape 4 Near park ID only Unplanted Landscape 2 Very weedy, no mulch General Trees 4.0 Park Trees 4.0 General Hardscape 3.0 Concrete 3 Uneven and lifting General Irrigation 3.0 System operation 2 Coverage issues System type (drip / spray) spray Controller 4 No observable problems General Lighting 3.0 System Operation 3 Wooden posts are worn General Signage 2.5 Park Rules wood 2 Park Rules metal 2 Moodel Signage 2.5 Querent Controller 4 General Signage 2.5 Querent Controller 4 Querent Control Data and Tracy Park Rules Querent Control Datis and Tracy Park Rules			Tables	wood	4	Wood bench
General Landscape 3.3 Turf 4 Non-Turf Ornamental Landscape 4 Unplanted Landscape 2 Very weedy, no mulch General Trees 4.0 Park Trees 4.0 Concrete 3.0 Concrete 3 Uneven and lifting General Irrigation 3.0 System operation 2 Controller 4 No observable problems General Lighting 3.0 System Operation 2 Controller 4 No observable problems General Lighting 3.0 System Operation 3 Wooden posts are worn General Signage 2.5 Park ID wood 2 Park ID wood 3 At corner of Darla and Tracy Park Rules Metal 2 Not legible General Drainage 4.0 Culvert 4 V-ditch along residences, No observable			Drinking Fountains	concrete	4	
Turf 4 Under irrigated Non-Turf Ornamental Landscape 4 Near park ID only Unplanted Landscape 2 Very weedy, no mulch General Trees 4.0 Park Trees 4 General Hardscape 3.0 Concrete 3 Uneven and lifting General Irrigation 3.0 System operation 2 Coverage issues System operation 2 Coverage issues System operation 2 Coverage issues System operation 3.0 Septem operation System operation 2 Coverage issues System Operation 3.0 Septem operation General Lighting 3.0 Septem operation System Operation 3 Wooden posts are worn General Barriers 2.0 Deteriorating General Signage 2.5 Park ID Park ID wood 3 At corner of Darla and Tracy Park Rules metal 2 Not legible General Drainage 4.0 Culvert 4			Trash/Recycling Receptacles	plastic	1	Deficient
Non-Turf Ornamental Landscape 4 Near park ID only Unplanted Landscape 2 Very weedy, no mulch General Trees 4.0 Park Trees 4 General Hardscape 3.0 Concrete 3 Uneven and lifting General Irrigation 3.0 System operation 2 Coverage issues System type (drip / spray) spray Controller 4 No observable problems General Barriers 2.0 Bollards wood 2 Deteriorating 3 General Signage 2.5 Park Rules metal 2.5 Park Rules metal 2 Drain inlet 4 V-ditch along residences, No observable		Gen	eral Landscape		3.3	
Unplanted Landscape 2 Very weedy, no mulch General Trees 4.0 Park Trees 4 General Hardscape 3.0 Concrete 3 Uneven and lifting General Irrigation 3.0 System operation 2 Coverage issues System type (drip / spray) spray Controller 4 No observable problems General Lighting 3.0 System Operation 3 Wooden posts are worn General Barriers 2.0 Bollards wood 2 Deteriorating General Signage Quevent 4.0 Curvert 4.0 Curvert 4.0			Turf		4	Under irrigated
General Trees 4.0 Park Trees 4 General Hardscape 3.0 Concrete 3 Uneven and lifting General Irrigation 3.0 System operation 2 Coverage issues System type (drip / spray) System type (drip / spray) Controller General Lighting System Operation System Operation System Operation System Operation System Operation System Operation System Operation System Operation System Operation System Operation System Operation Bollards wood Drain Iglet Quivert Quivert Quivert Quivert Quivert Quivert Quivert Quivert Quivert Quivert Quivert Quivert Quivert Quivert Quivert			Non-Turf Ornamental Landscape		4	Near park ID only
Park Trees4General Hardscape3.0Concrete3Uneven and liftingGeneral Irrigation3.0System operation2Coverage issuesSystem type (drip / spray)System type (drip / spray)ControllerControllerGeneral LightingGeneral LightingSystem OperationSystem OperationSystem OperationGeneral Barriers2.0BollardsGeneral Signage2.5Park IDWoodPark RulesMetalCulvert4.0CulvertCulvert4Curb and Gutter4V-ditch along residences, No observable			Unplanted Landscape		2	Very weedy, no mulch
General Hardscape3.0Concrete3Uneven and liftingGeneral Irrigation3.0System operation2Coverage issuesSystem type (drip / spray)spray2Controller4No observable problemsGeneral Lighting3.0System Operation3Wooden posts are wornGeneral Barriers2.0Bollardswood2Deteriorating2.5Park IDwood3At corner of Darla and TracyPark Rulesmetal2Culvert4Culvert4Curb and Gutter4Drain inlet4		Gen	eral Trees		4.0	
Concrete3Uneven and liftingGeneral Irrigation3.0System operation2Coverage issuesSystem type (drip / spray)sprayController4No observable problemsGeneral Lighting3.0System Operation3Wooden posts are wornGeneral Barriers2.0BollardswoodQeneral Signage2.5Park IDwoodPark RulesmetalGeneral Drainage4.0Culvert4Culvert4Curb and Gutter4V-ditch along residences, No observable			Park Trees		4	
General Irrigation 3.0 System operation 2 Coverage issues System type (drip / spray) Controller Controller General Lighting 3.0 System Operation System Operation System Operation System Operation Bollards Wooden posts are worn General Signage 2.5 Park ID Wood Park Rules General Drainage 4.0 Culvert 4 V-ditch along residences, No observable		Gen	eral Hardscape		3.0	
System operation2Coverage issuesSystem type (drip / spray)spray4Controller4No observable problemsGeneral Lighting3.0System Operation3Wooden posts are wornGeneral Barriers2.0Bollardswood2Deteriorating2.5Park IDwood3At corner of Darla and TracyPark Rulesmetal2Culvert4Culvert4Curb and Gutter4V-ditch along residences, No observable			Concrete		3	Uneven and lifting
System type (drip / spray) spray Controller 4 No observable problems General Lighting 3.0 System Operation 3 Wooden posts are worn General Barriers 2.0 Bollards wood 2 Deteriorating 2.5 Park ID wood 3 At corner of Darla and Tracy Park Rules metal 2 Not legible General Drainage 4.0 Culvert 4 4 Drain inlet 4 V-ditch along residences, No observable		Gen	eral Irrigation		3.0	
Controller 4 No observable problems General Lighting 3.0 System Operation 3 Wooden posts are worn General Barriers 2.0 Bollards wood 2 Deteriorating 2.5 Park ID wood 3 At corner of Darla and Tracy Park Rules metal 2 General Drainage 4.0 Culvert 4 Curb and Gutter 4 Drain inlet 4			System operation		2	Coverage issues
General Lighting 3.0 System Operation 3 General Barriers 2.0 Bollards wood 2 Deteriorating 2.5 Park ID wood 3 At corner of Darla and Tracy Park Rules metal 2 Not legible 4 Culvert 4 Drain inlet 4			System type (drip / spray)	spray		
System Operation 3 Wooden posts are worn General Barriers 2.0 Bollards wood 2 Deteriorating 2.5 Park ID wood 3 At corner of Darla and Tracy Park Rules metal 2 Not legible General Drainage 4.0 Culvert 4 Drain inlet V-ditch along residences, No observable			Controller		4	No observable problems
System Operation 3 Wooden posts are worn General Barriers 2.0 Bollards wood 2 Deteriorating 2.5 Park ID wood 3 At corner of Darla and Tracy Park Rules metal 2 Not legible General Drainage 4.0 Culvert 4 Drain inlet V-ditch along residences, No observable		Gen	eral Lighting		3.0	
General Barriers 2.0 Bollards wood 2 Deteriorating General Signage 2.5 Park ID wood 3 At corner of Darla and Tracy Park Rules metal 2 Not legible General Drainage 4.0 4 Culvert 4 V-ditch along residences, No observable					3	Wooden posts are worn
General Signage 2.5 Park ID wood 3 At corner of Darla and Tracy Park Rules metal 2 Not legible General Drainage 4.0 4 Culvert 4 4 Drain inlet 4 V-ditch along residences, No observable						
Park ID wood 3 At corner of Darla and Tracy Park Rules metal 2 Not legible General Drainage 4.0 Culvert 4 Curb and Gutter 4 Drain inlet 4			Bollards	wood	2	Deteriorating
Park ID wood 3 At corner of Darla and Tracy Park Rules metal 2 Not legible General Drainage 4.0 Culvert 4 Curb and Gutter 4 Drain inlet 4		Gen	eral Signage		2.5	
General Drainage 4.0 Culvert 4 Curb and Gutter 4 Drain inlet 4				wood	3	At corner of Darla and Tracy
Culvert 4 Curb and Gutter 4 Drain inlet 4			Park Rules	metal	2	Not legible
Culvert 4 Curb and Gutter 4 Drain inlet 4		Gen	eral Drainage		4.0	
Drain inlet 4 V-ditch along residences, No observable			-		4	
			Curb and Gutter		4	
l l l l l problems			Drain inlet		4	V-ditch along residences, No observable problems
Swales / Stormwater Infrastructure 4			Swales / Stormwater Infrastructure		4	p

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 7/8/21 Time: 10:17 - 10:47am Field Notes (all italicized noted are notes from maintenance staff)				
				2.0					
-	Oak Play	ground		2.9 1.0					
		Equipment*	Plastic/Metal	1.0	Slide on large structure is broken and blocked off				
		Surfacing	sand	4					
		Surfacing	rubber	4					
		Furnishings	Metal, table and benches	2	Excessive wear				
		Signs	metal	4					
		Drainage		4	No observable problems				
* The	* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk								
Note	e: Lim	ited assessment items are highlighted in g	grey						

	i			İ	Inventory Data: 7/0/21
	5		a	on	Inventory Date: 7/9/21
	hil	k l	eria	diti	Time: n/a
Park	Amenity	Asset	Type / Materia	Condition	Field Notes (all italicized noted are notes
⊢┛	◄	۸	⊢ 2	U U	from maintenance staff)
1				2.2	
Luth	er Bl	urbank Home and Gardens		3.3	
					General Site Observations: Decently
					maintained, super inviting & friendly staff
	Gon	eral Furnishings		3.2	
	Gen	Benches	wood and metal		
				4	
		Tables	wood	5	
		Bike Racks		1	
		Drinking Fountains	stone	1	Spigot attached to stone
		Trash/Recycling Receptacles	wood and metal	5	
	Gen	eral Landscape		3.0	
		Turf		2	Extremely patchy
		Non-Turf Ornamental Landscape		4	Weedy
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		2.5	
		Concrete		3	Uneven on sidewalk
		Pavers	brick	2	Uneven throughout
	Gen	eral Irrigation		2.5	
		System operation		2	
		System type (drip / spray)	spray		
		Controller		3	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	No observable problems
	Gen	eral Barriers		4.0	
		Fences / Walls	Raised planter/brick	4	
		Fences / Walls 2	split rail/wood	4	
		Fences / Walls 3	picket, wood	4	
		Guardrails	stone	4	St water feature
		Entrance/Maintenance Gates	ornamental metal	4	
		Handrails			
	Gen	eral Signage		4.3	
		Park ID	#1 composite, #2 wood	4	At corner of Santa Rosa and Sonoma and on brick planter
		Wayfinding	metal	4	Tour location numbers and plant ID signs
		Interpretive Signage	enamel tiles	5	Tiles with historic information under trellis

	٧	>	_	ч	Inventory Date: 7/9/21
	nity		/	itio	Time: n/a
Park	Amenity	Asset	Type / Materia	Condition	Field Notes (all italicized noted are notes
Ра	Ar	As	γ [†]	ů	from maintenance staff)
-		Irbank Home and Gardens		3.3	
		eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	
		Swales / Stormwater Infrastructure		4	
	Gen	eral Structures		3.0	
		Shade Structures (not assessed)	wood trellis		Present
		Pedestrian Bridges (not assessed)			
		Sheds		3	
		Restrooms (not assessed)			On site
	Wat	er Feature		3.5	
		Lighting		3	
		Mechanical water feature*	stone	4	Huge fountain, water in basin, pump turned off
	Com	nmunity Gardens		3.0	
		Barriers*	wood	3	
		Surfacing	DG	3	
		Storage/Sheds	wood	3	No observable problems
		Irrigation	spray and drip	4	
		Raised Beds	wood	3	
	Art			N/A	
		Surfacing (not assessed)			Present
		Statue (not assessed)			On site throughout
		Mural / Mosaic (not assessed)			On site
* The	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated	asset w	vith an asterisk
Note	e: Lim	ited assessment items are highlighted in g	grey		

	ij		 	:::	Inventory Date: 6/24/2021
¥	Amenity	et	Type / Materi al	Conditi on	Time: 3:18pm - 3:54 pm
Park	Am	Asset	al Aa	o C	Field Notes
Mar	tin Lu	uther King Jr. Park		2.9	
					General Site Observations: Few people
					observed at park on a weekday, staff
					present at preschool, some accumulated
					trash and dumping near picnic area, limited
					graffiti, restrooms locked, no encampments
					observed
	Gen	eral Furnishings		2.8	
		Benches	Steel	4	Minor wear
		Bike Racks	Steel	3	
		Drinking Fountains	Concrete	3	Minor cracking. Turned off.
		Trash/Recycling Receptacles		1	Deficient
	Gen	eral Landscape		2.3	
		Turf		3	Major damage where picnic area and play meet
		Non-Turf Ornamental Landscape		2	Weedy, no mulch
		Unplanted Landscape		2	No mulch
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		2.0	
		Asphalt		1	Large holes
		Concrete		3	Significant portions recently replaced
	Gen	eral Irrigation		3.5	
		System operation		3	No observable problems
		System type (drip / spray)	Spray		
		Controller		4	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	No observable problems
	Gen	eral Barriers		4.0	
		Bollards	Steel	4	
	Gen	eral Signage		2.5	
		Park ID	Wood	3	
		Park Rules		2	Poor locations, Hard to read
	Gen	eral Drainage		3.0	
		Culvert		3	
		Curb and Gutter		3	
		Drain inlet		3	No observable problems
		Swales / Stormwater Infrastructure		3	

Image: Second	
Martin Luther King Jr. Park 2.9 Picnic Areas 2.8 Tables* Wood and Concrete Barbecues Steel Surfacing Concrete Surfacing D.G. Trash Receptacles 1 Shade Trees 3 Parking Lot 2.0 Wheel stops Concrete Surfacing* Asphalt Signage 2 Equipment* Plastic and Metal Surfacing Sand Surfacing Sand Lequipment* Plastic and Metal Signs Metal Surfacing Sand Surfacing Sand Surfacing Sand Heavy weeds Structures have graffiti, needs cle Curb Concrete Surfacing Rubber Surfacing Sand Surfacing Sand Surfacing Sand Surfacing Sand Surfacing Sand Surfacing Sand Surfacing Sand Surfacing Sand Surfacing Sand Surfacing Sand Surfacing Sand Surfacing <	
Martin Luther King Jr. Park 2.9 Picnic Areas 2.8 Tables* Wood and Concrete 3 Barbecues Steel 4 Surfacing Concrete 4 Minor cracking D.G. 2 Heavy weeds 1 Deficient Surfacing D.G. 2 Heavy weeds 1 Deficient Shade Trees 3 3 Parking Lot 2.0 Wheel stops Concrete 3 Surfacing* Asphalt 2 Signage 2 Excessive wear Striping 1 Completely faded Playground 3.0 3 Equipment* Plastic and Metal 3 Surfacing Rubber 3 Minor holes Surfacing Sand Surfacing Sand Level is low Signs Metal 4 Drainage 2 No observable problems Surfacing* Asphalt 2 Signs Metal 4 Drainage 3 Heavel stope Surfacing Sand 3 Level is low Signs Major cracking and weed growth corners <td></td>	
Picnic Areas2.8Tables*Wood and Concrete3BarbecuesSteel4SurfacingConcrete4SurfacingD.G.2Heavy weeds1DeficientShade Trees3Parking Lot2.0Wheel stopsConcrete3Surfacing*Asphalt2Signage1Completely fadedPlayground3.0Equipment*Plastic and Metal3SurfacingStructures have graffiti, needs cleCurbConcrete4SurfacingSand1Level is lowSignsSignsMetal4Drainage2.0Striping1.0SurfacingSandSturfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacing*2.0Sport Type:BasketballSurfacing*AsphaltSurfacing*AsphaltSurfacing*AsphaltSurfacing*AsphaltSurfacing*AsphaltSurfacing*AsphaltSurfacing*AsphaltSurfacing*AsphaltSurfacing*AsphaltSurfacing*	
Tables*Wood and Concrete3BarbecuesSteel4SurfacingConcrete4Minor crackingD.G.2Heavy weeds1Deficient3Shade Trees3Parking Lot2.0Wheel stopsConcreteSurfacing*AsphaltSignage2Excessive wearStriping1Completely fadedPlayground3.0Equipment*Plastic and MetalSignageSurfacingSurfacingSandStriping1Concrete4Striping10SurfacingStructures have graffiti, needs cleCurbConcreteSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingAsphaltSignsMetalSport Field / Court 12.0Surfacing*AsphaltSurfacing*AsphaltSurfacing*3HeaveAsphaltSurfacing*3Major cracking and weed growth cornersSurfacing*3Surfacing*3Striping3Half of court needs to be restripeEquipmentHoopsSigns of deteriorationLighting3Half of court needs to be restripeEquipmentHoopsStriping3Striping4No observable problems <t< td=""><td></td></t<>	
Image: biology of the system	
SurfacingConcrete4Minor crackingSurfacingD.G.2Heavy weedsTrash Receptacles1DeficientShade Trees3Parking Lot2.0Wheel stopsConcrete3Surfacing*Asphalt2Signage2Excessive wearStriping1Completely fadedPlayground3.03.0Lequipment*Plastic and Metal3SurfacingSurfacing3.0SurfacingSand3Lequipment*Plastic and Metal3SurfacingSurfacingSandSurfacingSand3Level is lowSignage2SignsMetal4Drainage2No observable problemsSurfacing*Asphalt2SurfacingSand3Level is low3SignsSport Field / Court 12.0Surfacing*Asphalt2Striping3Half of court needs to be restripeEquipmentHoops3Signs of deteriorationLighting3Half of court needs to be restripeLighting3Half of court needs to be restripeDrainage4No observable problems	
SurfacingD.G.2Heavy weedsTrash Receptacles1DeficientShade Trees3Parking Lot2.0Wheel stopsConcrete3Surfacing*Asphalt2Signage2Excessive wearStriping1Completely fadedPlayground3.0ConcreteLquipment*Plastic and Metal3SurfacingSurfacing3SurfacingSand3Lquipment*Concrete4SurfacingRubber3Minor holesSurfacingSurfacingSand3Level is lowSignsSignsMetal4Drainage2.0Surfacing*BasketballSport Type:BasketballSurfacing*Asphalt2Lighting3Striping3Lighting4No observable problems2Lighting4No observable problems3Striping3Striping3Striping3Striping3Striping3Striping3Striping3Striping3Striping3Striping3Striping3Striping3Striping3Striping3Striping3Striping3Striping3Striping3<	
Trash Receptacles1DeficientShade Trees33Parking Lot2.0Wheel stopsConcrete3Surfacing*Asphalt2Signage2Excessive wearStriping1Completely fadedPlayground3.03.0Equipment*Plastic and Metal3SurfacingSurfacing3.0SurfacingSurfacing3.0SurfacingSurfacing1SurfacingSurfacing1SurfacingSand3SignsMetal4Drainage2.0No observable problemsSurfacing*Basketball2Sport Type:Basketball2Striping3Half of court needs to be restripeEquipmentHoops3Signs of deteriorationLighting3Signs of deterioration3Striping3Asphalt2Striping3Half of court needs to be restripeStriping3Signs of deteriorationStriping3Signs of deteriorationStriping3Signs of deteriorationStriping3Signs of deteriorationStriping3Signs of deteriorationStriping3Signs of deteriorationStriping3Signs of deteriorationStriping3Signs of deteriorationStriping3Signs of deteriorationStriping3Signs of deteriora	
Shade Trees3Parking Lot2.0Wheel stopsConcrete3Surfacing*Asphalt2Signage2Excessive wearStriping1Completely fadedPlayground3.00CurbConcrete4SurfacingPlastic and Metal3SurfacingRubber3Minor holesSurfacingSurfacingSand3Level is low2.0SurfacingMetalSurfacingSandSurfacingSandSurfacing2.0Surfacing2.0SurfacingSandSignsMetalSignsMetalSport Field / Court 12.0Surfacing*AsphaltSurfacing*AsphaltSurfacingSurfacingLighting3Striping3Striping3Surfacing*AsphaltSurfacing*3Surfacing*AsphaltSurfacing*AsphaltSurfacing*3Striping3Striping3Striping3Striping3Striping3Striping3Striping3Surfacing*4Striping3Striping3Striping3Striping3Striping3Striping3Striping3Striping	
Parking Lot2.0Wheel stopsConcrete3Surfacing*Asphalt2Signage2Excessive wearStriping1Completely fadedPlayground3.03.0Equipment*Plastic and Metal3SurfacingRubber3Minor holesSurfacingSurfacingSand3Level is lowSignsSports Field / Court 12.0Surfacing*Asphalt2Surfacing*Asphalt2Surfacing*Asphalt2Sport Type:BasketballStriping3Half of court needs to be restripeEquipmentHoops3Signs of deteriorationLighting3Asphalt2Drainage4No observable problems	
Wheel stopsConcrete3Surfacing*Asphalt2Signage2Excessive wearStriping1Completely fadedPlayground3.0Equipment*Plastic and Metal3SurfacingRubber3Minor holesSurfacingSurfacingSand3Level is low3SignsMetal4Drainage2.0Surfacing*Asphalt2.0Surfacing*Asphalt2Striping3Half of court needs to be restripeEquipmentHoops3Signs of deteriorationLighting3Half of court needs to be restripeDrainage3Jange3Motor Striping3Jange of the problemsStriping3Half of court needs to be restripeLighting3Jange4No observable problems3	
Surfacing*Asphalt2Signage2Excessive wearStriping1Completely fadedPlayround3.0Equipment*Plastic and Metal3CurbConcrete4SurfacingRubber3Minor holesSurfacingSignsMetal4Drainage2.0Sports Field / Court 12.0Surfacing*Asphalt2Surfacing*Asphalt2Surfacing*Asphalt2Surfacing*Asphalt2Surfacing*Asphalt2Striping3Half of court needs to be restripeEquipmentHoops3Signs of deteriorationLighting3Vo observable problemsDrainage4No observable problems	
Signage2Excessive wearStriping11Completely fadedPlayground3.03.0Equipment*Plastic and Metal3Structures have graffiti, needs cleCurbConcrete44SurfacingRubber3Minor holesSurfacingSand3Level is lowSignsMetal44Drainage2.0No observable problemsSports Field / Court 12.0Major cracking and weed growth cornersSurfacing*Asphalt2Major cracking and weed growth cornersStriping3Half of court needs to be restripeEquipmentHoops3Signs of deteriorationLighting3Jages4Drainage4No observable problems	
Signage2Excessive wearStriping11Completely fadedPlayground3.03.0Equipment*Plastic and Metal3Structures have graffiti, needs cleCurbConcrete44SurfacingRubber3Minor holesSurfacingSand3Level is lowSignsMetal44Drainage2.0No observable problemsSports Field / Court 12.0Major cracking and weed growth cornersSurfacing*Asphalt2Major cracking and weed growth cornersStriping3Half of court needs to be restripeEquipmentHoops3Signs of deteriorationLighting3Jages4Drainage4No observable problems	
Play:round 3.0 Image: Play:round Plastic and Metal 3.0 Image: Play:round Plastic and Metal 3.0 Image: Play:round Plastic and Metal 3.0 Image: Play:round Surfacing Surfacing Image: Play:round Concrete 4 Image: Play:round Concrete 4 Image: Play:round Sand 3 Image: Play:round Sand 3 Image: Play:round Sand 3 Image: Play:round Sand 3 Image: Play:round Metal 4 Image: Play:round Metal 4 Image: Play:round Metal 4 Image: Play:round Metal 4 Image: Play:round Metal 4 Image: Play:round Metal 4 Image: Play:round Metal 4 Image: Play:round Metal 4 Image: Play:round Metal 4 Image: Play:round Metal 4 Image: Play:round Metal 4 Image	
Play:round 3.0 Image: Play:round Plastic and Metal 3.0 Image: Play:round Plastic and Metal 3.0 Image: Play:round Plastic and Metal 3.0 Image: Play:round Concrete 4.0 Image: Play:round Concrete 4.0 Image: Play:round Concrete 4.0 Image: Play:round Rubber 3.0 Image: Play:round Sand 3.0 Image: Play:round Sand 3.0 Image: Play:round Metal 4.0 Image: Play:round Metal 4.0 Image: Play:round Metal 4.0 Image: Play:round Metal 4.0 Image: Play:round Metal 4.0 Image: Play:round Metal 4.0 Image: Play:round Metal 4.0 Image: Play:round Metal 4.0 Image: Play:round Metal 4.0 Image: Play:round Metal 4.0 Image: Play:round Metal 3.0 Image: Play:round Metal 4.0	
CurbConcrete4CurbConcrete4SurfacingRubber3SurfacingSand3SignsMetal4Drainage2No observable problemsSports Field / Court 12.0Sport Type:Basketball4Surfacing*Asphalt2Striping3Half of court needs to be restripeStripingHalf of court needs to be restripeLightingHoops3Drainage4No observable problems	
SurfacingRubber3Minor holesSurfacingSand3Level is lowSignsMetal4Drainage2No observable problemsSports Field / Court 12.0Sport Type:BasketballSurfacing*Asphalt2Striping3Half of court needs to be restripeEquipmentHoops3Signs of deteriorationLightingLighting3No observable problemsDrainage4No observable problems	aning
SurfacingSand3Level is lowSignsMetal4Drainage2No observable problemsSports Field / Court 12.02.0Sport Type:Basketball4Surfacing*Asphalt2Striping3Half of court needs to be restripeEquipmentHoops3Signs of deteriorationLighting034Drainage4No observable problems	
SignsMetal4Drainage2No observable problemsSports Field / Court 12.0Sport Type:BasketballSurfacing*Asphalt2Striping3Half of court needs to be restripeEquipmentHoops3Signs of deteriorationLighting3Mo observable problemsDrainage4No observable problems	
Drainage2No observable problemsSports Field / Court 12.0Sport Type:Basketball-Sport Type:Basketball-Surfacing*Asphalt2Major cracking and weed growth cornersStripingStriping3Half of court needs to be restripeEquipmentHoops3Signs of deteriorationLightingI3Vo observable problemsDrainageMo observable problems4	
Sports Field / Court 1 2.0 Sport Type: Basketball Surfacing* Asphalt Striping 3 Half of court needs to be restripe Equipment Hoops Lighting 3 Drainage 4	
Sport Type:BasketballMajor cracking and weed growth cornersSurfacing*Asphalt2Major cracking and weed growth cornersStripingStriping3Half of court needs to be restripeEquipmentHoops3Signs of deteriorationLightingImage4No observable problems	
Surfacing*Asphalt2Major cracking and weed growth cornersStriping3Half of court needs to be restripeEquipmentHoops3Signs of deteriorationLighting3Orainage4	
Surfacing*Asphalt2cornersStriping3Half of court needs to be restripeEquipmentHoops3Signs of deteriorationLighting3Jorainage4	
Equipment Hoops 3 Signs of deterioration Lighting 3 3 Drainage 4 No observable problems	, buckling
Lighting 3 Drainage 4	d
Drainage 4 No observable problems	
Sports Field / Court 2 3.5	
Sport Type: Soccer	
Surfacing* Turf 4 Minor spotting	
Equipment 4	
Irrigation 3 Coverage issues, spotting near tree Temple Ave	ees on
Drainage 3 No observable problems	
* The rating of the amenity shall not exceed the rating of the lowest rated asset w	
Note: Limited assessment items are highlighted in grey	

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/22/21 Time: 4:40pm - 4:50pm Field Notes (all italicized noted are notes from maintenance staff)
Mar	y Tra	verso Open Space		3.7	
					General Site Observations: Large open space adjacent to residences, some unformal trails lead down to creek, few benches
	Gen	eral Furnishings		3.5	
		Benches	Composite and Metal	5	
		Trash/Recycling Receptacles		2	Broken
	Gen	eral Landscape		4.0	
		Natural Landscape		4	No noxious weeds present / annual grasses with dense shrub growth restricted to riparian corridor, including Himalayan blackberry, ivy, willows, oaks
	Gen	eral Trees		4.0	
		Trees in Natural Areas		4	
	Gen	eral Hardscape		3.0	
		Concrete		3	Sidewalk
	Gen	eral Irrigation		N/A	
		System operation			None observed, but backflow present
	Gen	eral Drainage		4.0	No observable problems
┝─		Curb and Gutter		4	
		ng of the amenity shall not exceed the rat ited assessment items are highlighted in g	-	asset v	l vith an asterisk

					Inventory Date: 6/22/21			
	ty		a	ior	Time: 5:15 - 5:34pm			
<u> </u>	eni	et	e / teri	dit	Field Notes (all italicized noted are notes			
Park	Amenity	Asset	Type / Material	Condition	from maintenance staff)			
	-							
Mata	anzas	s Park		3.5				
					General Site Observations: Large shade			
					trees, adjacent to school, several families			
					playing on playground			
	Gen	eral Furnishings		1.0				
		Trash/Recycling Receptacles	Plastic	1	Deficient			
	Gen	eral Landscape		4.0				
		Turf		4	Slight yellow spot in one area			
	Gen	eral Trees		4.0				
		Park Trees		4				
	Gen	eral Hardscape		4.0				
		Concrete		4	Roadside sidewalk has uneven pavement			
	Gen	eral Irrigation		4.0				
		System operation		4				
		System type (drip / spray)	Spray					
		Controller		4	No observable problems			
	Gen	eral Drainage		4.0				
		Culvert		4				
		Curb and Gutter		4				
		Drain inlet		4				
		Swales / Stormwater Infrastructure		4				
	Play	ground		3.6				
		Equipment*		4				
		Curb		4	One section shows signs of lifting			
		Surfacing	Rubber	4				
		Surfacing	Sand	3	Looks low			
		Barriers		1	No fence, potential safety hazard			
		Signs		5				
		Drainage		4	No observable problems			
* The	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated	d asset v	vith an asterisk			
Note	Note: Limited assessment items are highlighted in grey							

				1	Inventory Date: 6/22/21
	ť		a	ion	Inventory Date: 6/22/21 Time: 3:55 - 4:27pm
	enit	s	e / eri	diti	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	Condition	-
–	٩	A	F 2	0	from maintenance staff)
Mes	auite	Park		3.4	
Inco	quite			0.4	General Site Observations: On a hill,
					amenities look a little worn, quiet, tucked in
					a neighborhood area
	Gen	eral Furnishings		2.7	
		Benches	Wood and Metal	3	Needs cleaning, lots of mold
		Tables	Concrete	4	
		Trash/Recycling Receptacles	Plastic	1	Deficient
	Gen	eral Landscape		2.5	
		Turf		3	Some areas need to be re-seeded
		Unplanted Landscape		2	No mulch
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		3.0	
		Concrete		3	Moderate cracking
	Gen	eral Irrigation		3.0	
		System operation		2	Coverage problems
		System type (drip / spray)	Spray		
		Controller		4	No observable problems
	Gen	eral Lighting		4.0	
		System Operation		4	Not new City standard
	Gen	eral Barriers		3.3	
		Fences / Walls	Chainlink	3	Some leaning posts
		Entrance/Maintenance Gates		4	
		Bollards	Metal and Wood	3	Wood bollards leaning
	Gen	eral Signage		4.0	
		Park Rules		4	* No Spanish
	Gen	eral Drainage		4.0	
		Culvert		4	No observable problems
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	

Park	Amenity	Asset	Type / Material		Inventory Date: 6/22/21 Time: 3:55 - 4:27pm Field Notes (all italicized noted are notes from maintenance staff)			
	-	Park		3.4				
		ground Equipment*		3.7 4				
		Curb		4				
		Surfacing	Rubber	2				
		Surfacing	Sand	3	Looks low			
		Furnishings		4				
		Signs		5				
		Drainage		4	No observable problems			
* Th	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated	asset v	vith an asterisk			
Note	Note: Limited assessment items are highlighted in grey							

		Ì		_	Inventory Date: 5/18/21
	ť		a	Condition	Time: AM
	eni	et	e / :eri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	Son	from maintenance staff)
<u> </u>	4	۹	F 2	0	
Naga	saw	l va Community Park		3.3	
Tug				5.5	
					General Site Observations: Park with a large
					lake, few park users during time of site visit
	Gen	eral Furnishings		2.7	
		Benches	Synthetic/wood	4	
		Tables	wood	3	
		Trash/Recycling Receptacles		1	Deficient (rolling bins; no infrastructure)
	Gen	ieral Landscape		4.0	
		Natural Areas		4	Natural landscape, grassy
		eral Trees		3.0	
		Trees in Natural Areas		3	Fire damage
	Gen	ieral Hardscape		4.0	
	Gen	Asphalt			
		Concrete		5	
		Decomposed Granite / Gravel		3	Weedy
	Gen	eral Irrigation		1.0	
	U CII	System operation		1	Fire damage assumed
		Controller		1	
	Gen	ieral Barriers		3.8	
				0.0	
		Fences / Walls	Wood restroom screen	5	
		Fences / Walls 2	Chainlink	4	
		Fences / Walls 3	Split rail	2	Perimeter fence
		Guardrails		4	Burned
		Bollards			
	Gen	eral Signage		3.0	
		Park Rules	Steel posts	4	
		Kiosks	Wood	2	Illegible
	Gen	eral Drainage		4.0	
		king Lot		3.8	
		Wheel stops		4	
		Lighting		4	No observable problems
		Surfacing*		5	
		Signage		4	
		Striping		2	worn
	Trai	ls		2.0	
		Surfacing*	Packed earth, rock	2	Informal, no formal improvements

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 5/18/21 Time: AM Field Notes (all italicized noted are notes from maintenance staff)			
Naga	asawa	a Community Park		3.3				
	Water Feature 5.0							
		Boat ramps		5	Entrance obstructed by shrubs			
* Th	* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk							
Note	e: Lim	ited assessment items are highlighted in g	grey					

Å	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/24/2021 Time: 4:00pm - 4:07pm Field Notes (all italicized noted are notes		
Park	Aπ	Ass	Т Ма	Co	from maintenance staff)		
New	hall I	Bike Trail		2.8			
					General Site Observations: Heavy		
					weathering on trail, heavy weeds		
					throughout, broken glass and trash along		
	-				trail. Safety could be a concern.		
	Gen	eral Landscape		4.0			
		Natural Areas		4	Needs to be mowed		
	Gen	eral Trees		4.0	No observable problems		
		Park Trees					
		Trees in Natural Areas		4			
	Gen	eral Hardscape		2.0			
		Concrete		2	some areas severely cracked, weeds growing		
	Gen	eral Lighting		3.0			
		System Operation		3	No observable problems		
	Gen	eral Barriers		3.0			
		Bollards	Steel	3			
	Gen	eral Signage		3.0			
		Park Rules		3	Heavy weathering		
	Gen	eral Drainage		2.0			
		Culvert		2			
		Swales / Stormwater Infrastructure		2			
	Trai	ls		1.0			
		Surfacing*	Asphalt	1	Hazardous, Major Cracks and falling apart edges		
	Art			N/A			
		Mural / Mosaic (not assessed)	Art Mural on Buildings		On Site		
* The	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated a	isset w	vith an asterisk		
Note	lote: Limited assessment items are highlighted in grey						

				_	Inventory Date: 6/23/2021
	tγ		a	ion	Time: 3:50pm - 3:59pm
>	eni	et	e / :eri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset / Type / Material	Condition	from maintenance staff)	
<u> </u>	4	4	F 2	0	
Nort	h Da	l rk		3.2	
NUT	IIFa			5.2	General Site Observations: A lot of people
					using playground on a weekday late
					afternoon, clean park overall
	Gen	l eral Furnishings		3.5	
		Benches	Composite and Wood	4	Mixed conditions
		Trash/Recycling Receptacles		3	
	Gen	eral Landscape		2.5	
		Turf		3	Patch
		Unplanted Landscape		2	
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		2.0	
		Concrete		1	Several cracks and uneven
		Pavers		3	Sidewalk uneven
	Gen	eral Irrigation		3.0	
		System operation		3	Coverage problems
		System type (drip / spray)	Spray		
		Controller		3	No observable problems
	Gen	eral Signage		3.5	
		Park ID	Wood	4	On North Street
		Park Rules	Metal	3	Fading
	Gen	eral Drainage		3.0	
		Curb and Gutter		3	
	Play	ground		3.9	
		Equipment*	Metal and Plastic	4	
		Curb	Concrete	4	Band was buried with sand on south side
		Surfacing	Sand	4	
		Surfacing	Rubber	4	
		Furnishings	Composite Bench	4	
		Barriers	Chainlink	4	
		Signs	Metal	4	
		Drainage		3	No observable problems
		ing of the amenity shall not exceed the ra	-	asset v	vith an asterisk
Note	: Lin	nited assessment items are highlighted in	grey		

	1				Inventory Date: 6/22/2021
	₹		a	ion	Inventory Date: 6/22/2021 Time: 3:40pm - 5:15pm
	eni	et	e / :eri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	Condition	from maintenance staff)
	4		Fζ		
Nort	hwo	st Community Park		3.1	
				5.1	
					General Site Observations: Very busy in the late afternoon, parking lot was completely full, dog owners bring their own furnishings and leave them in park, possible encampments at picnic tables behind and in creek, football field is closed off to public
	Gen	eral Furnishings		2.3	
		Tables		4	
		Drinking Fountains	Stone/Concrete	2	Water turned off
		Trash/Recycling Receptacles		1	Deficient
	Gen	eral Landscape		2.0	
		Turf		2	Behind pump track - extremely uneven, large amounts of dieback and weeds
		Unplanted Landscape		2	Possible mulch
	Gen	eral Trees		4.0	
		Park Trees		4	
		Trees in Natural Areas			
	Gen	eral Hardscape		2.0	
		Asphalt		2	
	Gen	eral Irrigation		3.0	
		System operation		2	Dieback indicates coverage problem
		System type (drip / spray)	Spray		
		Controller		4	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	
	Gen	eral Barriers		3.0	
		Fences / Walls	Chainlink	3	At edge of creek
		Entrance/Maintenance Gates	Metal	3	
		Bollards		3	
	Gen	eral Signage		2.7	
		Park ID	Wood	4	
		Park Rules	Wooden Posts	1	Poor location, illegible
		Kiosks	Wooden Posts	3	In large dog park
	Gen	eral Drainage		4.0	
		Culvert	Concrete	4	
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	

1				1	La salas Dala 6/22/2021
	7		le	uo	Inventory Date: 6/22/2021
	nit	÷	eria	liti	Time: 3:40pm - 5:15pm
Park	Amenity	Asset	Type / Materia	•	Field Notes (all italicized noted are notes
ä	Ā	A,	ĘΣ	ŭ	from maintenance staff)
Nort	huro	t Community Dark		3.1	
NOL	1	st Community Park eral Structures		3.1 4.0	
		Sheds			At softball field
				4	
	PICN	ic Areas		2.8	
		Tables*		3	
		Barbecues		3	
		Surfacing	Concrete	3	
		Trash Receptacles		1	Deficient
		Shade Trees		4	
	Park	king Lot		4.0	
		Wheel stops		4	
		Lighting		3	No observable problems
		Surfacing*	Asphalt	4	
		Signage		4	
		Striping		5	Relatively new
	_	ground		3.0	
		Equipment*		3	
		Curb		4	
		Surfacing	Sand	3	Level is low
		Surfacing	Rubber	4	
		Furnishings	Composite	2	Bench and trash, trash is deficient
		Barriers	Chainlink	4	
		Signs		2	Deficient at youth structure
		Drainage		4	No observable problems
	Spor	rts Field / Court 1		3.2	
		Sport Type:	Softball		
		Surfacing*	Infield/Mix	5	Well maintained
		Surfacing*	Outfield/Turf	4	
		Equipment		3	Chainlink fabric pulled off
		Barriers	Chainlink	3	
		Furnishings	Benches/Bleachers	3	
		Signage		3	
		Lighting		4	Not sure if LED. no observable problems
		Irrigation		3	Some patchy spots
		Drainage		3	
		Surfacing*	Asphalt	1	Well maintained

	1				Inventory Date: 6/22/2021
	t				Time: 3:40pm - 5:15pm
~	eni	et	e /	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	Condition	from maintenance staff)
	~	· · · · · · · · · · · · · · · · · · ·			
Nort	thwe	st Community Park		3.1	
		rts Field / Court 2		4.0	
		Sport Type:	Softball		
		Surfacing*	Turf	4	
		Equipment	Goals	4	
		Irrigation*		4	No observable problems
		Drainage		4	No observable problems
	Spo	rts Field / Court 3		3.0	
		Sport Type:	Track & Field		
		Surfacing*	Track fill	4	
		Surfacing*	Turf	3	
		Equipment	Goal Infield	3	Rusted
		Irrigation		2	Significant Dieback
		Drainage		4	No observable problems
	Spo	rts Field / Court 4		2.8	
		Sport Type:	Rugby		
		Surfacing	Turf	3	
		Equipment	Wooden Goal	3	
		Barriers	Chainlink	3	
		Furnishings	Benches/Wood	2	
		Irrigation*		2	Coverage problems
		Drainage		4	No observable problems
	Dog	Park		2.8	
		Surfacing	Mulch	2	Small dog park has no mulch, Large dog park
		Surfacing	IVIUICII	2	has a sparse amount
		Drinking Fountain		4	New hose bib with bucket
		Barriers*	Chainlink	3	
		Benches		2	
		Trash Receptacles		1	Deficient
		Signage		5	
	Bike	Pump Track		3.0	
		Surfacing*	Dirt	3	Significant amount of weeds outside track footprint
		Barriers	Split Rail/Wood	4	
		Furnishings	Metal	5	
* Th	e rat	ing of the amenity shall not exceed t	he rating of the lowest rated	asset v	vith an asterisk
Note	e: Lin	nited assessment items are highlighte	ed in grey		

			_	5	Inventory Date: 6/22/21
	Amenity		/ ria	Condition	Time: 3:01 - 3:30pm
Park		Asset	Type / Materia	pu	Field Notes (all italicized noted are notes
Pa	An	As	ĻΣ	S	from maintenance staff)
)akl	ake (Green Park		3.2	
					General Site Observations: Very lush turf
					area, play area poorly maintained
	Gen	eral Furnishings		2.0	
		Benches	Brick	3	Graffiti on Memorial Bench
		Trash/Recycling Receptacles	Plastic	1	Deficient, temporary bin
	Gen	eral Landscape		3.5	
		Turf		3	Majority of turf great, turf by play area is dead
		Natural Areas		4	
	Gen	eral Trees		4.0	
		Park Trees		4	
		Trees in Natural Areas		4	
	Gen	eral Hardscape		3.5	
		Asphalt		3	Extensive cracking with weed growth
		Concrete		4	
	Gen	eral Irrigation		3.0	
		System operation		2	Turf dead near play area
		System type (drip / spray)	Spray		Rotors
		Controller		4	Smart controller
	Gen	eral Lighting		2.0	
		System Operation		2	Not LED, light missing from 1 pole, light or during day
	Gen	eral Barriers		4.0	
		Guardrails		4	
		Bollards		4	
	Gen	eral Signage		3.5	
		Park ID		4	Paint worn, slight wood rot
		Park Rules		3	Poor location, off to side, far from road
	Gen	eral Drainage		4.0	
		Culvert		4	No observable problems
		Curb and Gutter		4	
		Drain inlet		4	
		Swales / Stormwater Infrastructure		4	Creek In orb. Of park
	Gen	eral Structures		N/A	
	Geil	Pedestrian Bridges (not assessed)		10/7	Present, wood splitting, paint chipping

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/22/21 Time: 3:01 - 3:30pm Field Notes (all italicized noted are notes from maintenance staff)				
Oak	ako (Green Park		3.2					
Uak		ground		2.7					
		Equipment*		3	Rope structure, ropes slightly loose, swing top bar sliding down				
		Curb	Asphalt	2	Major cracking, weed growth, crumbling				
		Surfacing	Fiber	1	Missing? Super low, tree roots growing				
		Surfacing	Concrete	4	Ramp				
		Furnishings	Wood & Metal	3	Worn, warped				
		Signs		4					
		Shade Structures (not assessed)			Present				
		Drainage		2	Needs new drain system				
_	* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk Note: Limited assessment items are highlighted in grey								

	<u> </u>			1	Inventory Data: 7/8/21
	Ł		a	lo l	Inventory Date: 7/8/21
	enit	et	e /	diti	Time: 2:26 - 2:45pm Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	Condition	from maintenance staff)
	٩	4	F 2		
Olive	e Par	k		3.4	
					General Site Observations: Nice use of space overall, however there's some accumulated
					trash/dumping within shade structure, large
					gathering of encampments facing Orange St.
		eral Furnishings		1.5	
		Drinking Fountains		2	
		Trash/Recycling Receptacles	plastic	1	deficient
	Gen	eral Landscape		2.5	
		Turf		3	patchy
		Unplanted Landscape		2	no mulch
	Gen	eral Trees		4.0	
		Park Trees		4	
		Trees in Natural Areas			
	Gen	eral Hardscape		4.0	
		Concrete		4	
		eral Irrigation		3.0	
		System operation		3	coverage issues
		System type (drip / spray)	spray		
		Controller		3	No observable problems
		eral Lighting		3.0	
		System Operation	metal	3	
		eral Barriers		4.0	
		Bollards	metal	4	
	Gen	eral Signage		3.5	
		Park ID	wood	4	
		Park Rules	metal	3	Spanish sign missing
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
		eral Structures		N/A	
		Shade Structures (not assessed)	wood		Major littering
		Pedestrian Bridges (not assessed)			Present
		Restrooms (not assessed)			On site

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 7/8/21 Time: 2:26 - 2:45pm Field Notes (all italicized noted are notes from maintenance staff)
Olive	e Par	k		3.4	
	Play	ground		4.0	
		Equipment*	metal, plastic and composite	4	
		Surfacing	sand	4	minor leaf litter
		Surfacing	rubber	4	
		Furnishings	metal benches	4	
		Barriers	ornamental metal	4	
		Signs	metal	4	on entry gate
		Drainage		4	No observable problems
	Trai	ls		N/A	
		Statue (not assessed)			on site
* The	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated a	asset v	vith an asterisk
Note	: Lim	ited assessment items are highlighted in g	grey		

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/23/21 Time: 1:35 - 1:35pm Field Notes (all italicized noted are notes from maintenance staff)
Owle		t Open Space		2.7	
					General Site Observations: Large hilly open space in the middle of a housing area. Some areas are a potential fire hazard.
	Gen	eral Landscape		1.0	
		Natural Areas		1	No noxious weeds present / annual grasses manageable by mowing, one section is a hazard due to tall brush
	Gen	eral Trees		4.0	
		Trees in Natural Areas		4	
	Gen	eral Drainage		3.0	
		Curb and Gutter		3	
		Drain inlet		3	
		ng of the amenity shall not exceed the rat	-	asset v	vith an asterisk
Note	e: Lim	ited assessment items are highlighted in g	rey		

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/24/2021 Time: 9:55 AM - 10:04 AM Field Notes (all italicized noted are notes from maintenance staff)
Park	ker Hi	ll Open Space		2.7	
					General Site Observations: Has potential for trail use
	Gen	eral Landscape		3.0	
		Natural Areas		3	Fire damage, grasses mowed
	Gen	eral Trees		2.0	
		Trees in Natural Areas		2	Fire Damaged
	Gen	eral Signage		N/A	
		Park ID			None
		Park Rules			None
	Gen	eral Drainage		3.0	
		Curb and Gutter		3	
		Drain inlet		3	
		Swales / Stormwater Infrastructure		3	Cobble channel on South edge
	Trai	s		N/A	Trail Opportunity
		ng of the amenity shall not exceed the rat	-	asset v	vith an asterisk
Note	e: Lim	ited assessment items are highlighted in g	grey		

			·	r			
	Amenity Asset Material		-	uo	Inventory Date: 6/22/21		
		liti	Time: 10:30am - 11:05am				
Park	me	Ameni Asset Materi	Condition	Field Notes (all italicized noted are notes			
Å	A	Ř	ĻΣ	Ŭ	from maintenance staff)		
_							
Park	trail	Open Space		2.8			
					General Site Observations: Nice natural trail, few visitors, furnishings appear worn		
	Gen	eral Furnishings		1.5			
		Benches	Wood	2	Chunk missing		
		Trash/Recycling Receptacles	Plastic	1	Deficient		
	Gen	eral Landscape		3.0			
		Natural Areas		3	No noxious weeds present / annual grasses manageable by mowing, shrub growth not dense, primarily native species (Poison Oak), planting strips along street weedy and needs mulch		
	Gen	eral Trees		3.0			
		Trees in Natural Areas		3			
	Gen	eral Barriers		3.3			
		Fences / Walls	Split Rail	1	Missing bolts, leaning		
		Fences / Walls 2	Metal stake, barbed wire	4			
		Entrance/Maintenance Gates	Chainlink	4			
		Bollards	Metal	4	light graffiti		
	Gen	eral Signage		2.5			
		Wayfinding		1	Extremely faded		
		Park Rules		4			
	Gen	eral Drainage		4.0			
		Culvert		4	No observable problems		
		Curb and Gutter		4			
		Swales / Stormwater Infrastructure		4	No observable problems		
	Trai	ls		2.0			
		Surfacing*	Gravel	2	Uneven, large rocks, natural trail		
		ing of the amenity shall not exceed the rat	5	asset v	vith an asterisk		
Note	lote: Limited assessment items are highlighted in grey						

	İ		ĺ		Inventory Data: 7/7/21
	≥	Asset Type / Material	a	on	Inventory Date: 7/7/21
	Amenity		diti	Time: 9:10-10:08am	
Park	Ĕ		, Vpc	Condition	Field Notes (all italicized noted are notes from maintenance staff)
	◄	٩	F 2	0	
Pear	blos	som Park		3.3	
					General Site Observations: clean and well
					maintained overall, safe environment
	Gen	leral Furnishings		3.4	
		Benches	Concrete	4	
		Bike Racks	Metal	4	
		Drinking Fountains	Concrete	4	
		Trash/Recycling Receptacles	Plastic	1	Deficient
		Other: Tree Grates	Iron	4	
	Gen	eral Landscape		2.0	
		Turf		3	Patchy
		Non-Turf Ornamental Landscape		1	Dead and missing
		Unplanted Landscape		2	No mulch
	Gen	eral Trees		4.0	
		Park Trees		4	Few dead / missing
	Gen	eral Hardscape		3.0	
		Concrete		3	Minor cracking
		Pavers		3	Uneven throughout
	Gen	eral Irrigation		3.0	
		System operation		2	Turf area has coverage issues
		System type (drip / spray)	Spray		
		Controller		4	
		eral Barriers		4.0	
		Handrails	Metal	4	Minor rust
		Bollards	Concrete and Metal	4	Few concrete bollards missing
	Gen	ieral Signage		3.0	
		Park Rules	Metal	3	
	Gen	eral Drainage		4.0	
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	
	Gen	eral Structures		N/A	
		Shade Structures (not assessed)	Wood Trellis/Concrete		Present, wood decay / multiple signs of
			Post		deterioration

		1			Inventory Date: 7/7/21		
	ť		a	Condition	Time: 9:10-10:08am		
	eni	et	e / :eri	dit	Field Notes (all italicized noted are notes		
Park	Amenity	Asset	Type / Materia	U U	from maintenance staff)		
	4	₹	F 2	0			
Pear	bloss	som Park		3.3			
	1	lic Areas		3.0			
		Tables*	Concrete	4			
		Barbecues	Metal	4	Minor rust		
		Surfacing	Concrete	4			
		Trash Receptacles	Plastic	1	Deficient		
		Shade Trees		2	Tree missing and one is struggling		
	Play	ground		3.4			
		Equipment*		4			
		Curb	Concrete	4			
		Surfacing	Sand	3	Sand is not level, half of play area has low levels of sand at curbs		
		Surfacing	Rubber	4			
		Surfacing	Concrete	2	Major lifting and cracking		
		Furnishings: Bench and Picnic Table	Concrete	4			
		Signs	Metal	2	Missing sign on second structure		
		Drainage		4	No observable problems		
	Spo	rts Field / Court 1		3.0			
		Sport Type:	Basketball				
		Surfacing*	Concrete	3	Minor cracks		
		Field striping		4			
		Equipment	Metal hoops	4			
		Drainage		4	No observable problems		
* Th	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated	asset v	l vith an asterisk		
		nited assessment items are highlighted in g					
	ster Einneed assessment items are insingliced in grey						

				c	Inventory Date: 7/7/21
	itγ		' ial	tiol	Time: 10:10 - 11;03am
¥	Amenity	set	Type / Materia	Condition	Field Notes (all italicized noted are notes
Park	Am	Asset	Ma	Ō	from maintenance staff)
Pear	blos	som Trail		3.1	
					General Site Observations: Clean/well
					maintained overall, safe environment
	Gen	eral Landscape		2.0	
		Non-Turf Ornamental Landscape		2	No mulch
		Unplanted Landscape		2	No mulch
		Natural Landscape		4	
	Gen	eral Trees		4.0	
		Park Trees		4	No observable problems
		Trees in Natural Areas		4	
	Gen	eral Hardscape		2.0	
					Minor cracking and lifting, and sidewalk
		Concrete		2	edging and parking has major lifting and
					signs of grinding
	Gen	eral Irrigation		3.0	
		System operation		3	Operation unknown
		System type (drip / spray)	Drip		Octo-bubblers
		Controller			Not found
	Gen	ieral Lighting		4.0	
		System Operation		4	Cant' verify if its not LED
	Gen	ieral Drainage		4.0	
		Curb and Gutter	Concrete	4	At parking lot, minor cracking
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	
	Trai	ls		3.0	
		Surfacing*	Asphalt	3	Minor cracking
		Barriers	Metal Bollards	4	
		ing of the amenity shall not exceed the rat		asset v	vith an asterisk
Note	e: Lim	nited assessment items are highlighted in g	grey		

	1				Inventory Date: 6/23/2021
	Ę		a	ion	Time: 8:12am-8:49am
	eni	ы с	e / :eri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	Condition	from maintenance staff)
⊢≞	4	7	F 2		
Pete	rson	Lane Park		2.8	
				2.0	
					General Site Observations: Few people
					observed on site using park for exercise, well
					maintained park, safe environment overall
	Gen	eral Furnishings		2.5	
		Benches	Wood	2	
		Bike Racks	Wood	3	
		Drinking Fountains		4	
		Trash/Recycling Receptacles		1	Deficient
	Gen	ieral Landscape		2.8	
		Turf		4	
		Non-Turf Ornamental Landscape		2	
		Unplanted Landscape		2	At side walk planting strip and fence line
		Natural landscape		3	Dense shrubs, blackberries
	Gen	eral Trees		4.0	
		Park Trees		4	
		Trees in Natural Areas		4	
	Gen	eral Hardscape		2.0	
		Asphalt		2	
		Concrete		2	
		Pavers		2	
	Gen	eral Irrigation		4.0	
		System operation		4	No observable problems
		Controller		4	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	Mixed lamps
	Gen	eral Barriers		2.0	
		Bollards	Wood and Metal	2	some are missing
	Gen	eral Signage		3.0	
		Park ID	Wood	4	At corner of Peterson Lane and Yardley St
		Park Rules	Metal	2	
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	Creek with blackberry shrubs, No observable problems

	Amenity	t	Type / Material	Condition	Inventory Date: 6/23/2021 Time: 8:12am-8:49am Field Notes (all italicized noted are notes
Park	Ame	Asset	Type / Mater	Con	from maintenance staff)
	-			_	,
Pete	rson	Lane Park		2.8	
	Gen	eral Structures		N/A	
		Pedestrian Bridges (not assessed)	Wood and Steel		Present, steel is rusty
	Picn	ic Areas		2.0	
		Tables*	Wood	2	Deteriorating wood and loose boards
		Surfacing	Concrete	3	
		Trash Receptacles	Stee;	1	Deficient
		Water Source	Concrete	4	Drinking Fountain, No observable problems water turned off
	Fitn	ess Equipment		2.0	
		Type: cluster/par course	Cluster		
		Equipment*	Metal and Wood	2	Excessive wear, low mulch
		Surfacing	Mulch	2	Very low level of mulch
		Barriers/Curb	Concrete	3	
	Play	ground		2.3	
		Equipment*	Metal and Wood	3	
		Curb	Concrete	3	
		Surfacing	Mulch	2	Very low mulch
		Furnishings	Bench/Wood	1	Loose boards at tot-lot, and missing boards at large play structure
		Signs		1	Deficient
		Drainage		4	No observable problems
				4	
* Th	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated a	I asset v	ı vith an asterisk
		ited assessment items are highlighted in g	-		

Image: Constraint of the second state of the seco		iity		/ rial	ition	Inventory Date: 6/22/21 Time: 11:30am to 11:50am		
Peter Springs Park 3.4 General Site Observations: Lush I area looks very worn, strong combetween neighborhoods General Furnishings 2.3 Benches Wood Tables Metal Tash/Recycling Receptacles Plastic Turf 4 Ceneral Landscape 4.0 Turf 4 Non-Turf Ornamental Landscape 4.0 General Hrigation 3.0 Concrete 4.0 Concrete 4.0 Concrete 4.0 Concrete 4.0 System operation 3.1 or 2 heads need repair System type (drip / spray) Spray Boollards 3.0 General Signage 4.0 Park Rules 3.0 General Signage 4.0 Park Rules 3.0 General Signage 4.0 Park Rules 3.0 General Signage 4.0 Park Rules 4 General Signage 4.0 Park Rules 4 General Signage 4.0 <t< th=""><th>rk</th><th>ner</th><th>set</th><th>pe , ate</th><th>ndi</th><th>Field Notes (all italicized noted are notes</th></t<>	rk	ner	set	pe , ate	ndi	Field Notes (all italicized noted are notes		
General Furnishings 2.3 Benches Wood 3 Wear, paint chips Tables Metal 3 Wear, old Trash/Recycling Receptacles Plastic 1 Temp, deficient General Landscape 4.0 1 Temp, deficient Mon-Turf Ornamental Landscape 4.0 1 Weavy General Trees 4.0 1 Concret 4 Park Trees 4.0 1 Concret 4 General Irrigation 3.0 1 Operation 3.0 System operation 3 1 or 2 heads need repair 8 System type (drip / spray) Spray Booster pump Controller 3 Wood 4 Bollards 3 Worn, functional General Signage 4.0 1 1 Curb and Gutter 4 1 1 1 Bollards 3 Worn, functional 1 1 1 1 Curb and Gutter 4 1 1 1 1 1 1 1 1	Ра	An	As	ζž	S	from maintenance staff)		
General Furnishings 2.3 Benches Wood 3 Wear, paint chips Tables Metal 3 Wear, old Trash/Recycling Receptacles Plastic 1 Temp, deficient General Landscape 4.0 1 Temp, deficient Mon-Turf 4 Lush, green, small dry spots (irrig Non-Turf Ornamental Landscape 4.0 1 Park Trees 4.0 1 Concrete 4.0 1 1 Concrete 4.0 1 1 System operation 3.0 1 1 or 2 heads need repair System type (drip / spray) Spray Booster pump Controller 3.0 3 Worn, functional General Barriers 3.0 3 Worn, functional General Signage 4.0 1 1 1 Cutvet 4 1 1 2 1 System type (drip / spray) Spray Booster pump 2 1 1 Cutve data 3 Worn, functional 4 4 1 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
General Furnishings 2.3 Benches Wood 3 Tables Metal 3 Tash/Recycling Receptacles Plastic 1 Turf 4.0 Mon-Turf Ornamental Landscape 4.0 Park Trees 4.0 General Hardscape 4.0 General Trees 4.0 Concrete 4.0 General Irrigation 3.0 System type (drip / spray) Spray System type (drip / spray) Spray Bollards 3.0 General Barriers 3.0 General Barriers 3.0 General Barriers 3.0 General Barriers 3.0 General Barriers 3.0 General Barriers 3.0 General Drainage 4.0 General Barriers 3.0 General Barriers 3.0 General Drainage 4.0 Curb and Gutter 4 Curb and Gutter 4 Drain inlet 4 No observable problems General Barriers 3.0 System openation 3.1 General Barriers 3.0 General Barriers 3.0 General Barriers <td>Pete</td> <td>r Spr</td> <td>ings Park</td> <td></td> <td>3.4</td> <td></td>	Pete	r Spr	ings Park		3.4			
General Furnishings 2.3 Benches Wood 3 Wear, paint chips Tables Metal 3 Trash/Recycling Receptacles Plastic 1 Trash/Recycling Receptacles Plastic 1 Turf 4 Lush, green, small dry spots (irrig Non-Turf Ornamental Landscape 4 Weedy General Trees 4.0 General Trees 4.0 Concrete 4 General Irrigation 3.0 System operation 3.0 System type (drip / spray) Spray Bollards 3.0 General Barriers 3.0 Bollards 3.0 Park Rules 4.0 Park Rules 4.0 Curbert 4.0 Park Rules 4.0 Curband Gutter 4.0 Park Rules 4.0 Curband Gutter 4.0 Park Rules 4.0 Curband Gutter 4.0 Park Rules 4.0 Curband Gutter 4.0 Drain inlet 4.0 Drain inlet 4.0 Drain inlet 4.0 Drain inlet 4.0 Drain inle						General Site Observations: Lush lawn, play		
General Furnishings 2.3 Benches Wood 3 Wear, paint chips Tables Metal 3 Wear, old Trash/Recycling Receptacles Plastic 1 Temp, deficient General Landscape 4.0 Lush, green, small dry spots (irrig Non-Turf Ornamental Landscape 4 Weedy General Trees 4.0 Image: Concrete 4 General Hardscape 4.0 Image: Concrete 4 General Irrigation 3.0 Image: Concrete 4 System type (drip / spray) Spray Booster pump Controller System type (drip / spray) Spray Booster pump Sobervable problems General Barriers 3.0 No observable problems General Signage 4.0 Image: Controller 3 Park Rules 4 Image: Controller 3 Wood Park Rules 4.0 Image: Controller 3 Wood Image: Controller General Signage 4.0 Image: Controller 3 Wood Image: Controller 1mage: Controller 1mage: Controller								
BenchesWood3Wear, paint chipsTablesMetal3Wear, oldTrash/Recycling ReceptaclesPlastic1Temp, deficientGeneral Landscape4.0Lush, green, small dry spots (irrigNon-Turf Ornamental Landscape4WeedyGeneral Trees4.0Park Trees4.0Concrete4.0General Hardscape4.0Concrete4.0General Irrigation3.0System operation31 or 2 heads need repairSystem operation31 or 2 heads need repairSystem type (drip / spray)SprayBooster pumpController3No observable problemsGeneral Signage4.0Park Rules4Curb and Gutter4.0Park Rules4.0Curb and Gutter4Curb and Gutter4Curb and Gutter4Curb and Gutter4Curb and Gutter4Curb and Gutter4Curb and Gutter2.0Equipment*MetalSurfacingSandSurfacingSandSurfacingSandSurfacingSandArtNo observable problemsArtNo observable problems		•			2.2	between neighborhoods		
TablesMetal3Wear, oldTrash/Recycling ReceptaclesPlastic1Temp, deficientGeneral Landscape4.04Lush, green, small dry spots (irrigNon-Turf Ornamental Landscape4.04WeedyGeneral Trees4.04MeedyGeneral Trees4.04General TreesGeneral Hardscape4.04General TreesGeneral Irrigation3.031 or 2 heads need repairSystem type (drip / spray)SprayBooster pumpController3No observable problemsGeneral Signage4.04General Signage4.0Park Rules4Curb and Gutter4Curb and Gutter4Curb and Gutter4Curb and Gutter4CurbConcreteGeneral Drainage4.0Curb and Gutter4Drain inlet4No observable problemsGingns3Metal2Missing swing, excess wearCurbConcreteSurfacingSandSigns4NoneSigns4NoDrainage4NoCurb And Gutter4CurbConcrete3CracksSurfacingSandSigns4NoneSigns4NoCurbConcreteSigns4No </td <td></td> <td>Gen</td> <td></td> <td>N4/</td> <td>-</td> <td></td>		Gen		N4/	-			
Trash/Recycling ReceptaclesPlastic1Temp, deficientGeneral Landscape4.0Lush, green, small dry spots (irrig Non-Turf Ornamental Landscape4WeedyGeneral Trees4.0Park Trees4.0Park Trees4.0General Hardscape4.0Concrete4General Hardscape4.0Concrete4General Hardscape3.0System operation31 or 2 heads need repairSystem type (drip / spray)SprayBooster pumpController3No observable problemsGeneral Signage4.03Mood4Park IDWood4Park Rules4General Drainage4.0Curbert4Curbert4Drain Inlet4AConcreteSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandArtNo eservable problems					-			
General Landscape 4.0 Turf 4 Non-Turf Ornamental Landscape 4 Weedy 4 General Trees 4.0 Park Trees 4.0 Concrete 4 General Irrigation 3.0 System operation 3 1 or 2 heads need repair System operation 3 1 or 2 heads need repair System type (drip / spray) Spray Booster pump Controller 3 No observable problems General Barriers 3.0 1 Bollards 3 Worn, functional General Signage 4.0 1 Park ID Wood 4 Culvert 4 1 Culvert 4 1 Curb and Gutter 4 1 Drain inlet 4 1 Playground 2.0 1 Barriers 3 Weedy, 0 Barriers 3 1 Drain inlet 4 1 Drain inlet 4 1 <td< td=""><td></td><td></td><td></td><td></td><td>-</td><td></td></td<>					-			
Turf4Lush, green, small dry spots (irrigNon-Turf Ornamental Landscape4WeedyGeneral Trees4.0Park Trees4.0Concrete4.0Concrete4General Irrigation3.0System operation3.1 or 2 heads need repairSystem type (drip / spray)SprayBooster pumpController3.0General Barriers3.0General Signage4.0Park Rules4General Drainage4.0Culvert4Cutrot4Cutrot4System type (drip / spray)SprayBollards3Worn, functionalGeneral Signage4.0Park Rules4Cutvert4Cutvert4Cutvert4Cutvert4Cutvert4Cutv2.0Equipment*MetalSurfacingSandSigns4NoneSigns4NoDrainage4NoneSurfacingSandSurfacingSandSurfacingSandArtNoN/A		•	•	Plastic	-	lemp, deficient		
Non-Turf Ornamental Landscape 4 Weedy General Trees 4.0 Park Trees 4.0 General Hardscape 4.0 Concrete 4 General Irigation 3.0 System operation 3.0 System operation 3 l or 2 heads need repair System type (drip / spray) Spray Booster pump Controller Controller 3.0 Bollards 3.0 General Signage 4.0 Park Rules 4 General Drainage 4.0 Culvert 4 Culvert 4 Culvert 4 Culvert 4 Drain inlet 4 No observable problems Playground 2.0 Equipment* Metal 2 Missing swing, excess wear Curb Curb Concrete 3 Surfacing Sand 3 Barriers Metal 2 Barriers None None Signs 4 <td></td> <td>Gen</td> <td>-</td> <td></td> <td></td> <td></td>		Gen	-					
General Trees 4.0 Park Trees 4 General Hardscape 4.0 Concrete 4 General Irrigation 3.0 System operation 3 System type (drip / spray) Spray Booster pump Controller 3 Mo observable problems General Barriers 3.0 Bollards 3 Worn, functional General Signage 4.0 Park Rules 4 Culvert 4 Culvert 4 Curb and Gutter 4 Playground 2.0 Equipment* Metal 2 Missing swing, excess wear Curb Curb Sand 3 Verain Gutter 4 1 Drain inlet 4 No observable problems Playground 2.0 1 Equipment* Metal 2 Surfacing Sand 3 Surfacing Sand 3 Barriers None 1 </td <td></td> <td></td> <td></td> <td></td> <td>-</td> <td></td>					-			
Park Trees4General Hardscape4.0Concrete4General Irrigation3.0System operation3System operation3System type (drip / spray)SprayBooster pumpController3No observable problemsGeneral Barriers3.0Bollards3Worn, functionalGeneral Signage4.0Park Rules4Culvert4Curb and Gutter4Drain inlet4No observable problemsPlayground2.0Equipment*MetalCurbConcreteSurfacingSandSurfacingSandSurfacingSandArtNo observable problems						Weedy		
General Hardscape4.0Concrete4General Irrigation3.0System operation3System operation3Controller3Controller3Bollards3General Barriers3.0Bollards3Worn, functionalGeneral Signage4.0Park IDWoodPark Rules4General Drainage4.0Culvert4Drain inlet4No observable problemsPlayground2.0Equipment*MetalSurfacingSandSigns4NoneSigns4NoArtNo observable problems		Gen	eral Trees		4.0			
Concrete4General Irrigation3.0System operation31 or 2 heads need repairSystem type (drip / spray)SprayBooster pumpController3No observable problemsGeneral Barriers3.0Bollards3Worn, functionalGeneral Signage4.0Park IDWood4Park Rules4.0Culvert4Curb and Gutter4Drain inlet4Playground2.0Equipment*Metal2CurbSand3Weeds, debris, low levelBarriers3ArtNo observable problems			Park Trees		4			
General Irrigation3.0System operation31 or 2 heads need repairSystem type (drip / spray)SprayBooster pumpController3No observable problemsGeneral Barriers3.0Bollards3Worn, functionalGeneral Signage4.0Park IDWood4Park Rules4.0General Drainage4.0Culvert4Curb and Gutter4Drain inlet4No observable problemsPlayground2.0Equipment*MetalSurfacingSandSurfacingSandSigns4NoneSigns4ArtNo observable problemsArtNoNo		Gen	eral Hardscape		4.0			
System operation31 or 2 heads need repairSystem type (drip / spray)SprayBooster pumpController3No observable problemsGeneral Barriers3.0Bollards3Worn, functionalGeneral Signage4.0Park IDWood4Park Rules4.0General Drainage4.0Culvert4Curb and Gutter4Drain inlet4Paryground2.0Equipment*MetalSurfacingSandSurfacingSandSurfacingSandSurfacingSandArtNo observable problemsArtNo observable problemsArtNoN/A			Concrete		4			
System type (drip / spray)SprayBooster pumpController3No observable problemsGeneral Barriers3.0Bollards3Worn, functionalGeneral Signage4.0Park IDWood4Park Rules4General Drainage4.0Culvert4Curb and Gutter4Drain inlet4Park Type (drip mather4Park Type (drip mather4Curb and Gutter4Drain inlet4Curb and Gutter2.0Equipment*Metal2Missing swing, excess wearCurbConcrete3SurfacingSand3Weeds, debris, low levelBarriers4No equipment labelsDrainage4No observable problemsArtN/A		Gen	eral Irrigation		3.0			
Controller3No observable problemsGeneral Barriers3.0Bollards3.0General Signage4.0Park IDWood4Park Rules4.0General Drainage4.0Culvert4.0Curb and Gutter4.0Drain inlet4.0Playground2.0Equipment*MetalCurbConcreteSurfacingSandSurfacingSandSigns4NoneSigns4ArtN/A			System operation		3	1 or 2 heads need repair		
General Barriers3.0Bollards3Worn, functionalGeneral Signage4.0Park IDWoodPark Rules4General Drainage4.0Culvert4Curb and Gutter4Drain inlet4Playground2.0Equipment*MetalSurfacingSandSurfacingSandBarriersADrainage4ArtNo observable problemsMetalPracksCurbConcreteSigns4No equipment labelsDrainage4NoNo bervable problems			System type (drip / spray)	Spray		Booster pump		
Bollards3Worn, functionalGeneral Signage4.0Park IDWood4Park Rules4General Drainage4.0Culvert4Curb and Gutter4Drain inlet4Playground2.0Equipment*Metal2Metal2SurfacingSand3Weeds, debris, low levelBarriers4Drainage4ArtNo observable problems			Controller		3	No observable problems		
General Signage4.0Park IDWood4Park Rules4General Drainage4.0Culvert4Curb and Gutter4Drain inlet4No observable problemsPlayground2.0Equipment*Metal2CurbConcrete3SurfacingSand3Weeds, debris, low levelBarriers4No neSigns4ArtN/A		Gen	eral Barriers		3.0			
Park IDWood4Park Rules4General Drainage4.0Culvert4Curb and Gutter4Drain inlet4Drain inlet4Playground2.0Equipment*Metal2CurbConcrete3SurfacingSand3BarriersNoneSigns4Drainage4ArtNo abservable problemsN/A			Bollards		3	Worn, functional		
Park Rules4General Drainage4.0Culvert4.0Culvert4Curb and Gutter4Drain inlet4Playground2.0Equipment*Metal2CurbConcrete3SurfacingSand3BarriersNo equipment labelsSigns4No observable problemsDrainage4ArtN/A		Gen	eral Signage		4.0			
General Drainage4.0Culvert4Curb and Gutter4Drain inlet4Playground2.0Equipment*Metal2CurbConcrete3CurbConcrete3SurfacingSand3BarriersMoneSigns4Drainage4ArtNo observable problems			Park ID	Wood	4			
Culvert4Curb and Gutter4Drain inlet4Playground4Requipment*MetalCurbConcreteCurbConcreteSurfacingSandBarriersNo equipment labelsSigns4Drainage4ArtNo dbservable problems			Park Rules		4			
Curb and Gutter4Drain inlet4Playground4Requipment*2.0CurbConcreteCurbConcreteSurfacingSandSurfacingSandBarriersNoneSigns4Drainage4ArtN/A		Gen	eral Drainage		4.0			
Drain inlet 4 No observable problems Playground 2.0 Equipment* Metal 2 Missing swing, excess wear Curb Concrete 3 Cracks Surfacing Sand 3 Weeds, debris, low level Barriers Ant No equipment labels No observable problems			Culvert		4			
Playground 2.0 Equipment* Metal 2 Curb Concrete 3 Cracks Surfacing Sand 3 Weeds, debris, low level Barriers None Signs 4 No equipment labels Drainage Art N/A N/A			Curb and Gutter		4			
Equipment* Metal 2 Missing swing, excess wear Curb Concrete 3 Cracks Surfacing Sand 3 Weeds, debris, low level Barriers None Signs 4 No equipment labels Drainage 4 No observable problems N/A			Drain inlet		4	No observable problems		
Curb Concrete 3 Cracks Surfacing Sand 3 Weeds, debris, low level Barriers None Signs 4 No equipment labels Drainage 4 No observable problems Art N/A		Play	/ground		2.0			
Surfacing Sand 3 Weeds, debris, low level Barriers None Signs 4 No equipment labels Drainage 4 No observable problems Art N/A			Equipment*	Metal	2	Missing swing, excess wear		
Barriers None Signs 4 No equipment labels Drainage 4 No observable problems Art N/A			Curb	Concrete	3	Cracks		
Barriers None Signs 4 No equipment labels Drainage 4 No observable problems Art N/A			Surfacing	Sand	3	Weeds, debris, low level		
Drainage 4 No observable problems Art N/A						None		
Drainage 4 No observable problems Art N/A			Signs		4	No equipment labels		
					4	No observable problems		
Mural / Mosaic (not assessed) Mural on residential fence		Art			N/A			
			Mural / Mosaic (not assessed)			Mural on residential fence		
* The rating of the amenity shall not exceed the rating of the lowest rated accot with an actorick	* Th	The rating of the emerity shall not evened the rating of the lowest rated exact with an extension						
Note: Limited assessment items are highlighted in grey		The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk						

	i –			1	Laurante and Deter (122/2021
	~		<u>–</u>	Condition	Inventory Date: 6/23/2021
	nit		eris	liti	Time: 11:13am - 11:48am
Park	Amenity	Asset	Type / Materia	ou c	Field Notes (all italicized noted are notes
ä	Ā	Ř	ĘΣ	Ŭ	from maintenance staff)
Dion	oneer Park			3.2	
FION				5.2	
					General Site Observations: Well maintained park, playground was highly used by locals
	Gen	eral Furnishings		3.4	
		Benches	Wood	4	
		Tables	Wood	4	
		Bike Racks	Metal	4	
		Drinking Fountains	Concrete	4	
		Trash/Recycling Receptacles		1	Deficient
	Gen	eral Landscape		3.0	
		Turf		4	
		Non-Turf Ornamental Landscape		3	
		Unplanted Landscape		2	
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		3.0	
		Concrete		3	Cracks and lifting throughout paths
	Gen	eral Irrigation		4.0	
		System operation		4	No observable problems
		System type (drip / spray)	Spray		
		Controller		4	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	
	Gen	eral Barriers		3.5	
		Fences / Walls	Wood	3	Low perimeter fence
		Bollards	Metal	4	
	Gen	eral Signage		3.0	
		Park ID		3	At corner of Red Oak and Pioneer. Signs of wood splitting.
		Park Rules		3	
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	

	1				Inventory Date: 6/23/2021
	ť		a	ion	Time: 11:13am - 11:48am
×	eni	et	e / teri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	Condition	from maintenance staff)
-					
Pion	eer F	Park		3.2	
	1	nic Areas		3.4	
		Tables*	Wood	4	
		Barbecues	Metal	4	
		Surfacing	Concrete	4	
		Trash Receptacles	Plastic and Steel	1	Deficient
		Shade Trees		4	
	Play	/ground		3.0	
	,	Equipment*		3	
		Curb		4	
		Surfacing	Sand	4	
		Surfacing	Rubber	4	
		Furnishings	Tables and Bench	4	
		Barriers	Wood	3	Deteriorating
		Signs		1	Deficient
		Surfacing	Concrete	3	Some lifting and cracks
		Shade Structures (not assessed)	Concrete		Present
		Drainage		4	No observable problems
	Sno	rts Field / Court 1		2.0	
	500	Sport Type:	Horseshoe	2.0	
		Surfacing*	D.G.	2	Weedy, surface needs to be redone
		Surfacing*	Concrete	2	Tree roots lifting path
		Equipment	Wood and Steel	2	Leaning posts and rotting wood
		Barriers	Wood	3	
		Drainage	Wood		No observable problems
	Sno	rts Field / Court 2		3.0	
	500	Sport Type:	Basketball	0.0	
		Surfacing*	Asphalt	3	
		Striping	Apriate	3	
		Equipment		3	
		Drainage		4	No observable problems
	Sno	rts Field / Court 3		3.0	
	240	Sport Type:	Handball	5.0	
		Surfacing*	Asphalt	3	
		Equipment	Wood/Metal Post	2	Broken Boards
		Furnishings	Wood Bench	3	
		Drainage		4	No observable problems
				+	
* Th	e rati	I ing of the amenity shall not exceed the r	I ating of the lowest rated	l asset v	L vith an asterisk
		nited assessment items are highlighted in	-		the an ascenor
		inter assessment items are inginighted if	0 1		

—	r		1	1	Inventory Date: 5/18/21 7/0/21
	≥		a	on	Inventory Date: 5/18/21, 7/8/21
	hil	t t	eri	diti	Time: 8:00am - 8:15am
Park	Amenity	Asset	Type / Materia	Condition	Field Notes (all italicized noted are notes
	◄	٩٩	⊢ 2	U	from maintenance staff)
During		harren Dark		4.0	
Prin	ce Ga	ateway Park		4.0	Conoral Site Observations: Eairly new park
					General Site Observations: Fairly new park, clean and well maintained overall,
	Con	l neral Furnishings		3.7	encampments utilizing benches
	Gen	Benches			
				4	
		Drinking Fountains		4	
	-	Trash/Recycling Receptacles		3	
	Gen	ieral Landscape		4.5	
		Turf		5	
		Non-Turf Ornamental Landscape		4	
	Gen	ieral Trees		5.0	
		Park Trees		5	
	Gen	eral Hardscape		4.7	
		Concrete		5	
		Pavers		4	
		Amphitheater		5	
	Gen	eral Irrigation		4.0	No observable problems
		System operation		4	
		Controller		4	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	
	Gen	eral Barriers		4.3	
		Fences / Walls	ornamental metal	4	with wooden posts
		Guardrails	ornamental metal	4	with wooden posts
		Handrails		5	
	Gen	eral Signage		4.0	
		Park ID		5	
		Wayfinding		5	
		Park Rules		3	
		Interpretive Signage		3	
	Gen	ieral Drainage		4.5	
		Culvert		4	
		Curb and Gutter		5	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		5	
	Gen	neral Structures		N/A	
	Jen	Pedestrian Bridges (not assessed)			Present
		Restrooms (not assessed)			Present
			<u>I</u>		l'resent

Park	Amenity	Asset	Type / Material		Inventory Date: 5/18/21, 7/8/21 Time: 8:00am - 8:15am Field Notes (all italicized noted are notes from maintenance staff)			
Prin	ce Ga	teway Park		4.0				
		ayground		2.0				
		Equipment*		2	UV light is outdated, Off for winter, water turned off			
		Surfacing	concrete	4				
	Art			N/A				
		Surfacing (not assessed)			brand new, on site			
		Structure (not assessed)			brand new, on site			
		Mural / Mosaic (not assessed)			brand new, on site			
* Th	* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk							
Note	e: Lim	ited assessment items are highlighted in g	rey					

					Inventory Date: 5/18/21
	ť		a	Condition	
	enit	t.	eri	diti	Time:
Park	Amenity	Asset	Type / Materia	o	Field Notes (all italicized noted are notes
	٩	Δ	⊢ 2	0	from maintenance staff)
During				2 5	
Princ		emorial Greenway		3.5	Concret Site Observationer Creaning with
					General Site Observations: Greenway with
					nice features (art, bridge) that add interest
					to the walking path. Issues with trash receptacles (some are overflowing or are left
					open)
	Gen	eral Furnishings		3.0	Benches not accessible
		Benches	wooden	3	quantity of 2, one missing a wooden slat
		Trash/Recycling Receptacles	metal	3	a few broken or missing pieces
	Gen	eral Landscape		3.5	
		Non-Turf Ornamental Landscape		3	weedy
		Natural landscape		4	
	Gen	eral Trees		4.0	
		Park Trees		4	vigorous, non-irrigated/maintained
		Trees in Natural Areas		4	
	Gen	eral Hardscape		4.0	
		Concrete	gray	4	good condition, minimal cracking/stains
	Gen	eral Irrigation		2.5	
		System operation		1	Main line wasn't put in w/ backflow or City
		System operation		T	water line. unknown not functional
		System type (drip / spray)	spray		
		Controller		4	enclosure, no visible issues
	Gen	eral Lighting		3.0	
		System Operation		3	Not LED, visibly worn
	Gen	eral Barriers		4.0	
		Fences / Walls	wood posts, metal clad	4	generally good, few damaged posts
		Fences / Walls 2	stone veneer walls	4	normal wear, stains
		Handrails	metal, black	4	no issues, normal wear
	Gen	eral Signage		3.7	Access: signs not at 40-70"
		Wayfinding		4	relatively new
		Park Rules	metal	3	normal wear
		Interpretive Signage		4	near new, minor stains and graffiti
	Gen	eral Drainage		4.0	No observable problems
		Culvert	corrugated	4	appears functional
		Curb and Gutter		4	
		Drain inlet		4	
		Swales / Stormwater Infrastructure		4	

Park	Amenity	Asset	Type / Material		Inventory Date: 5/18/21 Time: Field Notes (all italicized noted are notes from maintenance staff)		
Princ	ce Me	emorial Greenway		3.5			
	Gen	eral Structures		N/A			
		Shade Structures (not assessed)	wood trellis		Present, visibly worn, graffiti		
		Pedestrian Bridges (not assessed)	metal (qty:2)		Present, light, normal wear		
	Art			N/A			
		Surfacing (not assessed)	tile paving		Light wear		
		Structure (not assessed)			Present		
		Mural / Mosaic (not assessed)	painting, tile veneer		Minimal graffiti		
-		ng of the amenity shall not exceed the rat		asset v	vith an asterisk		
Note	e: Lim	ited assessment items are highlighted in g	rey				

					Inventory Date: 7/8/21
	ity		ia	tior	Time: 2:54 - 3:20pm
_	Amenity Asset Type / Material	Condition	Field Notes (all italicized noted are notes		
Park	Am	Asset	Ma	Cor	from maintenance staff)
			. –		
Rae	Stree	t Park		3.3	
					General Site Observations: Encampments in
					play structure and picnic table area, passing
					through park felt uncomfortable
	Gen	eral Furnishings		3.0	
		Benches	wood	4	
		Tables	aluminum	4	
		Trash/Recycling Receptacles	plastic	1	deficient
	Gen	eral Landscape		3.0	
		Turf		3	very patchy and lots od dieback
		Non-Turf Ornamental Landscape		3	very weedy
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete	aggregate	4	
	Gen	eral Irrigation		2.5	
		System operation		2	
		System type (drip / spray)	spray		
		Controller		3	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	post showing deterioration
	Gen	eral Barriers		3.0	
		Bollards	wood	3	signs of deterioration
		eral Signage		3.0	
		Park ID	wood	2	facing Hendly Street
		Park Rules	metal	4	
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	
		Swales / Stormwater Infrastructure		4	

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 7/8/21 Time: 2:54 - 3:20pm Field Notes (all italicized noted are notes from maintenance staff)				
_					, 				
	-	et Park		3.3 3.9					
	-	ground							
		Equipment*	plastic and metal	4					
		Curb	concrete	4					
		Surfacing	sand	4					
		Surfacing	rubber	4					
		Furnishings	wood bench	4					
		Signs		4	on structure				
		Drainage		3	No observable problems				
* Th	* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk								
Note	e: Lim	nited assessment items are highlighted in g	rey						

				İ _	Inventory Date: 7/8/21			
	tγ		a	ion	Time: 1:00 - 1:19PM			
	eni	ti di seconda di seconda di seconda di seconda di seconda di seconda di seconda di seconda di seconda di second	e / :eri	dit	Field Notes (all italicized noted are notes			
Park	Amenity	Asset	Type / Materia	Condition	from maintenance staff)			
<u> </u>	1	۲	F 2					
Railr	beo	Depot Park		3.4				
Nam	Jau			5.4	General Site Observations: Very friendly			
					pocket park, main path is highly used from			
					those coming from parking lot to storefront			
					across, signs of encampments within turf			
					areas			
	Gen	ueral Furnishings		4.0				
		Benches	wood and metal	4				
		Trash/Recycling Receptacles	metal	4				
	Gen	ieral Landscape	metai	3.3				
	001	Turf		3				
<u> </u>		Non-Turf Ornamental Landscape		3	very worn			
<u> </u>		Unplanted Landscape		4	light weed growth			
	Gon	neral Trees		3.0				
	Gen	Park Trees		3.0	nears have significant diaback			
—	Gan			3.0	pears have significant dieback			
	Gen	eral Hardscape		3.0	limited grading			
	Care			3.0	limited cracking			
	Gen	eral Irrigation		-				
		System operation		3	No observable problems			
		System type (drip / spray)	spray	2				
	6	Controller		3	No observable problems			
	Gen	eral Lighting		3.0				
	6	System Operation		3				
		eral Barriers		4.0				
		Handrails	metal	4				
	Gen	eral Signage		3.0				
		Park ID	stone	4				
		Park Rules	metal	2	poor location			
	Gen	eral Drainage		4.0				
		Culvert		4				
		Curb and Gutter		4				
		Drain inlet		4				
		Swales / Stormwater Infrastructure		4				
	Art			N/A				
		Surfacing (not assessed)			Present			
		Sculpture (not assessed)		<u> </u>	On site			
	The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk							
Note	ote: Limited assessment items are highlighted in grey							

king tag <thtag< th=""> <thtag< th=""> tag tag<th></th><th></th><th></th><th></th><th>_</th><th>Inventory Date: 6/22/21</th></thtag<></thtag<>					_	Inventory Date: 6/22/21
Red Hawk Park 3.5 General Furnishings 3.0 Tables 3.0 Trash/Recycling Receptacles Temp. Aluminum Other: Concrete Other: Concrete Other: Concrete Other: Concrete Other: Concrete Other: Concrete On-Turf Ornamental Landscape 3.0 Unplanted Landscape 3 General Trees 4.0 Park Trees 4.0 Concrete 4.1 General Irrigation 4.0 System operation 4.0 System operation 4.0 System operation 4.1 No observable problems System type (drip / spray) Spray Controller 4.1 Reneral Barriers 3.0 Park Rules Metal 3 Park Rules Metal 3 Park Rules Metal 3 Deteriorating, legibility issues General Drainage Curb and Gutter 4 No observable problems <td></td> <td>tγ</td> <td></td> <td>a</td> <td>ion</td> <td></td>		tγ		a	ion	
Red Hawk Park 3.5 General Furnishings 3.0 Tables 3.0 Trash/Recycling Receptacles Temp. Aluminum Other: Concrete Other: Concrete General Landscape 3.0 Turf 4 Non-Turf Ornamental Landscape 3.0 Unplanted Landscape 2 Lundscape 4.0 Concrete 4 General Hardscape 4.0 Qeneral Hirigation 4.0 Concrete 4.0 General Irrigation 4.0 System operation 4.0 System operation 4.0 No observable problems 5 System operation 4.0 No observable problems 3.0 System operation 4.0 System operation 4.0 System operation 4.0 System operation 4.0 System operation 4.0 Park Nalls Steel Posts and Chain General Barriers 3.0 Park Rules Metal 3 </td <td>_</td> <td>eni</td> <td>G</td> <td>e / teri</td> <td>dit</td> <td>· · ·</td>	_	eni	G	e / teri	dit	· · ·
Red Hawk Park 3.5 General Furnishings 3.0 Tables 3.0 Trash/Recycling Receptacles Temp. Aluminum Other: Concrete Other: Concrete General Landscape 3.0 Turf 4 Non-Turf Ornamental Landscape 3.0 Unplanted Landscape 2 Lundscape 4.0 Concrete 4 General Hardscape 4.0 Qeneral Hirigation 4.0 Concrete 4.0 General Irrigation 4.0 System operation 4.0 System operation 4.0 No observable problems 5 System operation 4.0 No observable problems 3.0 System operation 4.0 System operation 4.0 System operation 4.0 System operation 4.0 System operation 4.0 Park Nalls Steel Posts and Chain General Barriers 3.0 Park Rules Metal 3 </td <td>Par</td> <td>Am</td> <td>Ass</td> <td>Mai</td> <td>Con</td> <td></td>	Par	Am	Ass	Mai	Con	
General Furnishings 3.0 Tables Concrete Tables Concrete Trash/Recycling Receptacles Temp. Aluminum Other: Concrete Other: Concrete Other: Concrete Turf 4 Non-Turf Ornamental Landscape 3.0 General Trees 4.0 Unplanted Landscape 2 Landscape strip General Trees General Trees 4.0 General Hardscape 4.0 Concrete 4 System type (drip / spray) Spray Controller 4 No observable problems System type (drip / spray) Spray Controller 4 General Singae 3.0 Fences / Walls Steel Posts and Chain Steel Park Rules Metal 3 Park Rules Metal 3 Park Rules Metal 3 Deteriorating, legibility issues General Singae Curb and Gutter 4 No observable problems Curb and Gutter	⊢−-				•	
General Furnishings 3.0 Tables Concrete Tables Concrete Trash/Recycling Receptacles Temp. Aluminum Other: Concrete Other: Concrete Other: Concrete Turf 4 Non-Turf Ornamental Landscape 3.0 Unplanted Landscape 2 Unplanted Landscape 4.0 General Trees 4.0 General Trees 4.0 Concrete 4 General Infigation 4.0 System type (drip / spray) Spray Controller 4 No observable problems System type (drip / spray) Spray Controller 4.0 General Singage 3.0 Fences / Walls Steel Posts and Chain General Singage 3.5 Park Rules Metal Metal 3 Deteriorating, legibility issues General Singage 3.0 Curb and Gutter 4.0 Park Rules Metal Barriers 3.0 Curb and Gutter 4.0 No observable problems General Singage 3.0 Curb and Gutter <	Red	Haw	k Park		3.5	
General Furnishings 3.0 Tables Concrete 4 Trash/Recycling Receptacles Temp. Aluminum 1 Temp cans Other: Concrete 4 Planter circle seat wall General Landscape 3.0 1 Turf 4 Non-Turf Ornamental Landscape 3.0 Gaps 1 Unplanted Landscape 2 Landscape strip General Trees General Trees 4.0 1 General Trees 4.0 General Hardscape 4.0 1 General Trees 4.0 General Irrigation 4.0 No observable problems 5 System type (drip / spray) Spray 1 No observable problems System type (drip / spray) Spray 1 No observable problems General Barriers 3.0 1 No observable problems General Isignage 3.5 1 No observable problems General Signage 3.5 1 No observable problems General Signage 3.0 1 No observable problems General Signage 3.0 1						General Site Observations: Park looks worn,
Tables Concrete 4 Trash/Recycling Receptacles Temp. Aluminum 1 Temp cans Other: Concrete 4 Planter circle seat wall General Landscape 3.0 4 Non-Turf Ornamental Landscape 3 Gaps Unplanted Landscape 2 Landscape strip General Trees 4.0 General Hridscape 4.0 Concrete 4 General Irrigation 4.0 System operation 4 System type (drip / spray) Spray Controller 4 No observable problems System type (drip / spray) Spray Controller 3.0 Fences / Walls Steel Posts and Chain General Barriers 3.0 General Signage 3.5 Curb and Gutter 4 Park ID Wood Park ID Wood Park ID Wood Park ID Wood Park ID Quiberrial General Signage 3.0 Curb and Gutter						neighborhood park
Tables Concrete 4 Trash/Recycling Receptacles Temp. Aluminum 1 Temp cans Other: Concrete 4 Planter circle seat wall General Landscape 3.0		Gen	eral Furnishings		3.0	
Other: Concrete 4 Planter circle seat wall General Landscape 3.0 Turf 4 Non-Turf Ornamental Landscape 3 Unplanted Landscape 2 Landscape strip General Trees General Trees 4.0 Park Trees 4 General Hardscape 4.0 Concrete 4 General Irrigation 4.0 System operation 4 System type (drip / spray) Spray Controller 4 No observable problems System type (drip / spray) Spray Controller 4 General Barriers 3.0 Fences / Walls Steel Posts and Chain General Irrinage 3.5 Park Rules Metal General Orainage 4.0 Voo observable problems General Irrinage 3.0 Park Rules Metal 3 Deteriorating, legibility issues General Grainage Curb and Gutter 4 1 Playground 3.0				Concrete	4	
General Landscape 3.0 Turf 4 Non-Turf Ornamental Landscape 3 Unplanted Landscape 2 Landscape strip 40 General Trees 4.0 Park Trees 4 General Hardscape 4.0 Concrete 4 General Irrigation 4.0 System type (drip / spray) Spray Controller 4 No observable problems System type (drip / spray) Spray Controller 4 General Barriers 3.0 General Signage 3.5 Park Rules Metal 3 Deteriorating, legibility issues General Drainage Curb and Gutter 4 4 Park Rules Metal 3 Deteriorating, legibility issues General Drainage Curb and Gutter 4 4 Playground 3.0 Rust, paint chips, graffiti Curb and Gutter 4 13 Equipment* Metal 3 Surfacing Sand			Trash/Recycling Receptacles	Temp. Aluminum	1	Temp cans
Turf 4 Non-Turf Ornamental Landscape 3 Unplanted Landscape 2 General Trees 4.0 Park Trees 4.0 General Hardscape 4.0 Concrete 4 General Hardscape 4.0 Concrete 4 General Hardscape 4.0 Concrete 4 System operation 4.0 System type (drip / spray) Spray Controller 4 No observable problems System type (drip / spray) Spray Controller 4 Reneral Signage 3.0 Fences / Walls Steel Posts and Chain Steel Posts and Chain 3 No observable problems 4.0 Park Nules Metal 3 Deteriorating, legibility issues 4.0 General Drainage 4.0 No observable problems Curb and Gutter 4 4 Playground 3.0 0 Equipment* Metal 3 Rust, paint chips, graffiti			Other:	Concrete	4	Planter circle seat wall
Non-Turf Ornamental Landscape 3 Gaps Unplanted Landscape 2 Landscape strip General Trees 4.0 Park Trees 4 General Hardscape 4.0 Concrete 4 General Irrigation 4.0 System operation 4.0 System operation 4.0 System type (drip / spray) Spray Controller 4 General Barriers 3.0 Fences / Walls Steel Posts and Chain General Signage 3.5 Park ID Wood Park Rules Metal Curb and Gutter 4 Playground 3.0 Equipment* Metal Curb Concrete 4 Concrete 4 Deteriorating, legibility issues General Signage 4.0 No observable problems Curb and Gutter 4 Playground 3.0 Equipment* Metal 3 Curb and Gutter 4 Surfacing Sand <td></td> <td>Gen</td> <td>eral Landscape</td> <td></td> <td>3.0</td> <td></td>		Gen	eral Landscape		3.0	
Unplanted Landscape2Landscape stripGeneral Trees4.0Park Trees4General Hardscape4.0Concrete4General Irrigation4.0System operation4.0System type (drip / spray)SprayController4General Barriers3.0Fences / WallsSteel Posts and ChainGeneral Signage3.5Park IDWoodPark RulesMetalGeneral Orbinage4.0No observable problemsGeneral Signage3.5Park IDWoodVerbaued3Deteriorating, legibility issuesGeneral Curb CurbConcreteANo observable problemsCurb and Gutter4Playground3.0Equipment*MetalSurfacingRubberSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSigns4Mood and Wire4Drainage5No observable problems			Turf		4	
General Trees 4.0 Park Trees 4 General Hardscape 4.0 Concrete 4 General Irrigation 4.0 System operation 4.0 System operation 4.0 System operation 4.0 System type (drip / spray) Spray Controller 4 No observable problems General Barriers 3.0 Fences / Walls Steel Posts and Chain General Signage 3.5 Park ID Wood Park Rules Metal General Drainage 4.0 Vood 4 Playground 3.0 Equipment* Metal Surfacing Rubber Surfacing Sand Surfacing Sand Surfacing Sand Barriers Wood and Wire Barriers Wood and Wire Surfacing Sand Surfacing Sand Surfacing Sand Barriers Wood and Wire <			Non-Turf Ornamental Landscape		3	Gaps
Park Trees4General Hardscape4.0Concrete4General Irrigation4.0System operation4No observable problemsSystem type (drip / spray)SprayController4No observable problemsGeneral Barriers3.0Fences / WallsSteel Posts and ChainGeneral Signage3.5Park RulesMetalGeneral Drainage4.0Voodd4Park RulesMetalGeneral Drainage4.0Curb and Gutter4Payground3.0Equipment*MetalSurfacingRubberSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingAndSurfacingSandSurfacingSandSigns4Mood and Wire3Low, rust (no fence for 5-12, no gateSigns4No observable problemsSigns4No observable problemsSurfacing4Si			Unplanted Landscape		2	Landscape strip
General Hardscape4.0Concrete4General Irrigation4.0System operation4No observable problemsSystem type (drip / spray)SprayController4No observable problemsGeneral Barriers3.0Fences / WallsSteel Posts and ChainGeneral Signage3.5Park IDWoodPark RulesMetalGeneral Drainage4.0No observable problemsCurb and Gutter4Playground3.0Equipment*MetalSurfacingRubberSurfacingSandSurfacingSobervable problemsSigns4 <td></td> <td>Gen</td> <td>eral Trees</td> <td></td> <td>4.0</td> <td></td>		Gen	eral Trees		4.0	
Concrete4General Irrigation4.0System operation4System type (drip / spray)SprayController4No observable problemsGeneral Barriers3.0Fences / WallsSteel Posts and ChainGeneral Signage3.5Park IDWoodPark RulesMetalGeneral Drainage4.0No observable problemsGeneral Drainage4.0Curb and Gutter4Payground3.0Equipment*MetalSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSignsAMood and Wire1Curb ind Gutter4CurbConcreteASurfacingSurfacingSandSurfacingSandSurfacingSandSigns4Mood and Wire3LowCompositeSigns4Missing age sign for 5-12Drainage5No observable problems			Park Trees		4	
Concrete4General Irrigation4.0System operation4System operation4No observable problemsSystem type (drip / spray)SprayController4No observable problemsGeneral Barriers3.0Fences / WallsSteel Posts and ChainGeneral Signage3.5Park IDWoodPark RulesMetalGeneral Drainage4.0No observable problemsGeneral Drainage4.0Curb and Gutter4Playground3.0Equipment*MetalSurfacingRubberSurfacingSandLurbConcreteSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSurfacingSandSigns4Missing age sign for 5-12Drainage4Signs4Missing age sign for 5-12Drainage5No observable problems		Gen	eral Hardscape		4.0	
System operation4No observable problemsSystem type (drip / spray)SprayAController4No observable problemsGeneral Barriers3.0Fences / WallsSteel Posts and Chain3Needs re-paint3.5Park IDWood4Park RulesMetal3Deteriorating, legibility issuesGeneral Drainage4.0No observable problemsCurb and Gutter4Playground3.0Equipment*Metal3Rubber3SurfacingSunfacingSurfacingSand3LowFurnishingsBenchesBarriersWood and Wire3Low, rust (no fence for 5-12, no gateSigns4Missing age sign for 5-12Drainage5No observable problems					4	
System operation4No observable problemsSystem type (drip / spray)SprayAController4No observable problemsGeneral Barriers3.0Fences / WallsSteel Posts and Chain3Needs re-paint3.5Park IDWood4Park RulesMetal3Deteriorating, legibility issuesGeneral Drainage4.0No observable problemsCurb and Gutter4Playground3.0Equipment*Metal3Rubber3SurfacingSunfacingSurfacingSand3LowFurnishingsBenchesBarriersWood and Wire3Low, rust (no fence for 5-12, no gateSigns4Missing age sign for 5-12Drainage5No observable problems		Gen	eral Irrigation		4.0	
System type (drip / spray)SprayController4Controller3.0Fences / WallsSteel Posts and ChainGeneral Signage3.5Park IDWoodPark RulesMetalGeneral Drainage4.0No observable problemsCurb and Gutter4Playground3.0Equipment*MetalSurfacingRubberSurfacingSandSigns4Missing age sign for 5-12, no gateSigns4Drainage5No observable problems					4	No observable problems
Controller4No observable problemsGeneral Barriers3.0Fences / WallsSteel Posts and Chain3Needs re-paintGeneral Signage3.5Park IDWood4Park RulesMetal3Deteriorating, legibility issuesGeneral Drainage4.0No observable problemsCurb and Gutter4Playground3.0Equipment*Metal3Rufe SurfacingRubber3CurbConcrete4SurfacingSand3LowFurnishingsBenchesBarriersWood and Wire3Low, rust (no fence for 5-12, no gateSigns4Missing age sign for 5-12Drainage5No observable problems			· · ·	Spray		·
Fences / WallsSteel Posts and Chain3Needs re-paintGeneral Signage3.5Park IDWood4Park RulesMetal3Deteriorating, legibility issuesGeneral Drainage4.0No observable problemsCurb and Gutter4Playground3.0Equipment*Metal3Ruther4SurfacingRubber3Curb functionConcrete4SurfacingSand3LowSurfacingSandSurfacingBenches4Composite4Signs4Missing age sign for 5-12No observable problemsDrainage5No observable problems					4	No observable problems
General Signage3.5Park IDWood4Park RulesMetal3Deteriorating, legibility issuesGeneral Drainage4.0Curb and Gutter4Playground3.0Equipment*Metal3Rubber3SurfacingSand3LowFurnishingsBenchesBarriersWood and Wire3Signs4Drainage4Drainage5No observable problems		Gen	eral Barriers		3.0	
Park IDWood4Park RulesMetal3Deteriorating, legibility issuesGeneral Drainage4.0No observable problemsCurb and Gutter4Playground3.0Equipment*Metal3Rust, paint chips, graffitiCurbConcrete4SurfacingRubber3SurfacingSand3LowFurnishingsBenches4BarriersWood and Wire3Low, rust (no fence for 5-12, no gateSigns4Missing age sign for 5-12No observable problemsLow5No observable problems			Fences / Walls	Steel Posts and Chain	3	Needs re-paint
Park IDWood4Park RulesMetal3Deteriorating, legibility issuesGeneral Drainage4.0No observable problemsCurb and Gutter4Playground3.0Equipment*Metal3Rust, paint chips, graffitiCurbConcrete4SurfacingRubber3SurfacingSand3LowFurnishingsBenches4BarriersWood and Wire3Low, rust (no fence for 5-12, no gateSigns4Missing age sign for 5-12No observable problemsLow5No observable problems		Gen	eral Signage		3.5	
General Drainage4.0No observable problemsCurb and Gutter4Playground3.0Equipment*Metal3CurbConcrete4SurfacingRubber3SurfacingSand3FurnishingsBenches4BarriersWood and Wire3SignsSigns4Drainage5No observable problems				Wood	4	
General Drainage4.0No observable problemsCurb and Gutter44Playground3.0Equipment*Metal3Rust, paint chips, graffitiCurbConcrete44SurfacingRubber3CrackingSurfacingSand3LowFurnishingsBenches4CompositeBarriersWood and Wire3Low, rust (no fence for 5-12, no gateSignsSigns5No observable problemsNoAServable problems4SignsSand3Low, rust (no fence for 5-12, no gateSignsSignsSand5No observable problemsSignsSignsSand5No observable problemsSignsSignsSand5No observable problemsSignsSignsSand5So observable problemsSignsSignsSand5So observable problemsSignsSandSand5So observable problemsSignsSandSandSandSandSignsSandSandSandSandSignsSandSandSandSandSignsSandSandSandSandSignsSandSandSandSandSignsSandSandSandSandSignsSandSandSandSandSignsSandSandSandSandSandSand <t< td=""><td></td><td></td><td>Park Rules</td><td>Metal</td><td>3</td><td>Deteriorating, legibility issues</td></t<>			Park Rules	Metal	3	Deteriorating, legibility issues
Playground3.0Equipment*Metal3CurbConcrete4SurfacingRubber3SurfacingSand3FurnishingsBenches4BarriersWood and Wire3Signs4Mosservable problemsDrainageImage5ImageImageImage		Gen				
Equipment*Metal3Rust, paint chips, graffitiCurbConcrete4SurfacingRubber3CrackingSurfacingSand3LowFurnishingsBenches4CompositeBarriersWood and Wire3Low, rust (no fence for 5-12, no gateSigns4Missing age sign for 5-12Drainage5No observable problems			Curb and Gutter		4	
CurbConcrete4SurfacingRubber3CrackingSurfacingSand3LowFurnishingsBenches4CompositeBarriersWood and Wire3Low, rust (no fence for 5-12, no gateSigns4Missing age sign for 5-12Drainage5No observable problems		Play	/ground		3.0	
SurfacingRubber3CrackingSurfacingSand3LowFurnishingsBenches4CompositeBarriersWood and Wire3Low, rust (no fence for 5-12, no gateSignsSigns4Missing age sign for 5-12DrainageNo observable problems5No observable problems			Equipment*	Metal	3	Rust, paint chips, graffiti
SurfacingSand3LowFurnishingsBenches4CompositeBarriersWood and Wire3Low, rust (no fence for 5-12, no gateSigns4Missing age sign for 5-12Drainage5No observable problems			Curb	Concrete	4	
SurfacingSand3LowFurnishingsBenches4CompositeBarriersWood and Wire3Low, rust (no fence for 5-12, no gateSigns4Missing age sign for 5-12Drainage5No observable problems			Surfacing	Rubber	3	Cracking
Barriers Wood and Wire 3 Low, rust (no fence for 5-12, no gate Signs 4 Missing age sign for 5-12 Drainage 5 No observable problems			Surfacing	Sand	3	Low
Signs 4 Missing age sign for 5-12 Drainage 5 No observable problems Image Image Image			Furnishings	Benches	4	Composite
Drainage 5 No observable problems			Barriers	Wood and Wire	3	Low, rust (no fence for 5-12, no gate
			Signs		4	Missing age sign for 5-12
* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk			Drainage		5	No observable problems
* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk						
				-	asset v	vith an asterisk
Note: Limited assessment items are highlighted in grey	Note	e: Lim	nited assessment items are highlighted in	grey		

<u> </u>	1				Inventory Date: 6/24/2021
	₹		a	ion	Time: 8:48am - 9:00 am
	eni	t t	e / :eri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	Condition	from maintenance staff)
	4	¥	<u>⊢ ∠</u>		
Rinc	onad	a Park		2.8	
					General Site Observations: Large open turf
					field, has potential for amenities
	Gen	eral Furnishings		1.0	
		Benches		1	Deficient, only has two small temp. benches
	Gen	eral Landscape		4.0	
		Turf		4	
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		2.0	
		Asphalt		1	
		Concrete		3	Lifting on sidewalk
	Gen	eral Irrigation		3.5	
		System operation		3	Dry spot issues
		System type (drip / spray)	Spray		Rotor?
		Controller		4	No observable problems
	Gen	eral Lighting		3.0	
		System Operation	On wood post	3	
	Gen	eral Barriers		3.5	
		Entrance/Maintenance Gates	Land yard	4	
		Bollards	Wood	3	Shows deterioration
	Gen	eral Signage		2.0	
		Park Rules	Metal	2	Poor location
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	
		Swales / Stormwater Infrastructure		4	
	Trai	ls		1.0	
		Trailhead Sign			Along Bucker creek
		Surfacing*	Asphalt	1	Point of connection missing
		ng of the amenity shall not exceed the rat	-	asset v	vith an asterisk
Note	e: Lim	nited assessment items are highlighted in g	grey		

				1	Inventory Data: C/22/21
	Ň		a	on	Inventory Date: 6/23/21
	nit	ų	eris	liti	Time: 2:45 - 3:50pm
Park	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized noted are notes
ă	A	۷	ŕ≥	Ŭ	from maintenance staff)
Dine	Image: Non-Walley Community Park Image			2.9	
KIIIC				2.9	General Site Observations: Good number of
					park users late afternoon on a weekday,
					amenities look worn, community members
					might be bringing furniture to dog park and
					leaving them
	Gen	eral Furnishings		2.3	
			Wood, Composite,		
		Benches	Metal	3	
				3	
		Trash/Recycling Receptacles	Plastic	1	Deficient
	Gen	eral Landscape		3.0	
		Turf		3	Dry patches
		Unplanted Landscape		2	No mulch, dead grass
		Natural landscape		4	
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		3.7	
		Asphalt		3	Major bumps and cracking in some areas
		Concrete		4	
		Pavers		4	For swale
	Gen	eral Irrigation		3.0	
		System operation		3	Leaks, dry and splotches of green
		System type (drip / spray)	Drip & Spray		
		Controller		3	No observable problems
	-	eral Lighting		N/A	
		System Operation			
	Gen	eral Barriers		4.0	
		Entrance/Maintenance Gates	Metal, Chain	4	
		Guardrails	Metal	4	
		Bollards	Metal	4	
	Gen	eral Signage		3.7	
		Park ID		4	
		Park Rules		4	
		Kiosks		3	Some illegible

	l				Inventory Date: 6/23/21
	t≺	ia _	ion	Time: 2:45 - 3:50pm	
_	eni	et	e / teri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	Condition	from maintenance staff)
<u> </u>				Ť	
Rinc	ncon Valley Community Park			2.9	
-		eral Drainage		3.0	
		Culvert		3	No observable problems
		Curb and Gutter		3	
		Drain inlet		3	No observable problems
		Swales / Stormwater Infrastructure		3	Some weeds
	Gen	eral Structures		3.0	
		Shade Structures (not assessed)			
		Pedestrian Bridges (not assessed)			Present, needs paint
		Sheds		3	Signs of major deterioration
		Restrooms (not assessed)			Present
	Picn	ic Areas (North)		3.0	
		Tables*	Wood	3	Chipped / paint chips, splintering
		Barbecues		3	Some metal panels lifting / warped
		Surfacing	Concrete	4	
		Trash Receptacles	Metal & Plastic	1	Deficient
		Shade Trees		4	
		Shade Structures (not assessed)			Small picnic area arbor needs R/R , Signs of
					rot, graffiti on connections
		Water Source		3	
	Picn	ic Areas (South)		3.1	
		Tables*		4	
		Kiosk / sign		4	
		Barbecues		3	Rust
		Specialty Barbecue		3	Warped bottom rack, coating peeling
		Surfacing	Turf	3	Dieback, lots of dry patches
		Trash Receptacles	Plastic & Tin	1	Deficient
		Shade Trees		4	
		Water Source		3	Faucet will not turn on
	Parl	king Lot		3.0	
		Wheel stops	Concrete	4	Some ADA stalls missing, few are shifted
		Lighting			
		Surfacing*	Asphalt	3	
		Signage		4	Some sign poles are bent
		Striping		1	Completely faded in majority of lot

×	Amenity	et	Type / Material	Condition	Inventory Date: 6/23/21 Time: 2:45 - 3:50pm Field Notes (all italicized noted are notes
Park	Am	Asset	Тур Ма	Cor	from maintenance staff)
					,
Rinc	on Va	alley Community Park		2.9	
	Play	ground		2.0	
		Equipment*	Plastic, Wood, Metal	2	Chunks of wood missing, splintering, metal corrosion, paint peeling
		Curb		4	
		Surfacing	Rubber tile	1	Large hole, large seams, large tears at sides
		Surfacing	Sand	4	
		Furnishings	Wood & Metal	3	Signs of deterioration on benches
		Signs		1	Warning and age appropriateness labels not present
		Drainage		1	Standing water when it rains
	Spo	rts Field / Court 1		3.0	
		Sport Type:	Soccer		
		Surfacing*	Turf	3	Dry spots
		Field striping		3	Faded
		Equipment		4	
		Furnishings	Bleachers	3	Signs of deterioration, graffiti
		Irrigation		3	Turf has dry spots
		Drainage		3	No observable problems
	Spo	rts Field / Court 2		1.0	
		Sport Type:	Horseshoe		
		Surfacing*	Sand	4	
		Surfacing*	Turf	1	
		Equipment	Backstop & Chainlink	3	Signs of deterioration, wood chipping / rot, rust
		Barriers	Metal Guardrail	4	
		Irrigation		3	Dead grass
		Drainage		3	No observable problems

	Amenity	ti	Asset Type / Material Condition	Condition	Inventory Date: 6/23/21 Time: 2:45 - 3:50pm Field Notes (all italicized noted are notes			
Park	Ame	Asset	Type / Mater	Con	from maintenance staff)			
		alley Community Park		2.9				
		rts Field / Court 3		3.0				
		Sport Type:	Softball					
		Surfacing*	Infill Mix	4	Light weed growth			
		Surfacing*	Turf	3	Dieback in spots			
		Striping		1	None			
		Equipment		4	Shed needs paint			
		Barriers			Some railings bent, wood splintering or			
		burners			breaking			
					Benches in good condition, plastic trash			
		Furnishings		3	receptacle (deficient) , bleachers show signs			
					of deterioration			
		Signage		4				
		Irrigation		3	Coverage problems			
		Drainage		3	No observable problems			
	Dog	Park		2.0				
		Surfacing	Mulch and Turf	1	Extremely weedy, mulch thin in some areas			
		Drinking Fountain		3	Leaking			
		Barriers*		2	Fence ok, gates missing components, gate gets stuck			
<u> </u>		Benches		1				
		Trash Receptacles	Tin	1	Deficient			
 		Signage		4				
		Storage		3				
		Irrigation		3				
		ing of the amenity shall not exceed the rat	-	asset v	vith an asterisk			
Note	lote: Limited assessment items are highlighted in grey							

	ĺ	1 1			Inventory Date: 6/23/2021
	ť	ior al	ion	Time: 3:00pm - 3:20 pm	
_	eni	et	e / teri	•=	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	l o	from maintenance staff)
	4	7			
Santa	Santa Rosa Rural Cemetery			3.6	
		······			General Site Observations: Overall very well
					, maintained.
	Gen	eral Furnishings		2.0	
		Flag Pole	Metal	3	Main entrance, missing flag
		Trash/Recycling Receptacles		1	Deficient
		eral Landscape		3.5	
		Non-Turf Ornamental Landscape		3	Memorial rose garden and Habitat garden
		Natural landscape		4	
	Gen	eral Trees		4.0	
		Park Trees		4	
		Trees in Natural Areas		4	
	Gen	eral Hardscape		3.0	
		Decomposed Granite / Gravel	Gravel	3	Secondary paths, excessive weeds
		eral Irrigation		4.0	
		System operation		4	No observable problems
		System type (drip / spray)	Drip		Memorial rose garden and habitat garden
		Controller		4	No observable problems
	Gen	eral Barriers		3.7	
		Fences / Walls	Chainlink	4	
		Entrance/Maintenance Gates	Steel	4	
		Bollards	Metal	3	
	Gen	eral Signage		4.0	
		Park ID	Wood	4	On Street
		Wayfinding	Wood w/ Plastic	4	
		Park Rules	Metal	4	
		Kiosks	Wood	4	
	Gen	eral Drainage		5.0	
		Culvert		5	
		Curb and Gutter		5	
		Drain inlet		5	
		Swales / Stormwater Infrastructure		5	
		ng of the amenity shall not exceed the rat	-	asset v	vith an asterisk
Note	: Lim	ited assessment items are highlighted in §	grey		

				6	Inventory Date: 6/22/21
	ity	ita ita	tio	Time: 1:40 - 1:50pm	
¥	Amenity	et	Type / Materia	Condition	Field Notes (all italicized noted are notes
Park	Am	Asset	Ma Ma	l Ö	from maintenance staff)
					, ,
Skyh	awk	Creek Open Space		3.3	
					General Site Observations: Small open space
					area in the middle of a residential area.
					Several dead trees
	Gen	eral Landscape		4.0	
					Natural landscape, No noxious weeds
		Natural landscape		4	present / annual grasses manageable by
		Naturarianuscape		4	mowing, shrubs in riparian corridor not
					overly dense
	Gen	eral Trees		3.0	
		Trees in Natural Areas		3	Multiple dead trees
	Gen	eral Irrigation		N/A	
		System operation			None observed
	Gen	eral Barriers		3.0	
		Entrance/Maintenance Gates	Wood & Metal	3	Wood posts with chain
	Gen	eral Drainage		3.3	
		Culvert		4	No observable problems
		Curb and Gutter		3	
		Drain inlet		3	
* The	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated	asset v	vith an asterisk
Note	: Lim	ited assessment items are highlighted in g	grey		

			·	1	
	Y		<u>–</u>	uo	Inventory Date: 6/22/21 (Revisit)
	nit	ų	erià	liti	Time: 2:06pm - 2:33pm
Park	Amenity	Asset	Type / Materia	Condition	Field Notes (all italicized noted are notes
ă	A	۷	ŕ≥	Ŭ	from maintenance staff)
Clark	Y Y Y xyhawk Community Park xyhawk Community Park general Furnishings Benches Benches Bike Racks Trash/Recycling Receptacles General Landscape Turf General Trees Park Trees General Hardscape Concrete			3.4	
экуп	awk			5.4	
					General Site Observations: Expansive
					community park with interesting topography
					and spot areas that have fire damage
	Gen	eral Furnishings		3.7	
		Benches		4	
		Bike Racks	metal	4	
		Trash/Recycling Receptacles	metal	3	paint deterioration
	Gen			3.0	adjacent to playground
		Turf		3	Hillside dry
	Gen	eral Trees		4.0	worse condition along the east end
		Park Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	segments of east end brand new
	Gen	eral Irrigation		4.0	
		System operation		4	No observable problems
		System type (drip / spray)	spray for turf		Spray Pop Ups
		Controller		4	
	Gen	eral Lighting		3.0	recent repairs made, worn, not LED
		System Operation	metal post	3	
	Gen	eral Barriers		3.0	broken segments
		Fences / Walls	wooden split rail	2	
		Handrails			near new, removable
		Bollards	metal	4	
	Gen	eral Signage		3.7	normal wear, good condition
		Park ID	metal arch	4	
		Park Rules		4	scratches, visibly worn
		Interpretive Signage	metal	3	
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	
		Swales / Stormwater Infrastructure		4	
	Gen	eral Structures		N/A	
		Shade Structures (not assessed)		<u> </u>	Present
		Pedestrian Bridges (not assessed)			Present

					Inventory Date: 6/22/21 (Revisit)
	ť	·	a	ion	Time: 2:06pm - 2:33pm
	ine	t.	e / :eri	dit	Field Notes (all italicized noted are notes
Park	Amenity Asset Type / Material	Condition	from maintenance staff)		
Δ.	4	₹	⊢ ∠	0	irom maintenance starr)
Skyh	awk	Community Park		3.4	
onyn		ground		3.0	significantly worn, no major defects
	,	Equipment*		3	
		Curb		4	weedy
		Surfacing	sand	3	moderately worn
		Surfacing	rubber	3	normal wear
			100001	5	
		Furnishings	metal benches/tables	4	bent top rails, slight lean
		Barriers	Chainlink fence	3	
		Drainage		3	No observable problems
	Spo	rts Field / Court 1		3.0	
		Sport Type:	Soccer/Softball		
		Surfacing*	Grass	3	Some slight dry patches
		Striping		3	Temporary?
		Equipment		4	Soccer nets sagging slightly
		Barriers	Chainlink	4	
		Furnishings		4	Storage boxes
		Signage		4	
		Irrigation		4	Some slight dry patches in turf
		Drainage		4	No observable problems
	Spo	rts Field / Court 2		3.8	
		Sport Type:	Soccer		
		Surfacing*	Grass	4	Slight dry patches
		Striping		3	Faded, temporary
		Equipment	Goals	4	
		Furnishings		4	Storage box
		Irrigation		4	
		Drainage		4	No observable problems
	Trai	ls		2.0	
		Surfacing*	Asphalt	2	Lots of cracks, moderate weed growth
		Barriers	Split rail fence, metal bollard	3	Fence broken, bollards leaning
	Spra	ayground		N/A	
		Equipment*			Needs fiber vs. sand
		ing of the amenity shall not exceed the rat	-	isset v	vith an asterisk
Note	e: Lim	nited assessment items are highlighted in g	grey		

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 5/19/21 Time: Field Notes (all italicized noted are notes		
Pa	Ar	As	Ϋ́	ŭ	from maintenance staff)		
Skyh	awk	Open Space		3.7			
					General Site Observations: Standard		
					peaceful open space area		
	Gen	eral Landscape		4.0			
		Natural Landscape		4	Natural landscape, No noxious weeds present / annual grasses manageable by mowing, shrubs in riparian corridor not overly dense		
	Gen	eral Trees		2.0			
		Trees in Natural Areas		2	fire damage		
	Gen	eral Hardscape		4.0			
		Asphalt		4	partially new, partially normal wear		
		Other:	gravel	4	paths with stairs		
	Gen	eral Barriers		4.0			
		Handrails		4	located at stairways toward residential		
		Bollards	metal, removable	4			
	Gen	eral Signage		5.0			
		Park ID		5			
	Gen	eral Drainage		3.0			
		Culvert		3			
		Curb and Gutter		3			
		Drain inlet		3	no visible issues		
		Swales / Stormwater Infrastructure		3			
	Gen	eral Structures		N/A			
		Pedestrian Bridges (not assessed)	metal/wood		Present, near new condition		
*				<u> </u>			
		ng of the amenity shall not exceed the rat		asset w	vith an asterisk		
Note	Note: Limited assessment items are highlighted in grey						

					Inventory Dates 7/0/21
	≿		a	on	Inventory Date: 7/9/21
	ini	st	eri	diti	Time: n/a
Park	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized noted are notes
P	٩	A	⊢ 2	0	from maintenance staff)
Sonoi	ma A	Avenue Park		2.8	
					General Site Observations: Park at the corner of Sonoma & Santa Rosa Ave. looks
					to be apart of Luther Burbank Garden & is
					well maintained, Large encampment within
					park near water feature
	<u> </u>	and Francishings		2.0	
		eral Furnishings Benches	wood	2.0	
\vdash		Trash/Recycling Receptacles	plastic	3 1	deficient
		eral Landscape	μιαστις	2.7	
		Turf		3	patchy
		Non-Turf Ornamental Landscape		3	weedy
		Unplanted Landscape		2	no mulch, weedy
	Gen	eral Trees		4.0	
		Park Trees		4	
(eral Hardscape		3.0	
		Concrete	aggregate	3	uneven and lifting throughout
C	Gen	eral Irrigation		1.0	
		System operation		1	run on rain nodes, wires , coverage issues
		System type (drip / spray)	spray		cut by tree roots
		Controller		1	No observable problems
(Gen	eral Drainage		5.0	
		Culvert		5	
		Curb and Gutter		5	
$ _ $		Drain inlet		5	
		Swales / Stormwater Infrastructure		5	
(Gen	eral Structures		3.0	
		Pedestrian Bridges (not assessed)	wood and metal		Present, guardrail and handrail is damaged & deteriorating/falling off
		Sheds	wood	3	Roof show signs of wear
۱	Wat	er Feature		2.0	
		Lighting		4	
		Mechanical water feature*	concrete/steel	2	Large operating water feature, water & basin is very dirty
		Surfacing	concrete	4	

Park	Amenity	Asset	Type / Material	. .	Inventory Date: 7/9/21 Time: n/a Field Notes (all italicized noted are notes from maintenance staff)	
Sono	oma A	Avenue Park		2.8		
	Art			N/A		
		Surfacing (not assessed)			Present	
		Statue (not assessed)			On Site	
* Th	* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk					
Note	e: Lim	ited assessment items are highlighted in g	rey			

					Inventory Date: 7/7/21
	ity		ial		Time: 3;25pm
×	eni	et	Type / Material	libu	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Ча; Ма;	Co	from maintenance staff)
_					
Sout	outh Davis Park			2.8	
					General Site Observations: Park feels a bit
					hidden, clean overall, signs of encampments
					on south end of park
	Gen	eral Furnishings		2.3	
		Tables		3	Heavy wear
		Drinking Fountains	Concrete	3	
		Trash/Recycling Receptacles		1	Deficient
	Gen	eral Landscape		2.5	
		Turf		3	Patchy
		Unplanted Landscape		2	No mulch
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		3.0	
		Concrete		3	
	Gen	eral Irrigation		3.5	
		System operation		4	No observable problems
		System type (drip / spray)	Spray		
		Controller		3	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	
	Gen	eral Barriers		3.0	
		Bollards	Wood	3	Some show signs of deterioration
		eral Signage		2.0	
		Park Rules			
		Traffic Signs		2	Illegible
	Gen	eral Drainage		2.0	
		Curb and Gutter		2	
		Swales / Stormwater Infrastructure		2	
	Play	ground		4.0	
		Equipment*	Plastic/Metal	4	
		Curb	Concrete	4	
		Surfacing	Sand	4	Lead litter from trees
		Surfacing	Rubber	4	
		Furnishings	Benches, Wood	4	
		Signs	Metal	4	
		Drainage		4	No observable problems

Park	Amenity	Asset	Type / Material	onditio	Inventory Date: 7/7/21 Time: 3;25pm Field Notes (all italicized noted are notes from maintenance staff)				
Sout	h Da	vis Park		2.8					
_		rts Field / Court 1		2.0					
		Sport Type:	Basketball						
		Surfacing*	Asphalt	2	Uneven and cracking throughout				
		Striping		3					
		Equipment	Steel	2	Heavily weathered				
		Barriers	Bollards, steel with concrete	4					
		Drainage		4	No observable problems				
* Th	* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk								
		nited assessment items are highlighted in g	-						

	1				Inventory Date: 7/7/21
	₹		<u>a</u>	ion	Time: 11:12 - 12:30pm
_	eni	et	e / teri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	Condition	from maintenance staff)
<u> </u>	~	7			
Sout	thwe	st Community Park		2.8	
500				2.0	
					General Site Observations: Vendors and
					encampments on site, clean park overall
	Gen	neral Furnishings		3.5	
		Tables	Wood	3	
		Drinking Fountains	Concrete	3	Half operational, possible leak
		Flag Pole	Metal	4	
		Trash/Recycling Receptacles	Metal	4	
	Gen	neral Landscape		2.5	
		Turf		3	Patchy with minor dieback
		Unplanted Landscape		2	No mulch
	Gon	neral Trees		4.0	
	Gen	Park Trees		4.0	
	Gon	neral Hardscape		1.0	
	Gen			1.0	
					Major cracking and uneven throughout,
		Asphalt		1	additional pathways needed in the
					Southwest and North East
		Concrete			
	Gen	neral Irrigation		3.5	
		System operation		3	
		System type (drip / spray)	Spray		
		Controller	,	4	No observable problems
	Gen	neral Lighting		N/A	
		System Operation		,,,	Could be brighter
	Gen	neral Barriers		3.5	
		Fences / Walls	Wood/Wire	4	
		Bollards	Metal	3	
	Gen	neral Signage		3.0	
		Park ID		3	Facing Hearn Ave., heavily worn
		Park Rules		3	
	Gen	neral Drainage		3.3	
		Culvert		3	Culverts blocked
		Curb and Gutter		3	
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		3	
	Gen	neral Structures		N/A	
		Shade Structures (not assessed)			Needs repair / improvement
		Restrooms (not assessed)			On Site
[1			1	

	i –	ĺ			Inventory Date: 7/7/21
	≥		a	ion	Inventory Date: 7/7/21
	en it		eri	diti	Time: 11:12 - 12:30pm
Park	Amenity	Asset	Type / Materia	Condition	Field Notes (all italicized noted are notes
	◄	٩	⊢ 2	0	from maintenance staff)
Sout	hwe	l st Community Park		2.8	
5000	1	lic Areas		3.0	
	1 101	Tables*		3	
		Kiosk / sign		3	
		Barbecues	Metal	4	
			Wietai	-	Excessive gaps at shade structure, major
		Surfacing	Concrete	2	cracking
		Trash Receptacles		4	
		Shade Trees		4	
		Shade Structures (not assessed)			<i>Needs repair/Improvements,</i> deterioration on facia
	Parl	king Lot #1		3.0	
		Wheel stops	Concrete	3	Some show extreme wear
		Surfacing*	Asphalt	3	
		Signage	Metal	4	
		Striping		2	Extremely faded, needs restriping
	Parl	king Lot #2		1.0	
		Surfacing*	Gravel	1	Recommend asphalt pavement, uneven throughout, big holes/dips
	Play	/ground		3.0	
		Equipment*	Metal/Plastic	3	Signs of heavy wear
		Surfacing	Sand	3	
		Surfacing	Rubber	3	Signs of heavy wear
		Surfacing	Concrete	3	Major cracking
		Furnishings	Wood Bench	3	
		Barriers	Chainlink	3	Fabric is warped
		Signs	Metal	3	
		Drainage		4	No observable problems
	Spo	rts Field / Court 1		2.0	
		Sport Type:	Basketball		
		Surfacing*	Asphalt	2	Major lifting between courts
		Field striping		2	Needs repair
		Equipment	Metal Hoops	3	Signs of rust and a few of the nets need replacement
		Furnishings	Bench	2	Extreme signs of wear
		Drainage		4	No observable problems

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 7/7/21 Time: 11:12 - 12:30pm Field Notes (all italicized noted are notes from maintenance staff)			
Sout	hwes	st Community Park		2.8				
		rts Field / Court 2		3.2				
		Sport Type:	Soccer					
		Surfacing*	Turf	4				
		Striping		2				
		Equipment	Metal Goal Posts	3	Half of goals are broken/need netting			
		Furnishings		2				
		Irrigation	Spray	4	No observable problems			
		Drainage		4	No observable problems			
	Spo	rts Field / Court 3		2.0				
		Sport Type:	Softball					
		Surfacing*	Infield Mix	2	Uneven with heavy weeds			
		Surfacing*	Outfield, Turf	3	Patchy			
		Equipment	Backstop, Wood/Chainlink	2	Wood deteriorating			
		Furnishings	Bleachers and Bench, Metal	4				
		Irrigation	Spray	2	Outfield, coverage issues			
		Drainage		4	No observable problems			
	* The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk Note: Limited assessment items are highlighted in grey							

AreaAreaAreaInventory Date: 6/23/202Time: 1:30pm - 1:53pmField Notes (all italicized refrom maintenance staff)Steele Lane Park3.2Steele Lane Park3.2General Furnishings3.0TablesMetalMetal4Drinking Fountains4Vater turned offTrash/Recycling Receptacles1Deficient3General Landscape2.7Turf3Unplanted Landscape2Natural Landscape4Park Trees4.0General Trees4.0Asphalt3.0Concrete3.0System operation2.5ControllerCausing overspray and we areaController3No observable problems	noted are notes s: Overall well
Steele Lane Park 3.2 General Furnishings 3.0 Tables Metal Drinking Fountains 4 Water turned off Trash/Recycling Receptacles 1 Deficient 2.7 Turf 3 Unplanted Landscape 2.7 Natural Landscape 2 Natural Landscape 3 Weedy 4.0 Park Trees 4 General Hardscape 3.0 Asphalt 2 System operation 2.5 Causing overspray and we area 2.5 Controller 3	s: Overall well
Steele Lane Park 3.2 General Furnishings 3.0 Tables Metal Drinking Fountains 4 Water turned off Trash/Recycling Receptacles 1 Deficient 2.7 Turf 3 Unplanted Landscape 2.7 Natural Landscape 2 Natural Landscape 3 Weedy 4.0 Park Trees 4 General Hardscape 3.0 Asphalt 2 System operation 2.5 Causing overspray and we area 2.5 Controller 3	s: Overall well
Steele Lane Park 3.2 General Furnishings 3.0 Tables Metal Drinking Fountains 4 Drinking Fountains 4 Water turned off Trash/Recycling Receptacles 1 Deficient General Landscape 2.7 Turf 3 Unplanted Landscape 2 Natural Landscape 3 Weedy 4 General Trees 4.0 Park Trees 4 General Hardscape 3.0 Asphalt 2 System operation 2.5 Causing overspray and warea 2.5 Controller 3 No observable problems	
General Furnishings3.0TablesMetal4Drinking Fountains4Water turned offTrash/Recycling Receptacles1DeficientGeneral Landscape2.71Turf32Natural Landscape2Natural Landscape3Weedy3General Trees4.0Park Trees4General Hardscape3.0Asphalt3Concrete3Weeds in jointsGeneral Irrigation2.5Causing overspray and we areaController3No observable problems	
General Furnishings3.0TablesMetal4Drinking Fountains4Water turned offTrash/Recycling Receptacles1DeficientGeneral Landscape2.71Turf32Natural Landscape2Natural Landscape3Weedy3General Trees4.0Park Trees4General Hardscape3.0Asphalt3Concrete3Weeds in jointsGeneral Irrigation2.5Causing overspray and we areaController3No observable problems	
Image: Second second	
Image: Controller I	rns with safety.
Image: system operationImage: system	
Image: system operationImage: system	
Image: Trash/Recycling Receptacles 1 Deficient Image: General Landscape 2.7 2.7 Image: Turf 3 3 Image: Unplanted Landscape 2 2 Image: Natural Landscape 3 Weedy Image: Natural Landscape 3 Weedy Image: Natural Landscape 4.0 2 Image: Natural Landscape 4.0 2 Image: Natural Landscape 4.0 2 Image: Natural Landscape 4.0 2 Image: Natural Landscape 4.0 2 Image: Natural Landscape 4.0 2 Image: Natural Areas 4 2 Image: Natural Areas 4 2 Image: Natural Areas 3.0 3 Image: Natural Areas 3.0 3 Image: Natural Areas 3.0 3 Image: Natural Areas 3.0 3 Image: Natural Areas 3.0 3 Image: Natural Areas 3.0 3 Image: Natural Areas 3.0 3 Image: Nater Areas 3.0	
Image: Constraint of the constra	
General Landscape2.7Turf3Unplanted Landscape2Natural Landscape3WeedyGeneral Trees4.0Park Trees4Trees in Natural Areas4General Hardscape3.0Asphalt3Concrete3General Irrigation2.5System operation2.5Controller3No observable problems	
Turf3Unplanted Landscape2Natural Landscape3Weedy3General Trees4.0Park Trees4Trees in Natural Areas4General Hardscape3.0Asphalt3Concrete3General Irrigation2.5System operation2.5Controller3No observable problems	
Natural Landscape3WeedyGeneral Trees4.0Park Trees4Trees in Natural Areas4General Hardscape3.0Asphalt3Concrete3General Irrigation2.5System operation2.5Controller3No observable problems	
Natural Landscape 3 Weedy General Trees 4.0 Park Trees 4 Trees in Natural Areas 4 General Hardscape 3.0 Asphalt 3 Concrete 3 General Irrigation 2.5 System operation 2 Controller 3 No observable problems	
General Trees 4.0 Park Trees 4 Trees in Natural Areas 4 General Hardscape 3.0 Asphalt	
Image: System operation Image: System operation <td></td>	
Image: System operation Image: System operation <td></td>	
Asphalt Image: Concrete Image: C	
Asphalt Image: Concrete Image: C	
Concrete 3 Weeds in joints General Irrigation 2.5 System operation 2 Controller 3 No observable problems	
General Irrigation 2.5 System operation 2 Causing overspray and we area Controller 3	
System operation 2 Causing overspray and we area Controller 3 No observable problems	
	eed growth in play
General Lighting 3.0	
System Operation 3 No observable problems	
General Barriers 3.0	
Bollards Metal 3	
General Signage 3.7	
Park ID Wood 4	
Park Rules 2 Poor location	
Interpretive Signage 5 Tree plaques and sign	
General Drainage 4.0	
Culvert 4	
Curb and Gutter 4	
Drain inlet 4 No observable problems	
Swales / Stormwater Infrastructure 4	
General Structures N/A	
Pedestrian Bridges (not assessed) One out of two bridges ne pedestrian bridge closed,	

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/23/2021 Time: 1:30pm - 1:53pm Field Notes (all italicized noted are notes from maintenance staff)
<u> </u>	`				
Stee	le Lai	ne Park		3.2	
	Play	ground		3.0	
		Equipment*	Metal and Plastic	4	No observable problems
		Curb	Concrete	4	
		Surfacing	Sand	4	
		Surfacing	Rubber	3	Holes in rubber
		Surfacing	Mulch	1	Mulch is more than 6" below curb
		Signs		1	Deficient
		Drainage		4	No observable problems
	Trail	ls		3.5	
		Trailhead Sign		4	
		Surfacing*	Asphalt	3	
* Th	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated a	asset v	vith an asterisk
_		ited assessment items are highlighted in g			

	i —				Inventory Date: 6/23/21			
	₹		ial	Condition	Time: 8:20 - 8:52am			
_	eni	et	e / teri	Idit	Field Notes (all italicized noted are notes			
Park	Amenity	Asset	Type / Materia	Cor	from maintenance staff)			
Stra	wber	ry Park		3.6				
					General Site Observations: Adjacent to			
					elementary school, natural creek area on			
					one side, small number of folks using trail			
					early in the morning, some poison oak in the			
					creek area			
	Gen	eral Furnishings		4.5				
		Benches	Metal	5				
		Trash/Recycling Receptacles	Metal	4				
	Gen	eral Landscape		4.0				
		Turf		4	Hill and some spots lacking irrigation			
		Natural Landscape		4.0				
	Gen	eral Trees		3.0				
		Park Trees		3				
		Trees in Natural Areas		3				
	Gen	eral Hardscape		2.5				
		Asphalt		2	Major cracks in travel space			
		Concrete		3	Major chips on edge			
	Gen	eral Irrigation		3.0				
		System operation		2	Turf dieback due to broken spray heads			
		System type (drip / spray)	Spray					
		Controller		4	No observable problems			
	Gen	eral Barriers		4.0				
		Bollards	Wood, Metal	4				
	Gen	eral Signage		4.0				
		Park ID		4				
		Park Rules		4				
	Gen	eral Drainage		4.0				
		Culvert		4	No observable problems			
		Curb and Gutter		4				
		Drain inlet		4	No observable problems			
		Swales / Stormwater Infrastructure		4				
	Play	/ground		N/A				
		Equipment*			belongs to strawberry school			
	Trai			3.0				
		Surfacing*	Asphalt	3				
		ing of the amenity shall not exceed the rat	-	l asset v	vith an asterisk			
Note	ote: Limited assessment items are highlighted in grey							

				-	Inventory Date: 6/24/21
	tγ		a	ion	Time: 11:35am - 12:10pm
	eni	ti i	e /	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Material	Condition	from maintenance staff)
_	A	₹	F 2	0	
Tang	lewo	l Dod Park		3.0	
1 ang				5.0	General Site Observations: Few folks walking
					around, steep slopes at creek crossings, lot
					of lawn
	Gen	eral Furnishings		2.0	
		Benches		3	Worn, functional
		Trash/Recycling Receptacles	Plastic	1	Deficient
	Gen	eral Landscape		3.5	
		Turf		3	Gaps
		Natural Landscape		4	
	Gen	eral Trees		4.0	
		Park Trees		4	
		Trees in Natural Areas		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		3.5	
		System operation		3	No observable problems
		System type (drip / spray)	Spray		Rotors
		Controller	Metal Enclosure	4	Smart Controller
	Gen	eral Lighting		2.0	
		System Operation	Post Top	2	Worn ,Graffiti, Not LED
	Gen	eral Barriers		3.0	
		Fences / Walls	Wood bollards w/ chain	3	Worn, repairs needed
		Fences / Walls 2	Wood picket	2	Excess wear
		Entrance/Maintenance Gates	Metal posts w/ chain	3	Worn, functional
		Guardrails	Metal	4	Near park ID/Bridge
	Gen	eral Signage		3.5	
		Park ID		3	Starting to rot at base
		Park Rules		4	
	Gen	eral Drainage		3.0	
		Culvert	Plastic / Corrugated	3	No observable problems
		Curb and Gutter		3	
		Drain inlet		3	No observable problems
		Swales / Stormwater Infrastructure		3	Creek in NTB of Park
	Gen	eral Structures		N/A	
		Pedestrian Bridges (not assessed)	Concrete		Present

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/24/21 Time: 11:35am - 12:10pm Field Notes (all italicized noted are notes from maintenance staff)
Tang	lewo	ood Park		3.0	
	Play	ground		3.0	
		Equipment*	Metal	3	One item not functional, broken
		Curb	Concrete	4	
		Surfacing	Rubber	3	Holes
		Surfacing	Sand	4	
		Furnishings		2	Excess wear on bench, temp trash
		Barriers		4	Chainlink and wire mesh with T-posts
		Signs		3	Tot missing
		Shade Structures (not assessed)			Present, Tire play structure s/b r&r
		Drainage		4	No observable problems
	Spor	rts Field / Court 1		1.0	
		Sport Type:	Basketball		BB court in bad shape!
		Surfacing*	Asphalt	1	Major cracking, weeds, uneven, unplayable
		Striping		1	Barely noticeable
		Equipment		2	Defective, excess wear
		Lighting		3	
		Drainage		1	Pooling in divets
		ng of the amenity shall not exceed the rat ited assessment items are highlighted in g	-	l asset v	l vith an asterisk

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/24/2021 Time: 10:20AM - 10:25AM Field Notes (all italicized noted are notes from maintenance staff)			
Tho	nas L	ake Harris Open Space		3.0				
					General Site Observations: Few people observed using trail/path, Creek contains a lot of dense invasive plants			
	Gen	eral Landscape		1.0				
		Natural Landscape		1	Dense invasive plants			
	Gen	eral Trees		3.0				
		Trees in Natural Areas		3	Fire damaged			
	Gen	eral Hardscape		4.0				
		Pavers		4	Minor lifting			
	Gen	eral Barriers		4.0				
		Bollards	Steel	4	No observable problems.			
	Gen	eral Signage		N/A				
		Park ID			None			
		Park Rules			None			
	Gen	eral Drainage		3.0				
		Curb and Gutter		3				
		Drain inlet		3				
	The rating of the amenity shall not exceed the rating of the lowest rated asset with an asterisk Note: Limited assessment items are highlighted in grey							

				1	Investory Data (122/24
	2		a	on	Inventory Date: 6/22/21
	nit	r r	eria	diti	Time: 12:00 - 12:30pm
Park	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized noted are notes
	A	Δ	<u> </u>	Ŭ	from maintenance staff)
Trail	head	Park		3.6	
					General Site Observations: Urban trail
					connecting neighborhood, amenities look newer, couple of people walking around
	Gen	eral Furnishings		3.3	
		Benches	Metal	4	
		Bike Racks	Metal	4	
		Drinking Fountains		4	
		Trash/Recycling Receptacles	Rolling Bin, Metal	1	Deficient
	Gen	eral Landscape		2.5	
		Unplanted Landscape		1	No mulch
		Natural Landscape		4	
	Gen	eral Trees		4.0	
		Park Trees		4	
		Trees in Natural Areas		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	Small portion at water fountain
	Gen	eral Irrigation		4.0	
		System operation		4	No observable problems
		System type (drip / spray)	Bubblers		No observable problems
		Controller		4	No observable problems
	Gen	eral Barriers		3.8	
		Fences / Walls	Wood Split Rail	4	
		Fences / Walls 2	Stone Veneer	4	
		Handrails	Metal	4	At Stairs
		Bollards		3	Noticeable metal corrosion, rust
	Gen	eral Signage		3.3	
		Wayfinding		4	
		Park Rules		4	
		Interpretive Signage		2	Very dirty, needs cleaning
	Gen	eral Drainage		4.0	
		Culvert		4	No observable problems
		Curb and Gutter		4	
		Drain inlet		4	No observable problems

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/22/21 Time: 12:00 - 12:30pm Field Notes (all italicized noted are notes from maintenance staff)
Trail	hoad	l Park		3.6	
-		lic Areas		3.0	
		Tables*	Campsite, Wood & Metal	3	One slat missing
		Surfacing	DG	4	Uneven at drain inlet
		Trash Receptacles	Rolling Bin, Metal & wood composite	1	
		Water Source		4	Drinking fountain
	Trai	ls		4.0	
		Surfacing*	Asphalt	4	
* The	e rati	ing of the amenity shall not exceed the rat	ing of the lowest rated a	asset v	vith an asterisk
Note	e: Lim	nited assessment items are highlighted in g	grey		

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/23/2021 Time: 4:05pm - 4:14pm Field Notes (all italicized noted are notes from maintenance staff)
Triar		Dark		3.5	
	igie			3.3	General Site Observations: Very small park, One person using site, Assume irrigation is turned off for turf
	Gen	eral Furnishings		4.0	
		Benches		4	
	Gen	eral Landscape		2.0	
		Turf		1	
		Non-Turf Ornamental Landscape		2	
		Unplanted Landscape		3	
	Gen	eral Trees		4.0	
		Park Trees		4	
	-	eral Irrigation		2.5	
		System operation		1	Function unknown, dead turf
		System type (drip / spray)	Spray		
		Controller		4	No observable problems
	Gen	eral Drainage		5.0	
		Culvert		5	
		Curb and Gutter		5	
	Drain inlet			5	
		Swales / Stormwater Infrastructure		5	
* The	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated	l asset v	l vith an asterisk
		ited assessment items are highlighted in g	-		

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/24/2021 Time: 9:30AM - 9:41AM Field Notes (all italicized noted are notes from maintenance staff)
Unn	Jpper Brush Creek Trail Park			3.2	
Oppe				3.2	General Site Observations: Access unclear, unsure if site is intended to be used as a trail, not maintained well, unidentified bike pump track near Wild Lilac Ln.
		eral Landscape		4.0	
		Natural Landscape		4	
	Gen	eral Trees		4.0	
		Trees in Natural Areas		4	
	Gen	eral Hardscape		3.0	
		Concrete	Sidewalk	3	
	Gen	eral Signage		4.0	
		Park Rules	Metal	4	Site has neighborhood park sign at Wild Lilac Ln. only
	Gen	eral Drainage		3.0	
		Curb and Gutter		3	
		Drain inlet		3	
	Trai	s		1.0	
		Trailhead Sign			Access unclear, signage needed
		Surfacing*	Packed Earth	1	Undeveloped use trail at Wild Lilac Ln. Holes throughout trail and DIY bike jumps. makeshift bike pump track near Wild Lilac Ln
		ng of the amenity shall not exceed the rat	-	asset v	vith an asterisk
Note	e: Lim	ited assessment items are highlighted in g	rey		

				_	Inventory Date: 6/23/21
	tγ		a	Condition	Time: 9:10 - 9:35am
~	eni	et	e / :eri	dit	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	0 U	from maintenance staff)
<u> </u>	4	7		0	
Viet	nam	Vets Memorial Trail		3.1	
				0.1	General Site Observations: Several visitors,
					summer camp class visiting, natural trail,
					nice views of neighborhood
	Gen	eral Furnishings		1.5	
		Benches	Wood	2	Excess wear
		Trash/Recycling Receptacles	Plastic	1	Temp, deficient
	Gen	eral Landscape		4.0	
		Unplanted Landscape	Grassy		
		· · · ·			
		x , , , , , ,			No noxious weeds present / annual grasses
		Natural Landscape		4	manageable by mowing, shrub growth not
					dense, primarily native species (Baccharis)
	Gen	eral Trees		4.0	
		Trees in Natural Areas		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		N/A	
		System operation			Not observed
	Gen	eral Barriers		2.5	
		Fences / Walls	Split Rail Wood Fence	3	
		Fences / Walls 2	Barb Wire Fence	2	Loose, Broken in areas
	Gen	eral Signage		3.5	
		Park ID	Stone Veneer	3	
		Park Rules		4	
	Gen	eral Drainage		3.3	
		Culvert	Corrugated Metal Pipe	4	No observable problems
		Curb and Gutter		4	
		Swales / Stormwater Infrastructure		2	water bars on trail need to be renovated
	Trai	ls		2.0	
		Trailhead Sign	Stone Veneer	3	
		Surfacing*	Gravel	2	Uneven, rocky
		Barriers	Split Rail / Barb	2	Worn, broken
		ng of the amenity shall not exceed the rat	-	asset v	vith an asterisk
Note	e: Lim	ited assessment items are highlighted in	grey		

1	Ì			Ì	Inventory Dates 7/7/21
	Σ		al	on	Inventory Date: 7/7/21
	snit	st	eri	diti	Time: 1:50 - 2:22pm
Park	Amenity	Asset	Type / Materia	Condition	Field Notes (all italicized noted are notes
┣┻	◄	4	⊢ ∠	0	from maintenance staff)
Villa	llage Green Park			3.1	
					General Site Observations: Picnic area looked as is it was missing amenities, large encampment area on North side of park
	Gen	eral Furnishings		2.7	
		Benches	Wood	3	
		Drinking Fountains	Steel	4	Water turned off
		Trash/Recycling Receptacles		1	Deficient
	Gen	eral Landscape		2.7	
		Turf		3	Very patchy
		Non-Turf Ornamental Landscape		3	
		Unplanted Landscape		2	No mulch
	Gen	eral Trees		4.0	
		Park Trees		4	No observable problems
	Gen	eral Hardscape		3.0	
		Concrete		2	Major cracking and lifting
		Decomposed Granite / Gravel	Gravel	4	
	Gen	eral Irrigation		3.0	
		System operation		2	
		System type (drip / spray)	Both		Spray in turf, drip in planting
		Controller		4	No observable problems
	Gen	eral Barriers		3.5	
		Fences / Walls	Metal w/ wood post	3	Wood posts deteriorating
		Bollards	Metal	4	
	Gen	eral Signage		3.5	
		Park ID	Wood	4	On Sebastopol Rd.
		Park Rules		3	Poor distribution
	Gen	eral Drainage		3.0	
		Drain inlet		3	Some appear blocked
	Gen	eral Structures		N/A	
		Shade Structures (not assessed)	Trellis, Wood		Present

					Inventory Date: 7/7/21
	ity		' ial	Condition	Time: 1:50 - 2:22pm
¥	Amenity	set	Type / Materia	ipu	Field Notes (all italicized noted are notes
Park	Αm	Asset	A F	<u></u>	from maintenance staff)
Villa	illage Green Park			3.1	
	Picn	ic Areas		2.3	
		Tables*	Wood	3	Missing planks
		Barbecues		1	Appears there was once BBQs, posts remain
		Surfacing	Concrete	4	
		Trash Receptacles		1	Deficient
		Shade Trees		4	No observable problems
		Water Source	Drinking Fountain/Metal	1	No handle on spigot
	Play	ground		3.1	
		Equipment*	Plastic/Metal	4	
		Curb		1	Deficient
		Surfacing	Wood Fiber	2	Low mulch at swings
		Furnishings	Bench, Wood	3	Heavy weathering
		Barriers	Ornamental Metal	3	Wooden posts deteriorating
		Signs	Composite	4	
		Water play	Metal/Fabric	4	Shade post w/ mister not operating
		Drainage		4	No observable problems
	Spo	rts Field / Court 1		3.0	
		Sport Type:	Basketball		
		Surfacing*	Asphalt	3	
		Striping		3	
		Equipment	Metal Hoop	4	
		Furnishings	Bench, Wood	4	
		Drainage		4	No observable problems
* Th	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated a	asset w	l
		nited assessment items are highlighted in g	-		

				i	Lauratera Data 7/0/2021
	Y		a	on	Inventory Date: 7/8/2021
	nit	<u>ب</u>	erià	diti	Time: 10:55AM - 11:14AM
Park	Amenity	Asset	Type / Materia	Condition	Field Notes (all italicized noted are notes
٩	A	۷	μ 2	Ŭ	from maintenance staff)
West	taate	Park		3.2	
VVCS	igate			5.2	
					General Site Observations: Large open turf
					field with potential to add more amenities,
					clean and well maintained overall
	Gen	eral Furnishings		2.7	
		Tables		4	
		Drinking Fountains	concrete	3	water turned off
		Trash/Recycling Receptacles	plastic	1	deficient
	Gen	eral Landscape		3.0	
		Turf		3	weedy and patchy
	Gen	eral Trees		4.0	
		Park Trees		4	walnuts have significant dieback
	Gen	eral Hardscape		4.0	
		Concrete		4	mixed of worn and slightly worn
	Gen	eral Irrigation		3.0	
		System operation		3	under irrigated
		System type (drip / spray)	spray		
		Controller		3	No observable problems
	Gen	eral Barriers		2.0	
		Bollards	wood and metal	2	wood bollards show high signs of deterioration
	Gen	eral Signage		2.0	
		Park Rules	metal	2	poor location and falling apart
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	
		Drain inlet		4	
		Swales / Stormwater Infrastructure		4	
	Play	rground		3.6	
		Equipment*	plastic and metal	4	notable weathering
		Curb	concrete	3	
		Surfacing	sand	3	low levels
		Surfacing	rubber	4	
		Furnishings	wood benches	3	
		Signs		4	
		Drainage		4	No observable problems

Park	Amenity	Asset	Type / Material	Condition	Inventory Date: 7/8/2021 Time: 10:55AM - 11:14AM Field Notes (all italicized noted are notes from maintenance staff)
		Park rts Field / Court 1		3.2	
	•	Sport Type:	Basketball	3.4	
		Surfacing*	concrete	5	minor graffiti
		Striping		4	
		Equipment	metal hoop	3	heavily worn and rusted
		Furnishings	metal bench	1	surface mount bolts are exposed and hazardous
		Drainage		4	No observable problems
* Th	e rati	ng of the amenity shall not exceed the rat	ing of the lowest rated	asset v	vith an asterisk
Note	e: Lim	ited assessment items are highlighted in g	rey		

	<u> </u>		1	1	Investory Dates C/22/2021
	≥		a	on	Inventory Date: 6/23/2021 Time: 9:00AM - 10:50 AM
	hil	it i	e /	diti	Field Notes (all italicized noted are notes
Park	Amenity	Asset	Type / Materia	Condition	
┣┻	◄	٩	⊢ ∠		from maintenance staff)
Vout	th Co	mmunity Park		3.1	
Tour				5.1	General Site Observations: Pavilion used for
					kids summer camp, well maintained park,
					unidentified amenities on other side of
					creek; such as, disc golf course, bike pump
					track & archery. Horseshoe pit was not
					found on site
	Gen	eral Furnishings		4.0	
		Benches	Metal	4	
		Drinking Fountains		4	
		Trash/Recycling Receptacles		4	
	Gen	eral Landscape		3.0	
		Turf		4	
		Non-Turf Ornamental Landscape		3	
		Unplanted Landscape		2	No mulch
	Gen	eral Trees		4.0	
		Park Trees		4	
	Gen	eral Hardscape		3.0	
		Asphalt		3	Cracks throughout
		Concrete		4	Mostly new, some significant lifting
		Decomposed Granite / Gravel		3	Eroding at concrete
		Amphitheater		2	Refer to last page
	Gen	eral Irrigation		4.0	
		System operation		4	No observable problems
		System type (drip / spray)	Spray		
		Controller		4	No observable problems
	Gen	eral Lighting		3.0	
		System Operation		3	No observable problems
	Gen	eral Barriers		2.7	
					Significant damage on Folton Rd., Rating
		Fences / Walls	Split Rail/Wood	2	doesn't Include new fence at new
				<u> </u>	development
		Entrance/Maintenance Gates	Metal	3	Bent posts at left gate
		Bollards	Wood and Metal	3	
	Gen	eral Signage		3.0	
		Park ID		4	At front entrance
		Park Rules		2	Mixed conditions, poor locations

<u> </u>	1	1	1	1	
	>		-	uo	Inventory Date: 6/23/2021
	nit	Ŧ	erià	liti	Time: 9:00AM - 10:50 AM
Park	Amenity	Asset	Type / Materia	Condition	Field Notes (all italicized noted are notes
ق	4	Ŕ	μ	Ŭ	from maintenance staff)
Yout		mmunity Park		3.1	
	Gen	eral Drainage		4.0	
		Culvert		4	
		Curb and Gutter		4	In parking lot
		Drain inlet		4	No observable problems
		Swales / Stormwater Infrastructure		4	Unfinished detention basin along Peterson Creek Dr
	Gen	eral Structures		4.0	
		Pedestrian Bridges (not assessed)	Steel and Wood		Present, railing needs replacement
		Sheds		4	Shipping container for train
		Restrooms (not assessed)			On Site
	Picn	nic Areas		3.0	
		Tables*	Wood and Metal	3	Heavily used
		Kiosk / sign	Steel and Wood	4	
		Barbecues	Metal	3	Some rust
		Surfacing	D.G.	4	
		Trash Receptacles		4	
		Shade Trees		4	
		Shade Structures (not assessed)			Facade is deteriorating and rust on posts
		Water Source		4	
	Parl	king Lot		3.0	
		Wheel stops	Concrete	4	
		Lighting		3	
		Surfacing*	Asphalt	3	
		Signage	Metal	4	
		Striping		3	
	Play	/ground		3.2	
	<i>,</i>	Equipment*		4	
		Curb		4	No observable problems
 	1	Surfacing	Fiber	2	Extremely low
<u> </u>		Surfacing	Sand	4	,
<u> </u>		Surfacing	Rubber	4	
		Furnishings	Picnic Tables/Wood and Metal	3	
<u> </u>		Barriers	Split Rail/Wood	2	Falling apart
		Signs		2	Poor functionality/visibility, deficient on
<u> </u>		Drainago		4	other play features
		Drainage	I	4	No observable problems

¥	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/23/2021 Time: 9:00AM - 10:50 AM Field Notes (all italicized noted are notes
Park	Aπ	As	T _{VI}	S	from maintenance staff)
Yout	h Co	mmunity Park		3.1	
	Spo	rts Field / Court 1		1.0	Not operated by Recreation and Parks; not included in park ranking
		Sport Type:	Disc Golf		
		Surfacing*	Packed Earth	1	Not improved at all, full of divets
		Surfacing*	Natural Area	4	Unmowed grass
		Equipment	Metal	5	
		Barriers	Barbed wire	1	Fallen down
	Trai			1.5	
		Trailhead Sign		1	Deficient
		Surfacing	Packed Earth	2	Should be graveled, uneven throughout
	Skat	te Park		2.8	
		Surfacing*	Concrete	3	Wide spread minor cracking
		Skate Features	Rail/Concrete	3	Heavily worn and has rust
		Barriers	Chainlink	1	Missing sections, exposed rails and posts
		Furnishings	Bench/Steel	4	
	Bike	e Pump Track		4.0	Not operated and maintained by Recreation and Parks; not included in park ranking
		Surfacing*	Packed Earth	4	
	Art			N/A	
		Structure (not assessed)			Sundial near skate park
* The	e rati	ing of the amenity shall not exceed the rat	ing of the lowest rated	asset v	vith an asterisk
Note	e: Lim	nited assessment items are highlighted in g	rey		

Page is Intentionally Blank

APPENDIX



Roadway Landscape Assessment Summaries

					Inventory Date: 7/8/21
		Asset	a l		Time: 1:24 - 1:35pm
Roadway Landscape	Amenity		Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
B00001	NE			3.2	
	Gen	eral Landscape		2.0	
		Turf		1	Dead
		Non-Turf Ornamental Landscape		3	Dieback, weedy
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		1.0	
		System operation		1	Not observable, dead plants, maybe off because of drought
		System type (drip / spray)	Spray		
		Controller			Not found
	Gen	eral Drainage		5.0	
		Culvert		5	
		Curb and Gutter		5	
		Drain Inlet		5	
		Swales / Stormwater Infrastructure		5	
	Note	e: Limited assessment items are highlight	ed in grey		

					Inventory Date: 7/7/21
			a		Time: 3:59 - 4:01pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
C00001N	W			4.0	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Note	e: Limited assessment items are highlighte	d in grey		

			-		Inventory Date: 7/7/21
					Time: 2:50 - 2:52pm
Roadway Landscape	Amenity	Asset	Type / Material		Field Notes (all italicized notes are from maintenance staff)
C000019	W			4.0	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Note	e: Limited assessment items are highlighte	d in grey		

			a		Inventory Date: 7/7/21
					Time: 1:39 - 1:43pm
Roadway Landscape	Amenity	Asset	Type / Material		Field Notes (all italicized notes are from maintenance staff)
C00003N	W			3.0	
	Gen	eral Hardscape		3.0	
		Concrete		3	Some cracking, weed growth in cracks, section of curb missing
	Note	e: Limited assessment items are highlighte	d in grey		

					Inventory Date: 7/7/21
			a		Time: 12:23 - 12:25pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
C000045	W			4.0	
	Gen	eral Hardscape		4.0	
		Concrete		4	Little bit of weed growth in joints
	Note	: Limited assessment items are highlighte	ed in grey		

			Ē		Inventory Date: 7/7/21
					Time: 2:57 - 2:59pm
Roadway Landscape	Amenity	Asset	Type / Material		Field Notes (all italicized notes are from maintenance staff)
C00005	SW			3.0	
	Gen	eral Hardscape		3.0	
		Other:	Cobble	3	Significant weed growth
	Note	: Limited assessment items are highlighte	d in grey		

			-	Τ	Inventory Date: 7/7/21
					Time: 3:43 - 3:44pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
C000061	NE			3.0	
	Gen	eral Hardscape		3.0	
		Concrete		3	Minor cracks, chips
	Note	: Limited assessment items are highlighte	d in grey		

			a		Inventory Date: 7/7/21
					Time: 4:10 - 4:12pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
C00007N	W	·	•	3.7	
	Gen	eral Hardscape		3.7	
		Concrete		4	Light weeds
		Pavers		3	Light weeds, moderately worn
		Other:	Gravel	4	Light weeds
	Note	e: Limited assessment items are highlighte	d in grey		

			Ē		Inventory Date: 7/7/21
					Time: 2:43 - 2:45pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
C000085	W			4.0	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Note	: Limited assessment items are highlighte	d in grey		

					Inventory Date: 7/8/21
			a		Time: 1:41 - 1:43pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
C000095	E			4.0	
	Gen	eral Hardscape		3.0	
				3	Weeds growing in joints, minor cracks
		Concrete			
	Gen	eral Drainage		5.0	
		Culvert		5	
		Curb and Gutter		5	
		Drain Inlet		5	
		Swales / Stormwater Infrastructure		5	
	Note	Limited assessment items are highlight	ed in grey		

			-		Inventory Date: 7/9/21
					Time: 11:32 - 11:35am
Roadway Landscape	Amenity	Asset	Type / Material		Field Notes (all italicized notes are from maintenance staff)
C00012S	E			3.5	
	Gen	eral Hardscape		3.0	
		Pavers		3	Weedy
	Gen	eral Drainage		4.0	
		Curb and Gutter		4	
	Note	e: Limited assessment items are highlighte	d in grey		

					Inventory Date: 6/23/21
			a		Time: 12:30 - 12:37pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
C00013	W			4.0	
	Gen	eral Hardscape		4.0	
		Concrete		4	With weeds
	Note	e: Limited assessment items are highlighte	d in grey		

					Inventory Date:		
			ā		Time:		
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)		
C00015	SE		• •	3.8			
	Gen	eral Hardscape		3.5			
		Concrete		4	slight cracking and lifting, not new		
		Pavers		3	some lifting and sinking pavers		
	General Drainage			4.0			
		Curb and Gutter		4			
	Note: Limited assessment items are highlighted in grey						

					Inventory Date: 7/9/21		
			a		Time: 11:08 - 11:11am		
Roadway Landscape	Amenity	Asset	Type / Material		Field Notes (all italicized notes are from maintenance staff)		
C000175	5E			4.0			
	Gen	eral Hardscape		4.0			
		Concrete		4			
	Note: Limited assessment items are highlighted in grey						

					Inventory Date: 7/8/21			
			a		Time: 1:20-1:22pm			
Roadway Landscape Amenity	Asset	Type / Material		Field Notes (all italicized notes are from maintenance staff)				
C00045N	NE			5.0				
	Gen	eral Hardscape		5.0				
		Concrete		5	New			
	Gen	eral Drainage		5.0				
		Culvert		5				
		Curb and Gutter		5				
		Drain Inlet		5				
		Swales / Stormwater Infrastructure		5				
	Note: Limited assessment items are highlighted in grey							

					Inventory Date: 7/9/21		
			-		Time: 12:55 - 12:56pm		
Roadway Landscape	Amenity	Asset	Type / Material		Field Notes (all italicized notes are from maintenance staff)		
C00053N	IE			3.5			
	Gen	eral Hardscape		4.0			
		Concrete		4			
	Gen	eral Drainage		3.0			
		Curb and Gutter		3			
	Note: Limited assessment items are highlighted in grey						

					Inventory Date: 7/7/21		
			a		Time: 4:44 - 4:46pm		
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)		
C00056N	NE			4.0			
	Gen	eral Hardscape		4.0			
		Concrete		4			
	Note: Limited assessment items are highlighted in grey						

					Inventory Date: 7/7/21
			a		Time: 11:50 - 12:00pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
F00001S	W		-	3.1	
	Gen	eral Landscape		3.0	
		Turf		3	yellow patches
		Non-Turf Ornamental Landscape		3	weedy, little to no mulch
	Gen	eral Trees		4.0	
		Trees		4	3 trees with significant dieback
	Gen	eral Hardscape		3.0	
		Concrete		3	major lifts
	Gen	eral Irrigation		2.5	
		System operation		2	Leak, flooding
		System type (drip / spray)	Spray		
		Controller		3	No observable problems
	Gen	eral Drainage		3.0	
		Drain Inlet		3	
		Swales / Stormwater Infrastructure		3	
	Note	: Limited assessment items are highlighte	ed in grey		

					Inventory Date: 6/23/21
			ज		Time: 2:10 - 2:15pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
F00002S	Ε			3.4	General Observations:
					Appears lush, just slightly unkept
	Gen	eral Landscape		3.0	
		Non-Turf Ornamental Landscape		3	
		Unplanted Landscape			No mulch, huge gaps, dead plants
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		3.0	
		System operation		3	Evidence of plant dieback, no observable problems
		System type (drip / spray)			Not observable
		Controller			No observable problems
	Gen	eral Drainage		3.0	
		Curb and Gutter		3	
		Drain Inlet		3	
	Note	: Limited assessment items are highlighte	d in grey		

		Asset			Inventory Date: 7/7/21
			a		Time: 11:00 - 11:10am
Roadway Landscape	Amenity		Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
F000055	SW			2.9	
	Gen	eral Landscape		2.5	
		Non-Turf Ornamental Landscape		3	weedy, little to no mulch
		Unplanted Landscape		2	little to no mulch
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		1.0	
		System operation		1	Not observable, based off plant condition
		System type (drip / spray)	Spray		
		Controller			No observable problems
	Gen	eral Drainage		3.0	
		Curb and Gutter		3	
		Drain Inlet		3	
		Swales / Stormwater Infrastructure		3	
	Note	e: Limited assessment items are highlight	ed in grey		

					Inventory Date: 7/8/21
			-		Time: 3:18 - 3:24pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
F00013N	IE			3.4	
	Gene	eral Landscape		3.0	
					Big significant gaps, some plant
		Non-Turf Ornamental Landscape		3	dieback, lots of leaf litter
	Gene	eral Trees		4.0	
		Trees		4	
	Gene	eral Hardscape		4.0	
		Concrete		4	
	Gene	eral Irrigation		3.0	
		System eneration			Not observable, based off plant
		System operation		2	condition
		System type (drip / spray)			Unknown
		Controller		4	Onsite, NOP
	Gene	eral Drainage		3.0	
		Curb and Gutter		3	
	Note	e: Limited assessment items are highlighte	d in grey		

					Inventory Date: 7/7/21
			a		Time: 11:35 - 11:45am
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
F00014S	W		• •	2.8	
	Gen	eral Landscape		2.0	
				2	little to no mulch, weedy, dead
		Unplanted Landscape			planting
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		1.0	
		System operation		1	None observable, tree irrigation bags present, based off plant condition
		System type (drip / spray)			unknown
		Controller			not found
	Note	e: Limited assessment items are highlighte	d in grey		

					Inventory Date: 05/19/21
			a		Time: 10:10am to 10:20am
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
F00016N	W			2.8	
	Gene	eral Landscape		2.0	
		Non-Turf Ornamental Landscape		2	weeds
	Gene	eral Trees		4.0	
				4	relatively healthy, no structural issues
		Trees			
	Gene	eral Hardscape		4.0	
		Asphalt		4	small areas / segments, uneven
		Concrete		4	minimum cracking / lighting
	Gene	eral Irrigation		1.0	
		System operation			Not observable, based on plant
		System operation		1	condition
		System type (drip / spray)			unknown
		Controller			present with meter
	Gene	eral Drainage		N/A	
		Curb and Gutter			asphalt patches need repair
		Drain Inlet			no observable issues
	Note	: Limited assessment items are highlighte	d in grey		

					Inventory Date: 7/8/21
			-		Time: 2:32 - 2:36pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
F00020S	E			3.6	
	Gene	eral Landscape		3.0	
					gaps, weedy, some dieback, some bare
		Non-Turf Ornamental Landscape		3	spots
	Gene	eral Trees		4.0	
		Trees		4	
		eral Hardscape		4.0	
		Concrete		4	Little slippery because of sand
	Gene	eral Irrigation		3.0	
		System operation			Not observable, based off plant
		System Operation		3	condition
		System type (drip / spray)			Unknown
		Controller			Not found
	Gene	eral Drainage		4.0	
		Curb and Gutter		4	
	Note	: Limited assessment items are highlighte	d in grey		

					Inventory Date: 7/9/21
			.		Time: 11:50 - 11:57am
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
F00033N	IE			3.0	
	Gene	eral Landscape		3.0	
		Non-Turf Ornamental Landscape		3	Leaf litter, weedy
	Gene	eral Trees		4.0	
		Trees		4	
	Gene	eral Irrigation		2.0	
		System operation		2	Not observable, based off plant condition
		System type (drip / spray)	Spray		
		Controller			Not found
	Gene	eral Drainage		3.0	
		Curb and Gutter		3	
		Drain Inlet		3	
	Note	e: Limited assessment items are highlighte	d in grey		

					Inventory Date: 7/7/21
	Koadway Landscape Amenity Type / Material	a		Time: 2:30 - 2:32pm	
Roadway Landscape		Condition	Field Notes (all italicized notes are from maintenance staff)		
100003N	W			2.0	
	Gen	eral Landscape		1.0	
		Non-Turf Ornamental Landscape		1	Dead weeds, mowed
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Irrigation		1.0	
		System operation		1	Not observable, based off plant condition
		System type (drip / spray)			unknown
		Controller			not found
	Note	: Limited assessment items are highlighte	d in grey		<u> </u>

					Inventory Date: 7/8/21
		a		Time: 1:48 - 1:50pm	
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
100005S	E			2.7	
	Gene	eral Landscape		1.0	
		Non-Turf Ornamental Landscape		1	Weedy, plant material dead
	Gene	eral Trees		4.0	
		Trees		4	
	Gene	eral Irrigation		1.0	
		System operation		1	Not observable, based off plant condition
		System type (drip / spray)			Unknown
		Controller			Not found
	Gene	eral Drainage		4.8	
		Culvert		5	
		Curb and Gutter		5	
		Drain Inlet		5	
		Swales / Stormwater Infrastructure		4	
	Note	e: Limited assessment items are highlighte	d in grey		

	Roadway Landscape Amenity Asset Type / Material				Inventory Date: 7/9/21
			<u>–</u>		Time: 12:27 - 12:30pm
Roadway Landscape		Condition	Field Notes (all italicized notes are from maintenance staff)		
100008N	E			2.3	
	Gen	eral Landscape		2.0	
		Non-Turf Ornamental Landscape		2	Lots of leaf litter, weedy, gaps
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Irrigation		1.0	
		System operation		1	Not observable, based off plant condition
		System type (drip / spray)			Unknown
		Controller			Not found
	Note	: Limited assessment items are highlighte	d in grey		

					Inventory Date: 7/7/21
			a		Time: 2:11 - 2:15pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
100011N	W			1.7	
	Gen	eral Landscape		1.0	
					Little weedy, mowed, dead planting
		Non-Turf Ornamental Landscape		1	material
	Gen	eral Trees		3.0	
		Trees		3	Dieback on couple trees, mistletoe infestation
	Gen	eral Irrigation		1.0	
		System operation		1	Not observable, based off plant condition
		System type (drip / spray)			unknown
		Controller			not found
	Note	: Limited assessment items are highlighte	d in grey		

					Inventory Date: 7/9/21
			a		Time: 11:27 - 11:29am
Roadway Landscape	Amenity	Asset	Type / Material		Field Notes (all italicized notes are from maintenance staff)
1000125	E			2.8	
	Gene	eral Landscape		1.0	
		Non-Turf Ornamental Landscape		1	Super weedy, lots of dieback, patchy
	Gene	eral Trees		4.0	
		Trees		4	
	Gene	eral Hardscape		4.0	
		Pavers		4	
	Gene	eral Irrigation		1.0	
		System operation		1	Not observable, based on plant condition
		System type (drip / spray)			Unknown
		Controller			Not found
	Gene	eral Drainage		4.0	
		Curb and Gutter		4	
	Note	: Limited assessment items are highlighte	d in grey		

					Inventory Date: 6/23/21 & 7/7/21
			_		Time: 4:51-4:53pm, 3:08-3:10pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
1000155	E			3.5	
	Gen	eral Landscape		2.0	
		Unplanted Landscape		2.0	
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Irrigation		3.0	
		System operation		2	Does not seem to be running, not observable
		System type (drip / spray)			Bubblers on tree
		Controller		4	No observable problems
	Gen	eral Drainage		5.0	
		Culvert		5	
		Curb and Gutter		5	
		Drain Inlet		5	
		Swales / Stormwater Infrastructure		5	
	Note	e: Limited assessment items are highlighte	ed in grey		

	Roadway Landscape Amenity Asset Type / Material				Inventory Date: 7/7/21
			<u>–</u>		Time: 4:21 - 4:29pm
Roadway Landscape		Condition	Field Notes (all italicized notes are from maintenance staff)		
100017N	W			4.0	
	Gen	eral Landscape		4.0	
		Non-Turf Ornamental Landscape		4	Few dead plants, mulch good
	Gen	eral Trees		4.0	
		Trees		4	1 tree has dieback
	Gen	eral Irrigation		4.0	
		System operation		4	Not observable, based off plant condition
		System type (drip / spray)			Unknown
		Controller			Not found
	Note	: Limited assessment items are highlighte	d in grey		

					Inventory Date: 6/24/21			
			<u>-</u>		Time: 4:15 - 4:22pm			
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)			
1000195	E			3.3				
	Gen	eral Landscape		3.0				
		Non-Turf Ornamental Landscape		3	plant dieback, weedy, dead grasses			
	Gen	eral Trees		4.0				
		Trees		4				
	Gen	eral Hardscape		4.0				
		Concrete		4				
	Gen	eral Irrigation		2.0				
		System operation		2	Not observable, based off plant condition			
		System type (drip / spray)			not found			
		Controller			not found			
	Note: Limited assessment items are highlighted in grey							

					Inventory Date: 7/7/21
			a		Time: 1:48 - 1:52pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
100020N	W			1.0	
	Gen	eral Landscape		1.0	
		Non-Turf Ornamental Landscape		1	Weedy, dead plant material
	Gen	eral Irrigation		1.0	
		Custom en emilian			Not observable, based off plant
		System operation		1	material
		System type (drip / spray)			unknown
		Controller			not found
	Note	: Limited assessment items are highlighte	d in grey	-	

					Inventory Date: 7/8/21
			-		Time: 2:51 - 2:55pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
1000225	E			3.6	
	Gene	eral Landscape		4.0	
					Some gaps but looks intentional, mulch
		Non-Turf Ornamental Landscape		4	lacking
	Gene	eral Trees		4.0	
		Trees		4	
	Gene	eral Hardscape		4.0	
		Other:	Cobble	4	Looks new
	Gene	eral Irrigation		3.0	
		System eneration			plants doing well, cannot verify if
		System operation		3	efficient
		System type (drip / spray)			Unknown
		Controller		3	Not found
	Gene	eral Drainage		3.0	
		Curb and Gutter		3	
	Note	e: Limited assessment items are highlighte	d in grey		

					Inventory Date: 7/7/21
			a		Time: 2:02 - 2:07pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
100023N	W			1.0	
	Gen	eral Landscape		1.0	
		Non-Turf Ornamental Landscape		1	Dead plants, weedy
	Gen	eral Irrigation		1.0	
		Custom energian			Not observable, based off plant
		System operation		1	condition
		System type (drip / spray)			unknown
		Controller			not found
	Note	: Limited assessment items are highlighte	d in grey	-	

					Inventory Date: 7/9/21
			a		Time: 11:18 - 11:21am
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
100025N	E			3.0	
	Gen	eral Landscape		3.0	
					Weedy, large gaps, no mulch, lots of
		Non-Turf Ornamental Landscape		3	leaf litter
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Irrigation		2.0	
		Custom energian			not observable, based off plant
		System operation		2	condition
		System type (drip / spray)			Unknown
		Controller			Not Found
	Note	: E: Limited assessment items are highlighte	d in grey	-	•

					Inventory Date: 7/9/21
			a		Time: 12:17 - 12:18pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
100028N	IE			3.8	
	Gen	eral Landscape		2.0	
		Unplanted Landscape		2	needs mulch, weedy
	Gen	eral Trees		4.0	
		Trees		4	Valley oak?
	Gen	eral Hardscape		4.0	
		Asphalt		4	
	Gen	eral Irrigation		N/A	
		System operation			Assuming none because of oak
	Gen	eral Drainage		5.0	
		Culvert		5	
		Curb and Gutter		5	
		Drain Inlet		5	
		Swales / Stormwater Infrastructure		5	
	Note	e: Limited assessment items are highlight	ed in grey		

					Inventory Date: 6/23/21
			a		Time: 2:20 - 2:23pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
				2.0	General Observations:
					Triangular porkchop median with dead
					grass
	Gen	eral Landscape		2.0	
					mowed, dead grass, possibly turf
		Unplanted Landscape		2.0	previously
	Gen	eral Irrigation		1.0	
		System exerction			Not observable, based on plant
		System operation		1	condition
		System type (drip / spray)			None observable
		Controller			None observable
	Gen	eral Drainage		3.0	
		Curb and Gutter		3	
	Note	: Limited assessment items are highlighte	d in grey	•	·

					Inventory Date: 7/7/21
			.		Time: 3:49 - 3:52pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
100042N	E			4.5	
	Gen	eral Landscape		5.0	
					Pruning of dead flowers needed, need
		Non-Turf Ornamental Landscape		5	some mulch
	Gen	eral Irrigation		4.0	
		Custom en enstien			Not observable, based on plant
		System operation		4	condition
		System type (drip / spray)			Unknown
		Controller			Not found
	Note	e: Limited assessment items are highlighte	d in grey		

				1	Inventory Date: 7/7/21
	Amenity	Asset	.		Time: 12:10 - 12:15pm
Roadway Landscape			Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
M00001	SW			3.5	
	Gen	eral Landscape		3.0	
					One section very weedy, some bare
		Non-Turf Ornamental Landscape		3	areas
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		3.0	
		System eneration			Not observable, only one section with
		System operation		3	dead plants
		System type (drip / spray)			unknown
		Controller			not found
	Note	: Limited assessment items are highlighte	d in grey		

					Inventory Date: 7/7/21
	Amenity	Asset	Type / Material		Time: 4:13 - 4;19pm
Roadway Landscape				Condition	Field Notes (all italicized notes are from maintenance staff)
M00002	NW			3.8	
	Gen	eral Landscape		4.0	
		Non-Turf Ornamental Landscape		4	lots of weeds, overgrown
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		3.0	
		System operation		3	Not observable, based on plant condition
		System type (drip / spray)			Unknown
		Controller			Not found
	Note	e: Limited assessment items are highlighte	d in grey		

		Asset			Inventory Date: 7/8/121
			a		Time: 2:20 - 2:25pm
Roadway Landscape	Amenity		Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
M00006	SE			3.5	
	Gen	eral Landscape		2.0	
		Non-Turf Ornamental Landscape		2	Weedy, mowed, dry, gaps
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		2.5	
		System operation		3	Not observable
		System type (drip / spray)			Unknown
		Controller		2	NOP
	Gen	eral Drainage		5.0	
		Culvert		5	
		Curb and Gutter		5	
		Drain Inlet		5	
		Swales / Stormwater Infrastructure		5	NOP
	Not	e: Limited assessment items are highlight	ed in grey	-	·

					Inventory Date: 7/7/21
			a		Time: 12:15 - 12:20pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
M00006	SW			2.5	
	Gen	eral Landscape		1.0	
		Non-Turf Ornamental Landscape		1	Plants dead
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	light weed growth
	Gen	eral Irrigation		1.0	
		System operation		1	Not observable, planting dead
		System type (drip / spray)			Not observable
		Controller			not found
	Note	e: Limited assessment items are highlighte	d in grey		

		Asset			Inventory Date: 7/8/21
			a		Time: 2:20 - 2:25pm
Roadway Landscape	Amenity		Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
M00007	'SE			3.5	
	Gen	eral Landscape		2.0	
		Non-Turf Ornamental Landscape		2	Weedy, mowed, dry, gaps
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		2.5	
		System operation		3	Not observable, signs of irrigation (valve box)
		System type (drip / spray)			Unknown
		Controller		2	NOP
	Gen	eral Drainage		5.0	
		Culvert		5	NOP
		Curb and Gutter		5	
		Drain Inlet		5	
		Swales / Stormwater Infrastructure		5	NOP
	Note	: Limited assessment items are highlight	ed in grey		

Roadway Landscape	Amenity	Asset	Type / Material	Condition	Inventory Date: 6/23/21 Time: 2:00-2:05pm Field Notes (all italicized notes are from maintenance staff)
M00008	NE			3.5	General Observations:
					Plants unkept
	Gen	eral Landscape		3.0	
	Gen	Non-Turf Ornamental Landscape eral Trees		3	Weedy, dieback, gaps between shrubs
		Trees		4	London Plane
		eral Hardscape		4.0	
		Other:	Stone veneer	4	
	Gen	eral Irrigation		3.5	
		System operation		3	N.O.P, dead plant material
		System type (drip / spray)			N.O.P
		Controller		4	N.O.P
	Gen	eral Drainage		3.0	
		Curb and Gutter		3	
	Note	 e: Limited assessment items are highlighte	d in grey		

		Asset			Inventory Date: 7/8/21
			a		Time: 2:20 - 2:25pm
Roadway Landscape	Amenity		Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
M00008	SE			3.5	
	Gene	eral Landscape		2.0	
		Non-Turf Ornamental Landscape		2	Weedy, mowed, dry, gaps
	Gene	eral Trees		4.0	
		Trees		4	
		eral Hardscape		4.0	
		Concrete		4	
	Gene	eral Irrigation		2.5	
		System operation		3	Not observable, based off plant condition
		System type (drip / spray)			Unknown
		Controller		2	NOP
	Gene	eral Drainage		5.0	
		Culvert		5	NOP
		Curb and Gutter		5	
		Drain Inlet		5	
		Swales / Stormwater Infrastructure		5	NOP
	Note	: Limited assessment items are highlight	l ed in grey		

					Inventory Date: 7/7/21			
Roadway Landscape	Amenity	Asset	Type / Material		Time: 2:23 - 2:26pm			
				Condition	Field Notes (all italicized notes are from maintenance staff)			
M00010	NW			2.3				
	Gen	eral Landscape		1.0				
		Non-Turf Ornamental Landscape		1	dead weeds, mowed			
	Gen	eral Trees		4.0				
		Trees		4				
	Gen	eral Hardscape		3.0				
		Pavers		3	Worn			
	Gen	eral Irrigation		1.0				
		System operation		1	Not observable, based on plant condition			
		System type (drip / spray)	Spray					
		Controller			not found			
	Note: Limited assessment items are highlighted in grey							

					Inventory Date: 6/24/21
			a l		Time: 4:37 - 4:46pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
M00010	SE			3.1	
	Gene	eral Landscape		2.0	
		Unplanted Landscape		2.0	No mulch, all weeds
		eral Trees		4.0	
		Trees		4	
	Gene	eral Hardscape		2.5	
		Pavers	Cobble	3	at nosing on Burt St
		Decomposed Granite / Gravel	Brick Pavers	2	at nosing on other side
	Gene	eral Irrigation		2.0	
		System operation		2	Does not appear to be running
		System type (drip / spray)			
		Controller			N.O.P
		eral Drainage		5.0	
		Culvert		5	
		Curb and Gutter		5	
		Drain Inlet		5	
		Swales / Stormwater Infrastructure		5	
	Note	: Limited assessment items are highlight	ed in grey		

					Inventory Date: 7/7/21
			a		Time: 11 to 11:20am
Roadway Landscape Amenitv		Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
M00011	SW			4.0	
		eral Landscape		4.0	
		Non-Turf Ornamental Landscape		4	Weedy, some dieback
	Gene	eral Trees		4.0	
		Trees		4	
	Gene	eral Hardscape		4.0	
		Concrete		4	
	Gene	eral Irrigation		4.0	
		System operation		4	NOP/newer seemed City standard
		System type (drip / spray)			unknown
		Controller			NOP
	General Drainage			4.0	
		Curb and Gutter		4	Public Works?
	Note	: Limited assessment items are highlighte	d in grey		

					Inventory Date: 7/7/21
			Type / Material		Time: 1:50 - 1:54pm
Roadway Landscape	Amenity	Asset			Field Notes (all italicized notes are from maintenance staff)
M00018	NW			2.5	
	Gene	eral Landscape		1.0	
		Non-Turf Ornamental Landscape		1	Dead plants, no mulch, missing plants
	Gene	eral Trees		4.0	
		Trees		4	Dieback on 1 tree out of 20-ish
	Gene	eral Hardscape		4.0	
		Concrete		4	
				4	Light number of weeds growing
		Pavers			between cracks
	Gene	eral Irrigation		1.0	
		System operation			Not observable, based on plant
		System operation		1	condition
		System type (drip / spray)			unknown
		Controller			not found
	Note	e: Limited assessment items are highlighte	d in grey		

					Inventory Date: 7/9/21
			a		Time: 11:58 - 12:05pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
M00021	NE			3.0	
	Gen	eral Landscape		3.0	
		Non-Turf Ornamental Landscape		3	Weedy, dieback, some fire damage
	Gen	eral Trees		4.0	
		Trees		4	Some fire damage
	Gen	eral Hardscape		4.0	
		Concrete		4	At nosing only
	Gen	eral Irrigation		1.0	
		System energian			Fire damage, assuming irrigation does
		System operation		1	not work
		System type (drip / spray)	Spray		
		Controller			Not found
	Gen	eral Drainage		3.0	
		Curb and Gutter		3	
		Drain Inlet		3	
	Note	: Limited assessment items are highlight	ted in grey	•	·

					Inventory Date: 7/7/21
			a		Time: 1:29 - 1:35pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
M00021	NW			2.5	
	Gen	eral Landscape		1.0	
					very weedy, mowed, dead plant
		Non-Turf Ornamental Landscape		1	material
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		1.0	
		System operation		1	Not observable, based on plant condition
		System type (drip / spray)			unknown
		Controller			not found
	Note	: Limited assessment items are highlighte	d in grey		

				1	Inventory Date: 7/9/21
			_		Time: 12:43 - 12:46pm
Roadway Landscape Amenity		Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
M00028	NE			2.6	
	Gene	eral Landscape		1.0	
		Non-Turf Ornamental Landscape		1	weedy, mowed weeds, leaf litter
	Gene	eral Trees		4.0	
		Trees		4	
	Gene	eral Hardscape		4.0	
		Concrete		4	
	Gene	eral Irrigation		1.0	
		System operation		1	Not observable, based on plant condition
		System type (drip / spray)			unknown
		Controller			not found
	General Drainage			3.0	
		Curb and Gutter		3	
	Note	: Limited assessment items are highlighte	d in grey		

					Inventory Date: 7/7/21
			a		Time: 3:33 - 3:37pm
Roadway Landscape	Amenity	Asset	Type / Material	Condition	Field Notes (all italicized notes are from maintenance staff)
M00029	NW			4.2	
	Gen	eral Landscape		4.0	
		Non-Turf Ornamental Landscape		4	Some weeds, gaps with bare ground showing, minor, could use more mulch
	Gen	eral Trees		4.0	
		Trees		4	
	Gen	eral Hardscape		4.0	
		Concrete		4	
	Gen	eral Irrigation		4.0	
		System operation		4	plants alive
		System type (drip / spray)	Drip		Can see driplines
		Controller			not found
	Gen	eral Drainage		5.0	
		Culvert		5	
		Curb and Gutter		5	
		Drain Inlet		5	
		Swales / Stormwater Infrastructure		5	
	Note	 e: Limited assessment items are highlight	l ed in grey		

				Inventory Date: 7/7/21
		a		Time: 4:30 - 4:38pm
Amenity	Asset	Type / Materi	Condition	Field Notes (all italicized notes are from maintenance staff)
NE		•	3.4	
Gene	eral Landscape		3.0	
				Weedy, mowed, large gaps, some
			3	vigorous shrubs
			4.0	
			4	
	•		3.0	
			4	little bit weedy
		wood retaining wall		Split/broken on some, worn
Gene	eral Irrigation		2.0	
	System operation		2	Not observable, based on plant condition
	System type (drip / spray)			Unknown
	Controller			Not found
Gene	eral Drainage		5.0	
	Culvert		5	
	Curb and Gutter		5	
	Drain Inlet		5	
	Swales / Stormwater Infrastructure		5	
Note	: Limited assessment items are highlight	ed in grev		<u> </u>
	Gend Gend Gend Gend	VE General Landscape Non-Turf Ornamental Landscape General Trees Trees General Hardscape Pavers Other: General Irrigation System operation System type (drip / spray) Controller General Drainage Culvert Curb and Gutter Drain Inlet Swales / Stormwater Infrastructure	VE	NE 3.4 General Landscape 3.0 Non-Turf Ornamental Landscape 3 General Trees 4.0 Trees 4.0 General Hardscape 3.0 Pavers 4 Other: wood retaining wall 2 General Irrigation 2.0 System operation 2 System type (drip / spray) 2 Controller 5 Culvert 5 Curb and Gutter 5 Drain Inlet 5 Swales / Stormwater Infrastructure 5

Page is Intentionally Blank





Cost Estimate Table

Parks Prioritization Report

Appendices 305

ESTIMATED UNIT COST PER SQUARE FOOT

	ESTIMATED IMPROVEMENT COST (AVG)	ESTIMATED IMPROVEMENT COST	DEMOLITION, MOBILIZATION, STARTUP, CONTINGENCY	ESTIMATED SUBTOTAL CONSTRUCTION COST	ESTIMATED DESIGN COST	ESTIMATED TOTAL DESIGN + CONSTRUCTION COST
	wg. Unit Cost/SF	wg. Unit Cost/SF	%	vg. Unit Cost/SF	%	Avg. Unit Cost/SF
General Furnishings	\$ 0.27	\$ 0.40	40%	\$ 0.51	48%	\$ 0.75
General Landscape	\$ 1.18	\$ 2.00	40%	\$ 2.47	48%	\$ 3.66
General Trees	\$ 0.18	\$ 0.18	40%	\$ 0.26	48%	\$ 0.38
General Hardscape	\$ 22.59	\$ 22.59	40%	\$ 31.63	48%	\$ 46.82
General Irrigation	\$ 1.79	\$ 2.50	40%	\$ 3.22	48%	\$ 4.76
General Lighting	\$ 0.39	\$ 0.39	40%	\$ 0.54	48%	\$ 0.80
General Barriers	\$ 0.15	\$ 0.15	40%	\$ 0.21	48%	\$ 0.31
General Signage	\$ 0.15	\$ 0.15	40%	\$ 0.22	48%	\$ 0.32
General Drainage	\$ 0.95	\$ 0.95	40%	\$ 1.33	48%	\$ 1.97
General Structures	\$ 135.00	\$ 135.00	40%	\$ 189.00	48%	\$ 279.72
Picnic Areas	\$ 35.89	\$ 35.89	40%	\$ 50.25	48%	\$ 74.36
Parking Lot	\$ 12.73	\$ 12.73	40%	\$ 17.83	48%	\$ 26.38
Fitness Equipment	\$ 37.44	\$ 37.44	40%	\$ 52.41	48%	\$ 77.57
Playground	\$ 59.95	\$ 59.95	40%	\$ 83.93	48%	\$ 124.22
Sports Field / Court						
Tennis Court	\$ 15.37	\$ 15.37	40%	\$ 21.52	48%	\$ 31.84
Pickleball Court	\$ 10.97	\$ 10.97	40%	\$ 15.35	48%	\$ 22.72
Bocce/Horseshoe Court	\$ 22.20	\$ 22.20	40%	\$ 31.07	48%	\$ 45.99
Basketball Court / handball	\$ 11.79	\$ 11.79	40%	\$ 16.50	48%	\$ 24.43
Volleyball Court	\$ 16.20	\$ 16.20	40%	\$ 22.68	48%	\$ 33.57
Soccer Field	\$ 3.11	\$ 4.00	40%	\$ 5.25	48%	\$ 7.76
Softball/Baseball Field	\$ 15.84	\$ 15.84	40%	\$ 22.18	48%	\$ 32.83
Football Field	\$ 3.11	\$ 3.11	40%	\$ 4.36	48%	\$ 6.45
Track and Field	\$ 11.29	\$ 11.29	40%	\$ 15.81	48%	\$ 23.40
Trails	\$ 6.03	\$ 6.03	40%	\$ 8.44	48%	\$ 12.50
Dog Park	\$ 9.81	\$ 9.81	40%	\$ 13.73	48%	\$ 20.32
Skate Park	\$ 27.37	\$ 27.37	40%	\$ 38.31	48%	\$ 56.70
Bike Pump Track	\$ 20.00	\$ 20.00	40%	\$ 28.00	48%	\$ 41.44
Water Feature	\$ 100.00	\$ 100.00	40%	\$ 140.00	48%	\$ 207.20
Sprayground	\$ 562.31	\$ 562.31	40%	\$ 787.23	48%	1,165.10
Community Gardens	\$ 26.17	\$ 26.17	40%	\$ 36.64	48%	\$ 54.23

City of Santa Rosa



Text File

File Number: 22-334BCS

Agenda Date: 9/28/2022

Version: 1

Status: In Committee

In Control: Board of Community Services

Agenda Number: 9.1

File Type: BCS-Agenda Item

City of Santa Rosa



Text File

File Number: 22-335BCS

Agenda Date: 9/28/2022

Version: 1

Status: In Committee

In Control: Board of Community Services

Agenda Number: 9.2

File Type: BCS-Agenda Item

City of Santa Rosa



Text File

File Number: 22-336BCS

Agenda Date: 9/28/2022

Version: 1

Status: In Committee

In Control: Board of Community Services

Agenda Number: 10.1

File Type: BCS-Agenda Item



Person Senior Wing • 2060 W. College Ave, Santa Rosa, CA 95401 • 707-543-3745 Steele Lane Recreation Center • 415 Steele Lane, Santa Rosa, CA 95403 • 707-543-3282 Ext 1

SantaRosaRec.com

INSIDE THIS ISSUE!

Mark your Calendar

Activity Highlights	2
Community Center News	
Instructor Spotlight	2
Activity Spotlight	2
Senior Interest	
Guest Speaker Series	3
Senior Resources	
NOAA Weather Radio	3
Stay Actively Connected	3
What's Upcoming?	
	1



Steele Lane Center/Dohn Rm Sat, October 15 (10am-2pm) \$10 Pre-registration by Oct 10 required (code 55489) \$10 due at event. Additional bingo packs (9 games) are available for \$5 each Admission includes game sheets and Lunch. We have daubers!





Senior Expo Returns!

Held the 2nd Saturday of July, the Senior Expo welcomed more than 400 seniors back to the 21st annual event. Thank you to our sponsors and congratulations to our prize giveaway winners!

Celebrate Oktoberfest with a Festive BBQ

Come celebrate autumn at the annual Oktoberfest featuring a BBQ lunch with brats and non-alcohol beverages. Enjoy live accordion and polka dance music performed by Steve Balich. Oktoberfest originated in 1810 celebrating the marriage of the crown prince of Bavaria,

who later became King Louis I, to Princess Therese von Sachsen-Hildburghausen. Held outdoors so wear sunscreen and a hat.

Finley Courtyard

Fri, September 16 (12-1:30pm) \$6 members, \$12 non-members Pre-registration by Sep 12 required (code 53478)



Bingo Party Back by Popular Demand

Bingo is the American version of an Italian game called "Lo Giuoco del Lotto D'Italia" that was all the rage dating back as far as the mid-1500s. When the game reached North America in 1929 it was known as "beano" but later renamed bingo after a caller yelled out "BINGO" instead of beano. Bingo is more than just a fun activity. Researchers have found that playing bingo has multiple health benefits. It takes concentration - which improves listening, short-term memory skills and helps us maintain a happy and healthy lifestyle.

Mark Your Calendar

SEPTEMBER

- Sep 2 Dance, Tom Shader Trio, Finley
- Sep 5 Labor Day, Centers Closed
- Sep 9 Dance, Memory Lane Combo, Finley
- Sep 16 Oktoberfest BBQ, Finley Courtyard
- Sep 16 Dance, Steve Luther DJ, Finley
- Sep 23 Dance, SwingSet Band, Finley
- Sep 30 Dance, Steve Luther DJ, Finley

OCTOBER

- Oct 7 Dance, Tom Shader Trio, Finley
- Oct 14 Dance, Memory Lane Combo, Finley
- Oct 21 Dance, Steve Luther DJ, Finley
- Oct 28 Halloween Dance, SwingSet Band, Finley

NOVEMBER

- Nov 4 Dance, Tom Shader Trio, Finley
- Nov 11 Veteran's Day, Centers Closed
- Nov 18 Dance, Steve Luther DJ, Finley
- Nov 24-25 Thanksgiving, Centers Closed

Community Center News

A Special Class Just for Veterans Learn Pole Walking for Balance and Mobility

This course is for veterans ONLY. When Pole Walking, you feel energized, taller and more confident! This training is designed for people with mild to moderate mobility challenges and is ideal if you are preparing for or recovering from joint surgery. People with MS, Parkinson's, arthritis or aging joints find these skills invaluable for maintaining quality of life. Variety of poles are provided. Instructor: Jayah Faye Paley

Person Sr. Wing/Rm4

Fri, October 14 (9:30am-12:30pm) \$4 non-members Pre-registration required (code 53942)

Spanish - Luis (Brand New Beginning)

Brand new to Spanish? Instructor Luis Salvago-Toledo is offering to teach a group the basics.

Person Sr. Wing/Rm28 Tue, weekly 1-2:30pm \$3 non-members



Activity Spotlight

Common Ground Dog Training with Mike Ossenbeck

While the COVID pandemic threw much of normal life into a tailspin, there was one class that was able to come back safely and quickly -- Companion Dog Training. Mike Ossenbeck has been teaching classes with Santa Rosa Recreation & Parks for several years and has been working with dogs and their loved ones for over 30 years. Many class participants have been active adults, using their time to work on better manners for their furry family members. If your canine companion could use some training, please visit santarosarec. com to register for one of Mike's dog training classes.

FREE for Members!

Senior Interest

Guest Speaker Series for Senior Members

Join us for engaging, educational presentations on a wide variety of topics.

JOHNSTON | THOMAS

Johnston-Thomas Attorneys at Law presents: Create Your Own Basic Estate Plan – Roy Johnston

This workshop is suited for those who have a simple estate and do not own their home or real estate, thus do not need a trust (forms and guidance provided).

Wed, September 21, 10-11:30am Person Sr. Wing/Rm 23 \$5 non-members Pre-registration required (code 55138)



Premier World Discovery presents: Upcoming Travel Opportunities


Joan Thornton, Premier World Discovery representative, presents highlights of their travel package opportunities in 2023.

Thu, November 3, 1:30-2:30pm Person Sr. Wing/Rm 23 \$2 non-members Pre-registration required (code 55190

Senior Resources

Stay Actively Connected

A Mighty Good Time is a curated online calendar of events for adults 50 and older, featuring inperson, virtual, and phone-accessible activities, from around the country. The site is completely free to search and features thousands of events annually from recreation providers who are also passionate about facilitating connection, improving health, and aging-well, visit: amightygoodtime.com





Get a Free All Hazards NOAA Weather Radio

All Hazards NOAA Weather Radio (NWR) is a lowcost home alerting tool that can be remotely activated by the National Weather Service(NWS) to broadcast life-saving warnings issued by first responders. NWRs include battery backups.Available free at both senior center front counters. To learn more about the City's alert and warning tools, visit: srcity.org/ReadySR.






SRCity.org/Seniors

PRSRT STD U.S. POSTAGE PAID PERMIT NO. 526 SANTA ROSA, CA

Parks Make Life Better!

Fall Season Word Search

Find the words from the right column in the grid. Words may be forward, backward, up, down or diagonal. Good luck!



ΙQ LDGET QZIKNFYQ V Т WTZ PELWUEO QKD JJP С КΥ 0 YM KEAWQO M D Х J Η ΗC I R M E TH Ρ NWAQDD G Q S N DA CXF DM S U т UA IOC W N Μ RKS E VAELB E J С H N OOZLK CEE R D J RLI M 0 Y S K UMH L R Q M M Х D N Α G V G T R Μ U C L Ι Α M т J В Ν Ρ С VΜ M U D Z E ZG IKHSXLK v F V S Q J D MK DBHEARHH S Η Т R L W DE U N R BBMIABBE Q Ρ D H N DNB Т S Ι Ι XSEBEANT S E VR AHS v J. Κ K T YZT S RE BM ΕVΟ NWP C U Α U Ρ Q B 0 P L L Ε Α F ΚH ΗF E Ι T C D SMN FDE Ρ 0 C Q W Z L N R Υ 0 0 N CEURFPSXK R U P Y TL Т TR В DR A PLCVI SYD G VED v OED TEEWSAGQD v N IMYP UJI EDRLHQAGZKLRXGEA DWCLDGN IVIGSKNAHT DTI

ACORN APPLE AUTUMN CIDER FALL HALLOWEEN HARVEST LEAVES NOVEMBER OCTOBER PUMPKIN RAKE SCARECROW SEASON SEPTEMBER THANKSGIVING



(707) 543-3737/ TDD (707) 543-3289 M-F 8am-5pm For accessible information call (707)543-3292