Acacia Village SANTA ROSA, CA

Arborist's Report

May 22, 2018

Prepared for:

Robert Upton Campus Property Group

Submitted by:

Becky Duckles, Consulting Arborist ISA Certified Arborist #WE-0796A Sebastopol, CA. 707.829.0555 PH.

BECKY DUCKLES LANDSCAPE CONSULTANT & ARBORIST

SEBASTOPOL, CA 707.829.0555 PH

ACACIA VILLAGE Santa Rosa, CA

ARBORIST'S REPORT May 22, 2018

This site is presently occupied by a modest residence and outbuildings with some ornamental trees as well as a few natives scattered throughout. The existing trees on the property are all listed by number on the accompanying inventory with identification, diameter, condition and structure ratings, as well as outcome in relation to proposed development. Because of the tight site, and layers of requirements for utilities and stormwater infiltration, road and sidewalk improvements, etc. the project design team was only able to preserve two existing trees – two mature London planes (aka sycamores).

Also enclosed is a Tree Removal and Mitigation Calculation summary for the site, as per Santa Rosa Tree Ordinance requirements.

Please call if there are questions or more information is needed.

Respectfully submitted,

Becky Duckles

Becky Duckles

International Society of Arboriculture, Western Chapter Certified Arborist #WE-0796A

BECKY DUCKLES LANDSCAPE CONSULTANT & ARBORIST SEBASTOPOL, CA

707.829.0555 PH

ACACIA VILLAGE Santa Rosa, CA

TREE REMOVAL & MITIGATION CALCULATIONS May 22, 2018

Of the existing trees on this site, the following trees will be removed which require mitigation, based on the Tentative Map dated 3/28/18 by Munselle Civil Engineering. For every 6" of trunk diameter of protected trees, two 15 gal. size replacement trees, or \$200 (for each 6") in-lieu fee is required.

TREES TO BE REMOVED REQUIRING MITIGATION

Tree #	Diameter	Species	Comments/condition			
1	15"	Valley Oak	Good			
3	22"	Deodar Cedar	Good			
4	20"	Deodar Cedar	Good	5	,	17"
6	5,4"	Japanese Maple	Good			
8	47"	Coast Redwood	Good/Excellent			
10	13"	Valley Oak	Good/Excellent			
14	43"	Giant Sequoia	Fair/Good			
15	4,7,9,20"	Coast Redwood Good				
18	5"	Valley Oak	Excellent			
19	5"	Valley Oak	Excellent			
20	5,5,6"	Valley Oak	Excellent			
21	3,4"	Coast Live Oak	Excellent			

Total number of diameter inches of trees to be removed = 259" Divided by 6" increments = 44

Mitigation required per ordinance (2- $\frac{15 \text{ gal trees for each 6", or }}{200/6"}$ = 88 - 15 gal trees or

If 24" box trees are used, 1 = 2 - 15 gal trees, 1 - 36" box tree = 3 - 15 gal trees, 1 - 48" box tree = 4 - 15 gal trees

Respectfully submitted,

Becky Duckles

Becky Duckles, Certified Arborist #WE-0796A Member, American Society of Consulting Arborists

BECKY DUCKLES

LANDSCAPE CONSULTANT & ARBORIST SEBASTOPOL, CA. 707.829.0555 PH.

Acacia Village Santa Rosa, CA


TREE PROTECTION NOTES

May 2018

- 1. Where pruning for clearance is required on any trees to remain, it should be done by trained, qualified tree workers according to ISA & ANSI A300 Pruning Guidelines, prior to construction. Pruning should be the minimum necessary for hazard reduction, (i.e. the removal of deadwood 2" and larger, etc.) and for clearance.
- Plastic tree protection fencing should be installed at the driplines of trees within the zone of
 construction activity.
 If access within dripline will be required, fence to be placed at expected limit of grading.
 Fence should be installed prior to the start of clearing or grading operations, and kept in place
 throughout construction activities.
- 3. If any roots on trees to be preserved larger than 1" are encountered during construction activities which can't be preserved, they should be cut cleanly across the face of the root with a sharp saw, past any damaged portions.
- 4. No parking, operation of equipment, storage of materials, disposal of waste or other construction activity shall occur within driplines of trees to be preserved.

ACACIA VILLAGE - SANTA ROSA

TREE	CDECIEC	DIAMETER	GENERAL	STRUCTURAL	CONCEDUCTION IMPACT/DECOMMENDATIONS
#	SPECIES	(ln.)	HEALTH/CONDITI	INTEGRITY	CONSTRUCTION IMPACT/RECOMMENDATIONS
				Good, though co-	
1	Valley Oak/Quercus lobata	15"	Good	dominant leaders at 6'	To be removed for construction. Heritage tree
				Fair; previously	
2	Fruitless Mulberry/Morus alba	23" @ 3'	Excellent	pollarded	To be removed. Species exempt from mitigation
	Deodar Cedar/Cedrus			Good, though previously	
3	deodara	22"	Good	topped at 18'	To be removed for construction.
	Deodar Cedar/Cedrus				
4	deodara	20"	Good	Good	To be removed for construction.
	Deodar Cedar/Cedrus	47"	0	0	To be seen and for sometime
5	deodara	17"	Good	Good	To be removed for construction.
0	Japanese Maple/Acer	5 A!!	0	F-:-	To be seen and for sometime
6	palmatum	5,4"	Good	Fair Fair; previously	To be removed for construction.
7	Fruitless Mulberry/Morus alba	13,14,14"	Good	pollarded	To be removed. Species exempt from mitigation
,	Coast Redwood/Sequoia	10,14,14	0000	Good, though co-	To be removed. Openes exempt from magation
8	sempervirens	47"	Good/Excellent	dominant from 8'	To be removed for construction of home. Heritage tree
0	Gerripervirens		GOOG/EXCERCITE	dominant nom o	To be removed for constitueion of nome. Fichlage tree
9	Fruitless Mulberry/Morus alba	17" @ 3'	Good/Excellent	Good/Excellent	To be removed. Species exempt from mitigation
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
10	Valley Oak/Quercus lobata	13"	Good/Excellent	Good/Excellent	To be removed for construction of home. Heritage tree
	Monterey Pine/Pinus radiata	43"	Good	Good	To be removed. Species exempt from mitigation
	Western Red Cedar/Thuja		_		
	plicata	5,6,6"	Poor	Poor/dying	To be removed for construction.
	Western Red Cedar/Thuja	F C C 7"	D	De en/de des es	To be seen and for sometime
13	plicata	5,6,6,7"	Poor	Poor/dying	To be removed for construction.
	Sequoia/Sequoiadendron	40"	- · · · ·		
14	giganteum	43"	Fair/Good	Good	To be removed for construction.
	Coast Redwood/Sequoia	. =			
15	sempervirens	4,7,9,20"	Good	Good	To be removed for construction.
	London Plane/Platanus x				
16	hispanica	17"	Good	Good	To be preserved in common area.
	London Plane/Platanus x				
17	hispanica	23"	Good	Good	To be preserved in common area.
18	Valley Oak/Quercus lobata	5"	Excellent	Excellent	To be removed for construction.
40	N. II. O. I. O. I. I. I.	5"		.	<u> </u>
19	Valley Oak/Quercus lobata	5"	Excellent	Excellent	To be removed for construction.
20	Valley Oak/Quercus lobata	5,5,6"	Excellent	Good	To be removed for construction. Heritage tree
0.4	Coast Live Oak/Quercus	2.4"	Cycellant	Cood	To be removed for construction
21	agrifolia	3,4"	Excellent	Good	To be removed for construction.



TENTATIVE MAP PROPOSED SUBDIVISION & IMPROVEMENT PLAN





SBCA TREE CONSULTING

1534 Rose Street, Crockett, CA 94525 Phone: (510) 787-3075 Fax: (510) 787-3065

Website: www.sbcatree.com

Steve Batchelder, Consulting Arborist WC ISA Certified Arborist #228 CUFC Certified Urban Forester #134 CA Contractor License #(C-27) 53367

E-mail: steve@sbcatree.com

Molly Batchelder, Consulting Arborist
WC ISA Certified Arborist #9613A
ISA Tree Risk Assessment Qualified

E-mail: molly@sbcatree.com

Date: July 24, 2024

To: Montrell Nickerson

Villa Homes

1 Letterman Dr. Suite #C3500 San Francisco, CA 94129

Project: 746 Acacia Lane Tree Inventory

Assignment: Tag and inventory all trees 4" or greater in diameter in scope provided by Villa Homes.

Scope: Trees under 4" and those included on the City "Exempt Trees" list were not inventoried.

Appendix Items:

1. Tree Inventory Data in Excel Sheets

2. Photos of individual trees <u>link</u>

Santa Rosa Tree Ordinance

On Undeveloped Property

Permits are required for removal, alteration or relocation of all trees with a 4" or greater diameter in all zoning districts where development is being proposed or may occur in the future.

Protected Tree

A protected tree is any tree, including a Heritage tree, indicated to be preserved on an approved development plan, an approved tentative map or tentative parcel map, or other approved development.

Exempt Trees

The following trees are exempt from permit requirements in all zoning districts, whether the parcel is developed or not: *Acacias, Ailanthus*, Fruit and nut trees (except walnuts), Fruitless mulberry, Hawthorn, *Ligustrums*, Monterey *cypress, Monterey pine, Poplars, Pyracantha, Silver maple*

"Heritage tree" means any of the following:

- 1) A tree or grove of trees so designated by a resolution of the Planning Commission, upon nomination by the Director of Community Development or the Planning Commission and after the holding of a noticed public hearing, having a specific historical or cultural association or value due to its age, species, character, location, height and/or the circumstances of its planting or origin.
- 2) Any of the following trees, native to the County, whether located on private or public property, which has a diameter or a circumference equal to or greater than that listed below:

Species/Common Name	Diameter	Circumference	
1. Oak Family			
(a) Quercus lobata—valley oak	6"	19"	
(b) Q. agrifolia—live oak	18	57	
2. Sequoia sempervirens—redwood	24	75	

Summary

Arborist tree inventory tagged and collected data on 34 trees. Tag numbers begin with #101.

<u>Species amount</u> – Nine (9) different tree species were identified.

Protected trees – All 34 trees qualify as Protected under City ordinance. 1

<u>Heritage trees</u> – Ten (10) trees qualify as Heritage under City ordinance.

<u>Most numerous species</u> – The Valley Oak *(Quercus lobata)* represents 13 out of the 34 trees inventoried. Most appear to be volunteers as the species is native to the area.

<u>Table 1.</u> Table below provides a breakdown of species and arborist comments. The full tree inventory is in *Appendix 1.*

	Species	Common Name	Total Amount	Protected Tree Amount	Heritage Tree Amount	Overall Retention Suitability	Comments
1	Acer palmatum	Japanese maple	1	1	0	Poor	Declining and significant internal decay
2	Cedrus deodara	Deodar cedar	3	3	0	Fair, Good	#126 is a good specimen in health and form; #124 has multiple stem failures and is likely not suitable
3	Pinus halepensis	Aleppo pine	1	1	0	Fair-Poor	Very large tree and will require significant pruning maintenance if retention is desired
4	Platanus X hispanica	London plane	2	2	0	Good	Excellent specimens
5	Pyrus calleryana	Callery Pear	4	4	0	Fair	Likely volunteers; Species is somewhat invasive

¹ Based upon conversation with City staff in the Parks Department, multi stemmed trees are considered Protected or Heritage if they attain the specified diameter size below the stem bifurcation.



	Species	Common Name	Total Amount	Protected Tree Amount	Heritage Tree Amount	Overall Retention Suitability	Comments
6	Quercus agrifolia	Coast Live Oak	7	7	1	Good	Some minor fungal leaf blight (Cryptocline); Species native to area and doing well
7	Quercus lobata	Valley Oak	13	13	7	Good	Species doing very well at the site; #125 is not suitable due to high voltage power lines above
8	Sequoia giganteum	Giant sequoia	1	1	0	Good	Heathy specimen with ivy 25' up the trunk
9	Sequoia sempervirens	Coast Redwood	2	2	2	Good, Fair	Redwoods are no longer recommended for use due to high water demands; Tree #133 is inundated with ivy and adjacent trees; #117 is a very large specimen that is beginning to show signs of drought stress
	ı	Totals:	34	34	10		

7-24-24

3 of 4

Image 1. Tree Location Map



End

Report submitted by:

Store Botch

Steve Batchelder, Consulting Arborist ISA Certified Arborist WE 228A CaUFC Certified Urban Forester #138 Calif. Contractor Lic. (C-27) 533675

