

037-124-014

CE13-0012

211 THERESA STREET

CODE ENFORCEMENT OFFICER

CASSIDY ANDERSON

NOVEMBER 8, 2021

211 Theresa St
Property frontage



211 Theresa St
Window seal is not weather tight
Living room window



211 Theresa St
Glazing broken



211 Theresa St
Living room windows and kitchen windows




211 Theresa St.
Combo Smoke detector and carbon monoxide detector
Keyed locks on both bedrooms



211 Theresa St
Mildew on bathroom ceiling and wall



211 Theresa St
Inoperable and unregistered vehicle



211 Theresa St

Unapproved materials used to cover detached garage walls
penetration in fire rating, required 5/8 or 1/2 inch gypsum board



211 Theresa St

Detached garage door covered without benefit of permit


Extension cords have been removed

water intrusion at skylight



211 Theresa St

Foam spray and particle board surrounding wall base in detached garage



211 Theresa St

Penetration in fire rating requires 5/8 or 1/2 inch gypsum board

Water intrusion



211 Theresa St
glazing broken in window glazing



211 Theresa St

Existing accessory structure with unpermitted electrical



211 Theresa St
Unpermitted electrical in existing accessory structure



211 Theresa St
Unpermitted electrical throughout detached structure

