


Walking Audit

Infrastructure Recommendations from
Montgomery High School's Sustainable
Practices Class

Walking Audit



Making Recommendations



Franquette Avenue



No sidewalk
on the school
side



Flooded
sidewalk

Franquette Avenue School Entrance

No sidewalk

No crosswalk
at the school
entrance



Hoehn Ave

No crossing
from exiting
the footpath



No sidewalk
on the south
side

No crosswalk

Hoehn Ave at Footpath



No crosswalk
or sidewalk
exiting the
footpath



Hahman Drive – Main Entrance

Front school entrance with no crosswalk



Hahman Drive – Main Entrance

Main school entrance with no crosswalk



Thank you!