

PRIMARY RECORD

Primary #
HRI #

Trinomial

NRHP Status Code 6L – Determined ineligible for local
designation through local review.

Other Listings
Review Code

Reviewer

Date

Page 1 of 1

*Resource Name or #: 25 Rae St.

P1. Other Identifier:

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Sonoma

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad:

Date:

T

; R

; ¼ of

¼ of Sec

; M.D.

B.M.

c. Address: 25 Rae Street

City: Santa Rosa

Zip: 95404

d. UTM: Zone: 10 ; mE/ mN (G.P.S.)

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) Elevation:

APN 009-201-004-000 **BURBANK GARDENS DISTRICT**

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

Vacant lot

*P3b. Resource Attributes: (List attributes and codes)

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other (Isolates, etc.)

P5a. Photo or Drawing (Photo required for buildings, structures, and objects.)



P5b. Description of Photo: (View, date, accession #)

Photo taken 2002

*P6. Date Constructed/Age and Sources: ☐ Historic

☐ Prehistoric ☐ Both

Est. N/A

*P7. Owner and Address:

*P8. Recorded by: (Name, affiliation, and address)

Rosie Klein, Santa Rosa Dept. of
Community Development

*P9. Date Recorded: 2005

*P10. Survey Type: (Describe)

Windshield survey

*P11. Report Citation: (Cite survey report and other sources, or enter "none.")

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (List):

DPR 523A (1/95)

*Required information

State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary #
HRI #

Trinomial

NRHP Status Code 5D1- Contributor to a district that is listed
or designated locally

Other Listings
Review Code

Reviewer

Date

Page 1 of 1

*Resource Name or #: 715 Tupper St.

P1. Other Identifier:

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Sonoma

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad:

Date:

T

R

1/4 of

1/4 of Sec

M.D.

B.M.

c. Address: 715 Tupper Street

City: Santa Rosa

Zip: 95404

d. UTM: Zone: 10 ; mE/ mN (G.P.S.)

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) Elevation:

APN 009-201-009-000 **BURBANK GARDENS DISTRICT**

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

Vernacular Cottage

*P3b. Resource Attributes: (List attributes and codes)

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other (Isolates, etc.)

P5a. Photo or Drawing (Photo required for buildings, structures, and objects.)



P5b. Description of Photo: (View, date, accession #)

Photo taken 2002

*P6. Date Constructed/Age and Sources: ☒ Historic

☐ Prehistoric ☐ Both

Est. 1906

*P7. Owner and Address:

*P8. Recorded by: (Name, affiliation, and address)

Rosie Klein, Santa Rosa Dept. of
Community Development

*P9. Date Recorded: 2005

*P10. Survey Type: (Describe)

Windshield survey

*P11. Report Citation: (Cite survey report and other sources, or enter "none.")

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (List):

DPR 523A (1/95)

*Required information