

State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary #
HRI #

Trinomial
NRHP Status Code 6L – Determined ineligible for local
designation through local review.

Review Code

Reviewer

Date

Page 1 of 1

*Resource Name or #: 320 College Avenue

P1. Other Identifier:

*P2. Location: ☐ Not for Publication ☒ Unrestricted

*a. County: Sonoma

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad:

Date:

T ; R ; ¼ of ¼ of Sec ; M.D. B.M.

c. Address: 320 College Avenue

City: Santa Rosa

Zip: 95401

d. UTM: Zone: 10 ; mE/ mN (G.P.S.)

e. Other Location Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) Elevation:

APN 010-113-035 **ST. ROSE DISTRICT**

*P3a. **Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

Style: New/Modern

Alterations:

*P3b. **Resource Attributes:** (List attributes and codes)

*P4. **Resources Present:** ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other (Isolates, etc.)

P5a. Photo or Drawing (Photo required for buildings, structures, and objects.)



P5b. Description of Photo: (View, date, accession #)
Photo taken from the street in 2007 as part of the Cultural Heritage Survey Update Project.

*P6. **Date Constructed/Age and Sources:** ☐ Historic ☐ Prehistoric ☐ Both
Est. 1977

*P7. **Owner and Address:**

*P8. **Recorded by:** (Name, affiliation, and address)

Corbin Johnson, Santa Rosa
Dept. of Community Development

*P9. **Date Recorded:** 2007

*P10. **Survey Type:** (Describe)

Windshield survey

*P11. **Report Citation:**

None

*Attachments: ☒ NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record ☐ Other (List):

DPR 523A (1/95)

*Required information