State of California — The Resources Agency DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary # HRI#

Trinomial NRHP Status Code 6L-Determined ineligible for local listing

or designation through local government review process.

Date

Other Listings

Review Code Reviewer

Page 1 of 1

*Resource Name or #:502 Santa Rosa Ave.

P1. Other Identifier:

*P2. Location: ☐ Not for Publication ✓ Unrestricted

*a. County: Sonoma

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

; R ; 1/4 of

1/4 of Sec

; M.D. B.M.

*b. USGS 7.5' Quad:

Date:

City: Santa Rosa

c. Address: 502 Santa Rosa Avenue

mN (G.P.S.)

Zip: 95404

d. UTM: Zone: 10; mE/

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) Elevation:

APN 009-263-031-000 BURBANK GARDENS DISTRICT

Generic commercial

*P3b. Resource Attributes: (List attributes and codes)

*P4. Resources Present: ✓ Building □Structure □Object □Site □District □Element of District □Other (Isolates, etc.)

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)



P5b. Description of Photo: (View, date, accession #)

Photo taken 2002

*P6. Date Constructed/Age and Sources: □Historic

□Prehistoric □Both

Est. 1940

*P7. Owner and Address:

*P8. Recorded by: (Name, affiliation, and address)

Rosie Klein, Santa Rosa Dept. of Community Development

*P9. Date Recorded: 2005 *P10. Survey Type: (Describe)

Windshield survey

*P11. Report Citation: (Cite survey report and other sources, or enter "none.")

*Attachments: ✓ NONE □Location Map □Sketch Map □Continuation Sheet □Building, Structure, and Object Record □Archaeological Record □District Record □Linear Feature Record □Milling Station Record □Rock Art Record □Artifact Record □Photograph Record □ Other (List): DPR 523A (1/95) *Required information