

**APN: 043-053-055**

**CE26-0133**

**2371 Corby Ave #15**

**CODE ENFORCEMENT OFFICER**

**Jenny Marquez**

**February 6, 2026**

# Stairway to front door



## Step deteriorating



## Bedroom 1

Behind the bedroom door



Moisture reading from wall



## Bedroom 1

**Moisture reading under window**



**Condensation on the window and failed caulking around the window**



## Bedroom 1

**Insect screen required**




**Live roach on bedroom curtain**



## Bedroom 2

**Moisture reading on corner of bedroom wall**



**Condensation under the bed**



## Bedroom 2

**Moisture reading on windowsill**



**Wall texture peeling around the bedroom door**



## Bedroom 3

**Moisture reading on bedroom wall**



**Live roach on the bedroom wall**



## Bedroom 3

**Moisture reading on another bedroom wall**



**Live roach crawling on the wall**



## Bedroom 3

Moisture reading on windowsill



Another reading on the windowsill




## Bedroom 3

**Moisture reading on the wall behind the bedroom door**



**Condensation on the floor**



## Bathroom


**Entry of the bathroom**




**Bathroom light and fan shows  
buildup on the ceiling**



# Wall heater



# Exposed wires



# Thermostat



## Living Room

**Blackish buildup in the corner**



**Moisture reading on the wall with the black buildup**



## Living Room

**The other living room wall with a hole**




**Hole in wall covered with tape**



## Living Room

**Rodent feces**




# Kitchen

Sink



Under the sink



# Kitchen

Under sink




Water leak



## Kitchen

**Behind the stove**



**Sticky Tape Roach trap behind the stove with roaches and rat tail**



## Kitchen

**Wall behind the stove, hole in wood**



## Kitchen

**Heat sensor requires securing**



# Ceiling hole covered with duct tape



## Roof

**Vegetation maintenance required**




**Vent may require coverage possible  
entry for rodents**



## Floor Tiles

### Cracks in floor tiles



# Attachment 1



# Posting of the Notice and Order to Vaccate

