State of California — The Resources Agency DEPARTMENT OF PARKS AND RECREATION

## PRIMARY RECORD

Primary # HRI #

**Trinomial** 

City: Santa Rosa

NRHP Status Code 5D1- Contributor to a district that is listed

or designated locally

Other Listings Review Code

Reviewer

Date

Zip: 95404

Page 1 of 1

\*Resource Name or #: 628Wheeler St.

P1. Other Identifier:

\*P2. Location: ☐ Not for Publication ✓ Unrestricted \*a. County: Sonoma

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

\*b. USGS 7.5' Quad: Date: T ; R ; ¼ of ¼ of Sec ; M.D. B.M.

c. Address: 628 Wheeler Street

d. UTM: Zone: 10; mE/ mN (G.P.S.)

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate) Elevation: APN 009-262-007-000 BURBANK GARDENS DISTRICT

\*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

**Tudor Revival** 

\*P3b. Resource Attributes: (List attributes and codes)

\*P4. Resources Present: ✓Building □Structure □Object □Site □District □Element of District □Other (Isolates, etc.)

P5a. Photo or Drawing (Photo required for buildings, structures, and objects.)

P5b. Description of Photo: (View, date, accession #)

\*P6. Date Constructed/Age and Sources: ✓Historic

□Prehistoric
□Both

Est. 1931

\*P7. Owner and Address:

\*P8. Recorded by: (Name, affiliation, and address)

Rosie Klein, Santa Rosa Dept. of Community Development

\*P9. Date Recorded: 2005
\*P10. Survey Type: (Describe)

Windshield survey



\*P11. Report Citation: (Cite survey report and other sources, or enter "none.")

\*Attachments: ✓NONE □Location Map □Sketch Map □Continuation Sheet □Building, Structure, and Object Record □Archaeological Record □District Record □Linear Feature Record □Milling Station Record □Rock Art Record □Artifact Record □Photograph Record □ Other (List):

DPR 523A (1/95) \*Required information